

Case Details

Case Reference Number : TAX/01/19/2004
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4103A

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5179-ID
 Assigned By : B. Thaiyal Nayagi

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 02/01/2019 12:20 AM
 Vehicle Age(In Months) : 33

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	de	Replace
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	he	Replace
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	he	Replace
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0	X	Not Give
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	om	Replace
One Time Key In	Main			BRACKET, FR TURN	1	58.20	58.20	25.00	43.65	Replace	1	43.65	he	Replace
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	?	Check
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	?	Check
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	?	Check
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	X	Not Give
Total Spare Part Cost									4,879.80			Surveyor Total	1,237.91	
Lump Sum Discount (%)									0.00			Lump Sum Dis (%)	0	
Final Spare Part Cost									4,879.80			Final Sur Total	1,237.91	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	?	Check
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	0	0	X	Not Give
One Time Key In	Main			WIPER WASHER JAR	1	180.10	180.10	25.00	135.07	Replace	1	135.07	de	Replace
One Time Key In	Main			MOTOR NO:2, WIPER WASHER JAR	1	240.00	240.00	10.00	216.00	Replace	0	0	?	Check
One Time Key In	Main			MOTOR NO:1, WIPER WASHER JAR	1	239.00	239.00	25.00	179.25	Replace	0	0	?	Check
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	0	0	?	Check
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	mi ✓	Replace
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. RH	1	49.30	49.30	25.00	36.97	Replace	0	0	?	Check
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	0	Ry	Repair
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	mi ✓	Replace
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Ry	Repair
Total Spare Part Cost									4,879.80		Surveyor Total	1,237.91		
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0		
Final Spare Part Cost									4,879.80		Final Sur Total	1,237.91		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH FRONT PORTION	676.00	300	
Total:		676.00	300.00	

Spray Cost Detail



S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	TO RESPRAY FRONT FENDER RH	378.00	200	
4	TO RESPRAY RIM	180.00	100	
Total:		1,116.00	500.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80	
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	TO WASH AND VACUUM	60.00	0	
6	TO REPLACE SUNDRY PARTS	100.00	20	
7	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER	148.44	148.44	
Total:		728.44	308.44	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,879.80	1,237.91
Total Labour Cost	676.00	300.00
Total Spray Painting	1,116.00	500.00
Other	728.44	308.44
Overall Total	7,400.24	2,346.35
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	2,346.35
Surveyor Approved Amount		2,346.35
No of Repair Days*	5	3

Remarks	Estimator Assesment(\$)	Surveyor Assesment(\$)
		Resurvey before paint
Surveyor Name		Taufikh
Signature		
Survey Date	03/01/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>

Taufikh 97495744
 WP
 3/1/18 1620
 Resurvey before paint
 sure @ Blanktown.
 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: