

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 4 January 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel : 97237799

VEHICLE NO : FBH 2285R

SYM GTS 200

ACCIDENT DATE: 24 December 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Front Cowling <i>cut</i>	1	280.00 ✓
2 Front Mudguard <i>broken</i>	1	190.00 ✓
3 RH Mirror <i>cut</i>	1	85.00 ✓
4 Handle Bar <i>bst</i>	1	160.00 ✓
5 Brake Lever <i>cut</i>	1	85.00 ✓
6 Front Signal RH <i>hid</i>	1	95.00 ✗
7 Front RH Fairing Panel <i>broken</i>	1	160.00 ✓
8 Fork Tube <i>cut</i>	1 set	490.00 ✓
9 Footrest RH <i>broken</i>	1	75.00 ✓
10 Step Panel RH <i>broken</i>	1	150.00 ✓
11 Inner Compartment - Centre <i>hid</i>	1	280.00 ✗
12 Belly Pan <i>broken</i>	1	190.00 ✓
13 Lid Cover <i>defaced hid</i>	1	150.00 <i>max-bid</i> ✗
14 Rear Panel RH <i>cut</i>	1	180.00 ✓
15 Exhaust Guard <i>cut</i>	1	190.00 ✓
16 Exhaust Pipe <i>hid</i>	1	900.00 ✗
17 RH Side Garnish Cover <i>cut</i>	1	220.00 ✓
Sub-Total		3,880.00
Less 10%		388.00
Sub-Total		3,492.00

VEHICLE NO : FBH 2285R

SYM GTS 200

Nett items

1	Rear box C wt	280.00 180/-
2	Dashboard Compartment Nt	280.00 x
3	Towing fee	40.00 ✓
4	Remove & replace necessary parts, align & etc	350.00 250/-
5	Remove & replace fork & top up fork oil	150.00 80/-
6	Putty & respray paint touch-up where necessary	350.00 200/-

Sub-Total 1,450.00

Nett Total 4,942.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

:L.G

04/01/2019 e 1700hrs

Nt Authn

2/5mm 4 days

Signature

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: