



**TeamWork Garage Pte Ltd**  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC: 201015366H

**3RD PARTY CLAIM ESTIMATION**

Vehicle number	SLU1931D
Make / Model	TOYOTA/WISH
Chassis number	JTDGG20W10J008189
Accident date	28 December 2018
Reference	1812-40

AIG Building  
 78 Shenton Way #07-16  
 Singapore 079120

- LRK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and approved by the Insurance Company

Acknowledged by Repairer

Signature:

Date:

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER <i>Dented</i>	593.10 ✓
1	FRONT LH BUMPER COVER <i>M/S</i>	155.95 X
2	FRONT BUMPER RETAINER <i>See M/S broken o/s M/S</i>	120.30 <del>X</del> ✓
1	FRONT BUMPER SPONGE <i>Not torn</i>	120.21 <del>X</del> ✓
1	FRONT BUMPER LOWER GRILLE <i>M/S</i>	395.2 X
1	FRONT LH FENDER <i>Dented</i>	855.93 ✓
1	FRONT LH FENDER INNER SHILED <i>dented / torn</i>	185.83 ✓
1	FRONT LH WHEEL HOUSE PANEL <i>M/S</i>	650.81 X
1	FRONT LH KNUCKLE <i>distorted</i>	580.56 <del>X</del> ✓
1	FRONT LH KNUCKLE BEARING <i>Distorted</i>	155.85 <del>X</del> ✓
1	FRONT LH LOWER ARM <i>distorted</i>	592.51 <del>X</del> ✓
1	FRONT LH SHOCK ABSORBER <i>distorted</i>	501.95 <del>X</del> ✓
1	FRONT LH HEADLAMP <i>scratched</i>	1050.04 ✓
		5563.04
	Less 25 %	1390.76
	Subtotal	4172.28
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	4172.28
1 SET	FRONT BUMPER CLIP <i>M/S</i>	50.00 <del>30/-</del>
1 SET	FRONT FENDER INNER TRIM CLIP <i>M/S</i>	40.00 <del>20/-</del>
1	RIM <i>cut</i>	600.00 <del>350/-</del>
1 BOT	BRAKE FULID <i>M/S</i>	50.00 X
	Subtotal	740.00
	Balance C/F	4912.28
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	4912.28
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 <del>30/-</del>
2	CHECK FRONT WHEEL ALIGNMENT	150.00 <del>60/-</del>
3	REMOVE AND REPLACE FRONT WHEEL UNDERCARRIAGE	200.00 <del>150/-</del>
4	PANEL BEATING ON AFFECTED AREAS	600.00 <del>500/-</del>
5	SPRAY PAINTING ON AFFECTED AREAS	700.00 <del>400/-</del>
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <del>40/-</del>
	Subtotal	1860.00
	Grand total	6772.28

04/01/2019 @ 1600 hrs  
 Not Antised 4 days.  
 L/Sum  
 LRK Auto