

(INSUR)

INS. CASE OWNER:

SUNDARA

CC 3 / III 1900 0215, Ti h/3/19

LKK:

IDAC:

Surveyor:

TAUPIKH

DOI:

16/01/19

Date / Time:

4/1/19

Registered in Merimen:

4/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 16436

Name of Insured:

LPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

3/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN NAM PEE

Driver Tel No.:

(V/L) YES / NO)

Claim No.:

HOT 19010091

Policy No.:

M100015

Make / Model:

Miyazaki

Place of Accident:

JW INTERVIEWED MINTO KO 7mi

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SKX 12435

INSRS:
WSP:
Tel:
Liability:
RMKS:

Performance

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

10/1/19

SKX 12435

SHC 16436

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call Of:

After call Itr to Of:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to Of:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTALGIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS

4,025.20

(4 days)

Reduction:

35 %

Email

Call

FINAL SETTLEMENT

Date/Time:

03/06/19

Confirm with:

CAROLINE

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NL

If NO or B 28, Ass. Lia:

Repair Cost: (w/gst)

SS

4,306.96

Loss of Rental (LOR):

SS

—

(

days)

Loss of Use (LOU):

SS

400.00

x 6

days)

Loss of Income (LOI):

SS

—

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

SS

7.45

Medical:

SS

—

Disbursement:

SS

—

(e.g. Tow/Independent)

Legal Cost:

SS

—

Total:

SS

4,794.41

Global Sum SS:

—

FINAL PAYMENT

Date/Time:

03/06/19

Confirm with:

CAROLINE

Email

Call

Payee 1:

SS

4,794.41

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

SS

—

Name 2:

—

Payee 3: (Strike if N.A.)

SS

—

Name 3:

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4350.00

ASSIGNMENT

From: Date: 16/11/19

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKX 12475

at Workshop m/s

Performance

of

303 Alexander Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Inthiran

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lump Sum:

-

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKX 12475 Yr Regn: 2015 NSV

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216D

CC

1496

Colour:

Bronze

A/C

Insured / Std / NI / NA

Sp. Reading:

55927

T/Radio:

Insured / Std / NI / NA

Eng/No:

W5A2F32080P836751

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 R17.

R:

-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

16/11/19

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Resurvey Hasn't started photo

P/R \$ 4,025.20

(ROR: \$ 2,113.95 / 55%)

Date/Time, File Pass to?

☐

: Prefi. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. \$ + RS. \$

1. PHODA

1. Times

TOTAL:

Report Format :

Lump Sum / I.B.I. (\$) :

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC3/III19000245/hb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 04-01-2019	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1643C		Veh. Inspected	SKX 1247S
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	04/01/2019
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4. Description of Damages				
5. General Information				
Accident Date	03/01/2019		Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

288, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

04 JAN 2019

ESTIMATE

Estimate No. : b1 49631
Date Estimated : 04/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Mohamed Yazid Bin Abdullah
32A Jalan Ismail

Singapore 419287

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX1247S	P836751	27/11/2015	216d G TOURER	0

DESCRIPTION

To replace rear bumper, attachments and repair rear right fender.

1700 - 2,550.00

Painting rear bumper and rear right fender.

1730 - 1,923.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 - 177.00

Sundries. *new*

? 80.00

Total Labour 1: 4,730.00

DESCRIPTION

RR BUMPER RH SIDE GUIDE
REAR BUMPER PANEL PRIMED (LINES PDC
SET MOUNTS PDC SENSOR REAR
REAR LH LIGHT IN THE SIDE PANEL

QTY	PRIC
1	61.50
1	1,029.50
1	62.95
1	365.20

61.50
1,029.50
62.95
365.20

Total Parts : 1,519.15

Claims QQ / 3rd Party / Uninsured losses / Direct Settlement
Inq No. : 161/1901340
Date & Time : 16/1/19 01:34
Surveyor's Name : *Tan Jiah*
Surveyor's Tel : 92498149
Authorized Date : *wp*
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No : *Yes* PML Yes / No : *Yes*
Surveyor's E-mail : *tanjiah@lkkauto.com*
No. of Working Days Recommended : *3-4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- The repairer is on a "Without Prejudice" basis
- No insurance claim is allowed
- Supplies must be resurveyed and is subject to final approval from Insurance Company

Labour 1	4,730.00
Parts	1,519.15
Labour 2	0.00
Excess	0.00
Total GST @ 7%	437.44
Grand Total	6,686.59

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

6,249.15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599W, GST Reg. No. M2-0020081-K



FINAL REPORT

Estimate No. : b1 49631
Date Estimated : 04/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Mohamed Yazid Bin Abdullah
32A Jalan Ismail

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 419287

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SKX1247S	P836751	27/11/2015	216d G TOURER	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace rear RH light in side panel include making good the rear bumper, rear RH fender and knocking out dents caused by the accident			1700.00		1,700.00
To spray paint rear bumper and rear RH fender			1730.00		1,730.00
To check electrical wiring systems and lightings at the rear section for proper function			150.00		150.00
Sundries			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR RH LIGHT IN THE SIDE PANEL	365.20	1.00		365.20

SUPPLEMENTARY ITEMS

Total Labour :	3,660.00
Total Parts :	365.20
Total Labour & Parts :	4,025.20
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,025.20
GST @7%:	281.76
Grand Total :	4,306.96

Vic (LKKAUTO)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Thursday, 14 March, 2019 6:01 PM
To: Taufikh (LKKAUTO); SUR; Vic (LKKAUTO)
Subject: FINAL REPORT / SKX1247S
Attachments: Final Report SKX1247S.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 3,660.00
Total Parts : 365.20
Total Labour & Parts : 4,025.20

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Print Received Message

This mail is associated with :

***SKX1247S (MCT19010091)**
[SHC1643C]

TP

MOHAMED YAZID BIN ABDULLAH


Jan 3 2019 9:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 08/05/2019 15:30 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4794.41) - SKX1247S - Claim Handler: Sundari Nagarajan

Approved:4794.41:



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 2 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg 26 Jul 1990

NF 428A



Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

105, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



H Car Lu
on 16/01

TP repaired.
Pending India's
approval.

GST REG. NO : M2 - 0020081 - X

04 JAN 2019

ESTIMATE

Estimate No. : b1 49631 1331047 Page No. : 1 of 4
Date Estimated : 04/01/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -
Mohamed Yazid Bin Abdullah
32A Jalan Ismail

Singapore 419287

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX1247S	P836751	27/11/2015	216d G TOURER	0

DESCRIPTION

To replace rear bumper, attachments and repair rear right fender.

1700 2,550.00

Painting rear bumper and rear right fender.

1730 1,923.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: 4,730.00

DESCRIPTION

RR BUMPER RH SIDE GUIDE
REAR BUMPER PANEL PRIMED (LINES PDC
SET MOUNTS PDC SENSOR REAR
REAR LH LIGHT IN THE SIDE PANEL

QTY	PRIC	VALUE
1	61.50	? 61.50
1	1,029.50	Rx 1,029.50
1	62.95	? 62.95
1	365.20	any 365.20

Total Parts : 1,519.15

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.
Date&Time 16/1/2019 1340 Excess \$

Surveyor's Name Sign

Surveyor's Tel 63449519 Authorised Yes / No

Authorised Date WP Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjir @ kuantan.com

Est. of Working Days Recommend 3-4 days

Labour 1	:	4,730.00
Parts	:	1,519.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	437.44
Grand Total	:	6,686.59

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate/Policy Number : DMPG18005071
Vehicle Registration Number : SKX1247S
Cover Type : Superior Comprehensive
Policy Type : Private Car
Name of Policyholder/Insured : MOHAMED YAZID ABDULLAH
Commencement Date of Insurance : 27/11/2018
Expiry Date of Insurance : 26/11/2019
Excess :
EXCESS: (SECTION I) S\$ 500.00
ADD'L EXCESS: UNNAMED DRIVERS (SECTION I) ... S\$ 500.00
ADD'L EXCESS: NON-AUTH WORKSHOPS (SECTION I) ... S\$ 300.00
EXCESS: WINDSCREEN S\$ 100.00
YOUNG & INEXP DRIVERS (SECTION I) S\$ 3,000.00

24-Hour Motor Accident Reporting
and Assistance Helpline

6333 2222

www.ergo.com.sg

Finance Company/Hire Purchase Owner : DBS BANK LTD

*Persons or Classes of Persons entitled to drive:

1. The Policyholder
2. NORAIDEE BINTE ABDUL SUKOR
3. Any Person who is driving on the Policyholder's order or permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

* Limitations as to Use:

- 1) Use only for social domestic and pleasure purposes
- 2) Use for Policyholder's business

This Policy does not cover


- 1) Use for hire or reward, racing, pace-making, reliability trial or speed-testing and on race track
- 2) Use for the carriage of goods other than samples in connection with any trade or business
- 3) Use for any purpose in connection with the Motor Trade

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings (*).

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

For and on behalf of **ERGO Insurance Pte. Ltd.**

Approved Insurer



Authorized Signature

D000311(D000311)	DIRECT APPLICATION ACCOUNT	
Vehicle Chassis Number : WBA2E32080P836751, Vehicle Engine Number : 37569380B37C15A		PC1, 01/11/2018 10:41



(Vc)

India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

"Without Prejudice"

Your Ref
Our Ref
Date
Subject

09 April 2019

ACCIDENT INVOLVING VEHICLES SKX1247S & SHC1643C ON 03.01.2019

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	4306.96
Loss of use	:	S\$	480.00 (S\$80.00 x 6 days)
LTA search fee	:	S\$	7.45
Total	:	S\$	4794.41

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & LTA search slip
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Cresendo Lagman
Customer Service Manager, Body & Paint

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W



LETTER OF AUTHORISATION

ACCIDENT INVOLVING 3KX1247S & SHC 1643C ON 03-01-2019.

I, Mohamed Yazid owner of Vehicle Registration No. 3KX1247S hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:


Name : 51780859 A (Date)

NRIC No.: Mohamed Yazid Abdullah

In the presence of:


Name : _____ (Date)

NRIC No.:

PERFORMANCE MOTORS LIMITED
38, Persiaran Pahlawan
Sime Darby Perdana Commerce
Sungaiway 150011
Tel: 0319 0100 (Main)
0319 0111 (Extension)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III-Direct Settlement (PODS)

India Ref: 40519010091
 Claimant Ref: SKK12475

We/I, Performance Motors Ltd (workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 4356.54 (repair cost), S\$ 480.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SKK12475 that was damaged pursuant to the accident which occurred on 3-1-19 (date) at Jalan Sultan (location) involving vehicle no. SHC1433 (insured vehicle). This is pursuant to the inspection conducted on 16-1-19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Richmond Razul Bin Abdullah ("the third party claimant") of vehicle no. SKK12475 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKK12475 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,394.41 to PERFORMANCE MOTORS LIMITED

Dated this 03 day of 06 20 19

CLAIMANT:

Signature: [Signature]
 Signed by "the workshop" (with chop)

Name: _____

NRIC: PERFORMANCE MOTORS LIMITED

Address: 303 Alexandra Road
Prime Darby Performance Centre
Singapore 159941
TEL: 63190100 (Sales)
63190111 (After sales)

Nationality: _____

Occupation: _____

WITNESS:

Signature: [Signature]
 Signed by appointed Surveyor

Name: LKK AUTO CONSULTANTS Pte Ltd

NRIC: _____

Address: 51 Ubi Ave 1 #11-25
Paya Ubi 2nd park (S) 408933

Nationality: _____

Occupation: _____

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1331047
Date IN : 16/01/2019
Motor Claim Advisor Inthiran A/L Thurasamy

Page No. : 1 of 2
Invoice Number : 2081939 / WSB
Invoice Date : 28/03/2019
Payment Terms : 30 Days From Invoice
Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -
Mr Mohamed Yazid Bin Abdullah
32A Jalan Ismail

Singapore 419287

- INVOICE TO - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX1247S	P836751	27/11/2015	216D G TOURER	55929

--- LABOUR 1 ---

	NETT
To replace rear right light in side panel including make good the rear bumper, rear right fender and knock out dented area caused by the accident.	1,700.00
To respray rear bumper and rear right fender.	1,730.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 03.01.2019. 3RD PARTY CAR : SHC1643C.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON 16.01.2019 AT 1:40PM. AUTHORISED REPAIR BY MS VIC ALPEH FROM LKK AUTO ON 15.01.2019 VIA EMAIL.	
PROPOSE LOSS OF USE = \$80x6. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
LTA SEARCH FEE = \$7.45.	0.00

Total Labour 1: **3,660.00**

--- PARTS ---

REAR RH LIGHT IN THE SIDE PANEL

Qty	Retail Price	NETT
1	365.20	365.20
Total Parts :		365.20



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 04 Jan 2019 / 16:11:09

Receipt Date/Time : 04 Jan 2019 / 16:11:09

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190104-003339

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
--	---------------------------------	---------------------------------------

Result of Insurance Enquiry - SHC1643C

As at 03 Jan 2019/21:40:00

Insurance Co: INDIA INT'L INS PTE LTD

1 Insurance Enquiry - SHC1643C
Enquiry Fee
20190104160902626170

7.00	0.49	7.49
------	------	------

Sub-Total	7.00	0.49	7.49
------------------	------	------	------

Total Before Rounding	7.00	0.49	7.49
------------------------------	------	------	------

Rounding Difference			0.04
----------------------------	--	--	------

Total Amount Payable			7.45
-----------------------------	--	--	------

Paid By

xxxxxxxxxxxx9609	Credit Card: Visa/MasterCard	7.45
------------------	---------------------------------	------

Total		7.45
--------------	--	------

Cash Change		0.00
--------------------	--	------

Tendered Amount		7.45
------------------------	--	------

Excess Refundable Amount		0.00
---------------------------------	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2019 Edit Reg		16 Jan 2019 00:00 Edit Adj Rpt	S\$4,025.20 Edit Estimates	S\$4,025.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD. Co. Reg. No.: -								
Main Claimant:	MOHAMED YAZID BIN ABDULLAH ID: S1780859A								
Vehicle Reg. No.:	SKX1247S	Date of Loss:	03/01/2019 21:00 - :59 [37 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19010091	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC1643C	Policy No. (Claimant):	DMPG18005071						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (08/05/2019): Alert - Adj Mandate Approved (S\$4794.41) - SKX1247S - Claim Handler: Sundari Nag... III_SG (15/01/2019): Alert - Adj Mandate Approved (S\$0.00) - SKX1247S - Claim Handler: Sundari Nagara... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX1247S (MCT19010091)
[SHC1643C]
TP
MOHAMED YAZID BIN ABDULLAH
Jan 3 2019 9:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/19 09:26	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	28/03/19 09:26	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
23	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
24	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
25	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
26	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
27	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
28	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
29	28/03/19 09:27	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/01/19 16:53	TP EST & GIA REPORT	Load PDF	
2	18/01/19 15:18	TP ESTIMATE- MARKED	Load PDF	
3	29/04/19 14:00	WORKSHOP INVOICE	Load PDF	
4	29/04/19 14:00	LTA SEARCH	Load PDF	
5	29/04/19 14:00	LOD	Load PDF	
6	13/06/19 10:40	DISCHARGE VOUCHER	Load PDF	
7	13/06/19 10:40	AUTHORISATION TO ACT FORM	Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
			1	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	07/01/19 08:47	Singapore Accident Statement	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19000245/T1HB3Q2

Date: 13/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : SKX1247S **Insured Vehicle No :** SHC1643C
 Date of Loss: 03/01/2019 Nature of Claim: TP Claim No: MCT19010091

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX1247S**
 Make & Model: BMW 216i, 1.5 (A) Engine No: HIDDEN
 Reg. Date: 27/11/2015 (Man. Year: 2015) Chassis No: MBA2E32080P836751
 Colour: Bronze Odometer: 55927 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,599.15	445.20	1,153.95	72.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	3,580.00	1,070.00	23.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,249.15	4,025.20	2,223.95	35.59
+ GST 7.00/7.00% (S\$)	437.44	281.76	155.68	35.59
Nett Amount (S\$)	6,686.59	4,306.96	2,379.63	35.59
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,794.41		

INSPECTION

Date of Assignment: 16/01/2019
 Date Inspected: 16/01/2019 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2019)
Parts: M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKX1247S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	61.50 FS	*- FS
3	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Repair	1,029.50 FS	*- FS
4	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.95 FS	*- FS
5	1		*REAR LH LIGHT IN THE SIDE PANEL	Cracked	365.20 FS	*365.20 FS
				Total Parts (\$\$)	1,599.15	445.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,ATTACHMENTS AND REPAIR REAR RIGHT FENDER	New	2,550.00	1,700.00
2	PAINTING REAR BUMPER AND REAR RIGHT FENDER	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			4,650.00	3,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >