

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1474/2018/GW
Date : 29-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr. Zhang Ying
Address : Blk 10 Bedok Rise
#01-32
Singapore 469601
Telephone : (HP) 97246918
Type of Claim : Own damage claims
Policy No. : 2100507392-01
Vehicle No : **SMG 3230 S**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Dec-18
Engine No : CZE 847980
Chassis No : WAUZZZ8V3K1012123
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Allan Wu / Johnny Boo
Accident Date : 27-Dec-18
Place of Accident : TAKASHIMAYA CAR PARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 3230 S

| S/N | Nature of Jobs | | Estimated Charges | Surveyor's recommendation |
|----------------------|--|-----|--------------------|---------------------------|
| 1 | To remove and reinstall rear parking aid. Check function. | S/N | \$ 280.00 | ✓ |
| 2 | To renew lhs 1/4 glass and rear windscreen to facillitate fender renewal. | S/N | \$ 600.00 | X |
| 4 | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. | S/N | \$ 1,400.00 | X |
| 5 | To remove and reinstall rear seat assy, back rest, ABCD pillar trims, luggage compartment trims. Dislodge rood liner and disengage curtain airbag etc. | S/N | \$ 1,400.00 | X |
| TOTAL LABOUR CHARGES | | : | <u>\$ 3,680.00</u> | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 3230 S

| S/N | Nature of Jobs | Estimated Charges |
|-----------------------------|---|-----------------------|
| 6 | To dismantle rear bumper, rear lid. Cut out and weld lhs rear fender and end panelling. Renew rear bumper. Re-organize rear crash management components. Reinstall all parts removed. | \$ 7,200.00 1000 |
| 7 | To respray rear bumper, lhs rear fender, lhs ill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works. | \$ 3,900.00 1100 |
| 10 | To carry out diagnostic check. | S/N \$ 192.00 ✓ |
| TOTAL LABOUR CHARGES | | : \$ 14,972.00 |

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3230 S

| S/N | Parts Description | Damage Parts & Prices | |
|------------------------------|---|-----------------------|---------|
| | | S/NETT | REMARKS |
| 1 | REAR BUMPER <i>Distorted</i> | \$ 1,697.00 | ✓ |
| 2 | REAR BUMPER STICKY PAD <i>new</i> | 4 | TBC ✓ |
| 3 | REAR BUMPER FIXING PARTS <i>new</i> | \$ 166.00 | + |
| 4 | ADAPTER WHEEL HOUSING LIUNER - LH <i>new</i> | \$ 32.00 | + |
| 5 | REAR BUMPER UPPER GUIDE SECTION-LH <i>new</i> | \$ 14.00 | + |
| 6 | REAR BUMER LOCKING MECHANISM <i>new</i> | \$ 25.00 | + |
| 7 | REAR BUMPER SPOILER <i>new</i> | \$ 206.00 | + |
| 8 | REAR LIGHT REFLECTOR-LH <i>new</i> | \$ 35.00 | + |
| 9 | REAR BUMPER SIDE REINFORCEMENT ? | \$ 501.00 | ? |
| 10 | REAR BUMPER BRACKET-LH <i>new</i> | \$ 23.00 | X |
| 11 | REAR BUMPER GUIDE SECTION-LH <i>new</i> | \$ 57.00 | + |
| 12 | REAR SENSOR <i>new</i> | 2 \$ 421.00 | + |
| 13 | REAR SENSOR SEAL RING <i>new</i> | 4 \$ 14.00 | + |
| 14 | REAR VENT TRIM <i>new</i> | \$ 60.00 | + |
| 15 | AERIAL FOR ACCESS AND START AUTHORISATION | \$ 65.00 | + |
| 16 | LED TAIL LIGHT-LH <i>new</i> | \$ 730.00 | ✓ |
| 17 | LED TAIL LIGHT TRIM-LH <i>new</i> | \$ 26.00 | + |
| 18 | REAR SIDE PANEL-LH <i>Repair</i> | \$ 2,006.00 | + |
| 19 | REAR WINDOW | \$ 704.00 | + |
| 20 | PRIMER | 2 \$ 37.00 | + |
| 21 | REAR SIDE WINDOW-LH | \$ 502.00 | + |
| SUB-TOTAL SPARE PARTS | | \$ 7,321.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3230 S

| S/N | Parts Description | Damage Paid | |
|----------------------|--|-------------|-----------|
| | | S/NETT | RE |
| 21 | REAR CROSS PANEL <i>Repair</i> | \$ | 317.00 + |
| 22 | REAR CROSS PANEL REINFORCEMENT <i>Repair</i> | | TBC + |
| 23 | REAR CONNECTING PLATE-LH <i>Repair</i> | \$ | 126.00 + |
| 24 | ACRYLIC SEALANT | S/N \$ | 180.00 + |
| 25 | CAVITY WAX | S/N \$ | 140.00 + |
| 26 | STONE CHIP | S/N \$ | 180.00 + |
| 27 | METAL FILLER POWDER | S/N \$ | 280.00 + |
| 28 | REAR WINDSCREEN SEALANT | S/N \$ | 200.00 + |
| 29 | 1/4 GLASS SEALANT | S/N \$ | 100.00 + |
| 30 | SUNDRIES ? | \$ | 800.00 ? |
| TOTAL SPARE PARTS | | \$ | 9,644.00 |
| TOTAL LABOUR CHARGES | | \$ | 14,972.00 |
| GRAND TOTAL | | \$ | 24,616.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 04/01/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , OS Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant