

INS. CASE OWNER:

Wang Peter

CC

4, Asm 1900

0253

K 2039

LKK:
IDAC:

91546

Surveyor:

KSC

DOI:

4/1/2019

Date / Time:

4/1/2019

Registered in Meridian:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKR 1983G

Name of Insured:

Low Chiew Leng

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A: 30/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8m01827

Policy No.:

Make / Model:

Place of Accident:

C76

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SDA 9638Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

Ah Lim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

10/1
Asm

SDA 9638Z - X

SKR 1983G - 01/11/18 10:45 / 11/18 10:45 / 11/18 10:45

10/1/19

PDR REQUESTED TO SWAMP W/P REPORT.

* TP PPS LOWPC.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Asst. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

(\$

x

days)

Loss of Income (LOI):

\$5

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle / WP

2) Report Format:

TP

3) Survey fee:

25%

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2086G

Vehicle Details

Vehicle No.: SDA9638Z
Vehicle to be Exported: No
Intended Deregistration Date: 31 Dec 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: A180 (R17)
Primary Colour: Black
Manufacturing Year: 2013
Engine No.: 27091030330142
Chassis No.: WDD1760422J229693
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$23,222.00
Original Registration Date: 03 Mar 2014
First Registration Date: 03 Mar 2014
Transfer Count: 1
Actual ARF Paid: \$14,511.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Mar 2024
PARF Rebate Amount: \$10,883.00

Intended COE Rebate Details

COE Expiry Date: 02 Mar 2024
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$77,201.00
COE Rebate Amount: \$39,928.00
Total Rebate Amount: \$50,811.00

The information contained herein is correct as at 31 Dec 2018

OK

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: SDA9638Z

Version: 1712

Date calculated: 01/03/2019 11:32 AM

Full Report

Registration: SDA9638Z

Printed: 01/03/2019 11:33 AM

Code	Description	WU	Price SGD
72-5712 01	R + R R/F WINDOW REGULATOR DRIVE MOTOR (DOOR TRIM REMOVED)	2.0	9.00
72-7933 01	R + R RIGHT FRONT DOOR EDGE PROTECTION	3.0	13.50
72-7935 01	R + R RIGHT REAR DOOR EDGE PROTECTION	2.0	9.00
88-5232 01	R + R RIGHT SILL TRIM	4.0	18.00
68-1040 01	R + R RIGHT A-PILLAR LOWER TRIM	2.0	9.00
68-1093 01	R + R R/LOWER B-PILLAR TRIM	5.0	22.50
1782	R/R DOOR REPAIR	10 30.0*	135.00
2102	R/SILL PANEL REPAIR	30.0* ?	135.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		13.00	130.0
Total of Labour			585.00

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	RIGHT FRONT DOOR NEW PART PAINTING	16.0	
	R/SILL PANEL COVER NEW PART PAINT K1R	7.0	
	R/R DOOR REPAIR PAINTING >50%	23.0	
	R/SILL PANEL REPAIR PAINTING >50%	15.0	

Paint Material Per Part

Code	Description	Price SGD
1482	RIGHT FRONT DOOR NEW PART PAINTING	45.92
2208	R/SILL PANEL COVER NEW PART PAINT K1R	26.57
1782	R/R DOOR REPAIR PAINTING >50%	30.42
2102	R/SILL PANEL REPAIR PAINTING >50%	12.25

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		61.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total	10 WU/h	91.0	409.50

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: SDA9638Z
 Version: 1712
 Date calculated: 01/03/2019 11:32 AM

Full Report
 Registration: SDA9638Z
 Printed: 01/03/2019 11:33 AM

Material Cost - Paint	Price SGD
New Part Painting	45.92
New Part Painting - Plastic K1R	26.57
Repair Painting	42.67
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	152.76

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
1480	R/F DOOR MODULE	176 720 6600		350.00 ?
1482	RIGHT FRONT DOOR	176 720 0205		B ₁ 950.00 ✓
1488	R/F UPPER DOOR HINGE	246 720 1237		n 70.00 X
1496	R/F LOWER DOOR HINGE	246 720 0437		n 85.00 X
1510	R/F DOOR SEAL	204 727 1187		me 180.00 ?
1552	R/F WINDOW MOTOR	246 906 5200		330.00 ?
1578	R/F DOOR LOCK	166 720 0235		n 190.00 X
1714	R/F DOOR TRIM	176 720 0800 9J00		su 555.00 X
2208	R/SILL PANEL COVER	246 698 0654 9999		cm 250.00 —
1000	SIDE SKIRT CLIPS	123		me 100.00 ✓
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				3,060.00
Addition(+15.00%)				459.00
Sundry Parts(+2.0%)				2.30
Total				3,521.30

Extras

Code	Description	Price SGD
1001	TRANS DOOR FITTING	me 80.00* 609
1002	RESET & DIAGNOSE	180.00* 7
1003	FULL WRAP STICKER	(Bill) 1,800.00* X?
Total Extras		2,060.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

SURVEYOR COPY

Claim Reference:
Assessment number: SDA9638Z
Version: 1712
Date calculated: 01/03/2019 11:32 AM

Full Report
Registration: SDA9638Z
Printed: 01/03/2019 11:33 AM

LKK
12:30

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	2018-12-30
Estimated Repair Time:	10 4 day	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	A-CLASS (W176)
Sub Model:	A 180 BE
Model Sheet Number:	03 A2 41
Registration:	SDA9638Z
VIN number:	WDD1760422J229693
Odometer:	

Model Specs

FR PRODUCTION START	TECH CHANGES 13/02	MODEL 2014	A/C THERMATIC
RAIN SENSOR	DIPPING DOOR MIRROR	COLLISION WARNER	ELECT FOLDING MIRROR
AUDIO SYSTEM 20 CD	LIGHT-/VIEW PACKAGE	CLOTH/IMI LEATH PAD	STYLE-PACK
MULTI FUNCT S-WHEEL	SILL MLDG ILLUMINAT	S/WHEEL TIP SWITCHES	DRIVER SEAT MEMORY
PASS SEAT MEMORY	ELECT LUMBAR ADJUST	SEAT COMFORT PACKAGE	MEDIA INTERFACE
ILLUM SUN VISOR	DRIVER SEAT TRAY	PASS SEAT ST/BOX	FRT SEAT LUGGAGE NET
POWER REDUCTION	SOCKET 12V	EMISSION STD EURO 6	STORAGE PACKAGE
ECO START/STOP	CRUISE CONTROL	7 SPEED AUTOMATIC	TYRES 225/45 VR 17
WHEELS 7.5J X 17 ALU	TYRE W/FLAT RUNNING	ELECTRIC HORN	KNEE AIRBAG
PARKTRONIC	COMPRESSOR VARIABLE	TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD			

Not Notified
I.B.I
Resurvey By paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: SDA9638Z

Version: 1712

Date calculated: 01/03/2019 11:32 AM

Full Report

Registration: SDA9638Z

Printed: 01/03/2019 11:33 AM

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐

Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	13.50
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	9.00
61-1117 01	R + R R/UNDERFLOOR COVER		3.0	13.50
72-1515 01	RENEW R/F DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE		31.0	139.50
72-2690 01	RENEW R/F UPPER DOOR HINGE		3.0	13.50
72-6665 01)	RENEW R/F DOOR TRIM (REMOVED)		5.0	22.50
72-5886 01	RENEW RIGHT FRONT DOOR BASIS SUPPORT (DOOR MODULE REMOVED)		5.0	22.50

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: SDA9638Z

Version: 1712

Date calculated: 01/03/2019 11:32 AM

Full Report

Registration: SDA9638Z

Printed: 01/03/2019 11:33 AM

Final Calculation

	SGD	SGD
Parts	3,060.00	
Addition(+15.00%)	459.00	
Sundry Parts(+2.0%)	2.30	
Total Parts		3,521.30
Labour Time Base 10 WU/h		
Total 130.0 WU X 45.00 SGD/h	585.00	
Total of Labour		585.00
Total Of Extras		2,060.00
Paint Work Time Base 10 WU/h		
Labour Cost 91.0 WU X 45.00 SGD/h	409.50	
Material Cost	152.76	
Total Paint Including Material		562.26
Repair Cost Excludes GST		6,728.56
GST (+7.0%)		471.00
Repair Cost Included GST		7,199.56

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

◀ Service Request Details

Claim

S8M018L7

Reference

None ✎

Loss Date

30 December 2018

Request Date

4 January 2019

Due Date

11 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDA9638Z

Make

TPVD MERCEDES-BENZ

04/01/2019 @ 10:12am

Zila vehin

Kenneth

Service Address

...

Primary Contact/Insured

LOW CHIEW LENG (LIU QIULING)
26 BENDEMEER ROAD, #17-553 BENDEMEER VILLE, 330026, Singapore
98710233

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19000253/Kea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Date : 18-03-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 1983G	Veh. Inspected	SDA 9638Z	
Policy No.	GA230754/1	Coverage (\$)	0.00	
Claim No.	S8M018L7	Excess (\$)	0.00	
Assign From		Assign Date	04/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ A180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD1760422J229693	Colour	METALLIC GREY	
Odometer	97748	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	5 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	5 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/12/2018	Inspection Date	04/01/2019	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDA 9638Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	R/F DOOR MODULE (CONSISTENT) (WCP)	* CHECK	350.00	-
1	RIGHT FRONT DOOR (CONSISTENT) (WCP)	BENT	950.00	950.00
1	R/F UPPER DOOR HINGE (CONSISTENT) (WCP)	TO REPAIR SEE LABOUR	70.00	-
1	R/F LOWER DOOR HINGE (CONSISTENT) (WCP)	TO REPAIR SEE LABOUR	85.00	-
1	R/F DOOR SEAL (CONSISTENT) (WCP)	NECESSARY	180.00	180.00
1	R/F WINDOW MOTOR (CONSISTENT) (WCP)	* CHECK	330.00	-
1	R/F DOOR LOCK (CONSISTENT) (WCP)	TO REPAIR SEE LABOUR	190.00	-
1	R/F DOOR TRIM (CONSISTENT) (WCP)	SERVICEABLE	555.00	-
1	R/ SILL PANEL COVER (CONSISTENT) (WCP)	CRACKED	250.00	250.00
1	SIDE SKIRT CLIPS (CONSISTENT) (WCP)	NECESSARY	100.00	100.00
	COST PLUS 15%		459.00	222.00
			3,519.00	1,702.00
	SPECIAL NETT ITEMS			
1	TRANS DOOR FITTING (SN)(CONSISTENT)	NECESSARY	80.00	60.00
1	RESET & DIAGNOSE (SN)(CONSISTENT)	* CHECK	180.00	-
1	FULL WRAP STICKER (SN)(CONSISTENT)	* CHECK	1,800.00	-
			2,060.00	60.00
	LABOUR			
	LABOUR COST.INCLUSIVE OF THE REPAIR OF R/F UPPER DOOR HINGE,R/F LOWER DOOR HINGE AND R/F DOOR LOCK.		409.50	409.50
	METERIAL COST.		152.76	152.76
			-	-
			-	-
			-	-
			562.26	562.26
	GRAND TOTAL		6,141.26	2,324.26
	RECOMMENDED COST OF REPAIRS			2,324.26

Report Ref No. CC4/ASM19000253/Kea3q2



Report Ref No. CC4/ASM19000253/Kea3q2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

58H018L7

Reference

CCA/ASM19000253/KoaJd2

Loss Date

30 December 2018

Report Date

4 Jan 2019 9:20:00 AM

Request Date

16 January 2019

Due Date

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SDA963BZ
Make	TPVD MERCEDES-BENZ
Model	A180 R17-1.6 L
Service Address	
...	
Primary Contact/Insured	

LOW CHEW LENG (LIU QIULING)
26 BENDEMEER ROAD, #17-553 BENDEMEER
VILLE, 230026, Singapore
98710233

Claim Handler

WONG Wee Fu
6568804888
weefu.wong@laxa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Reports & Statement				
Accident Statement			Merimen	
Invoice				
LKK Invoice 1.pdf		Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 March 2019

