



Mercedes-Benz

LKK Survey

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLX228S

Ling Kwee Lee

60 Elias Road
#14-01
Singapore 519938

Mobile: 96600400

Vehicle & Document Information

WIP No 29624
Reg No/Reg Date SLX228S / 12/02/2018
Date In/Mileage / 0
Chassis No WDD2130422A339550
Engine No 27492031237670
Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim 029 988 Diamond Sil/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	03/01/2019/ 18:51	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

M BPNSUN
POLICY NO/ACC DATE : 1800012558 // 22/12/2018
DRIVE IN/EXCESS : 03/01/2019 // TP VEH NO SJS1035A AXA
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW
BODY PANELS WITH REFINISH.

A BPIRES
RESpray FRONT BUMPER

A BPILAB
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO
STANDARD SETTINGS.

A BPILAB
CHECK HEADLAMP WITH FOCUS ADJUSTMENT, NETT

M RIGHT HEADLAMP UNIT

M RIGHT FRONT INNER DISTANCE SENSOR

M RIGHT FRONT OUTER DISTANCE SENSOR

960 1200.00

600 750.00

0.10 ✓ 380.00

? 120.00

? 3352.04

1.00 3352.04 00.00

1.00 177.22 00.00

1.00 177.22 00.00

? 177.22

? 177.22

Tanjin 97495749
- WP
16/1/19 @ 1535
Ready after repair.
03 days.
surelkhanto.wn

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Nett 6,156.48
7% GST on 6156.48 430.95
Total Payable 6,587.43

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg