

Driver:

MPG

DOI:

ASSIGNMENT

4-1-19

Date / Time:

3/1/2019

Registered in Merimen:

2/1/2019

Pre-assign / CCU / FTE

SH 9493J



Insured Vehicle No.:

CTM

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

3/1/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Miomovis

Make / Model:

H. 140

Place of Accident:

Woodlands Ave 6

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLQ 76327



INSRS:

WSP:

Tel:

Liability:

RMKS:

World Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

9/1/19

Joy

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

9/1/19

SLQ 76327. x
SH 9493J. LK/M/1702383/Am39+. 007 23/1/19
- 103/11/16059. 001 11/03/19. 001 11/03/19

Seek liability (Pending approval) Approved.

File PACC RT type report.

Pending mandate approval.

Offer #2316-17 (Pending acceptance)

Settle #2316-17, DV send (Pending DV)

DV in (File PACC Admin to close).

STAGE	DATE / PIC	
Non-Reporting ltr (1st):		
Non-Reporting ltr (2nd):		
Non-Reporting ltr (Final):		
Notification ltr (if non-pickup):		
Call OI:		
After call ltr to OI:		
Documentation Check List: Handler Typist		
Notification ltr (if non-pickup)	☒	☐
After call ltr to OI:	☒	☐
Authorization To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice	☒	☐
LTA / GIA :	☒	☐
Medical Bill:	☒	☐
PIR:	☒	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☒	☐
Others:	☒	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	S\$ 1931.00	(3 days) Reduction:	S\$ 454.75	% 20	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:	Confirm by:	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27	Email ☒ Call ☐	
Repair Cost:	S\$ 2066.17	If NO or B 28, Ass. Lia:			
Loss of Rental (LOR):	S\$ -	a year ended TP			
Loss of Use (LOU):	S\$ 750.00 (\$ 50 x 5 days)				
Loss of Income (LOI):	S\$ - (\$ x days)				
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]			
GIA/LTA Search:	S\$ -				
Medical:	S\$ -				
Disbursement:	S\$ -	(e.g. Tow/ Independent)			
Legal Cost:	S\$ -				
Total:	S\$ 2316.17	Global Sum S\$:			
FINAL PAYMENT		Date/Time:	Confirm with:	Confirm by:	
Payee 1:	S\$ 2316.17	Name 1:	World Auto Pte Ltd		
Payee 2: (S\$ 0.00)	S\$ -	Name 2:			
Payee 3: (S\$ 0.00)	S\$ -	Name 3:			

COPY SENT 4/1/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP


\$750/-

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SLQ 76322**
 at Workshop n/s: **WORLD AUTO**
 of: **No. 1, Kamsi Loop**
 Insured: **111**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res: Yes or No
 Lump Sum: **1-1-1** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **up**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLQ 76322** Yr Regn: **2017 July**
 Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **TOYOTA PRINS 1.8 A** C.C: **1798**
 Colour: **WHITE** A/C: Insured / Std / NI / NA
 Sp. Reading: **107857** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **3TDKB3FU003562297**
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ STD A/Rim or
 Tyre Size: F: **195/65R15**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **03/01/19** D.O.I: **04/01/19**
 Survey held at: **WORLD AUTO**
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/O = \$1931.00 / 3 repair days. (Red = \$7541.75 / 80%)

*** 3 repair days + 2 PRS = 5 days.**

Call/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) S + PG \$1

1) Phone

1) Other

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

TOTAL

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD Supplementary Estimate : ES000006

64 CECIL STREET,
#04-05 IOB BUILDING 049711

Attention : Motor Claim Department

Contact : 6347 6100 Fax No. : 6224 4174

Date : 07/01/2019
Vehicle Num. : SLQ 7632Z(LCR)
Make/Model : TOYOTA PRIUS HYBRID
Chassis/Eng# :
Accident Date : 03/01/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.		LIST ITEMS :		
		REAR LOWER BUMPER		570.00
		List TotalS\$:		570.00
		25.00% Discount S\$:		142.50
				427.50

E. & O.E.

Total S\$: 427.50

for WORLD AUTO PTE LTD

9472.75

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000142

Date : 03/01/2019
 Vehicle Num. : SLQ 76322 (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# : JTDKB3FN0V / 2017
 Accident Date : 03/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1	1	REAR BOOTLID OUTER GARNISH X		570.00 X
2	1	REAR BOOT HYBRID EMBLEM (PRIUS) X		89.00 X
3	1	REAR BOOT PRIUS EMBLEM X		89.00 X
4	1	REAR BOOT WEATHER STRIP X		280.00 X
5	2	REAR TAIL LAMP X add damage	900.00	1,800.00 X
6	1	REAR BUMPER X repair		900.00 458-
7	1	REAR END PANEL X repair		750.00 X
8	1	REAR END PANEL TOP GARNISH X repair		170.00 X
9	1	REAR BUMPER TOW COVER add 7.61		89.00 82-
10	1	REAR BUMPER REINFORCEMENT		350.00 318-
11	2	REAR BUMPER TAIL LAMP X add damage	750.00	1,500.00
12	2	REAR BUMPER RETAINER X add	110.00	220.00
List Total S\$:				6,807.00
25.00% Discount S\$:				1,701.75
				5,105.25
SPECIAL NETT ITEMS :				
1	1	REAR BOOTLID OUTER GARNISH CLIPS X add		40.00 X
2	2	REAR TAILLAMP CLIPS X add	40.00	80.00 X
3	1	REAR BUMPER CLIP add		40.00 30-
4	1	REAR END PANEL TOP GARNISH CLIPS add		40.00 20-
5	1	REVERSE SENSOR X add		200.00 200? X
Special Nett Total S\$:				480.00
LABOUR :				
TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT				180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldauto@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000142

Date : 03/01/2019
 Vehicle Num. : SLQ 7632Z (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 03/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO REPLACE PARTS

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER
 REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
 PANEL WHERE NECESSARY & REPLACE ABOVE PARTS

~~1,200.00~~ 350

TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS

~~1,000.00~~ 400

TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS
 REVERSE SENSORS AND START/STOP UNIT CAPACITORS

~~180.00~~ 60

DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE
 REPAIRS AND REACTIVATE BACK SAME
 (HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 X

810

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING
 FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST
 REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 X

Labour Total S\$:

3,460.00

643.50

50.00

810.00

1503.50

E. & O.E.

Total S\$: 9,045.25

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- To display damaged parts during resurvey
- To display damaged parts during resurvey

Acknowledged by Repairer

Signature:

Date:

Resue
 H# 50010068
 3 days
 P/P

04/01/19 @ 1110

Resue by paint

3 days
 P/P

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES000142

Date : 03/01/2019

Vehicle Num. : SLQ 7632Z (LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 03/01/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOTLID OUTER GARNISH X		570.00
2.	1	REAR BOOT HYBRID EMBLEM (PRIUS) X		89.00
3.	1	REAR BOOT PRIUS EMBLEM X		89.00
4.	1	REAR BOOT WEATHER STRIP X		280.00
5.	2	REAR TAIL LAMP X old damage	900.00	1,800.00
6.	1	REAR BUMPER X		900.00
7.	1	REAR END PANEL repair		750.00
8.	1	REAR END PANEL TOP GARNISH ?		170.00
9.	1	REAR BUMPER TOW COVER cut ?		89.00
10.	1	REAR BUMPER REINFORCEMENT ?		350.00
11.	2	REAR BUMPER TAIL LAMP X old damage	750.00	1,500.00
12.	2	REAR BUMPER RETAINER X	110.00	220.00
List Total S\$:				6,807.00
25.00% Discount S\$:				1,701.75
				5,105.25
SPECIAL NETT ITEMS :				
1.	1	REAR BOOTLID OUTER GARNISH CLIPS X		40.00
2.	2	REAR TAILLAMP CLIPS X	40.00	80.00
3.	1	REAR BUMPER CLIP na		40.00 30
4.	1	REAR END PANEL TOP GARNISH CLIPS na		40.00 20
5.	1	REVERSE SENSOR ?		280.00 200?
Special Nett Total S\$:				480.00
LABOUR :				
TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT				180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000142

Date : 03/01/2019
 Vehicle Num. : SLQ 7632Z (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 03/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REPLACE PARTS		
		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	1,200.00	350
		TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS	1,000.00	400
		TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	180.00	60
		DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	X
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	X
		Labour Total S\$:		3,460.00

E. & O.E.

Total S\$: 9,045.25

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
 Hg 500100 68
 3 days
 P/P
 04/01/19 @ 1110
 Resue by paint

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 3 January 2019 3:32 PM
To: ainee31@worldauto.com.sg; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: worldautopl@yahoo.com.sg; Sundari Nagarajan - III
Subject: RE: Request for Third Party Motor Claim Survey (SLQ7632Z) DOA: 03-01-2019

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLQ7632Z and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

3.40pm @ 3/01/2019
vehicle In
person @ Ainee

From: ainee31@worldauto.com.sg [mailto:aine31@worldauto.com.sg]
Sent: 03 January, 2019 3:12 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: worldautopl@yahoo.com.sg
Subject: RE: Request for Third Party Motor Claim Survey (SLQ7632Z) DOA: 03-01-2019

Dear All,

- LKK Auto Consultants Pte Ltd

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, January 3, 2019 2:54 PM
To: aine31@worldauto.com.sg
Cc: worldautopl@yahoo.com.sg
Subject: RE: Request for Third Party Motor Claim Survey (SLQ7632Z) DOA: 03-01-2019

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: aine31@worldauto.com.sg [<mailto:aine31@worldauto.com.sg>]
Sent: 03 January, 2019 12:31 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: worldautopl@yahoo.com.sg
Subject: Request for Third Party Motor Claim Survey (SLQ7632Z) DOA: 03-01-2018

Good afternoon,

We would like to request for a Third Party Motor Claim Survey, details as follow;

Our Vehicle: SLQ7632Z
Your Insured: SH9493J
DOA: 03-01-2018

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd
No.1, Kranji Loop
Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

View Received Message

This mail is associated with :

***SLQ7632Z (MCT19010056)**
[SH9493J]

TP
LCRF PTE LTD
Jan 3 2019 12:00AM
[-]
World Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **23/09/2019 13:38 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2366.17) - SLQ7632Z - Claim Handler: Sundari Nagarajan

Approved:2366.17:Request TP WS to issue Tax invoice for Repairs in III's favour

DOCUMENTS SUMMARY

There are no documents.



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 377200

Tel: 64513933 Fax: 64557576

Date: 19/7/2019

Your ref: SH 9493J

Our ref: TP//18

India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711

BY EMAIL

Dear Sirs

ACCIDENT INVOLVING SLQ 7632Z & SH 9493J ON 3.1.2019 ALONG WOODLANDS AVE 2 & 5

Reference is made to the aforesaid matter (on behalf of our clients M/S LCRF PTE LTD)

Enclosed herewith are the following documents for your information and necessary actions only:-

- A. Final Repair Bill;
- B. Letter of Authorisation

We are claiming the following:-

1. Final bill	:	\$1,931.00
2. Gst 7%	:	\$ 135.17
3. Pre-repair inspection (\$60 x 2 day)	:	\$ 120.00
4. Loss of use (\$60 x 3 days)	:	\$ 180.00
		<u>\$2,366.17</u>

Kindly revert with your clients' mandate for settlement.

Yours faithfully,

World Auto Pte Ltd

World Auto Pte Ltd

Encls:

LETTER OF AUTHORISATION

In the matter of the following accident:-

DATE OF ACCIDENT : **03/01/2019**

CLIENT'S VEHICLE NO : **SLQ7632Z**

PLACE OF ACCIDENT : **WOODLANDS AVE 2 & AVE 5**

THIRD PARTY VEHICLE NO : **SH9493J**

I/We, **LCRF PTE LTD**

ADDRESS: **29 PAYA LEBAR ROAD, PAYA LEBAR OFFICE CENTRE**

UEN/NRIC/FIN NO : **201624597K**

Tel. (O) _____ (H) _____ (MOBILE) _____

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us in respect of the above matter up to the final conclusion of the said matter.

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us for the purpose of negotiating and enter into settlement with the tortfeasor, their insurers or solicitors appointed by the tortfeasor/insurers without the need to commence action.

I/We hereby authorize World Auto Pte Ltd to receive on my/our behalf all settlement sums and disbursements including loss of use/rental to pay to yourselves all costs you may at any time receive in connection with the above mention matter.

DATED THIS 03TH OF JANUARY YEAR 2019



Name: **LCRF PTE LTD**

UEN No: **201624597K**

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT19010055
Claimant Ref: SLQ 7632Z

We/I, WORLD AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 2,066.17 (repair cost), S\$ 250.00 (loss of use/rental), S\$ - (search fee), vehicle no. SLQ 7632Z that was damaged pursuant to the accident which occurred on 03/01/2019 (date) at WOODLANDS AVE 6 (location) involving vehicle no. SH 9493J (insured vehicle). This is pursuant to the inspection conducted on 04/01/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LCRF PTE LTD ("the third party claimant") of vehicle no. SLQ 7632Z to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLQ 7632Z (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,316.17 to WORLD AUTO PTE LTD

Dated this 27 day of September 2019

CLAIMANT:

Signature: 

Name: Sophia Tan

NRIC: 61434588/D


Address: 5 Kim Chuan Lane

Nationality: Overseas

Occupation: Claims Manager

Signed by "the workshop" (with stamp)

WITNESS:

Signature: 

Name: LKK AUTO CONSULTANTS PTE LTD

NRIC: 199607198R

Address: 51 UBI AVE 1 #02-25

Nationality: PAYA LEE INDUSTRIAL PARK S(408933)

Occupation:



Signed by appointed Surveyor

WORLD AUTO PTE LTD
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
 S'PORE 577200
 Tel No. : 64513933 Fax No. : 64557576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST, #04/#05/#06-02 IOB BUILDING
 S'PORE 049711

Attention : Motor Claim Department
 Contact : 63476100 63476139-LALITA Fax No. : 62244174

Tax Invoice : F189451

Date : 18/07/2019
 Vehicle Num. : SLQ 76322
 Make/Model : TOYOTA PRIUS, 1.8 HYBRID
 Chassis/Eng# :
 Accident Date : 03/01/2019
 Claim No. : TP/2402/2019
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER		458.00
2.	1	REAR BUMPER TOW COVER		82.00
3.	1	REAR BUMPER REINFORCEMENT		318.00
4.	1	REAR LOWER BUMPER		570.00
List Total S\$:				1,428.00
25.00% Discount S\$:				357.00
				1,071.00
SPECIAL NETT ITEMS :				
1.	1SET	REAR BUMPER CLIPS		30.00
2.	1SET	REAR END PANEL TOP GARNISH CLIPS		20.00
Special Nett Total S\$:				50.00
LABOUR :				
REMOVE & REPLACE DAMAGED PARTS TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL				350.00
PUTTY & SPRAY PAINT ON AFFECTED AREAS				400.00
CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS & START/STOP UNIT CAPACITORS				60.00
Labour Total S\$:				810.00

Total S\$: 1,931.00
 GST 7% S\$: 135.17
 Amount Due S\$: 2,066.17
 =====

World Auto Pte Ltd
 WORLD AUTO PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019 Edit Reg		03 Jan 2019 00:00 Edit Adj Rpt	\$51,931.00 Edit Estimates	\$51,931.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: LCRF PTE LTD , Co. Reg. No.: 201624597K									
Vehicle Reg. No.: SLQ7632Z		Date of Loss: 03/01/2019 00:00 - :59 [18 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MCT19010056		Policy/Cover Note No.: MCOM0015							
Vehicle Reg. No. (Insured): SH9493J		Policy No. (Claimant): 999995071							
		Excess:							
Repairer: World Auto Pte Ltd (HQ) No.5, Kim Chuan Lane, 537070 Tai Seng - Tel: 6451 3933									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 16/01/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (23/09/2019): Alert - Adj Mandate Approved (\$2366.17) - SLQ7632Z - Claim Handler: Sundari Nag... - III_SG (22/08/2019): Alert - Adj Mandate Maintained - SLQ7632Z - Claim Handler: Sundari Nagarajan - III_SG (09/07/2019): Alert - Adj Mandate Approved (\$0.00) - SLQ7632Z - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ7632Z (MCT19010056)
[SH9493J]
TP
LCRF PTE LTD
Jan 3 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
World Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

1 per page

Thumbnail

Print

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

22/08/19 17:14

General View

Load JPG

2

22/08/19 17:14

General View

Load JPG

3

22/08/19 17:14

General View

Load JPG

4

22/08/19 17:14

General View

Load JPG

5

22/08/19 17:14

General View

Load JPG

6

22/08/19 17:14

General View

Load JPG

7

22/08/19 17:14

General View

Load JPG

8

22/08/19 17:14

General View

Load JPG

9

22/08/19 17:14

General View

Load JPG

10

22/08/19 17:14

General View

Load JPG

11

22/08/19 17:14

General View

Load JPG

12

22/08/19 17:14

General View

Load JPG

13

22/08/19 17:14

General View

Load JPG

14

22/08/19 17:14

General View

Load JPG

15

22/08/19 17:14

General View

Load JPG

16

22/08/19 17:14

General View

Load JPG

17

22/08/19 17:14

General View

Load JPG

18

22/08/19 17:14

General View

Load JPG

19

22/08/19 17:14

General View

Load JPG

20

22/08/19 17:14

General View

Load JPG

21

22/08/19 17:14

General View

Load JPG

22

22/08/19 17:14

General View

Load JPG

23

22/08/19 17:14

General View

Load JPG

24

22/08/19 17:14

General View

Load JPG

25

22/08/19 17:14

Reinspection Photo

Load JPG

26

22/08/19 17:14

Reinspection Photo

Load JPG

27

22/08/19 17:14

Reinspection Photo

Load JPG

28

22/08/19 17:14

Reinspection Photo

Load JPG

29

22/08/19 17:14

Reinspection Photo

Load JPG

30

22/08/19 17:14

Reinspection Photo

Load JPG

Documentation

1 per page

Thumbnail

Print

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

07/01/19 10:19

ACKNOWLEDGEMENT EMAIL TO III DD 03.01.

Load PDF

2

10/01/19 14:40

TP ESTIMATE - MARKED

Load PDF

3

10/01/19 14:40

TP GIA REPORT

Load PDF

4

09/10/19 08:51

WORKSHOP INVOICE

Load PDF

5

09/10/19 08:51

AUTHORISATION TO ACT FORM

Load PDF

6

09/10/19 08:51

DISCHARGE VOUCHER

Load PDF

7

09/10/19 08:51

LOD

Load PDF

No

Finalized On

India International Insurance Pte Ltd (HQ)

Thumbnail

Print

1

08/01/19 09:18

Singapore Accident Statement

Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19000289/R1GA3Q2

Date: 09/10/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SLQ7632Z Insured Vehicle No: SH9493J
 Vehicle No: SLQ7632Z
 Date of Loss: 03/01/2019 Nature of Claim: TP Claim No: MCT19010056

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ7632Z
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: HIDDEN
 Reg. Date: 01/07/2017 (Man. Year: 2017) Chassis No: JTDKB3FU003562297
 Colour: White Odometer: 107887 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,012.75	1,121.00	4,891.75	81.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	810.00	2,650.00	76.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,472.75	1,931.00	7,541.75	79.62
+ GST 7.00/7.00% (S\$)	663.09	135.17	527.92	79.62
Nett Amount (S\$)	10,135.84	2,066.17	8,069.67	79.62
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
	Nett Liability (S\$)	2,316.17		

INSPECTION

Date of Assignment: 03/01/2019
 Date Inspected: 04/01/2019 Inspected At: 1 KRANJI LOOP
 Estimated Period of Repair: 3.0 days Repairer: World Auto Pte Ltd (HQ)

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Aug 2019)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ7632Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID OUTER GARNISH	Not Necessary	570.00 FL	*- FL
2	1		*REAR BOOT HYBRID EMBLEM (PRIUS)	Not Necessary	89.00 FL	*- FL
3	1		*REAR BOOT PRIUS EMBLEM	Not Necessary	89.00 FL	*- FL
4	1		*REAR BOOT WEATHER STRIP	Not Necessary	280.00 FL	*- FL
5	2		*REAR TAIL LAMP	Not Necessary	1,800.00 FL	*- FL
6	1		*REAR BUMPER	Deformed	900.00 FL	*458.00 FL
7	1		*REAR END PANEL	Repair	750.00 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	Not Necessary	170.00 FL	*- FL
9	1		*REAR BUMPER TOW COVER	Cut	89.00 FL	*82.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	350.00 FL	*318.00 FL
11	2		*REAR BUMPER TAIL LAMP	Not Necessary	1,500.00 FL	*- FL
12	2		*REAR BUMPER RETAINER	Not Necessary	220.00 FL	*- FL
13	1		*REAR BOOTLID OUTER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
14	2		*REAR TAILLAMP CLIPS	Not Necessary	80.00 FS	*- FS
15	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
16	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
17	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
18	1		*REAR LOWER BUMPER	Dented	570.00 FL	*570.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,857.00	1,478.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,844.25	357.00
Total Parts (\$\$)	6,012.75	1,121.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO REPLACE PARTS	New	180.00	0.00
2	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER REPAIRS INCLUDING PANEL BEAT ,CUT /WELD ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	1,200.00	350.00
3	TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS	New	1,000.00	400.00
4	TO CHECK REAR WIRES ,CONNECTORS ,REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	New	180.00	60.00
5	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	0.00
6	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	0.00
Gross Labour Cost (\$\$)			3,460.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >