

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

## INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

## Estimate : ES000142

Date : 03/01/2019

Vehicle Num. : SLQ 7632Z (LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 03/01/2019

Claim No. :

Reference :

Policy No. :

| S/N                                         | Quantity | Particular                          | Unit Price | Amount S\$  |
|---------------------------------------------|----------|-------------------------------------|------------|-------------|
| LIST ITEMS :                                |          |                                     |            |             |
| 1.                                          | 1        | REAR BOOTLID OUTER GARNISH X        |            | 570.00      |
| 2.                                          | 1        | REAR BOOT HYBRID EMBLEM (PRIUS) X   |            | 89.00       |
| 3.                                          | 1        | REAR BOOT PRIUS EMBLEM X            |            | 89.00       |
| 4.                                          | 1        | REAR BOOT WEATHER STRIP X           |            | 280.00      |
| 5.                                          | 2        | REAR TAIL LAMP X old damage         | 900.00     | 1,800.00    |
| 6.                                          | 1        | REAR BUMPER X                       |            | 900.00      |
| 7.                                          | 1        | REAR END PANEL repair               |            | 750.00      |
| 8.                                          | 1        | REAR END PANEL TOP GARNISH ?        |            | 170.00      |
| 9.                                          | 1        | REAR BUMPER TOW COVER cut 1/2       |            | 89.00       |
| 10.                                         | 1        | REAR BUMPER REINFORCEMENT           |            | 350.00      |
| 11.                                         | 2        | REAR BUMPER TAIL LAMP X old damage  | 750.00     | 1,500.00    |
| 12.                                         | 2        | REAR BUMPER RETAINER X              | 110.00     | 220.00      |
| List TotalS\$ :                             |          |                                     |            | 6,807.00    |
| 25.00% Discount S\$ :                       |          |                                     |            | 1,701.75    |
|                                             |          |                                     |            | 5,105.25    |
| SPECIAL NETT ITEMS :                        |          |                                     |            |             |
| 1.                                          | 1        | REAR BOOTLID OUTER GARNISH CLIPS X  |            | 40.00       |
| 2.                                          | 2        | REAR TAILLAMP CLIPS X               | 40.00      | 80.00       |
| 3.                                          | 1        | REAR BUMPER CLIP na                 |            | 40.00 30    |
| 4.                                          | 1        | REAR END PANEL TOP GARNISH CLIPS na |            | 40.00 20    |
| 5.                                          | 1        | REVERSE SENSOR ?                    |            | 280.00 200? |
| Special Nett Total S\$ :                    |          |                                     |            | 480.00      |
| LABOUR :                                    |          |                                     |            |             |
| TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT |          |                                     |            | 180.00      |

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**INDIA INTERNATIONAL INSURANCE PTE LTD**

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

**Estimate : ES000142**

Date : 03/01/2019

Vehicle Num. : SLQ 7632Z (LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 03/01/2019

Claim No. :

Reference :

Policy No. :

| S/N | Quantity | Particular                                                                                                                                                 | Unit Price | Amount S\$ |
|-----|----------|------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------|
|     |          | TO REPLACE PARTS                                                                                                                                           |            |            |
|     |          | LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS            | 1,200.00   | 350        |
|     |          | TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS                                                                                                           | 1,000.00   | 400        |
|     |          | TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS                                                      | 180.00     | 60         |
|     |          | DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)                                  | 450.00     | X          |
|     |          | PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES) | 450.00     | X          |
|     |          | Labour Total S\$ :                                                                                                                                         |            | 3,460.00   |

**E. & O.E.****Total S\$ : 9,045.25**

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur  
Hf 500100 68  
3 days  
P/P  
04/01/19 @ 1110  
Resur by paint