

AYA

P

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

31-03-19

Date Of Accident : 03-01-19

OUR REF : SKU 14U/T/18 (3)

Date in/out : 03/03/19 to 07/03/19

Teem Yoke Chai

14 Selet Green View

Singapore 805119

ESTIMATE BILL ON VEH. NO. : SKU 14U

MODEL : LAND ROVER RANGE ROVER EVOQUE 2.0 AT

CHASSIS NO. : SALVA2AG9DH816683

LIST ITEM

Rear Bumper Fascia		20/2e	2,450.00
Rear Bumper Exhaust Chorme Pipe LH		su	580.00 X
Rear Bumper Reflector LH		71	361.00 X
Rear Bumper Clips	10pcs @ 10.00	ser	100.00
Rear Bumper Parking Sensor	2pcs @ 313.60	su	617.20 X
Rear Bumper Parking Sensor Holder	2pcs @ 110.00	71	220.00 X
Rear Bumper Parking Sensor Wiring		71	461.00 X
Tail Gate Emblum "Range Rover"		71	89.00 X
Tail Gate Emblum "Evoque"		su	81.00
Tail Gate Emblum "S14"		su	78.00
Tail Gate Badge		su	88.00
			5,125.20
			10% Less Discount : 512.52
			4,612.68

LABOUR CHARGE

To check wiring system	30	80.00
To respray affected areas (2 Tone)	600	1,050.00
To reset electrical module system	71 X	280.00
To renew damaged parts, straighten & repair tail gate, rear end panel and aligned all parts	300	850.00

P-2797
107
2517.30
3447.30
1757

GST 7% :

AMOUNT DUE :

6,872.68
481.09
<u>7,353.77</u>