

REF: CS3/ATL-18018367/Gwb^{er}

Special Instructions:

46: \$ 6400.00

From (Person): Bernie Tan of MLH Date/Time: 03/01/2019
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: Lee Automobile

Workshop: Two Lim Motor.

OD/TP Re-inspection)/ Evaluation

To Inspect Vehicle No: SFY 5088L Insured: SKK 2858R

at Workshop m/s T.W. Lim Motor Tel: _____
of Blk 160 Sin Miao Dine #08-12

Policy No: _____ Claim No: 149550737056-003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05-10-2018

(Client's Record)

17/01/2019 (Thursday) @ 3pm

H.O.D. Enrolment/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 12/1 Confirmed with IS Final Fig. , days (Red \$ / %; Original 5 days)

Date/Time: 17/1 Submit Final Fig 15, 12.00 days (Red \$ 5200 / 81 %; Original days)

[illegible]

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

RECEIVED 21 JUL 2019

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

200

Transport

Photos

Others

Total

200

1) Date/Time 18/1- typist File Pass to

2) Date/Time File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. _____

at Workshop mis _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFY5088L Yr Regn: 28 Jun 2018
 Type: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota Camry cc 2487Colour: silver A/C Insured / Std / NI / NASp. Reading: 23894 Ti/Radio: Insured / Std / NI / NA

Eng/No: _____

Ct/No: AXVH 70 100 23 59Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / A/Rim orTyre Size: F: 215 / 55 R17R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MI / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 8 mm R/Bal: 8 mmL/Bal: 8 mm L/Bal: 8 mmD.O.A. _____ D.O.I. 17-01-19Survey held at: w/s 3pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

11

☐ : Final Report

Date/Time, File Return to?

21

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. 3 + P.S. 50

1. Photo

1. Others

1. 1

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ Site Insp. (\$) _____☐ Interview (\$) _____☐ Tech. Invs (\$) _____☐ Weekend (\$) _____

[Signature]
 18/1/2019

4173F ✓

ASSIGNMENT

Catherine Chong (LKK Auto)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Friday, 4 January, 2019 3:13 PM
To: Tan, Bennie-WZ; Oracle Law Corp
Cc: CS A Team; SUR; assignments
Subject: RE: Our Ref: 1495507370SG-003 || Your Ref: SB/PO/Acc/2018-8830

Hi Bennie,

Thank you for your email.

By copy to Assign Team,

FYNA: CS3/AIG18018367/Gcd3e2

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Thursday, 3 January 2019 11:52 PM
To: Oracle Law Corp <mail@oraclelaw.sg>
Cc: CS A Team <cs-a@lkkauto.com>
Subject: RE: Our Ref: 1495507370SG-003 || Your Ref: SB/PO/Acc/2018-8830

Your Ref: SB/PO/Acc/2018-8830

Our Ref: 1495507370SG-003

WITHOUT PREJUDICE

Dear Sir / Mdm

We refer to the above matter.

In view of the high cost of repair to your client's vehicle, we wish to conduct a physical re-inspection on said vehicle (ie **SFY5088L**). Kindly liaise with our appointed surveyor, LKK. Please let us know the date, time and location at least 05 working days in advance.

In the meantime, kindly forward us the following documents for our consideration:-

1. Coloured Accident Scene Photos
2. Video Footage (Per indicated in your client's report)
3. Police Investigation Results
4. Any Other Supporting Documents

Should you have any further enquiry, please do not hesitate to contact the undersigned.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

From: Tan, Bennie-WZ
Sent: Thursday, October 25, 2018 4:22 PM
To: 'Oracle Law Corp'
Subject: Our Ref: 1495507370SG-003 || Your Ref: SB/PO/Acc/2018-8830

Your Ref: SB/PO/Acc/2018-8830
Our Ref: 1495507370SG-003

WITHOUT PREJUDICE

Dear Sir / Mdm

We refer to the above matter.

We acknowledge receipt of your claim notification (SFY5088L) against our Insured for the above auto accident.

Kindly be advised that I am the officer-in-charge handling the above matter. **Please quote our above Ref no in any of our future correspondence(s).**

Please forward us the following documents for our consideration:-

1. Quantification to Claim
2. Final Repair Bill
3. Full Survey Report & Photos
4. Coloured Accident Scene Photos
5. Video Footage (Indicated in your client's report)
6. Police Investigation Results

7. Any Other Supporting Documents

We hereby reserve our rights to re-inspect your client's vehicle After Repair

Should you have any further enquiry, please do not hesitate to contact the undersigned.

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1718| Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

This email should not construed as an admission of liability on the part of whomsoever is concerned.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Catherine Chong (LKK Auto)

From: Oracle Law Corp <mail@oraclelaw.sg>
Sent: Monday, 7 January, 2019 9:24 AM
To: Hsiao Tong (LKKAuto); Tan, Bennie-WZ
Cc: CS A Team; SUR; assignments
Subject: RE: Our Ref: 1495507370SG-003 || Your Ref: SB/PO/Acc/2018-8830

FOR YOUR IMMEDIATE ATTENTION

Dear Hsiao Tong

1. We refer to your fax dated 4th January 2019.
2. We write to inform you that our client's vehicle will be available be a re-inspection on **Thursday, 17th January 2019 @ 3.00 p.m.** Kindly arrange with your appointed assessor to attend at **TW Lim Motor Works** located at **Block 160 Sin Ming Drive #08-12 Sin Ming Autocity Singapore 575722** on the said scheduled date and time to conduct the re-inspection.
3. Kindly note that we have our client's instructions to claim for further downtime fees in the event your assessor is not present at said venue on the scheduled date and time without giving us prior notice or fails to arrive punctually.

Regards

Pauline Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 2009045722

237 Alexandra Road #04-11
The Alexcler, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Friday, 4 January 2019 3:13 PM
To: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>; Oracle Law Corp <mail@oraclelaw.sg>
Cc: CS A Team <cs-a@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: Our Ref: 1495507370SG-003 || Your Ref: SB/PO/Acc/2018-8830

Hi Bennie,

Thank you for your email.

By copy to Assign Team,

FYNA, CS3/AIG18018367/Gcd3e2

MOTORCAR (Rear)

Vehicle No: **CFY 5088L**

Keur Portlan

NAC	INC	Item	CON	ACQ	Qb
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	111	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NE6	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler	1		
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	ACQ
1202	993784	Spare Tyre Board		
1203	994328	Spare Tyre Panel		
1204	995065	Spare Tyre		
1205	994326	Spare Tyre Lock Screw		
1206	993787	Spare Tyre Cover		
1207	995323	Triangle Breakdown Sign		
1208	990507	CD Changer Assy		
1209	990164	Antenna		
1210	990534	Centre Exhaust Pipe Assy		
1211	990532	Centre Exhaust Mounting		
1212	993364	Rear Exhaust Pipe		
1213	993357	Rear Exhaust Chrome Pipe		
1214	993361	Rear Exhaust Mounting		
1215	993358	Rear Exhaust Heat Shield		
1216	995223	Rear LH Chassis Member		
1217	993165	Rear RH Chassis Member		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1220	993420	Rear LH Fender Inner Panel		
1221	993431	Rear LH Fender Inner Trim		
1222	993415	Rear LH Fender Inner Garnish		
1223	993425	Rear LH Fender Inner Shield		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1228	993456	Rear RH Fender		
1229	993450	Rear RH Fender Protector		
1230	993420	Rear RH Fender Inner Panel		
1231	993431	Rear RH Fender Inner Trim		
1232	993415	Rear RH Fender Inner Garnish		
1233	993425	Rear RH Fender Inner Shield		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1238	995162	Rear Fender Extension Panel LH		
1239	993471	Rear Fender Extension Panel RH		
1240	993430	Rear Fender Inner Top Garnish		
1241	993673	Rear Fender 1/4 Glass		
1242	993452	Rear Fender 1/4 Glass Rubber		
1243	993453	Rear Fender 1/4 Glass Sealant		
1244	993949	Rear Windscreen Glass		
1245	993976	Rear Windscreen Rubber		
1246	993961	Rear Windscreen Moulding		
1247	993955	Rear Windscreen Sealant		
1248	994729	Third Brake Light		
1249	993385	Rear Fender Air Grille		
1250	992167	Fuel Lid		
1251	992168	Fuel Neck		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1254	992191	Fuel Tank Float		
1255	990247	Sticker		

No. of Items	Assessors
10	10
20	20
30	30
40	40
50	50
60	60
70	70
80	80
90	90
100	100

Town Lin
15/10/18

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18018367/GCD3E2

Date: 17/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100344323
 Claimant Vehicle No: SFY5088L Insured Vehicle No: SKK2858R
 Date of Loss: 05/10/2018 Nature of Claim: TP Claim No: 1495507370SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFY5088L
 Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: A25A0024693
 Reg. Date: 28/06/2018 (Man. Year: 2018) Chassis No: AXVH701002359
 Colour: Silver Odometer: 14273 km
 Engine Capacity: 2487 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm
 Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/10/2018
 Date Inspected: 10/10/2018 Inspected At: 160 SIN MING DRIVE # 08-12
 Repairer: T.w.lim Motor Works (HQ)
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Officer.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GSA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

ACCIDENT STATEMENT	
Date Of Report	06/10/2018 13:24
Date Of Accident	05/10/2018 17:25
Exact Location Of Accident	NEW UPP. CHANGI RD / BEDOK SOUTH AVE 3
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFYS388L
Insured/Policyholder	
Name Of Registered Owner	TAN SIEW HONG RINA
NRIC No	S7404173F
Email Address	HOCKIE69@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90666969
Alternative Phone No	OTHERS-90666969
Vehicle Particulars	
Manufacturer	TOYOTA
Model	CAMRY 2.5 HYBRID
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101388831
Cover Note Number	
Driver	
Name of Driver	STEPHEN LOW WEI HONG
NRIC No	S2207590Z
Date Of Birth	15/03/1973
Occupation	INDOOR
Date Of Driving Pass	13/10/1999
Driving Experience	18 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90666969
Fax Number	
Contact Number	OTHERS-90666969
Email Address	HOCKIE69@GMAIL.COM

Address	BLK 10 PARI DEDAP WALK
	#06-21
Postcode	486062
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKC2858R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WANG SHING CHUN JOHN
NRIC/Passport Number	
Contact Number	97301260
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, contracting or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Date:
NIC/FIN No:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along New Upper Changi Road and stop at traffic junction due to Red light, car skid and bang into my back and stop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Name & Title

Driver's Signature _____
(If driver is not the policyholder)
Date & Time _____

Supervising Control Personnel's Signature
Name: _____
NRC/OTIS No.: _____

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/10/2018 08:39
 Date Of Accident 05/10/2018 17:25
 Exact Location Of Accident UPPER CHANGI ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKK2858R
Insured/Policyholder
 Name Of Registered Owner WANG SHING CHUN JOHN

Vehicle Particulars

Manufacturer MAZDA
 Model MAZDA 3
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 2100344323-05
 Cover Note Number

Driver

Name of Driver WANG SHING CHUN JOHN
 NRIC No 57374046J
 Address 455 UPPER EAST COAST ROAD
 #06-02

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 Number of Passengers (Including Driver) 1

Circumstances of Accident

REFER TO SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SFY5088C

Vehicle Make/Model/Colour

Name of Driver

STEPHEN LOW WEI HONG

Insurance Company Name

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After leaving British Mall, I was driving along Upper Chancery Road at the right hand lane. There was a queue, so I stopped my car (SHE 225RN) behind SEY 508RY. When I noticed the traffic ahead of me started to move, I pressed my accelerator & hit SEY 508RY. It was a small impact. My car (SHE 225RN) sustained no damage (see photos). The bumper of SEY 508RY sustained some cracks near the left rear sensor (see photos). At the time of my accident, my son, David Wong was in the car with me.

In the midst of us taking down each other's particulars, a man stopped his car and approached us. He then handed his car's card to the driver of SEY 508RY, claiming to be a car workshop representative.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

John Wong
 Submitter's Signature
 Date & Time
 6/12/18 11:00am

Driver's Signature
 If driver is not the submitter
 Date & Time


[Signature]
 Date & Time

Oct 6, 18

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **rescind policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Accounts Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my reinsurer and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured with GIA(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or letters to me, which must involve disclosure of certain personal data about me to bring about delivery of the sum as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time
6/11/12 3:00 PM

Driver's Signature
(If driver is not the policyholder)
Date & Time


Insurer's Signature
Date & Time
6/11/12 3:00 PM

Accident Photo



Accident Photo



LEE**LEE AUTOMOBILE APPRAISERS SERVICES**

CORRESPONDENCE: 10 KIT PANJANG POST OFFICE, PO BOX 244, SINGAPORE 910009
FAX: (65) 6761 9271, (HANDPHONE): 6100 2811
BUSINESS REG. NO.: 32991420D

PHOTOCCSM

TO: TAN SIEW HONG
c/o BLK 160 SIN MING DRIVE
#08-12
SINGAPORE 575722

INVOICE NO. L18111089
YOUR REF
OUR REF LEE/TP/10/2258/18
DATE 28 NOV 2018

PARTICULARS		AMOUNTS (S\$)
VEHICLE REGISTRATION NO.	SFY 5088 L	
MAKE/MODEL	TOYOTA CAMRY 2.5	
TO OUR PROFESSIONAL CHARGES FOR		
☒ INSPECTION OF VEHICLE		
☒ APPRAISAL REPORT		
☒ PHOTOGRAPHY		
☒ TRANSPORT CHARGES		\$674.00
☒ REINSPECTION OF VEHICLE		
☐ AUTOMOTIVE CONSULTATION		
☒ CORRESPONDENCE, POSTAGE & OTHER DISBURSEMENT		
☐ OTHERS		
☐		
☐		
DOLLARS: SIX HUNDRED AND SEVENTY FOUR ONLY		

(* CHEQUE SHOULD BE CROSSED AND MAKE PAYABLE TO "LEE AUTOMOBILE APPRAISERS SERVICES")

kk
宋



LEE AUTOMOBILE APPRAISERS SERVICES



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX: (65) 6763 3827, HANDPHONE: 8188 2833
BUSINESS REG. NO. 52891429D

TO: TAN SIEW HONG

c/o BLK 160 SIN MING DRIVE
#08-12
SINGAPORE 575722

OUR REF. LEE/TP/10/2258/18

DATE 28 NOV 2018

AUTOMOBILE APPRAISAL REPORT

Vehicle Registration No. : SFY 5088 L
Make/Model : Toyota Camry 2.5
Year Manufacture/Register : 2018
Colour : Silver
Engine No. : Obscure
Chassis No. : AXVH70-1002359
Mileage : 14273km
Nature Of Inspection : Third Party
Date Of Accident : 05 Oct 2018
Date Of Inspection : 10 Oct 2018
Name of Workshop : T.W. Lim Motor Works
: Blk 160 Sin Ming Drive #08-12
: Singapore 575722

TYRE CONDITION ON VEHICLE

Location	Make	Size	Thread Balance
Nearside Front	Michelin	215/55R17	8mm
Offside Front	Michelin	215/55R17	8mm
Nearside Rear	Michelin	215/55R17	8mm
Offside Rear	Michelin	215/55R17	8mm

*(The above represent an estimated remaining life of the tyre thread in mm)

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The damages sustained on the vehicle were apparently confined at its rear portion.

(Details are describe in the attached schedule)

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items in this survey, kindly notify the company within (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.



APPRAISEMENT SCHEDULE

Our Ref. LEE/TP/10/2258/18

$\begin{array}{l} X \\ X \\ X \\ X \end{array} \left. \vphantom{\begin{array}{l} X \\ X \\ X \\ X \end{array}} \right\} NN$
 $\begin{array}{l} X \\ X \\ X \\ X \\ X \\ X \end{array} \left. \vphantom{\begin{array}{l} X \\ X \\ X \\ X \\ X \\ X \end{array}} \right\} NN$
 $X \quad NN$
 1093.75
 $X \quad NN$
 40
 $X \quad NN$
 200
 200
 $X \quad NN$
 440
 1523.75
 20%: 1200



LEE AUTOMOBILE APPRAISERS SERVICES

CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809
FAX : (65) 6763 3827, HANDPHONE: 8100 2833
BUSINESS REG. NO.: S28914290

Vehicle Number: - SFY 5088 L.

Our Ref: LEE/TP/10/2258/18

ASSESSMENT SUMMARY

The damages sustained on the vehicle were thoroughly inspected and every item that was mentioned in the repair estimate against the actual damages found on the vehicle. Before we arrived at our recommendation as to whether the parts needed to be replaced or repair.

We have listed the breakdown of our finding and our recommendation as per schedule attached.

Our assessment to reinstate the vehicle is **\$7488.00** revised amount of the repairer's estimate of **\$11016.00**. The aforesaid recommendation, in our opinion, is fair and reasonable for the restoration of the vehicle to its pre-accident condition.

However, after taken into consideration the age and condition of the vehicle and the availability of the recondition components and to economize the repair, we therefore recommend a contract **Lump Sum** at **\$6400.00** corresponding to supply of parts, labour and spraypainting charges.

49 photographs were taken at the times of static inspection.

Under normal circumstances, the repairs should be completed within a reasonable period **05** full working day

This inspection was conducted entirely on a '**Without Prejudice**' basis and we have not given authorization and instruction to the repairer to proceed with the repair.

We are reverting the matter to you for your discretion.

Very truly yours

KK
榮



.....
K. W. LEE Dip Auto. Engrg.
MIAME, AMIM, CAE, ENG. TECH, MSAE, AMIRTE, AMSOE
AUTOMOTIVE ENGINEER ASSESSOR



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18018367/Gvbe2-1		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 ATTN : BENNIE TAN		Date : 22-01-2019		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SKK 2858R	Veh. Inspected	SFY 5088L	
Policy No.		Coverage (\$)	0.00	
Claim No.	1495507370SG-003	Excess (\$)	0.00	
Assign From	BENNIE TAN	Assign Date	03/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	AXVH701002359	Colour	SILVER	
Odometer	23894	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	MICHELIN	8 mm	
L/H Front Tyre	215/55 R17	MICHELIN	8 mm	
R/H Rear Tyre	215/55 R17	MICHELIN	8 mm	
L/H Rear Tyre	215/55 R17	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	05/10/2018	Inspection Date	17/01/2019	
Survey held at	160 SIN MING DRIVE #08-12			
Repairer	T.W.LIM MOTOR WORKS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 5088L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	REPAIRED SEE LABOUR	1,122.00	-
1	BOOT LID OPEN SENSOR	NOT NECESSARY	232.00	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	191.00	-
2	TAILLAMP @\$872.00	NOT NECESSARY	1,744.00	-
1	REAR BUMPER	REPLACED	1,445.00	1,445.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	271.00	-
1	REAR BUMPER LOWER LID	NOT NECESSARY	305.00	-
2	REAR BUMPER SIDE RETAINER @\$121.00	NOT NECESSARY	242.00	-
2	REAR BUMPER LOWER REFLECTOR @\$75.00	NOT NECESSARY	150.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	766.00	-
1	REAR END PANEL GARNISH	REUSE	290.00	-
1	REAR END PANEL	NOT NECESSARY	638.00	-
	LESS 25% DISCOUNT		-	-361.25
			7,396.00	1,083.75
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	500.00	-
			500.00	-
	<u>LABOUR</u>			
	TO CHECK REAR WIRING AND FUNCTION INCLUDING TO REMOVE & REFIX REAR REVERSE SENSOR & CAMERA.		150.00	40.00
	TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH TO FACILITATE REPAIR.	NOT NECESSARY	850.00	-
	LABOUR CHARGE AS RECOMMENDED FOR REPAIRED & REPLACED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID.		1,000.00	200.00
	TO PUTTY AND SPRAYPAINTING INCLUDING TOUCH UP ALL AFFECTED AREAS.		1,000.00	200.00
	TO APPLY RUSTPROOF TREATMENT TO THE REPLACED / REPAIRED PANELS.	NOT NECESSARY	120.00	-
			3,120.00	440.00
	GRAND TOTAL		11,016.00	1,523.75

Report Ref No. CS3/AIG18018367/Gvbe2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00
---	--	--	----------

Report Ref No. CS3/AIG18018367/Gvbe2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.