

ASS. REC. BY:

REF:

CS/FCI 9000302 / Dg d3ⁿ²

Special Instruction:

Surveyor

ASSIGNMENT (Office)

CWS

From (Person)

Eileen Lee

of

per

Date/Time

10:04am 7/1/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 2027B

Insured:

SHA 2168L

at Workshop m/s

Teamwork Garage

Tel:

68442475

of

Blk 53 Ubi Ave 1 # 01-24

Policy No:

Claim No:

D19000109MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time: 10:10am 7/1/19

Person Contacted:

Darren

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLH 2027B - NA / LP19000158/24	DoA: 24/12/18
	SHA 2168L - NA / HP19000158/24	DoA: 24/12/18
17/1/19 @ 11.10am	loan revised to Eileen Lee by email.	

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8LH 2027 B Yt Regn: 2016 OctType: M/C / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota AltisCC: 1598Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 195009

T/Radio: Insured / Std / NI / NA

Eng/No: 12RX588737C/No: MR053REH104555670Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal: S mmR/Bal: S mmL/Bal: S mmL/Bal: S mmD.O.A: 29/12/2018D.O.I: 16/01/2019Survey held at: Teamwork Page Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First report SHA2168L

Jump 2/5 25501- with 3 dgs. 2 m
Chkd 6 4408.86 63%

RECEIVED 11 MAR 2019

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + P.S. \$

) Photos

) Other:

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / L.P. (\$

2550

TOTAL

145505018263



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000109MFSH
Our Ref: CS/FCI19000302/Dqd3

Date: 17 January 2019

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 2027B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/01/2019 at the premises of M/s TEAMWORK GARAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ 6,958.86 .
Revised Estimate Amount	: S\$ 3,243.57 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s body.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	31-12-2018	Our Ref No.	D19000109MFSH
Accident Date	29-12-2018	Claim Type.	Third Party
Insured Vehicle	SHA2168L	Third Party Vehicle.	SLH2027B
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK		
Contact Person.	LETITIA		
Contact No.	68442475/ 0	Fax No.	68442474
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 17 January 2019 11:10 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000109MFSH/1
Attachments: CSFCI19000302Dqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLH 2027B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 7 January 2019 10:20 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000109MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 7 January 2019 10:04 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000109MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

Vehicle number	SLH2027B
Make / Model	TOYOTA/ALTIS
Chassis number	MR053REH10455670
Accident date	29 December 2018
Reference	1901-01

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT LH DOOR PANEL <i>Dentel</i>	1209.30 ✓
1	FRONT LH DOOR TAPE <i>Nec</i>	151.20 ✓
1	FRONT LH DOOR WING MIRROR <i>broken</i>	790.43 ✓
1	FRONT LH FENDER <i>Dentel</i>	795.50 ✓
1	FRONT LH FENDER INNER SHIELD <i>NH</i>	220.40 X
1	FRONT LH FENDER EMBLEM LOGO-VVTI <i>Nec</i>	45.00 ✓
1	FRONT LH SHOCK ABSORBER <i>NH</i>	598.00 X
1	FRONT LH KNUCKLE ARM <i>NH</i>	654.00 X
1	FRONT LH KNUCKLE BEARING <i>NH</i>	165.30 X
1	FRONT LH LOWER ARM <i>NH</i>	569.34 X
	<i>2991.43</i>	
	<i>2243.67</i>	
	Less 25%	1299.61
	Subtotal	3898.86
	Balance C/F	3898.86
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	3898.86
1 SET	FRONT FENDER INENR SHIELD CLIP <i>NH</i>	50.00 X
1	RIM <i>NH</i>	600.00 X
1 BOT	BRAKE FUILD <i>NH</i>	50.00 X
	Subtotal	700.00
	Balance C/F	4598.86
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	4598.86
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 <i>NH</i>
2	CHECK FRONT WHEEL ALIGNMENT	150.00 <i>NH</i>
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 <i>NH</i>
4	TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW <i>1000/-</i>	200.00 60/-
5	PANEL BEATING ON AFFECTED AREAS	800.00 400/-
6	SPRAY PAINTING ON AFFECTED AREAS	800.00 400 500/-
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	2360.00
	Grand total	6958.86

12/01/2019 1030m

NH Adu

2/15m

2 Kk Adu

3243.57

452550/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19000302/Dqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2168L	Veh. Inspected	SLH 2027B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000109MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	07/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104555670	Colour	GREY	
Odometer	195009	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GITI	5 mm	
L/H Front Tyre	205/55 R16	GITI	5 mm	
R/H Rear Tyre	205/55 R16	GITI	5 mm	
L/H Rear Tyre	205/55 R16	GITI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/12/2018	Inspection Date	16/01/2019	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2027B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LH DOOR PANEL	DENTED	1,209.30	1,209.30
1	FRONT LH DOOR TAPE	NECESSARY	151.20	151.20
1	FRONT LH DOOR WING MIRROR	BROKEN	790.43	790.43
1	FRONT LH FENDER	DENTED	795.50	795.50
1	FRONT LH FENDER INNER SHIELD	NOT NECESSARY	220.40	-
1	FRONT LH FENDER EMBLEM LOGO-VVTI	NECESSARY	45.00	45.00
1	FRONT LH SHOCK ABSORBER	NOT NECESSARY	598.00	-
1	FRONT LH KNUCKLE ARM	NOT NECESSARY	654.00	-
1	FRONT LH KNUCKLE BEARING	NOT NECESSARY	165.30	-
1	FRONT LH LOWER ARM	NOT NECESSARY	569.34	-
	LESS 25% DISCOUNT		-1,299.61	-747.86
			3,898.86	2,243.57
SPECIAL NETT ITEMS				
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	50.00	-
1	RIM (SN)	NOT NECESSARY	600.00	-
1	BOT BRAKE FLUID (SN)	NOT NECESSARY	50.00	-
			700.00	-
LABOUR				
	CHECK FRONT WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	-
	CHECK FRONT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.	NOT NECESSARY	200.00	-
	TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS.		800.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	500.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			2,360.00	1,000.00
GRAND TOTAL			6,958.86	3,243.57



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00
---	--	--	----------

Report Ref No. CS/FCI19000302/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.