



JCN Autolution Pte Ltd

COMPANY REG NO: 201813309W

8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
Singapore 415875

+65 6981 1772 sales@jcngroup.com

ESTIMATE

PATRICK DENTAL CERAMIC ARTS
33 UBI AVE 3 #08-30, TOWER B VERTEX
SINGAPORE Singapore 408868

Contact : 6842 3371 6842 7040

Code : C100038

Date in : 31/12/2018

Vehicle Num. : GBG5488H

Model : SUZUKI EVERY PA660 AUTO

Chassis/Eng# : DA17V241471/R06A2099016

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR TAILGATE	1	675.05	675.05
REAR TAILGATE GLASS	1	845.75	845.75
Subtotal before discount			1,520.80
Percentage discount 15%			228.12
Sub-total 1			1,292.68
REAR TAILGATE SEALANT	1	60.00	60.00
Subtotal before discount			60.00
Percentage discount 0%			0.00
Sub-total 2			60.00
Parts-total			1,352.68

LABOUR

Description	Price
TO PROVIDE TOWING CHARGE	50.00
TO DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	100.00
TO REMOVE, CHANGE REAR TAILGATE WINDSCREEN.	100.00
TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	400.00
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	250.00
Labour Total	900.00
Parts & Labour Total	2,252.68