

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0030/2019/JE
Date	:	8-Jan-19

Vehicle IN workshop. Kindly arrange for survey.

United Overseas Insurance Limited

3 Anson Road

#28-01 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

Tel: 6222 7739 - Fax 6327 3869

Owner's Name	:	Mr. Kuek Tong Au
Address	:	Blk 85 Lucky Heights Singapore 467630
Telephone	:	9672 8338
Type of Claim	:	Own Damage Claims
Policy No.	:	DHOM110165471800
Vehicle No	:	SDD 9229 E
Model Code	:	Audi A5 SB 2.0 TFS
Model / Year	:	27/12/2017
Engine No	:	CVK 050785
Chassis No	:	WAUZZZF52JA049889
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	4-Jan-19
Place of Accident	:	Junction Of Bedok North Rd/ New Upper Changi Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDD 9229 E.

S/n	Nature of Jobs	Estimated Charges
1	To tow and recover vehicle from scene of accident.	S/N
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00
4	To remove and renew, aircon condenser, charge air cooler, radiator, electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00
5	To remove center console, instrument panels and clusters. Renew dashboard, both frontal airbags. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and central protection.	S/N \$ 3,600.00
6	To remove and transfer both front door's multi-lock system and power window devices, Inspect for damages.	S/N \$ 560.00
7	To remove and reinstall engine assy with gearbox assy to facilitate car-o-liner repairs. Inspect for damages.	S/N \$ 3,600.00
8	To remove and reinstall front suspension assy with subframe to facilitate car-o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 2,800.00
9	To setup vehicle on car-o-liner for repair.	S/N \$ 2,400.00
10	To dismantle and renew front bumper, bonnet, both front fenders, both headlights, both front door, lhs sill panel trim and both wing mirror assy. To repair both upper A-pillar. Re-align front chassis frames to specification of origin. Renew front lock carrier. To inspect both fender top support and lhs lower A-pillar for further damages. Reorganize crash management components. Reinstall all parts removed.	\$ 11,900.00
11	To respray front bumper, both front fenders, bonnet, both upper A-pillar, both front door, lhs sill panel trim and both wing mirror cover.	\$ 8,200.00
12	To renew both front rim and lhs front tyre. To carry out wheel alignment.	S/N \$ 320.00
13	To carry out diagnostic checks.	S/N \$ 384.00
TOTAL LABOUR CHARGES		: <u>\$ 36,244.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 9229 E.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,073.00	
2	FRONT BUMPER FIXING PARTS	\$ 368.00	
3	FRONT BUMPER STRIP COVER	2 \$ 64.00	
4	FRONT GRILLE - CENTER	\$ 178.00	
5	FRONT BUMPER LOWER CENTRE ELEMENT	\$ 207.00	
6	FRONT BUMPER SPOILER	\$ 489.00	
7	FRONT BUMPER AIR GUIDE - LH	\$ 56.00	
8	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	
9	FRONT RADIATOR GRILLE - DARK CHROME	\$ 2,131.00	
10	FRONT ULTRASOUND SENSOR - LH&RH	2 \$ 96.00	
11	FRONT COVER RADIATOR GRILLE - UPPER	\$ 174.00	
12	FRONT BUMPER FOG LIGHT GRILLE - LH&RH	2 \$ 862.00	
13	FRONT BUMPER REINFORCEMENT	\$ 733.00	
14	FRONT BUMPER BRACKET - LH&RH	2 \$ 390.00	
15	FRONT BUMPER GUIDE - LH&RH	2 \$ 66.00	
16	FRONT UPPER BUMPER RADIATOR COVER	\$ 116.00	
17	FRONT FOAM FILLER PIECE	\$ 113.00	
18	FRONT BUMPER LOCK CARRIER	\$ 125.00	
19	FRONT SUPPORT BRACKET SUPPORT - LH&RH	2 \$ 52.00	
20	SENSOR - FRONT OUTER	2 \$ 462.00	
SUB-TOTAL SPARE PARTS		: \$ 8,811.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 9229 E.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	SENSOR - FRONT INNER	2 \$	462.00
2	SENSOR HARNESS	\$	470.00
3	HORN - HIGH TONE LEFT	\$	37.00
4	HORN - LOW TONE RIGHT	\$	262.00
5	HORN MOUNT BRACKET - LH&RH	2 \$	52.00
6	FRONT FENDER - LH&RH	2 \$	1,936.00
7	FRONT FENDER ATTACHMENT PARTS	\$	95.00
8	FRONT FENDER ELEMENT - LH&RH	2 \$	136.00
9	FRONT FENDER BRACKET - LH&RH	2 \$	64.00
10	FRONT FENDER SUPPORT BRACKET - LH&RH	2 \$	106.00
11	FRONT FENDER BRACKET - LEFT A RIGHT	2 \$	63.00
12	FRONT FENDER SUPPORT BRACKET FRONT- LH&RH	2 \$	214.00
13	FRONT FENDER CENTER BRACKET - LH&RH	2 \$	90.00
14	FRONT FENDER COVER ELEMENT - LH&RH	2 \$	60.00
15	FRONT FENDER LEDGE COVER - LH&RH	2 \$	64.00
16	WHEEL HOUSING LINER - LH&RH	2 \$	512.00
17	WHEEL HOUSING LINER ATTACHMENT PARTS	2 \$	164.00
18	FRONT WHEEL SPOILER - LH&RH	2 \$	132.00
19	FRONT FENDER SPLASH SHIELDS - LH	\$	32.00
20	FRONT FENDER SPLASH SHIELDS - RH	\$	34.00
SUB-TOTAL SPARE PARTS		:	\$ 4,985.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 9229 E.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	STONE CHIP GUARD - LH&RH	2 \$	92.00
2	BUMPER HOLDER - LH&RH	2 \$	44.00
3	SIDE MEMBER TRIM - LH	\$	754.00
4	SIDE MEMBER TRIM ATTACHEMENT PARTS	\$	118.00
5	ADHESIVE TAPES	\$	192.00
6	DOUBLE-SIDED ADHESIVE TAPES	\$	54.00
7	TRIM FENDER CHROME - LH&RH	2 \$	290.00
8	BONNET	\$	2,602.00
9	BONNET ATTACHMENT PARTS	\$	111.00
10	BONNET LID HINGE - LH&RH	2 \$	764.00
11	HOOD PLUG	2 \$	37.00
12	IMPACT PROTECTION - CENTER	\$	25.00
13	IMPACT PROTECTION - LEFT	\$	25.00
14	IMPACT PROTECTION - RIGHT	\$	25.00
15	STRIKER - LEFT	\$	46.00
16	STRIKER - RIGHT	\$	46.00
17	FRONT BONNET STRUT	2 \$	217.00
18	BONNET LID LOCK	2 \$	391.00
19	BONNET CABLE - CENTER	\$	53.00
20	BONNET RELEASE CABLE - CENTER	\$	53.00
SUB-TOTAL SPARE PARTS		:	\$ 5,939.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 9229 E.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT WINDSCREEN WIPER COVER	\$ 89.00	
2	FRONT LED HEADLIGHT - LH&RH	2 \$ 14,408.00	
3	FRONT HEADLIGHT POWER MODULE	2 \$ 1,385.00	
4	FRONT HEADLIGHT CONTROL UNIT	2 \$ 1,370.00	
5	LED UNIT WITH HEAT SINK - LH&RH	2 \$ 2,106.00	
6	HEADLAMP ASSY SPACER	2 \$ 72.00	
7	LIFT CYLINDER - LH&RH	2 \$ 362.00	
8	HEADLAMP HOSE CLEANING PIPE	\$ 72.00	
9	CORRUGATED PIPE	\$ 35.00	
10	WASH WATER RESERVOIR	\$ 130.00	
11	FRONT RADIATOR CARRIER WITH MOUNTING	\$ 928.00	
12	A/C CONDENSER WITH FLUID RESERVOIR	\$ 568.00	
13	AIR CONDITIONING HOSE AIR LINE	\$ 152.00	
14	DISCHARGE LINE	\$ 310.00	
15	AIR CONDITIONING LINE	\$ 226.00	
16	PRESSURE SENSOR	\$ 180.00	
17	VALVE HIGH-PRESSURE SWITCH	\$ 48.00	
18	AIRCOND COOLER	\$ 676.00	
19	COOLANT	4 \$ 84.00	
20	COOLING FAN-RADIATOR FAN SHROUD	\$ 242.00	
SUB-TOTAL SPARE PARTS		: \$ 23,443.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 9229 E.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	RADIATOR FAN WITH CONTROL UNIT	\$ 2,107.00	
2	AIR GUIDE - LH&RH	2 \$ 56.00	
3	CHARGE AIR COOLER	\$ 535.00	
4	SEAL RING - CHARGE AIR COOLER	\$ 84.00	
5	PRESSURE HOSE - RIGHT	\$ 320.00	
6	PRESSURE HOSE	\$ 381.00	
7	AIR FILTER	\$ 340.00	
8	INTAKE AIR DUCT - RIGHT	\$ 20.00	
9	AIR GUIDE	\$ 48.00	
10	AIR MASS METER	\$ 533.00	
11	INTAKE HOSE	\$ 85.00	
12	TURBO INLET HOSE	\$ 284.00	
13	BONNET SOUNDABSOR	\$ 311.00	
14	FRONT DOOR	\$ 2,829.00	
15	OUTER DOOR SEAL - LEFT A RIGHT	\$ 201.00	
16	BONDING AGENT	\$ 45.00	
17	CLEANING SOLUTION	\$ 65.00	
18	FRONT DOOR	\$ 2,829.00	
19	OUTER DOOR SEAL - LEFT A RIGHT	\$ 201.00	
20	BONDING AGENT	\$ 45.00	
SUB-TOTAL SPARE PARTS		: \$ 11,319.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 9229 E.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	CLEANING SOLUTION	\$ 65.00	
2	DOOR CATCH - LEFT A RIGHT	2 \$ 436.00	
3	DOOR CATCH COVER - LEFT A RIGHT	2 \$ 52.00	
4	TRIM DOOR CHROME - LH&RH	2 \$ 290.00	
5	MOLDING - ROOF CHROME - LH&RH	2 \$ 1,148.00	
6	EDGE PROTECTION - LH&RH	2 \$ 282.00	
7	WATER DEFLECTOR STRIP	2 \$ 122.00	
8	WINDOW SLOT SEAL - LH&RH	2 \$ 728.00	
9	CORNER TRIM - LH&RH	2 \$ 84.00	
10	ELECTRIC ADJUSTING MIRROR - LH&RH	2 \$ 1,998.00	
11	MIRROR CAP - LH&RH	2 \$ 440.00	
12	MIRROR GLASS - LH	\$ 1,132.00	
13	MIRROR GLASS - RH	\$ 1,553.00	
14	ALUMINIUM RIM	2 \$ 1,886.00	
15	STICKER	\$ 23.00	
16	TYRE PRESSURE DATE PLATE	\$ 35.00	
17	TYRE 'BRIDGESTONE'	\$ 1,293.00	
18	NOISE INSULATION	\$ 520.00	
19	FRONT UNDERBODY COVER - LH	\$ 37.00	
20	FRONT UNDERBODY COVER - RH	\$ 37.00	
SUB-TOTAL SPARE PARTS		: \$ 12,161.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 9229 E.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	SUNDRIES	\$ 1,500.00	
2	FRONT NUMBER PLATE	\$ 25.00	
3	AIRBAG UNIT FOR STEERING WHEEL	\$ 3,384.00	
4	AIRBAG UNIT (PASSENGER)	\$ 4,019.00	
5	HEAD AIRBAG UNIT -LH&RH	2 \$ 3,416.00	
6	CONTROL UNIT AIRBAG	\$ 1,927.00	
7	CRASH SENSOR - FRONT	3 \$ 1,145.00	
8	CONTROL MODULE	\$ 485.00	
9	DASHBOARD WITH AIR DUCT	\$ 4,838.00	
10	MOULDED HEADLINER	\$ 1,872.00	
11	A-PILLAR TRIM - LH&RH	2 \$ 374.00	
12	C-PILLAR TRIM - LH	\$ 137.00	
13	AUTOMATIC SEAT BELT WITH TENSIONER - LH&RH	2 \$ 2,010.00	
14	SEAT BELT HEIGHT ADJUSTER	2 \$ 323.00	
15	ROOF GRAB HANDLE - FRONT	\$ 129.00	
16	ROOF GRAB HANDLE - LH REAR	\$ 129.00	
17	ROOF GRAB HANDLE - RH REAR	\$ 129.00	
TOTAL SPARE PARTS CHARGES		:	\$ 92,500.00
TOTAL LABOUR CHARGES		:	\$ 36,244.00
GRAND TOTAL		:	\$ 128,744.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant