

### REPAIR ESTIMATE\*

**VEHICLE NO : SHB 6352P**

DATE 5/1/2019 12:23

MAKE :

**MODEL : MERCEDES**

L/Sum  
AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt ?			\$ 1,890.50
	Bumper Grille, Frt/Centre ?			\$ 290.50
	<b>SUB TOTAL</b>			<b>\$ 2,181.00</b>
	<b>LESS 20%</b>			<b>\$ 436.20</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,744.80</b>
	Number Plate, Frt (Merc Taxi) sc ✓			<b>\$ 50.00</b> Neft
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>200</del> 300.00
	Spray Painting Charge			\$ <del>200</del> 300.00
	<b>TOTAL LABOUR</b>			<b>\$ 600.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,394.80</b>
	<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>			
			Repair Hp 90010068 2 days L/S 08/01/19 @ 1500 Resy after repair	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.