



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/12/2018

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB83X
Case Reference Number	BUS/12/18/5047
Registration Date	08/07/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Choo Yong Bin
Type of Accident	Head to Rear
Accident Date and Time	23/12/2018 5:55 PM
Accident Reported Date and Time	22/12/2018 6:50 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099444
Special Instruction to ARC, if any	SMB83X - REAR PORTION XD2298P (TP) - FRONT PORTION. INSURED WITH EQ INSURANCE
Prepared Date and Time	28/12/2018 12:01 PM
Chassis Number	WEB63442021000202
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,240.00	\$0.00
Total Spray Cost	\$1,232.00	\$0.00
Total Spare Part Cost	\$25,275.55	\$0.00
Total Other Cost	\$2,800.00	\$0.00
TOTAL COST	\$33,547.55	\$0.00
Lump Sum Total	\$33,550.00	\$0.00
Number of Repair Days	16.0	
Prepared / Adjusted By	Jeong Choon Hwee	15 Days.
ARC / Surveyor Sign Off Date		
Signature		
Remarks		Kaki Maly

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/12/2018

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & REPLACE ABOVE ITEMS AND REPAIR REAR LHS PORTION.	\$4,240.00	3710
Total Labour	\$4,240.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$1,232.00	1000
Total Spray Painting & Panel Beating	\$1,232.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$500.00	200
TO CHECK WIRING AND SYSTEM FUNCTION	\$100.00	50
CHASSIS ALIGNMENT	\$2,000.00	450
TOWING CHARGE	\$200.00	150
Total Other Costs	\$2,800.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009342	GLASS	9006	GLASS, SIDE-5MM, L6, 12 74MMX1547MM, MBOC5 00	1.00	\$569.30	10.00	\$512.37	Replace	✓
6009518	VE		LED LICENCE PLATE LAMP FOR MB OC500 LE	1.00	\$172.50	10.00	\$155.25	Replace	✓
		a6344901210	exhaust pipe	1.00	\$0.00	0.00	\$0.00	Replace	✓
		A6344920202	rear exhaust pipe	1.00	\$0.00	0.00	\$0.00	Replace	✓
		A6554920140	Clamp	1.00	\$0.00	0.00	\$0.00	Replace	✓
		A4572010231	cooling water outlet	1.00	\$0.00	0.00	\$0.00	Replace	✓
		A0015010882	radiator hose	2.00	\$0.00	0.00	\$0.00	Replace	✓
		A6345016424	cooling water pipe return D=60MM	1.00	\$0.00	0.00	\$0.00	Replace	✓
		A0008321794	molded hose Gr90	1.00	\$0.00	0.00	\$0.00	Replace	✓
		N00000000146 8	clamp 60-80x13MM	2.00	\$0.00	0.00	\$0.00	Replace	✓
		N00000000353 0	clamp 65-85x13MM	2.00	\$0.00	0.00	\$0.00	Replace	✓
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00		✓
			GIVE WAY STICKER	1.00	\$35.00	0.00	\$35.00	Replace	✓
6009365	Body		PANEL, REAR, FIBREGLASS, FOR MB OC500 BUS	1.00	\$2,173.50	10.00	\$1,956.15	Replace	✓
6009369	BODY RH		COVER, LAMP, REAR, RH, FOR MB OC500 BUS	1.00	\$1,242.00	10.00	\$1,117.80	Replace	✓
6009368	BODY LH		COVER, LAMP, REAR, LH, FOR MB OC500 BUS	1.00	\$1,242.00	10.00	\$1,117.80	Replace	✓
6009367	Body	6013	DOOR, REAR, ENGINE, F OR MB OC500 BUS	1.00	\$2,484.00	10.00	\$2,235.60	Replace	✓
6009366	Body		BUMPER, REAR, FIBREGLASS, FOR MB OC500 BUS	1.00	\$1,863.00	10.00	\$1,676.70	Replace	✓
6010260	Body	5041	FRAME, REAR, ENGINE DOOR, FOR MB OC500 BUS	1.00	\$1,090.60	10.00	\$981.54	Replace	✓
6010416	BODY RH	5047	HINGE RH	1.00	\$285.00	10.00	\$256.50	Replace	✓
6010415	BODY LH	5046	HINGE LH	1.00	\$285.00	10.00	\$256.50	Replace	✓



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/12/2018

User ID : GohKK2

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009517	VE		LED THIRD BRAKE LAMP FOR MB OC500 LE	1.00	\$207.00	10.00	\$186.30	Replace	✓
6009516	VE		LED REAR MARKER LAMP FOR MB OC500 LE	1.00	\$138.00	10.00	\$124.20	Replace	✓
6009514	VE		LED TAIL/STOP LAMP FOR MERCEDES OC500 LE	1.00	\$862.50	10.00	\$776.25	Replace	✓
6009515	VE		LED REVERSE LAMP FOR MERCEDES OC500 LE	1.00	\$862.50	10.00	\$776.25	Replace	✓
6009512	VE		LED REAR SIGNAL LAMP FOR MB OC500 LE	1.00	\$862.50	10.00	\$776.25	Replace	✓
6009518	VE		LED LICENCE PLATE LAMP FOR MB OC500 LE	1.00	\$172.50	10.00	\$155.25	Replace	✓
6009354	GLASS		GLASS,REAR:895MM X 2165MM,MB OC500 BUS	1.00	\$2,932.50	10.00	\$2,639.25	Replace	✓
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE-DIRECT GLAZING	12.00	\$37.00	0.00	\$444.00	Replace	✓
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	✓
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	✓
6010220	BODY LH	5008	PANEL,SKIRT:L8,FOR MB OC500 BUS	1.00	\$96.60	10.00	\$86.94	Replace	✓
6010221	BODY LH	5009	PANEL,SKIRT:L9,FOR MB OC500 BUS	1.00	\$709.00	10.00	\$638.10	Replace	✓
6010222	BODY LH	5010	PANEL,SKIRT:L10,FOR MB OC500 BUS	1.00	\$1,418.00	10.00	\$1,276.20	Replace	✓
6010223	Body	5077	GRILLE,AIR INTAKE:L11,FOR MB OC500 BUS	1.00	\$552.00	10.00	\$496.80	Replace	✓
6010238	Body	5032	FRAME,SKIRT PANEL:L5,FOR MB OC500 BUS	1.00	\$572.70	10.00	\$515.43	Replace	✓
6010239	Body	5033	FRAME,SKIRT PANEL:L9,FOR MB OC500 BUS	1.00	\$365.70	10.00	\$329.13	Replace	✓
6010240	Body	5034	FRAME,SKIRT PANEL:L10,FOR MB OC500 BUS	1.00	\$572.70	10.00	\$515.43	Replace	✓
6009655	VM	0014920404	PIPE,EXHAUST:REAR,F OR MB OC500 LE BUS	1.00	\$6,230.40	10.00	\$5,607.36	Replace	✓
6010210	VM	0004910285	MOUNTING:RUBBER,FO R MB OC500 LE BUS	1.00	\$119.70	10.00	\$107.73	Replace	✓
6009655	VM	0014920404	PIPE,EXHAUST:REAR,F OR MB OC500 LE BUS	1.00	\$6,230.40	10.00	\$5,607.36	Replace	✓
Total					\$34,618.60		\$31,594.44		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Complete Repair After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: