

INS. CASE OWNER:

CC 4 / LPC 1900

0328 / 21/11/2019

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost: (w/loss)

S\$ 2495.45

OI REPAIR ENDED TP

Loss of Rental (LOR):

S\$ -

(

days)

Loss of Use (LOU):

S\$ 100.00

(\$ 50

x 2

days)

Loss of Income (LOI):

S\$ -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

3450

Total:

S\$ 2597.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 2597.45

Name 1:

Tan Chong Motor Sales Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

SYNOPSIS

Rasul

REF:

328 / 11003 / 2

17086

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 778B

at Workshop n/s

TAN CHONG

of

911 BUKIT TIMAH

Insured:

LPC

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Lamborghini

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 778B

Yr Regn: 2017 / SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN PULSAR 1.2

c.c. 1197

Colour:

RED

A/C: Insured / Std / NI / NA

Sp. Reading

21364

T/Radio: Insured / Std / NI / NA

Eng/No:

ChNo:

VSK B0AC1340107102

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/12/18

D.O.I.

11/01/19

Survey held at

TAN CHONG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P - \$2332.20 (Red \$2408.50 (511)

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$))

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$4

) Photos

) Others

) TOTAL

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/19/VP05/021297
Our ref: CC4/LPC19000328/R1ea3

Date: 14/01/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLW 778B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/01/2019 at the premises of M/s Tan Chong Motor Sales Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,740.76
Revised Estimate Amount	: S\$	2,332.00
"Check" Items Amount	: S\$	948.56
Total (Including Check Items)	: S\$	3,280.56
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Asher

1164
07/01/19.

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832 FAX : 64697472

Like

PM
11/10/19
APPT
11 AM
12 PM

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW778B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
2	RP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120 /
3	RS	SUPPLY & INSTALL REVERSE SENSOR	55.00	/
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X M
5	22/001	REPAIR END PANEL, TAILGATE AND RENEW REAR BUMPER	1200.00	780 /
6	22/002	S/PAINT REAR BUMPER, END PANEL AND TAILGATE	1200.00	3500 /
TOTAL LABOUR CHARGES			3035.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAR W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW778B

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 EMBLEM PULSAR	90891-3GF0B	87.00	OK	
2 CROMMET BUMPER \$2.50 EA X 02	63846-5V000	5.00	OK	
3 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80	OK	
4 ABS ENERGY RH	85092-3ZL0A	157.20	?	} SUE
5 ABS ENERGY LH	85093-3ZL0A	154.60	?	
6 REINT INNER	85030-3ZLMA	486.40	?	
7 BRKT RR BUMPER RH	85226-3ZL0A	59.30	OK	
8 BRKT RR BUMPER LH	85227-3ZL0A	59.30	OK	
9 FASCIA KIT RR	85022-3ZLMH	731.10	DE	
10 SUNDRIES	NPN			100.00 ? } XMM
11 SENSOR-REVERSE	SENSOR			210.00 ? }
SUB TOTAL		1744.70	0.00	310.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		348.94	0.00	0.00
GRAND TOTAL		1395.76	0.00	310.00
OVERALL TOTAL		1705.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Auto Consultants hence no
the Repairer of the following:

- To resurvey before/after spray paint
- To display damaged part(s) during
- Parts prices are subject to change
- Third party survey is on a "no"
- No illegal modification(s)
- Supplementary item(s) is subject to final approval

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLW778B

TOTAL LABOUR CHARGES	3035.00
TOTAL SPARE PARTS CHARGES	1705.76
GRAND TOTAL	4740.76 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	Resue - 149 9006068
SURVEYED DATE	11/01/19 @ 1130
AUTHORIZED DATE	
EXCESS CLAUSE	0.00 4 days
LIABILITY	0.00
REMARKS	Resueing by paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0015/2019
DATE : 03-JAN-2019

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : MDN IVY LEE CHOR ING
ADDRESS : BLK 119 JURONG EAST STREET 13
#03-107
S(600119)
TELEPHONE NO : 92228023

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SJA2876C
VEHICLE NO : SLW778B
MODEL CODE : DRLARDZC13UEAB-H-E
MODEL/YEAR : NISSAN PULSAR 1.2 MY2017
ENGINE NO : HRA2446637A
CHASSIS NO : VSKDDAC13U0107102
MILEAGE : 1 KM
DATE IN : 03/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 30/12/2018

DLS

PASUK

DLS

\$ 50 X 02

= \$100/-

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW778B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	120.00
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	350.00	120.00
3	RS	SUPPLY & INSTALL REVERSE SENSOR	55.00	55.00
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
5	ZZ/001	REPAIR END PANEL, TAILGATE AND RENEW REAR BUMPER	1200.00	780.00
6	ZZ/002	S/PAINT REAR BUMPER, END PANEL AND TAILGATE	1200.00	500.00
TOTAL LABOUR CHARGES			3035.00	1575.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLN778B

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 EMBLEM PULSAR	90891-3GF0B	87.00			OK
2 CROMMET BUMPER \$2.50 EA X 02	63846-5V000	5.00			OK
3 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80			OK
4 ABS ENERGY RH	85092-3ZL0A	157.20			X
5 ABS ENERGY LH	85093-3ZL0A	154.60			X
6 REINF INNER	H5030-3ZLMA	486.40			X
7 BRKT RR BUMPER RH	85226-3ZL0A	59.30			OK
8 BRKT RR BUMPER LH	85227-3ZL0A	59.30			OK
9 FASCIA KIT RR	H5022-3ZLMH	731.10			OK
10 SUNDRIES	NPN			100.00	X
11 SENSOR-REVERSE	SENSOR			210.00	X
SUB TOTAL		946.50	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		189.30	0.00	0.00	
GRAND TOTAL		757.20	0.00	0.00	
OVERALL TOTAL		757.20			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLW778B

NETT ITEM	946.50
LESS 20.00%	-189.30
NETT AMOUNT	757.20
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	1575.00
TOTAL SPARE PARTS CHARGES	757.20
TOTAL CHARGES	2332.20
ADD 7 % GST	163.25
GRAND TOTAL	2495.45

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0015/2019
DATE : 03-JAN-2019

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : MDM IVY LEE CHOR ING
ADDRESS : BLK 119 JURONG EAST STREET 13
#03-107
S(600119)
TELEPHONE NO : 92228023

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SJA2876C
VEHICLE NO : SLW778B
MODEL CODE : DRLARDZC13UEAB-H-E
MODEL/YEAR : NISSAN PULSAR 1.2 MY2017
ENGINE NO : HRA2446637A
CHASSIS NO : VSKDDAC13U0107102
MILEAGE : 1 KM
DATE IN : 03/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 30/12/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

Like

11/01/19
APPT
11/01/19

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW778B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120
3	RS	SUPPLY & INSTALL REVERSE SENSOR	55.00	/
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
5	ZZ/001	REPAIR END PANEL, TAILGATE AND RENEW REAR BUMPER	1200.00	780
6	ZZ/002	S/PAINT REAR BUMPER, END PANEL AND TAILGATE	1200.00	1500
TOTAL LABOUR CHARGES			3035.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW778B

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 EMBLEM PULSAR	90891-3GF0B	87.00	<i>OK</i>	
2 CROMMET BUMPER \$2.50 EA X 02	63846-5V000	5.00	<i>OK</i>	
3 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80	<i>OK</i>	
4 ABS ENERGY RH	85092-3ZL0A	157.20	?	
5 ABS ENERGY LH	85093-3ZL0A	154.60	?	
6 REINF INNER	H5030-3ZLMA	486.40	?	
7 BRKT RR BUMPER RH	85226-3ZL0A	59.30	<i>OK</i>	
8 BRKT RR BUMPER LH	85227-3ZL0A	59.30	<i>OK</i>	
9 FASCIA KIT RR	H5022-3ZLMH	731.10	<i>OK</i>	
10 SUNDRIES	NPN			100.00 ?
11 SENSOR-REVERSE	SENSOR			210.00 ?
SUB TOTAL		1744.70	0.00	310.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		348.94	0.00	0.00
GRAND TOTAL		1395.76	0.00	310.00
OVERALL TOTAL		1705.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLW778B

TOTAL LABOUR CHARGES	3035.00
TOTAL SPARE PARTS CHARGES	1705.76

GRAND TOTAL	4740.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - HP 90010068
SURVEYED DATE	:	11/01/19 @ 1130
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 4 days
LIABILITY	:	0.00
REMARKS	:	Resurvey by paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 7 January, 2019 11:37 AM
To: Admin-D (LKKAuto)
Cc: MT_Claim_SG; lawrenceteo@tanchong.com
Subject: FW: ACCIDENT INVOLVING SLW778B & SJA2876C ON 30.12.2018
INS/IC/LAW/0015/2019 DIRECT SETTLEMENT
Attachments: 1101_001.pdf

Our Ref : 18/18/19/VP05/021297

07012019 @ 11:47am

Lawrence veh not in

Dear Catherine ,

Kindly proceed with the survey and revert on Direct Settlement once our insured lodged the report.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Lawrence Teo [mailto:lawrenceteo@tanchong.com]

Sent: Monday, 7 January, 2019 11:16 AM

To: MT_Claim_SG

Subject: ACCIDENT INVOLVING SLW778B & SJA2876C ON 30.12.2018 INS/IC/LAW/0015/2019 DIRECT SETTLEMENT

Dear Office In Charge,

Our customer, IVY LEE CHOR ING the owner of SLW778B is insured with AIG Insurance at the material time of the accident. The 3rd party SJA2876C is insured with you at the material time of the accident.

Our customer holds your insured driver liable for the accident and would like to claim against your insured driver. On behalf of our customer, we hereby enquire whether you would like to have a Direct Settlement with our customer.

Our customer's claiming for Cost Of Repair and Loss Of Rental @\$100/Day.GIA Report / Estimate attached for your action.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472

Email: lawienceteo@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 17 January 2019 2:45 PM
To: Lawrence Teo; Mei Kwan (LKKAUTO)
Cc: CS A Team; Admin A
Subject: Re: ACCIDENT INVOLVING SLW778B & SJA2876C ON 30.12.2018
INS/IC/LAW/0015/2019 DIRECT SETTLEMENT *** LKK REF: CC4/LPC19000328/R1ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Lawrence Teo <lawrenceteo@tanchong.com>

Sent: Tuesday, January 15, 2019 4:21 PM

To: Mei Kwan (LKKAUTO); Asher Sng (LKKAUTO)

Cc: CS A Team; Admin A

Subject: RE: ACCIDENT INVOLVING SLW778B & SJA2876C ON 30.12.2018 INS/IC/LAW/0015/2019 DIRECT SETTLEMENT

*** LKK REF: CC4/LPC19000328/R1ea3

Dear Asher,

Please assist update me.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472

Email: lawrenceteo@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>

Sent: 15 January 2019 16:18

To: Lawrence Teo <lawrenceteo@tanchong.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SLW778B & SJA2876C ON 30.12.2018 INS/IC/LAW/0015/2019 DIRECT SETTLEMENT *** LKK REF: CC4/LPC19000328/R1ea3

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lawrence Teo [<mailto:lawrenceteo@tanchong.com>]

Sent: Monday, 7 January, 2019 11:39 AM

To: GERALD POH WEE BIN <geraldpoh@lonpac.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: ACCIDENT INVOLVING SLW778B & SJA2876C ON 30.12.2018 INS/IC/LAW/0015/2019 DIRECT SETTLEMENT

Dear LKK,

Please revert to me on Liability.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472

Email: lawrenceteo@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: 07 January 2019 11:37

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Lawrence Teo <lawrenceteo@tanchong.com>

Subject: FW: ACCIDENT INVOLVING SLW778B & SJA2876C ON 30.12.2018 INS/IC/LAW/0015/2019 DIRECT SETTLEMENT

Our Ref : 18/18/19/VP05/021297

Dear Catherine ,

Kindly proceed with the survey and revert on Direct Settlement once our insured lodged the report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Lawrence Teo [<mailto:lawrenceteo@tanchong.com>]

Sent: Monday, 7 January, 2019 11:16 AM

To: MT_Claim_SG

Subject: ACCIDENT INVOLVING SLW778B & SJA2876C ON 30.12.2018 INS/IC/LAW/0015/2019 DIRECT SETTLEMENT

Dear Office In Charge,

Our customer, IVY LEE CHOR ING the owner of SLW778B is insured with AIG Insurance at the material time of the accident. The 3rd party SJA2876C is insured with you at the material time of the accident.

Our customer holds your insured driver liable for the accident and would like to claim against your insured driver. On behalf of our customer, we hereby enquire whether you would like to have a Direct Settlement with our customer.

Our customer's claiming for Cost Of Repair and Loss Of Rental @\$100/Day.GIA Report / Estimate attached for your action.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472

Email: lawrenceteo@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

SATISFACTORY NOTE

W12140935
\$2495.45

TAN CHONG MOTOR SALES PTE LTD (TCMS)

AUTOLUTION INDUSTRIAL PTE LTD (AIPL)

TC AUTOCLINIC PTE LTD (TCAC)

DATE:

OWNER NAME:

JAY LEE CHOR INC.

NRIC NO.:

ADDRESS:

BLK 119 JUNE EAST
ST 13 #03-104
S 60019

VEHICLE MODEL:

NISSAN PULSAR

REGN. NO.:

SLW 778 B

CHASSIS NO.:

TYPE OF CLAIM:

OWN DAMAGE (OD)

OWN DAMAGE (OD) & UNINSURED LOSS
(EXCESS & LOSS OF USAGE) VIA

TCMS / AIPL / TCAC

THIRD PARTY THROUGH
TCMS / AIPL / TCAC

THIRD PARTY - OWNER

DIRECT CLAIM AGAINST

THIRD PARTY INSURANCE

WINDSCREEN / GLASS (W/S)

INSURANCE CO.:

AIC - LAMPAGE

CLAIM NO.:

POLICY NO.:

DATE OF ACCIDENT:

30/12/18

DATE RECEIVED:

18/02/19

DATE COMPLETED:

21/02/19

We / I hereby confirmed that the accident repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd and that all necessary repairs as resulted of the accident of the above vehicle have been completed to our / my satisfaction and that We / I have no further claim whatsoever against the above Company in respect thereof. Terms and Conditions as stipulated in the overleaf applies.

We / I have taken delivery of my car after all necessary repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd *

Note: In the event of an Own Damage Claim, your Insurance Company may under policy terms & conditions, or as standard Industrial Practice, increase the loading on your premium during Insurance Policy renewal. Your NCD [Non Claim Discount] may also be affected, subject to business policy of respective Insurance Company.

[Signature]
(NAME / SIGNATURE OF INSURED)

FOOTNOTE:

TCMS / AIPL / TCAC* WILL CLAIM ON BEHALF
OF OWNER
THROUGH TCMS'S LEGAL AID

DEPOSIT PAID BY OWNER

OWNER WILL MAKE CLAIM AGAINST
THIRD PARTY INSURANCE COMPANY

DOCUMENTS RETURNED TO
OWNER

TCMS / AIPL / TCAC* WILL CLAIM ON BEHALF
OF OWNER UNINSURED LOSS (EXCESS
PAYMENT & LOSS OF USAGE)

INSURANCE CO. COPY

* Delete When Necessary




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19000328/R1da3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 04-10-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJA 2876C	Veh. Inspected	SLW 778B	
Policy No.	Z18VP05020670	Coverage (\$)	0.00	
Claim No.	18/18/19/VP05/021297	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	07/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN PULSAR 1.2	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VSKDDAC13U0107102	Colour	RED	
Odometer	21364	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R15	CONTINENTAL	6 mm	
L/H Front Tyre	215/65 R15	CONTINENTAL	6 mm	
R/H Rear Tyre	215/65 R15	CONTINENTAL	6 mm	
L/H Rear Tyre	215/65 R15	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/12/2018	Inspection Date	11/01/2019	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 778B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	EMBLEM PULSAR (N)	NECESSARY	87.00	87.00
2	GROMMET BUMPER @\$2.50 (N)	NECESSARY	5.00	5.00
4	CLIP BUMPER @\$1.20 (N)	NECESSARY	4.80	4.80
1	ABS ENERGY RH (N)	SERVICEABLE	157.20	-
1	ABS ENERGY LH (N)	SERVICEABLE	154.60	-
1	REINF INNER (N)	SERVICEABLE	486.40	-
1	BRKT RR BUMPER RH (N)	NECESSARY	59.30	59.30
1	BRKT RR BUMPER LH (N)	NECESSARY	59.30	59.30
1	FASCIA KIT RR (N)	DEFORMED	731.10	731.10
	LESS 20% DISCOUNT		-348.94	-189.30
			1,395.76	757.20
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	SENSOR -REVERSE (SN)	NOT NECESSARY	210.00	-
			310.00	-
LABOUR				
	REMOVE /INSTALL & TEST REAR REVERSE CAMERA.		120.00	120.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL .		360.00	120.00
	SUPPLY & INSTALL REVERSE SENSOR.		55.00	55.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	-
	REPAIR END PANEL ,TAILGATE AND RENEW REAR BUMPER.		1,200.00	780.00
	S/PAINT REAR BUMPER ,END PANEL AND TAILGATE.		1,200.00	500.00
	-		-	-
	-		-	-
	-		-	-
			3,035.00	1,575.00
GRAND TOTAL			4,740.76	2,332.20



RECOMMENDED COST OF REPAIRS			2,332.20
-----------------------------	--	--	----------

Report Ref No. CC4/LPC19000328/R1da3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.