

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0015/2019
DATE : 03-JAN-2019

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : MDM IVY LEE CHOR ING
ADDRESS : BLK 119 JURONG EAST STREET 13
#03-107
S(600119)
TELEPHONE NO : 92228023

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SJA2876C
VEHICLE NO : SLW778B
MODEL CODE : DRLARDZC13UEAB-H-E
MODEL/YEAR : NISSAN PULSAR 1.2 MY2017
ENGINE NO : HRA2446637A
CHASSIS NO : VSKDDAC13U0107102
MILEAGE : 1 KM
DATE IN : 03/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 30/12/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

Lee

11/01/19
APPT
11/01/19
11/01/19

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW778B

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	/ 120
3 RS	SUPPLY & INSTALL REVERSE SENSOR	55.00	/
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
5 ZZ/001	REPAIR END PANEL, TAILGATE AND RENEW REAR BUMPER	1200.00	/ 780
6 ZZ/002	S/PAINT REAR BUMPER, END PANEL AND TAILGATE	1200.00	/ 500
TOTAL LABOUR CHARGES		3035.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW778B

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 EMBLEM PULSAR	90891-3GF0B	87.00	<i>Re ✓</i>	
2 CROMMET BUMPER \$2.50 EA X 02	63846-5V000	5.00	<i>Re ✓</i>	
3 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80	<i>Re ✓</i>	
4 ABS ENERGY RH	85092-3ZL0A	157.20	?	
5 ABS ENERGY LH	85093-3ZL0A	154.60	?	
6 REINF INNER	H5030-3ZLMA	486.40	?	
7 BRKT RR BUMPER RH	85226-3ZL0A	59.30	<i>Re ✓</i>	
8 BRKT RR BUMPER LH	85227-3ZL0A	59.30	<i>Re ✓</i>	
9 FASCIA KIT RR	H5022-3ZLMH	731.10	<i>DE ✓</i>	
10 SUNDRIES	NPN			100.00 ?
11 SENSOR-REVERSE	SENSOR			210.00 ?
SUB TOTAL		1744.70	0.00	310.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		348.94	0.00	0.00
GRAND TOTAL		1395.76	0.00	310.00
OVERALL TOTAL		1705.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLW778B

TOTAL LABOUR CHARGES	3035.00
TOTAL SPARE PARTS CHARGES	1705.76
GRAND TOTAL	4740.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Razul - 149 9000068
SURVEYED DATE	:	11/01/19 @ 1130
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 4 days
LIABILITY	:	0.00
REMARKS	:	Resurvey by paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.