

INS. CASE OWNER:

CC 4/ LPC 1900

0331, Rida 312

LKK:

IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBC 2970 L



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sng Ah Tee



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

Nil

If NO or B 28, Ass. Lia:

Repair Cost: (w/651)

S\$ 2705.97

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$ 400.00

(\$ 100 x 4 days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$ 3107.97

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 3107.97

Name 1:

Sng Ah Tee Motor & Panel Service Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$450

COPY SENT 16/9/19

wh 9/9/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/19/VC30/021296
Our ref: CC4/LPC19000331/R1fa3

Date: 24/01/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBE 2970L


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/01/2019 at the premises of M/s Sng Ah Tee Motor & Panel Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,771.85
Revised Estimate Amount	: S\$	2,448.94
"Check" Items Amount	: S\$	426.06
Total (Including Check Items)	: S\$	2,875.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0079M

Vehicle Details

Vehicle No.:	GBE2970L
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	ZD30001152N
Chassis No.:	JN1SC2F24Z0857505
Maximum Power Output:	-
Open Market Value:	\$25,089.00
Original Registration Date:	23 Oct 2015
First Registration Date:	23 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$1,255.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	22 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,799.00
COE Rebate Amount:	\$3,227.00
Total Rebate Amount:	\$3,227.00

The information contained herein is correct as at 17 Jan 2019

OK

EMPLOYEE STATEMENT



Name: Nagarajan Eswaran	Statement Taken By: Hossain Mohammad Monowar
Designation : Driver	Designation : Coordinator, HSSE
Emp No#: 80002621	Statement Date: 26/12/2018
Date Hire: 13/06/2017	Statement Time: 13:30hrs
Site : MCY	Statement Location: 19 Tuas, MCY office

On 24th December 2018 at 6pm, I was parked my lorry at jalan papan dormitory car park lot no 30 and I went to my room. On that day at 11.50pm, Jalan papan dormitory security guard informed me that the Rotary company van driver hits my (PEC-GBE2970L) lorry at front left side, while he was reversing the van for parking beside my (PEC-GBE2970L) lorry. After hits, the Rotary company driver informed to the security guard.

Rotary company driver details.

Name : Chandrasekar s/o Anand Krishnan

Vehicle no: PA7693 J

Signature : 	Signature : 
Name : Nagarajan Eswaran	Name : Hossain Mohammad Monowar
Date : 26/12/2018	Date : 26/12/2018

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004540

LONPAC INSURANCE BHD

100 BEACH ROAD #19-00

SHAW TOWER 189702

ATTENTION:

CONTACT: 6250 7388

FAX NO: 6296 3767

DATE 19/01/2019

ACCIDENT DATE : 24/12/2018

VEHICLE NO : GBE2970L

CHASSIS/ENG.NO : JN1SC2F24Z0857505

VEHICLE MODEL : NISSAN.CABSTAR

CLAIM NO : CC4/LPC19000331/fa3

POLICY NO :

REMARK : 2970 TP LONPAC AGST
PA7693J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

** LIST PRICE **

SUB-TOTAL: 0.00

** NETT PRICE **

1	1	PC	FRT BUMPER <i>see</i>	945.10	10	850.59	850.59 ✓
2	1	PC	FRT CORNER PANEL (LH) <i>BA</i>	389.90	10	350.91	350.91 ✓
3	6	PC	FRT CORNER PANEL CLIP <i>BA</i>	6.40	10	5.76	34.56 ✓
4	1	PC	FRT HEADLAMP (LH) <i>? x sm</i>	473.40	10	426.06	426.06 X
5	1	PC	FRT SIDE MIRROR RECTANGLE(LH) <i>see</i>	191.90	10	172.71	172.71 ✓
6	1	PC	FRT DOOR (LH) <i>repair</i>	1,396.50	10	1,256.85	1,256.85 R
7	1	PC	FRT SIDE MIRROR OUTER COVER (LH) <i>SA</i>	111.30	10	100.17	100.17 ✓

SUB-TOTAL 3,191.85

\$1508.94

** SPECIAL NETT PRICE **

1	1	PC	FRT DOOR ROC STICKER (LH) <i>see</i>	20.00		20.00	20.00 ✓
---	---	----	--------------------------------------	-------	--	-------	---------

SUB-TOTAL 20.00

** WORK LABOUR **

TO CHECK WIRING	30.00	30.00
TO APPLY ANTI RUST COAT	80.00 <i>40</i>	80.00
TO REMOVE & REFIX DOOR GLASS (LH)	150.00 <i>X 2</i>	150.00
TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	700.00 <i>500</i>	700.00

Redraw company Logo - 120.80

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ004540

RCB, Reg. / GST Reg. No: 200810440N

LONPAC INSURANCE BHD

100 BEACH ROAD #19-00
SHAW TOWER 189702

ATTENTION:

CONTACT: 6250 7388

FAX NO: 6296 3767

DATE : 19/01/2019
ACCIDENT DATE : 24/12/2018
VEHICLE NO : GBE2970L
CHASSIS ENG.NO : JN1SC2F24Z0857505
VEHICLE MODEL : NISSAN.CABSTAR
CLAIM NO : CC4/LPC19000331/fa3
POLICY NO :
REMARK : 2970 TP LONPAC AGST
PA7693J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

TO SPRAY PAINTING ON AFFECTED AREAS

600.00 ~~350~~ 600.00
SUB-TOTAL 1,560.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Person

4p 90010068

4 days

P/P

21/01/19 @ 1420

Resurvey before paint

1508.94
20.00
1000.00
2528.94

total \$2814.40

*part by part
ok? no permit.
17/1/2019*

4891.85

JOYCE

PAGE: 2 of 2

SUB-TOTAL : S\$ 4,771.85
ADD 7% GST. S\$ 334.03
GRAND TOTAL : S\$ 5,105.88

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004540

LONPAC INSURANCE BHD

100 BEACH ROAD #19-00
SHAW TOWER 189702

ATTENTION:

CONTACT: 6250 7388

FAX NO: 6296 3767

DATE : 19/01/2019
ACCIDENT DATE : 24/12/2018
VEHICLE NO : GBE2970L
CHASSIS/ENG.NO : JN1SC2F24Z0857505
VEHICLE MODEL : NISSAN.CABSTAR
CLAIM NO : CC4/LPC19000331/fa3
POLICY NO :
REMARK : 2970 TP LONPAC AGST
PA7693J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
						SUB-TOTAL:	0.00
** NETT PRICE **							
1	1	PC	FRT BUMPER <i>sea</i>	945.10	10	850.59	850.59
2	1	PC	FRT CORNER PANEL (LH) <i>BA</i>	389.90	10	350.91	350.91
3	6	PC	FRT CORNER PANEL CLIP <i>AM</i>	6.40	10	5.76	34.56
4	1	PC	FRT HEADLAMP (LH) <i>? X sea</i>	473.40	10	426.06	426.06
5	1	PC	FRT SIDE MIRROR RECTANGLE(LH) <i>sea</i>	191.90	10	172.71	172.71
6	1	PC	FRT DOOR (LH) <i>repair</i>	1,396.50	10	1,256.85	1,256.85
7	1	PC	FRT SIDE MIRROR OUTER COVER (LH) <i>sea</i>	111.30	10	100.17	100.17
						SUB-TOTAL	3,191.85
** SPECIAL NETT PRICE **							
1	1	PC	FRT DOOR ROC STICKER (LH) <i>me</i>	20.00		20.00	20.00
						SUB-TOTAL	20.00
** WORK LABOUR **							
TO CHECK WIRING						30.00	30.00
TO APPLY ANTI RUST COAT						80.00 <i>40</i>	80.00
TO REMOVE & REFIX DOOR GLASS (LH)						150.00 <i>X</i>	150.00
TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS						700.00 <i>500</i>	700.00

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ004540

RCB. Reg. / GST Reg. No: 200810440N

LONPAC INSURANCE BHD

100 BEACH ROAD #19-00
SHAW TOWER 189702

ATTENTION:

CONTACT: 6250 7388

FAX NO: 6296 3767

DATE: 19/01/2019
ACCIDENT DATE: 24/12/2018
VEHICLE NO: GBE2970L
CHASSIS/ENG.NO: JN1SC2F24Z0857505
VEHICLE MODEL: NISSAN.CABSTAR
CLAIM NO: CC4/LPC19000331/fa3
POLICY NO:
REMARK: 2970 TP LONPAC AGS1
PA7693J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO SPRAY PAINTING ON AFFECTED AREAS			600.00 350	600.00
						SUB-TOTAL	1,560.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Reson
HP 90010068
4 days
P/P
21/01/19 @ 1420
Resurvey before paint

JOYCE

PAGE: 2 of 2

SUB-TOTAL: S\$ 4,771.85
ADD 7% GST. S\$ 334.03
GRAND TOTAL: S\$ 5,105.88

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 7 January, 2019 11:02 AM
To: admin@sngahtee.com
Cc: MT_Claim_SG; Admin-D (LKKAuto)
Subject: RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE GBE2970L AND YOUR INSURED PA7693J ON 24/12/2018

WITHOUT PREJUDICE

Our Ref : 18/18/19/VC30/021296

Dear Joyce,


Our insured has not notify us of the accident and we are unable to ascertain liability yet.

If you require the vehicle to be survey, please contact LKK Auto Consultants Pte Ltd to make the necessary arrangements.

07012019 @ 1203pm

Janice veh no in.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: admin@sngahtee.com [mailto:admin@sngahtee.com]
Sent: Monday, 7 January, 2019 10:26 AM
To: MT_Claim_SG
Subject: ACCIDENT INVOLVING OUR CLIENT VEHICLE GBE2970L AND YOUR INSURED PA7693J ON 24/12/2018

Hi All,

Have your insured reported the accident?
Is liability in our favour?
Hope to hear from you.
Thanks you

Best Regards

Joyce Tan

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 17 January 2019 11:12 AM
To: 'admin@sngahtee.com'
Cc: Admin A; Admin-D (LKKAuto); assignments
Subject: RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE GBE2970L AND YOUR INSURED PA7693J ON 24/12/2018

Importance: High

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC4/LPC19000331/fa3
Your Ref: GBE 2970L

Dear Joyce,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Thursday, 24 January, 2019 11:33 AM
To: 'ONG LI LI'
Cc: MT_Claim_SG; Admin A; CS A Team
Subject: RE: Our Ref : 18/18/19/VC30/021296 RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE GBE2970L AND YOUR INSURED PA7693J ON 24/12/2018
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/18/19/VC30/021296
LKK REF: CC4/LPC19000331/R1fa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: GBE 2970L

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Please take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 16 January, 2019 9:46 AM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Our Ref : 18/18/19/VC30/021296 RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE GBE2970L AND YOUR INSURED PA7693J ON 24/12/2018

Dear Mei Kwan

Attached is our Insured's GIA report for your handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd

WITHOUT PREJUDICE

Our Ref : 18/18/19/VC30/021296

Dear Joyce,

Our insured has not notify us of the accident and we are unable to ascertain liability yet.

If you require the vehicle to be survey, please contact LKK Auto Consultants Pte Ltd to make the necessary arrangements.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: admin@sngahtee.com [mailto:admin@sngahtee.com]

Sent: Monday, 7 January, 2019 10:26 AM

To: MT_Claim_SG

Subject: ACCIDENT INVOLVING OUR CLIENT VEHICLE GBE2970L AND YOUR INSURED PA7693J ON 24/12/2018

Hi All,

Have your insured reported the accident?

Is liability in our favour?

Hope to hear from you.

Thanks you

Best Regards

Joyce Tan

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457


TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>





LONPAC INSURANCE BHD

CLAIM NO : 18/18/19/VC30/021296
DATE : 02 AUGUST 2019



DISCHARGE VOUCHER

I/We, PEC LTD confirmed acceptance from M/s LONPAC INSURANCE BHD and/or owner of PA 7693J the sum of Singapore Dollar Three Thousand One Hundred Seven and Cents Ninety-Seven Only (\$3,107.97) in full and final satisfaction, liquidation and discharge of all property losses competent to me/us upon the said M/s LONPAC INSURANCE BHD in respect of all property losses sustained by me/us whether now or hereafter to become manifest, arising either directly or indirectly from an accident involving GBE 2970L and PA 7693J on 24 December 2018 along INSIDE 5 JLN PAPAN #06-10 WESTLITE DORM.

I /We hereby agree to indemnify and keep indemnify (LONPAC INSURANCE BHD/ ROTARY ENGINEERING PTE LTD AND/OR CHANDRASEKARAN ANANTHAKRISHNAN) against all claims and any claims whatsoever made by any person/persons on our behalf in respect of the said accident.

I/We further authorize you to pay the above settlement sum directly to SNG AH TEE MOTOR & PANEL SERVICE PTE LTD.

I/We hereby acknowledged that this payment is made on a without admission of liability basis and without prejudice to all related claims and in respect of our insured's recovery action.

ABDUL RAHMAN
28/7/19



.....
Signature of vehicle owner/Date

15/8/19

.....
Name of vehicle owner /Date




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19000331/R1da3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 17-09-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PA 7693J	Veh. Inspected	GBE 2970L	
Policy No.	Z/18/VC30/102592	Coverage (\$)	0.00	
Claim No.	18/18/19/VC30/021296	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	07/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR 3.0 5M/T	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1SC2F24Z0857505	Colour	GREY	
Odometer	120209	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	YOKOHAMA	7 mm	
L/H Front Tyre	195 R15C	YOKOHAMA	7 mm	
R/H Rear Tyre	155 R13C (D)	YOKOHAMA	5/5 mm	
L/H Rear Tyre	155 R13C (D)	YOKOHAMA	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/12/2018	Inspection Date	21/01/2019	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 2970L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER (N)	SCRATCHED	945.10	945.10
1	FRT CORNER PANEL (LH)(N)	BENT	389.90	389.90
6	FRT CORNER PANEL CLIP @\$6.40 (N)	NECESSARY	38.40	38.40
1	FRT HEADLAMP (LH)(N)	SERVICEABLE	473.40	-
1	FRT SIDE MIRROR RECTANGLE (LH)(N)	SCRATCHED	191.90	191.90
1	FRT DOOR (LH)(N)	TO REPAIR SEE LABOUR	1,396.50	-
1	FRT SIDE MIRROR OUTER COVER (LH)(N)	SCRATCHED	111.30	111.30
	LESS 10% DISCOUNT		-354.65	-167.66
			3,191.85	1,508.94
SPECIAL NETT ITEMS				
1	FRT DOOR ROC STICKER (LH) (SN)	NECESSARY	20.00	20.00
			20.00	20.00
LABOUR				
	TO CHECK WIRING.		30.00	30.00
	TO APPLY ANTI RUST COAT.		80.00	40.00
	TO REMOVE & REFIX DOOR GLASS (LH).	NOT NECESSARY	150.00	-
	TO KNOCK ,WELD ,REMOVE & REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRT DOOR (LH) .		700.00	500.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		600.00	350.00
	REDRAW COMPANY LOGO.		120.00	80.00
			1,680.00	1,000.00
GRAND TOTAL			4,891.85	2,528.94
RECOMMENDED COST OF REPAIRS				2,528.94

Report Ref No. CC4/LPC19000331/R1da3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.