

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G**AAD1901-025***Not Authorized**Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5986G

JTDKB3FU403075667

RENAULT

LATITUDE

3.1.2019

AIG

1/11/2018

PART**LIST**

1	1 FRONT BUMPER	\$	<i>Tn</i> 499.90	✓
2	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	101.20	?
3	1 REINFORCEMENT, FRONT BUMPER	\$	<i>Bz</i> 696.40	✓
4	1 ABSORBER, FRONT BUMPER, LOWER	\$	<i>CM</i> 130.20	✓
5	1 ABSORBER, FRONT BUMPER ENERGY	\$	<i>CM</i> 78.10	✓
6	1 FRONT BUMPER SIDE RETAINER RH	\$	<i>CM</i> 78.00	✓
7	1 FRONT BUMPER SIDE RETAINER LH	\$	<i>DIV</i> 78.00	✓
8	1 FRONT BUMPER SUPPORT	\$	81.70	?
9	1 EXTENSION, FRONT BUMPER, RH	\$	117.80	?
10	1 EXTENSION, FRONT BUMPER, LH	\$	<i>Sn</i> 117.80	X
11	1 FRONT LED LAMP (LOWER) RH	\$	<i>Mit</i> 907.75	✓
12	1 FRONT LED LAMP (LOWER) LH	\$	<i>Sn</i> 907.75	X
13	1 FRONT HEADLAMP RH	\$	<i>Bru</i> 2,909.04	✓
14	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>Sn</i> 492.30	X
15	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>Sn</i> 413.10	X
16	1 FRONT HEADLAMP LH	\$	<i>CM</i> 2,909.04	✓
17	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>Sn</i> 492.30	X
18	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>Sn</i> 413.10	X
19	1 FRONT FENDER RH	\$	<i>Bru</i> 945.30	✓
20	1 EXTENSION, FRONT FENDER, RH	\$	<i>R</i> 48.80	X
21	1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>Mit</i> 98.30	✓
22	1 LINER, FRONT FENDER, RH	\$	<i>Mit</i> 200.70	✓
23	1 FRONT FENDER EMBLEM RH	\$	<i>Mit</i> 86.50	✓
24	1 SEAL, FENDER APRON MUDGUARD, RH	\$	<i>Sn</i> 50.90	X
25	1 FRONT BONNET	\$	<i>Bz</i> 950.50	✓
26	1 FRONT LOWER ARM	\$	631.90	?
27	1 FRONT SHOCK ABSORBER	\$	398.20	?
28	1 SHAFT ASSY, FRONT DRIVE, RH	\$	<i>R</i> 1,186.20	X
29	1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	637.50	?

Trans-cab Auto Services Pte Ltd**AAD1901-025**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G

30	1 KNUCKLE, STEERING, RH	\$	562.30	?
31	1 LINK ASSY, FRONT STABILIZER, RH	\$	199.00	X
32	1 BAR, STABILIZER, FRONT	\$	360.30	X
33	1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	200.60	X
34	1 ABSORBER ASSY, SHOCK, FRONT RH	\$	401.80	?
35	1 COCK ASSY, RESERVE TANK	\$	117.80	✓
		\$	18,500.08	
25%		\$	4,625.02	
		\$	13,875.06	

Specical Nett

1	1 FRONT WHEEL RIM	\$	1,570.55	X
2	1 FRONT WHEEL RIM COVER	\$	175.80	X
3	1 CLIP, FRONT FENDER LINER	\$	22.00	✓
TOTAL		\$	1,768.35	
TOTAL PARTS		\$	15,643.41	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	800
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	500
To Rust-Proofing Of The Affected Areas.	\$	170.00	600
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1901-025**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G

To transfer of front windscreen fittings and conduct water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$		220.00	601
To vacuum, replace, refix and recharge air condenser	\$	nn	380.00	X
To replace, refix and top up coolant for radiator	\$	nn	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn	170.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn	380.00	X

TOTAL \$ 10,400.00**Over All Total \$ 39,918.47****(PART-BY-PART) Repair Days**~~14 days~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: