

MBM WHEELPOWER PTE LTD

Your Ref: SKC1124Z

Our Ref: SJA189R

To: AXA

CC

Fax

*Not Authorised
After
Resurvey By perim
6/1/2019 3 days*

Date: 9/1/2019
From: Yin Siew
Fax: 64525333
Contact: 85883198
Make / Model: AUDI TTC
Chassis No.: TRUZZZ8J871038195
Engine No.: BWA145538
Year of Make: 2007
Accident Date: 1 January 2019

ESTIMATE FOR VEHICLE NO. : SJA189R

DESCRIPTION

REAR BUMPER
REAR LOWER DIFFUSER LH (CARACTERE)
REAR BUMPER RETAINER LH
REAR BUMPER BRACKET LH
REAR BUMPER CLIPS
REAR FENDER LH
REAR FENDER INNER SHIELD LH
REAR FENDER INNER SHIELD CLIPS LH
TAIL LAMP LH

QTY	List Price
1	\$ 1,860.00 ✓
1	\$ 1,950.00 X
1	\$ 65.00 ✓
1	\$ 75.00 X
1 SET	\$ 110.00 ✓
1	\$ 10,035.00 X
1	\$ 345.00 7
10	\$ 80.00 7
1	\$ 850.00 ✓
Total:	\$ 15,370.00
LESS 10%	\$ (1,537.00)
Parts Total:	\$ 13,833.00

SPECIAL NETT

REAR BUMPER SENSOR
G-GUARD COATING FOR REAR BUMPER & RH REAR FENDER

1	\$ 250.00 X
1	\$ 500.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO
KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$ 1,000.00

4001

TO REMOVE & REFIT REAR BUMPER SENSOR

\$ 100.00

601

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ 100.00

201

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 1,000.00

5001

Total: \$ 16,783.00

7% GST: \$ 1,174.81

Grand Total: \$ 17,957.81

Mbm wheelpowerpte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t62628888 f64525333

Company Registration Number : 200204110W