

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 242/IC/TCAC/CCR/2018
DATE : 21-DEC-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR LIM HUA LENG
ADDRESS : 27 HILLVIEW AVENUE
#03-09
S(669559)
TELEPHONE NO : 81126116

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100500152-01
VEHICLE NO : SBB1001G
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014
ENGINE NO : MR20449339W
CHASSIS NO : SJNFBAJ11U1892629
MILEAGE : 27025 KM
DATE IN : 21/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 21/12/2018

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must resurvey and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfilin 97495749
- WP
10/1/19 @ 1110.
Resing before paint
sur @ lkkauto.com
tanfilin @ lkkauto.com.
4 days.

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBB1001G

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	X
5 ZZ/001	REPLACE FRONT BUMPER, FRONT RIGHT FENDER & TRIM, ENERGY ABSORBER, REINFORCEMENT ETC. REPAIR PANELS	1000.00	2500 ✓
6 ZZ/002	RESPRAY FRONT BUMPER, FRONT RIGHT FENDER	600.00	2000 ✓
7 ZZ/003	QC, RETUNE & CONSULT CHECK		
8 ZZ/004	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES		1961.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBB1001G

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 RIGHT HEADLAMP	26010-4EAOB	1617.00	at	
2 FENDER TRIM	63810-4EAOA	483.00	at	
3 FRONT BUMPER	62022-4EAOH	614.60	de	
4 FRONT RIGHT FENDER	F3100-4EAMB	622.70	Ry	
5 RIGHT BUMPER BRACKET	62222-4EAOA	20.90	re	
6 ENERGY ABSORBER	62090-4EA1B	195.70	X	
SUB TOTAL		3553.90	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		710.78	0.00	0.00
GRAND TOTAL		2843.12	0.00	0.00
OVERALL TOTAL		2843.12		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SBB1001G

TOTAL LABOUR CHARGES	1961.00
TOTAL SPARE PARTS CHARGES	2843.12

GRAND TOTAL	4804.12 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.