

Surveyor **menmen** ASSIGNMENT (Office)
From (Person) **Jowyn Tay** of **MSG** Date/Time **07012019**

Estimated Cost Bill to

OD (T) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. **SLT 5436X** Insured **FBM1380D**

at Workshop no/s **Kok Wang Car Grooming** Tel. **91839633**

of **No 1 Soun Lee St # 06-40**

Policy No. **MSD/VMS17-369619-CA** Claim No. **MSC/V/18-00195**

Sum Insured - Excess.

Make of Veh. (Client's Record) D.O.A. **22/05/2018**

CA / REV / REP. / REV 24 HRS ^{1up} H.O.D. Endorsement

Date/Time **10:35am @ 7/1/18** Person Contacted: **Mr. kok** Vehicle IN **(OUT)**

Date/Time	Action/Instruction (X) Estimate
	SLT 5436X - X
	FBM1380D - X
	Dismantle: 12/9/2018
	After repair: 13/9/2018
	Rasul,

Pls check parts prices & see my remarks.
US \$3650, 3 days (Red \$3450, 49%10)
15/1/2019

RECEIVED 16 JAN 2019

Person

REF: MSIG

V403F

ASSIGNMENT

Date:

10/9/18

Year:

SLT 5436X

Yr Regn: 2017 Jan

Vehicle Use:

① M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

UD ① TP WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

Transport Vehicle No:

SLT 5436X

Make:

Mercedes Benz C180

CC: 1595

Workshop No:

Kok wang

Colour:

Blue

A/C Insured / Std / NI / NA

Chassis No:

No.1 soon lee st. # 06-40

Sp Bearing:

32411

T/Radio Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

WDD 205 3402FA494963

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Date Insured:

Express

Steering: ① Order / Jammed / Leaked / Burnt or

(Client's Record)


After 12pm

Brake: ① Order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Nil / ① Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F: 245/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ① PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? Yes or No

R/Bal

mm

R/Bal

mm

GIA / PR Seen:

Consistent? Yes or No

L/Bal

mm

L/Bal

mm

Est. Repair:

4

days

Res: Yes or No

D.O.A

22/08/18

D.O.I

11/09/18

Lump Sum:

%

3 Val: Yes or No

Survey held at

Kok wang

CA / REV / REP: 1-24 HRS (up)

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

Date:

Person Contacted

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Estimated repair range \$5,300 - \$6,000

17/9/2018

Check/Case File Pass 1/1

☐ Prel. Report
☐ Final Report

Days Of Repair:

4

Check/Case File Return 1/1

Resurvey No. of Trip:

2

Survey Fee
Transportation

Add Fee:

☐ Site Insp \$
☐ Interview \$
☐ Tech. Insp \$
☐ Workshop \$

Report Format:

PRE

Lump Sum / LB 1/1

5/1/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018		07 Sep 2018 08:13 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		LIOW KIM CHONG, ID: S7068570A							
Main Claimant:		MUN WAI HO, KELVIN, ID: S8824403F							
Vehicle Reg. No.:		SLT5436X	Date of Loss:	22/05/2018 12:00 - :59 [15 Months and 29 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / MSC/V/18-001195	Policy/Cover Note No.:	MSD/VMS/17-369619-CA Coverage: 31/07/2017 - 30/07/2018					
Vehicle Reg. No. (Insured):		FBM1380D	Policy No. (Claimant):						
		Excess:							
Repairer:		Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 09/01/2019]							
Adj Asg. Remarks:		on WP. OI non reporting. Liability not clear, TP reject SJE- assign LKK Auto Consultants Pte Ltd. contact: Mr. Kok - 9183 9633							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (07/01/2019): Report Send Back Alerts - SLT5436X (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Jowyn Tay <jowyn_tay@sg.msig-asia.com>
Sent: Monday, 7 January, 2019 3:23 PM
To: SUR; Admin-D (LKKAuto)
Subject: ASSIST TO DO PAPER RE-SURVEY OF SLT5436X (OUR REF: MSC/V/18-001195)

Importance: High

Dear Sirs / Madam,

Refer to the said matter.

Please assist to do the paper resurvey of SLT5436X. Rights has been granted via Merimen for your side to assess the documents.

Thank you.

Best Regards,

Jowyn Tay
Executive, Claims Services (Motor)
D: +65 6643 1307 | F: +65 6225 7402 | jowyn_tay@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

12/3/2018

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-186807
Date of Request: 03/12/2018

Your Ref No: RSS/1809-4263 (KW)(PD)

R.S. SOLOMON LLC
300 Beach Road
#12-03/04 The Concourse
Singapore 199555

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 22/05/2018
Place of Accident: BLK 496 JURONG WEST STREET 41
Client Vehicle No: SLT5436X

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408866
Tel +65 6547 0000
Fax +65 6547 4889
www.police.gov.sg

Our Ref : TP/IP/32677/2018
Date : 26 June 2018

Mun Wai Ho, Kelvin
Blk 10 Tao Ching Road
#18-24
Singapore 618725

Dear Sir / Madam,

TRAFFIC ACCIDENT INVOLVING FBM1380D AND SLT5436X ALONG JURONG WEST STREET 41 ON 22/05/2018 AT ABOUT 1300 HRS

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver of **FBM1380D** had committed the following offences:
- (i) Failing to exchange particulars after an accident under Section 84(1) of the Road Traffic Act Chapter 276;
 - (ii) Failing to report an accident within 24 Hours under Section 84(2) of the Road Traffic Act Chapter 276.

Action has been initiated against the driver for the said offences.

3. If you have any clarification, you may contact the Investigation Officer, SSS Leslie Tan at office number: 6547 6144.

4. Thank you.

Yours faithfully,

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.



SINGAPORE
POLICE FORCE

PAYMENT

TAX INVOICE
Invoice No :

SPF2018092701000454

Date/Time:

27/09/2018 21:29:29

Application Paid Via:
GST Reference No:

Master
MG-8400000-5

Transaction Ref No:

TP000114814

	Service Type	Service Fee	eService Reference No	Unit Price (S\$)	GST (S\$)	Qty	Amount (S\$)
1	Police Document	Search Fee	0050000001937541	14.00	0.00	1	14.00
Total (S\$)							14.00

This is a computer-generated invoice. No signature is required.
Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2018 08:22
Date Of Accident	22/05/2018 12:55
Exact Location Of Accident	BLK 496 JURONG WEST ST 41 OSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5436X
Insured/Policyholder	
Name Of Registered Owner	MUN WAI HO, KELVIN (WEN WEIHAO)
NRIC No	S8824403F
Email Address	KELVINMUN@LIVE.CO.UK
Mobile Phone No	(LOCAL) +65-98634739
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095875358
Cover Note Number	

Driver

Name of Driver	MUN WAI HO, KELVIN (WEN WEIHAO)
NRIC No	S8824403F
Date Of Birth	18/07/1988
Occupation	INDOOR
Date Of Driving Pass	09/05/2008
Driving Experience	10 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98634739
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	KELVINMUN@LIVE.CO.UK

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN

A: SLT5436x

B: FBm 1380D



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Location: Blk 496 Jurong West St 41 OSCB
Weather: Clear
Road: Dry
Traffic: Moderate

Refer to Police Report
from Jurong West NPC

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time: 13/05/2019

420512

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature _____

Name Ryan J. Hall

NRIC/PIN No: 771022



SINGAPORE POLICE FORCE



T/20180522/2066

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 4

Report No. T/20180522/2066

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/05/2018 13:29	Vide Report No.:	Station Diary No.: 105
--	------------------	---------------------------

Name of Informant: MUN WAI HO, KELVIN		Address: APT BLK 10 TAO CHING ROAD #18-24 SINGAPORE 618725	
ID Type / ID No.: NRIC NO / S8824403F		Contact No.: Home/Office: Mobile: 98634739	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 29	Date of Birth: 18/07/1988	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Business development manager		Driving Licence Information: Class: 3 Date of Expiry:	

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 22/05/2018 13:00	Type of Location: Car Park
Location: JURONG WEST STREET 41 Open space car park of B/496 Jurong West Street 41			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow:	Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head On			Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Colour	Condition	No. of Passenger
FBM1380D	Motorcycle				No Damage	0
SLT5436X	Car	MERCEDES BENZ	C180 COUPE AMG LINE (R18 LED)	Blue	Slightly Damaged	1

Details of Vehicle Involved			
Vehicle No.	Insurance Company	Effective	Expiry Date



**SINGAPORE
POLICE FORCE**



T/20180522/2066

Police Station Of Origin:

Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

3 of 4

Report No. T/20180522/2066

CONTINUATION OF REPORT

Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
138 Robinson Road #07-09
The Corporate Office
Singapore 068906
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS

Original Report No: MA 11 168734 Vehicle Registration No: ST 5486
Name (as shown in NRIC): MAN WAI HO, KELVIN
(*Vehicle Driver/Vehicle Owner) (*)Please delete as appropriate
NRIC/Passport No: S8824403F
Address: 10 JAO CHUAN ROAD #12-74 LOKELIFE 6618725
Contact (Tel): _____ (M/P): 98674739
(Email): kelvinmm@live.co.uk
Date Of Accident: 22/05/2016 Time Of Accident: 12.55
Place Of Accident: BK 896 Jooong West St 41.034P
Insurance Company: INCCMG

(B) ADDITIONAL INFORMATION / AMENDMENTS

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:-


change from claiming own insurance to reporting only




SIGNATURE OF VEHICLE OWNER/DRIVER

DATE: 16/8/18

Accident Photo



Accident Photo



Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong West N.P.C.
700 Corporation Road SINGAPORE 619818
Tel No: 1800-2689999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 63474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J1

Sgt 2 PERRY P NG WEE PHONG

Signature Of Informant:

[Signature]

Signature Of Interpreter:

Not applicable

Date/Time:

22/09/2018 13:29

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt TAN JEOK LENG

Contact No.: 65476144

IN-129

Categorisation Of Case:

Authentication Stamp

NP/18

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong West N.P.C.
100 Corporation Road SINGAPORE 640810
Tel No: 1800-2680229



Report No: 1701020000010

CONTINUATION OF REPORT

Details of Vehicle Insurance				Expiry Date
Vehicle No.	Insurance Co-Operative	Policy No.	15/11/2017	14/11/2018
SLT5436X	NTUC Income Insurance Co-Operative Limited	6005875358		

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: Nil		Use of Pedestrian Crossing: No	

Driver			
Name	Unknown Rider	ID No.	NIL
Related Vehicle	FBM13300 (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving License & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Driver			
Name	MUN WAI HO, KELVIN	ID No.	80824400P
Related Vehicle	SLT5436X (Car)	Contact No.	88834730
Hospital/Clinic	NIL	Class of Driving License & Expiry Date	Class: J Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

On the 22/05/2018 at about 1255hrs, I have entered the open space car park near to B/436 Jurong West Street 41. I then saw a car park lot which near to B/495 and I intend to park. As I was reversing my vehicle to the said lot, I noticed that there was a motorcycle which ride by a male Chinese person travelling from the left side of my vehicle. The said motorcycle was then collided onto the front left side of my vehicle. I did signalled the said rider to stop however he has leave the said car park after the incident.

I managed to take down his motorcycle number before he left. There was in car camera installed in my vehicle however I have yet to check whether any footage recorded. I am not sure whether any CCTV around the vicinity.



**SINGAPORE
POLICE FORCE**

PAYMENT

TAX INVOICE

Invoice No : SPF2018111201000535

Date/Time: 12/11/2018 20:21:16

Application Paid Via: Master
GST Reference No: MG-8400000-5

Transaction Ref No: TP000114814

	Service Type	Service Fee	eService Reference No	Unit Price (S\$)	GST (S\$)	Qty	Amount (S\$)
1	Police Document	Document Fee	0050000001955774	16.00	0.00	1	16.00
Total (S\$)							16.00

This is a computer-generated invoice. No signature is required.

Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION

Enquire Vehicle & Owner Information (Vehicle No. FBM1380D As At 22 May 2018 / 12:55:00)**Law Firm Search Details****Search Reason:** Insurance claim in relation to traffic accident**Law Firm Case No.:** 1809-4263**Current Owner Details****Owner ID Type:** Singapore NRIC**Owner ID:** S7068570A**Owner Name:** LIOU KIM CHONG**Registered Address Type:** HDB / HUDC**Registered Block/House No.:** 34**Registered Street Name:** MARSILING DRIVE**Registered Unit No.:** # 10 - 393**Registered Building Name:** -**Registered Postal Code:** 730034**Current Vehicle Details****Vehicle No.:** FBM1380D**Make Description/Model:** HONDA / CB400SF MANUAL**Insurance Company Name:** MSIG INSURANCE (SINGAPORE) PTE LTD



Thank you!

Slaw Kon Yew has successfully logged out.
Your last login date and time was 05 Sep 2018, 09:21:14.
To return to ONE.MOTORING, please click [here](#).
For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History


S.No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	FEM1350D		18:19 Enquire Vch Owner Info (Other) by Law Firm	7.49	05 Sep 2018 / 09:29:20

Please do not use your browser's Back or Forward buttons as this may result in information loss.

Our Ref. : RSS/1809-4263 (KW)(PD)
Your Ref. : MSC ✓ 18 00119 ✓

W: Natalie Ng
E: natalie_ng@rssolomon.com

3 December 2018



R. S. SOLOMON LLC

Advocates & Solicitors | Commissioner for Oaths

MSIG INSURANCE (SINGAPORE) PTE LTD

No. 4 Shenton Way
#21-01
SGX Centre 2
Singapore 068807
Kind Attn: Motor Claim Dept

**By PDX: [8173]
WITHOUT PREJUDICE**

Dear Sirs,

TRAFFIC ACCIDENT INVOLVING SLT5436X AND FBM1380D AT BLK 496 OF JURONG WEST STREET 41 OSCP ON 22nd MAY 2018 AT ABOUT 1255HRS

We act for Mun Wai Ho Kelvin (our "Client"), the owner and driver of vehicle registration no. SLT5436X, and refer to the above-captioned matter.

2. We are instructed that you are the insurers of vehicle registration no. FBM1380D at the material time. We are further instructed that the aforesaid accident was caused solely by your insured driver's negligence in his driving, controlling and/or management of the said vehicle. As a result of the accident, our Client's vehicle was damaged and he has been put to loss and expense, particulars of which are as follows:-

(a) Cost of Repairs	\$ 7,100.00
(b) Loss of use for 5 working days at \$80.00 per day (i.e. including two days for Pre-repair survey)	\$ 400.00
(c) Survey report fee	\$ 554.00
(d) GIA report & search fees [No search results]	\$ 15.00
(e) Police report and search fees	\$ 30.00
(f) LTA search fee	\$ 7.49
(g) Costs	\$ 700.00
(h) Transport, Xerox, postages & Other Incidentals	\$ 50.00
Total:	\$ 8,856.49

3. We enclose herewith copies of the following documents in support of our Clients' claim:-

- (a) Final Repair Bill No. KWC/SLT5436X from Kok Wang Car Grooming;
- (b) Survey Report with Invoice No. NS-2018-388 from Absolute Appraisal Services Pte Ltd;
- (c) GIA and Police reports lodged by our clients;
- (d) Payment advice for no search result fee;
- (e) Final police investigation result with payment advice for search and report fees;
- (f) LTA Search result with payment advice; and
- (g) 20 coloured photographs depicting damages to our client's vehicle registration No. SLT5436X.

...2

Our Ref. : RSS/1809-4263 (KW) (PD)
Your Ref. :

W: Natalie Ng
E : natalie_ng@rssolomon.com

3 December 2018



R. S. SOLOMON LLC

Advocates & Solicitors | Commissioner for Oaths

PAGE 2

4. **TAKE NOTICE** that unless we receive your acknowledgement of receipt to this letter and enclosures **within fourteen (14) days from the date hereof**, our Client will have no alternative but to commence proceedings against your insured and/or their driver without further notice to you.

Yours faithfully,

R. S. SOLOMON LLC
Advocates & Solicitors

Encl.

Cc LIOW KIM CHONG
34 Marsling Drive
#10-393
Singapore 730034

BY CERTIFICATE OF POSTING
WITHOUT PREJUDICE

Note to insured and/or the driver: No enclosures have been provided to you; should you require copies of the afore-mentioned enclosures, please contact our office.

TAKE NOTICE that if you have a counterclaim against our Client arising out of the above-captioned accident, you are required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of you receiving this letter.

KOK WANG CAR GROOMING

No. 1 Soon Lee Street #06-40 Pioneer Centre Singapore 627605

Tel No.: +65 91839633 | Fax: +65 6694 4864

Date: 27th September 2018

Invoice No.: KWC/SLT5436X-220518

Messrs: Mun Wai Ho Kelvin

Vehicle No.: SLT5436X

	Amount
FINAL REPAIR COST	\$7,100.00
(LUMP SUM)	

Total: \$7,100.00

SGD SEVEN THOUSAND ONE HUNDRED ONLY



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0415 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Invoice

Customer: Mun Wai Ho Kelvin
10 Tao Ching Road #18-24
Lake Life (S) 618725

Date: 27.09.2018

Invoice No: NS-2018-388

Description		Amount
Vehicle No:	SLT5436X	
Make & Model:	Mercedes C180 Coupe AMG (A)	
Our reference:	AAS/2018/388	
Services rendered for appraiser / inspection report		
Survey Fee		
Photographs		
Transport Fees		
Re-inspection Fees		
SGD Dollar : Five hundred and forty dollar only	Total:	SGD \$ 540.00

Notes

All cheques payment should be crossed and made payment to "Absolute Appraisal Services Pte Ltd"
Please indicate our "Invoice No." on the reverse side of the cheque
Please do not hesitate to contact us should you have any enquires



Absolute Appraisal Services Pte Ltd



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7596
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Mun Wai Ho Kelvin
10 Tao Ching Road #18-24
Lake Life (S) 618725

Date of report: 27.09.2018
Date of request: 12.09.2018
Date of inspection: 12.09.2018
Date of accident: 22.05.2018
Claim type: Third Party Claim

Report No: AAS/2018/388

Particulars of affected vehicle:

Registration no: SLT5436X
Make/Model: Mercedes C180 Coupe AMG (A)
Year of registration: 2016/17
Colour: Metallic Blue

Odometer: 32411 km
Engine Capacity: 1595 cc
Engine no: 27491030912517
Chassis no: WDD2053402F494963

Condition of tires:

Front Left: 6mm
Make: Pirelli
Rear Left: 6mm
Make: Pirelli

Front Right: 6mm
Make: Pirelli
Rear Right: 6mm
Make: Pirelli

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conducted at M/s. Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 9,290.40
Revised estimate:	\$ 8,895.40
Recommended reserve:	\$ 7,100.00 (Lump sum)
Estimated normal duration of repairs : 3 Working days	



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
 Mobile: 9666-0413 Fax: 6266-7396
 Email: absolute.app.svcs@gmail.com

Vehicle No: SLT5436X
 Appraisal Schedule

Report No: AAS/2018/388

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	Front bumper (AMG)	1	Dented/Cut	\$ 4,242.00	\$ 4,242.00
2	Front bumper centre chrome	1	Necessary	\$ 157.00	\$ 157.00
3	Front bumper side chrome LH/RH	2	Necessary	\$ 180.00	\$ 180.00
4	Front bumper corner sensor	1	Malfunctioned	\$ 255.00	\$ 255.00
5	Front bumper sensor decoupling	4	Necessary	\$ 32.00	\$ 32.00
6	Headlamp LH	1	Loop Broken	\$ 3,890.00	\$ 3,890.00
Total:				\$ 8,756.00	\$ 8,756.00
-10%				\$ 875.60	\$ 875.60
List total:				\$ 7,880.40	\$ 7,880.40

S/N	Labour Description	Repairer's Est	Revised Est
1	Rust proofing on affected panels.	\$ 60.00	\$ 40.00
2	Renew & transfer parking sensor.	\$ 100.00	\$ 60.00
3	To check lightings & wirings.	\$ 50.00	\$ 40.00
4	Spray painting on affected & replacement panels.	\$ 700.00	\$ 500.00
5	Renew damaged parts, reform affected panel, realign affected area.	\$ 500.00	\$ 375.00
Labour Total:		\$ 1,410.00	\$ 1,015.00

The final adjusted lump sum amount is \$7,100.00

Grand Total: \$ 9,290.40 \$ 8,895.40

Under normal circumstances, the repair should be completed within a reasonable period of 3 working days.

20 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Sep 2018		07 Sep 2018 08:13 Edit Adj Rpt	S\$3,650.00 Edit Estimates	S\$3,650.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIOW KIM CHONG, ID: S7068570A		
Main Claimant:	MUN WAI HO, KELVIN, ID: S8824403F		
Vehicle Reg. No.:	SLT5436X	Date of Loss:	22/05/2018 12:00 - :59 [15 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001195	Policy/Cover Note No.:	MSD/VMS/17-369619-CA Coverage: 31/07/2017 - 30/07/2018
Vehicle Reg. No. (Insured):	FBM1380D	Policy No. (Claimant):	
		Excess:	
Repairer:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 09/01/2019]		
Adj Asg. Remarks:	on WP. OI non reporting. Liability not clear. TP reject SJE- assign LKK Auto Consultants Pte Ltd, contact: Mr. Kok - 9183 9633		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (07/01/2019): Report Send Back Alerts - SLT5436X (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLT5436X (MSC/V/18-001195)**
[FBM1380D]




































TP

MUN WAI HO, KELVIN

May 22 2018 12:00PM

[LIOW KIM CHONG]

Kok Wang Car Grooming - Pioneer

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
2	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
3	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	13/09/18 11:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	13/09/18 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	17/09/18 19:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
33	17/09/18 19:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
34	17/09/18 19:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	17/09/18 19:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	17/09/18 19:20	Photo After Spray	1 Load JPG	✓
37	17/09/18 19:20	Photo After Spray	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/09/18 09:19	TP GIA REPORT	1 Load PDF	
2	06/09/18 09:19	TP PRI NOTICE	1 Load PDF	
3	31/12/18 11:07	LOD WITH SUPPORT DOCS	1 Load PDF	
4	07/01/19 16:42	TPD SLT5436X - SURVEY PHOTOGRAPHS	1 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/19 13:10	PRS INVOICE	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#)
[Save](#)
[Print](#)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016348/R1QBS2-1
Date: 17/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/17-369619-CA

Claimant Vehicle No : SLT5436X Insured Vehicle No : FBM1380D

Date of Loss: 22/05/2018 Nature of Claim: TP Claim No: MSC/V/18-001195

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT5436X**

Make & Model: MERCEDES-BENZ C180, 1.6 COUPE AMG LINE (R18 LED SR) (A) Engine No: 27491030912517

Reg. Date: 23/01/2017 (Man. Year: 2016) Chassis No: WDD2053402F494963

Colour: Blue Odometer: 32411 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,880.40	4,038.30	3,842.10	48.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	560.00	850.00	60.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,290.40	4,598.30	4,692.10	50.50
Approved Total (Overridden) (S\$)		3,650.00		
Nett Amount (S\$)	9,290.40	3,650.00	5,640.40	60.71

INSPECTION

Date of Assignment: 07/09/2018

Date Inspected: 11/09/2018 Inspected At:

Kok Wang Car Grooming - Pioneer (HQ)
No. 1 Soon Lee Street, #06-40 Pioneer Centre
Singapore 627603

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jan 2019)

Parts: M1-COUPE MERCEDES-BENZ C180 1.6 COUPE AMG LINE (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT5436X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (AMG)	Dented / Cut	4,242.00 FL	*1,485.00 FL
2	1		*FRONT BUMPER CENTRE CHROME	Not Necessary	157.00 FL	*- FL
3	1		*FRONT BUMPER SIDE CHROME LH/RH	N/s Necessary	180.00 FL	*90.00 FL
4	1		*FRONT BUMPER CORNER SENSOR	Malfunction	255.00 FL	*255.00 FL
5	4		*FRONT BUMPER SENSOR DECOUPLING	Necessary	32.00 FL	*32.00 FL
6	1		*HEADLAMP LH	Loop Broken	3,890.00 FL	*2,625.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,756.00	4,487.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	875.60	448.70
Total Parts (\$\$)	7,880.40	4,038.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RUST PROOFING ON AFFECTED PANELS.	New	60.00	0.00
2	RENEW & TRANSFER PARKING SENSOR.	New	100.00	30.00
3	TO CHECK LIGHTING & WIRINGS.	New	50.00	30.00
4	SPRAY PAINTING ON AFFECTED & REPLACEMENT PANELS.	New	700.00	250.00
5	RENEW DAMAGED PARTS, REFORM AFFECTED PANEL, REALIGN AFFECTED AREA.	New	500.00	250.00
Gross Labour Cost (\$\$)			1,410.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >