

ASS. REC. BY:

REF:

CS/CIT19000347/RHd3/n2

Special Instruction:

Surveyor:

Mehmen

Rasul

ASSIGNMENT (Office)

From (Person):

Chong Boon Sun

of

CTE

Date/Time:

07/11/19 @ 2:25pm

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMF 3141X

Insured:

XD 70717

at Workshop m/s

~~Performance Motor~~

Tel:

G319 0174

of

303 Alexandra Road

MOVA. AUTOMOTIVE.

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/12/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

2:57pm @ 7/11/19

Person Contacted:

Cenulpre

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SMF 3141X-X
	XD 70717-NA / INC 15020115/13
	Change WS to Mova.
	lump sum \$6750, 6 days confirm
	(Red: 2723.70; 30%)

Person

REF:

74297

ASSIGNMENT

From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMF 3141X Yr Regn: 2017 / APR Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: B.M.W 1160502 C.C.: 1496

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 35609 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA1V72050V728864

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: -

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/12/18 D.O.I. 11/01/19

Survey held at Nova (Faw) road

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

old Reme

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 13 MAR 2019

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I. (\$

6250/-

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Insp (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

☐ : S + RS. \$

☐ : Photos

☐ : Others:

☐ :

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		07 Jan 2019 14:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LEAN PEK KWAN		
Vehicle Reg. No.:	SMF3141X	Date of Loss:	28/12/2018 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	XD7071T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/01/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

74291

Vehicle Details

Vehicle No.:

SMF3141X

Vehicle to be Exported:

Yes

Intended Deregistration Date:

09 Jan 2019

Vehicle Make:

B.M.W.

Vehicle Model:

116D 5DR HATCH DSC LED

Primary Colour:

White

Manufacturing Year:

2017

Engine No.:

36539847B37D15A

Chassis No.:

WBA1V72050V725864

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$25,094.00

Original Registration Date:

28 Apr 2017

First Registration Date:

28 Apr 2017

Transfer Count:

0

Actual ARF Paid:

\$12,132.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Apr 2027

PARF Rebate Amount:

\$9,099.00

Intended COE Rebate Details

COE Expiry Date:

27 Apr 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$51,600.00

COE Rebate Amount:

\$41,280.00

Total Rebate Amount:**\$50,379.00**

The information contained herein is correct as at 09 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/12/2018 15:58
Date Of Accident	28/12/2018 09:15
Exact Location Of Accident	AYE SLIP ROAD TO AHMAD IBRAHIM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF3141X
Insured/Policyholder	
Name Of Registered Owner	LEAN PEK KWAN
NRIC No	S2007429I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98170116
Alternative Phone No	OTHERS-68622440
Vehicle Particulars	
Manufacturer	BMW
Model	F20 116D
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1928811
Cover Note Number	
Driver	
Name of Driver	CHNG SEE ANN
NRIC No	S0117928D
Date Of Birth	17/11/1948
Occupation	INDOOR
Date Of Driving Pass	05/07/1959
Driving Experience	49 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98170116
Fax Number	
Contact Number	
Email Address	SACPL@SINGNET.COM.SG

Address	15 VICTORIA PARK GROVE
Postcode	266098
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	SKK5675K
	-
Insurance Company of Driver's Own Vehicle	AXA INSURANCE PTE LTD
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	GOOD

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD7071T
Vehicle Make/Model/Colour	TIPPER TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KADAPPAN CHENNAPPANYAN
NRIC/Passport Number	
Contact Number	94215538
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	REAR & RIGHT
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 28/12/18

Driver's Signature
(if driver is not the policyholder)
Date & Time: 28/12/18

Reporting Centre Personnel's Signature
Name: 28/12/18
NRIC/FIN No.: @ 1537W

Sketch Plan Pg. 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As Per attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

28/12/18
3:25 PM

Reporting Centre Personnel's Signature

Name:

NRJC/FIN No.:


28/12/16

Signature
@ 1536W

DEC 28, 2018

I WAS DRIVING ALONG THE AYE, TURNING INTO A SLIP ROAD LEADING TO JALAN AHMAD IBRAHIM, AT APPROXIMATELY 9:15 A.M. ON FRIDAY (DECEMBER 28, 2018) WHEN SUDDENLY A TIPPER TRUCK, REGISTRATION NO: XD 7071T, COLLIDED ONTO MY CAR AND HIT THE RIGHT HAND REAR AND SIDE DOOR OF THE PASSENGER SIDE.


CHNG SEE ANN
I/C NO: 50117928D



Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/01/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- SMF3141X

Veh Model :- BMW X 116D

Estimate# :- CK418546

Claim # :-

ACC. Date :- 28/12/18

Terms :- C.O.D Days

Remarks :- *Alan 96869276*

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER <i>SC</i>	1 PC	978.00	978.00
2.	REAR BUMPER SIDE BRACKET RH <i>SC ? X SC</i>	1 PC	140.00	140.00
3.	REAR FENDER RH <i>SC</i>	1 PC	1,980.00	1,980.00
4.	REAR FENDER INNER SHIELD RH <i>SC ? X SC</i>	1 PC	195.00	195.00
5.	INNER SHIELD CLIPS <i>SC</i>	10 PCS	5.00	50.00
6.	REAR SPORTS RIM RH <i>SC</i>	1 PC	1,480.00	1,480.00
7.	REAR WHEEL HUB W/BEARING RH <i>SC ? X</i>	1 PC	450.00	450.00
8.	REAR LOWER ARM RH <i>SC ? X</i>	1 PC	580.00	580.00
9.	REAR KNUCKLE ARM RH <i>SC ? X</i>	1 PC	680.00	680.00
10.	REAR SHOCK ABSORBER RH <i>SC ? X</i>	1 PC	313.00	313.00
LIST TOTAL S\$				6,846.00
5% DISCOUNT S\$				-342.30
				<u>6,503.70</u>

LABOUR :

TO REMOVE & INSTALL REAR COMPARTMENT
GARNISHES CARPET & ETC IN ORDER TO CUT OFF RH
REAR FENDER

✓ 100 250.00

TO REMOVE & INSTALL FUEL TANK

✓ 60 80.00

TO REMOVE & RENEW RH REAR UNDERCARRIAGE
DAMAGED PARTS

✓ 100 200.00

TO CHECK ALL WHEELS ALIGNMENT

✓ 60 80.00

TO CUT OFF RH REAR FENDER & STRAIGHTEN
AFFECTED AREAS AND RENEW DAMAGED PARTS

✓ 600 900.00

TO APPLY BODY JOINT SEALANT ON CUTTING AREAS

✓ 40 60.00

TO APPLY RUST PROOF ON AFFECTED AREAS

✓ 60 100.00

TO SPRAY PAINT ON REPLACED, REPAIRED AREAS

✓ 600 800.00

LABOUR TOTAL S\$

2,470.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/01/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1 133731
Veh # :- SMF3141X
Veh Model :- BMW X 116D
Estimate# :- CK418546
Claim # :-
ACC. Date :- 28/12/18
Terms :- C.O.D Days
Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	8,973.70
GST @ 7 %	628.16
AMOUNT DUE S\$	9,601.86

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey vehicle after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:

Rasul
Hp 90010068
6 days
P/P 4/5
11/01/19 @ 1720
Resurvey by part after

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1006,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

\$ 6250
6 days

Estimate

09/01/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SMF3141X

Veh Model :- BMW X 116D

Estimate# :- CK418546

Claim # :-

ACC. Date :- 28/12/18

Terms :- C.O.D Days

Remarks :- Alan 96869276

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER <i>SCA</i>	1	PC 978.00	978.00
2.	REAR BUMPER SIDE BRACKET RH <i>SCA ?</i>	1	PC 140.00	140.00
3.	REAR FENDER RH <i>SCA</i>	1	PC 1,980.00	1,980.00
4.	REAR FENDER INNER SHIELD RH <i>?</i>	1	PC 195.00	195.00
5.	INNER SHIELD CLIPS <i>SCA</i>	10	PCS 5.00	50.00
6.	REAR SPORTS RIM RH <i>SCA</i>	1	PC 1,480.00	1,480.00
7.	REAR WHEEL HUB W/BEARING RH <i>?</i> - Bent	1	PC 450.00	450.00
8.	REAR LOWER ARM RH <i>?</i> - Bent	1	PC 580.00	580.00
9.	REAR KNUCKLE ARM RH <i>?</i> - Bent	1	PC 680.00	680.00
10.	REAR SHOCK ABSORBER RH <i>?</i> - Bent	1	PC 313.00	313.00
LIST TOTAL S\$				6,846.00
5% DISCOUNT S\$				-342.30
				6,503.70
LABOUR :				
TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES CARPET & ETC IN ORDER TO CUT OFF RH REAR FENDER				
TO REMOVE & INSTALL FUEL TANK				
TO REMOVE & RENEW RH REAR UNDERCARRIAGE DAMAGED PARTS				
TO CHECK ALL WHEELS ALIGNMENT				
TO CUT OFF RH REAR FENDER & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS				
TO APPLY BODY JOINT SEALANT ON CUTTING AREAS				
TO APPLY RUST PROOF ON AFFECTED AREAS				
TO SPRAY PAINT ON REPLACED, REPAIRED AREAS				
LABOUR TOTAL S\$				2,470.00

P-6511
-58

P-6185.45

+ LC-1620.00

7805.45

-2080.15

6244.30

100 250.00
60 50.00
100 200.00
60 80.00
600 900.00
40 60.00
60 100.00
600 800.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/01/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 133731

Veh # :- SMF3141X

Veh Model :- BMW X 116D

Estimate# :- CK418546

Claim # :-

ACC. Date :- 28/12/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	8,973.70
AMOUNT S\$	
GST @ 7 %	628.16
AMOUNT DUE S\$	9,601.86

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To recover costs after spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
6 days
Pfr 45
11/01/19 @ 1720
Recovery 64 part

Mova Automotive Pte Ltd

15 Fan Yoong Road.
Singapore 629792

Phone Number: 62623377
Fax Number: 62643151

Customer:		Date:	1/25/2019 2:58 PM
Company:		VIN	BMW 116i
License No:	SMF 3141 X	Technician:	LONG
Odometer:	36010	Order No.:	23146

VEHICLE ALIGNMENT REPORT

BMW, 1 SERIES (F20), 2011-2015, Standard Suspension 16" Wheel

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6.60°	---	---	6.55°
		Right	6.50°	---	---	6.63°
	Camber	Left	-0.28°	-0.75°	0.08°	-0.28°
		Right	0.00°	-0.75°	0.08°	-0.01°
	Toe	Left	0.04°	0.08°	0.15°	0.03°
		Right	0.28°	0.08°	0.15°	0.28°
Total		0.32°	0.17°	0.30°	0.31°	
Rear	Camber	Left	-0.87°	-1.75°	-1.58°	-0.87°
		Right	-0.99°	-1.75°	-1.58°	-0.99°
	Toe	Left	0.06°	0.12°	0.18°	0.05°
		Right	-0.05°	0.12°	0.18°	-0.07°
		Total	0.01°	0.23°	0.37°	-0.02°
	Thrust Angle		-0.06°	-0.20°	0.20°	-0.06°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13.22°	---	---	13.22°
	Right		12.82°	---	---	12.82°
Included Angle	Left		12.94°	---	---	12.94°
	Right		12.82°	---	---	12.81°
Toe Out On Turns	Left		1.54°	1.55°	1.55°	1.54°
	Right		1.44°	1.55°	1.55°	1.44°
Maximum Turns	Left		---	40.40°	40.40°	---
	Right		---	40.40°	40.40°	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		0.32"	---	---	0.25"
	Rear		-0.17"	---	---	-0.17"
Track Width Diff.			-0.56"			-0.56"
Wheel Base Diff.			0.49"			0.41"
Front Ride Height	Left		23.10"	22.40"	23.19"	23.10"
	Right		23.10"	22.40"	23.19"	23.10"
Rear Ride Height	Left		22.90"	22.17"	22.95"	22.90"
	Right		22.90"	22.17"	22.95"	22.90"
Frame Angle			---			

Mova Automotive Pte Ltd

15 Fan Yoong Road.
Singapore 629792

Phone Number: 62623377
Fax Number: 62643151

Customer:		Date:	1/29/2019 3:18 PM
Company:		VIN	BMW 116 i
License No:	SMF 3141 X	Technician:	LONG
Odometer:	36011	Order No.:	23146

VEHICLE ALIGNMENT REPORT

BMW, 1 SERIES (F20), 2011-2015, Standard Suspension 16" Wheel

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6.64°	---	---	6.62°
		Right	6.51°	---	---	6.48°
	Camber	Left	-0.33°	-0.75°	0.08°	-0.36°
		Right	0.03°	-0.75°	0.08°	0.09°
	Toe	Left	0.08°	0.08°	0.15°	0.16°
		Right	0.24°	0.08°	0.15°	0.18°
Total		0.32°	0.17°	0.30°	0.34°	
Rear	Camber	Left	-0.92°	-1.75°	-1.58°	-0.81°
		Right	-0.99°	-1.75°	-1.58°	-1.04°
	Toe	Left	0.05°	0.12°	0.18°	0.15°
		Right	-0.06°	0.12°	0.18°	0.14°
		Total	-0.01°	0.23°	0.37°	0.29°
	Thrust Angle		-0.06°	-0.20°	0.20°	-0.01°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13.23°	---	---	13.23°
	Right		12.82°	---	---	12.82°
Included Angle	Left		12.90°	---	---	12.87°
	Right		12.85°	---	---	12.91°
Toe Out On Turns	Left		1.57°	1.55°	1.55°	1.57°
	Right		1.43°	1.55°	1.55°	1.43°
Maximum Turns	Left		---	40.40°	40.40°	---
	Right		---	40.40°	40.40°	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		0.34"	---	---	0.21"
	Rear		-0.17"	---	---	-0.18"
Track Width Diff.			-0.56"			-0.55"
Wheel Base Diff.			0.51"			0.39"
Front Ride Height	Left		23.10"	22.40"	23.19"	23.10"
	Right		23.10"	22.40"	23.19"	23.10"
Rear Ride Height	Left		22.90"	22.17"	22.95"	22.90"
	Right		22.90"	22.17"	22.95"	22.90"
Frame Angle						---

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19000347/R1TD3N2
Date: 19/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17527717000	
Claimant Vehicle No :	SMF3141X	Insured Vehicle No :	XD7071T	
Date of Loss:	28/12/2018	Nature of Claim:	TP	Claim No: SNM19D200198

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3141X	Engine No:	36539847B37D15A
Make & Model:	BMW 116D, 1.5 D 5DR HATCH LED (A)	Chassis No:	WBA1V72050V725864
Reg. Date:	28/04/2017 (Man. Year: 2017)	Odometer:	35609 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,503.70	6,185.45	318.25	4.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,620.00	850.00	34.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,973.70	7,805.45	1,168.25	13.02
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	8,973.70	6,250.00	2,723.70	30.35
+ GST 7.00/7.00% (S\$)	628.16	437.50	190.66	30.35
Nett Amount (S\$)	9,601.86	6,687.50	2,914.36	30.35

INSPECTION

Date of Assignment:	07/01/2019	
Date Inspected:	11/01/2019 Inspected At:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre Singapore 629792

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2019)
Parts:	144	BMW 116D 1.5 D 5DR HATCH LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF3141X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	978.00 FL	*978.00 FL
2	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	140.00 FL	*- FL
3	1		*REAR FENDER RH	Bent	1,980.00 FL	*1,980.00 FL
4	1		*REAR FENDER INNER SHIELD RH	Serviceable	195.00 FL	*- FL
5	10		*INNER SHIELD CLIPS	Necessary	50.00 FL	*50.00 FL
6	1		*REAR SPORTS RIM RH	Scratched	1,480.00 FL	*1,480.00 FL
7	1		*REAR WHEEL HUB W/BEARING RH	Bent	450.00 FL	*450.00 FL
8	1		*REAR LOWER ARM RH	Bent	580.00 FL	*580.00 FL
9	1		*REAR KNUCKLE ARM RH	Bent	680.00 FL	*680.00 FL
10	1		*REAR SHOCK ABSORBER RH	Bent	313.00 FL	*313.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,846.00	6,511.00
- List Item Discount on L Items 5.00/5.00% (S\$)	342.30	325.55
Total Parts (S\$)	6,503.70	6,185.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES CARPET & ETC IN ORDER TO CUT OFF RH REAR FENDER	New	250.00	100.00
2	TO REMOVE & INSTALL FUEL TANK	New	80.00	60.00
3	TO REMOVE & RENEW RH REAR UNDERCARRIAGE DAMAGED PARTS	New	200.00	100.00
4	TO CHECK ALL WHEELS ALIGNMENT	New	80.00	60.00
5	TO CUT OFF REAR FENDER & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	900.00	600.00
6	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00	40.00
7	TO APPLY RUST PROOF ON AFFECTED AREAS	New	100.00	60.00
8	TO SPRAY PAINT ON REPLACED,REPAIRED AREAS	New	800.00	600.00
Gross Labour Cost (S\$)			2,470.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >