

Case Details

Case Reference Number : TAX/12/18/2137
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB431J

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5194-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 31/12/2018 12:30 PM
 Vehicle Age(In Months) : 52

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair ▾
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair ▾
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ▾
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ▾
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give ▾
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give ▾

Total Spare Part Cost	4,074.56		Surveyor Total	149.40	
Lump Sum Discount (%)	20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost	3,259.65		Final Sur Total	119.52	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair
Total Spare Part Cost									4,074.56		Surveyor Total	149.40	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									3,259.65		Final Sur Total	119.52	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH PORTION	845.00	350	
Total:		845.00	350.00	

Spray Cost Detail


S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY REAR DOOR RH	378.00	200	
2	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
3	TO RESPRAY REAR FENDER RH	378.00	200	
4	TO RESPRAY RIM	180.00	0	
5	TO REPSRAY REAR BUMPER	378.00	200	
Total:		1,494.00	700.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
Total:		940.00	40.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	TO TRANSFER DOOR MECHANISM	120.00	0	
4	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	
5	TO REMOVE / REFIT SEAT	120.00	0	
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
7	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
8	TO WASH AND VACUUM	60.00	0	
9	TO REPLACE SUNDRY PARTS	100.00	0	
Total:		940.00	40.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,259.65	119.52
Total Labour Cost	845.00	350.00
Total Spray Painting	1,494.00	700.00
Other	940.00	40.00
Overall Total	6,538.65	1,209.52
Lump Sum Repair Option	☒	☐
Lump Sum Total	6,550.00	1,209.52
Surveyor Approved Amount		1,209.52
No of Repair Days*	5	5
Remarks	-	RESURVEY AFTER REPAIR / LUMP SUM
Surveyor Name		Rasul
Signature		
		Save Clear

Estimator Assesment(\$)

Surveyor Assesment(\$)

Survey Date

04/01/2019