

ASS. REC. BY:

REF:

CS/FCI19000358/R1+d3ⁿ²

Special Instruction:

Surveyor:

Rashid

ASSIGNMENT (Office)

From (Person):

CWS

Sereh Jer

of

FCI

Date/Time:

4/11/19 @ 6.01pm

Estimated Cost:

Bill to:

OD ⁽¹⁾ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 1460E

Insured:

SHB 4098L

at Workshop m/s

Hitachi Capital

Tel:

9643 5107 / 6833 6274

of

8 Fourth Lok yang Road

Policy No:

Claim No:

DIQ000256m#SH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3/1/19

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

9:30am @ 7/1/19

Person Contacted:

jongtaw

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLE 1460E - CS/FCI18017261 / 1/1/d3

DUA: 18/09/18

SHB 4098L - CS/FCI14015538 / Uqm3u2

DUA: 12/08/14

9/1 @ 1:34pm - revised prev advise email.

Surveysor *Ram*

REF:


0399N

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: **SLE 1460E**
 at Workshop n/s **HITACHI CAPITAL**
 of **4th Loymun Rd**
 Insured: **FCI**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **2/5**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. **SLE 1460E** Yr Regn: **2016 / June**
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **TOYOTA COROLLA ALTIS 1.6 cc : 1598**
 Colour: **GRAY** A/C: Insured / Std / NI / NA
 Sp. Reading: **193044** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MR053REH104553895**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **205/55R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **HANKOOK**
 Front: **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **03/01/19** D.O.I. **07/01/19**
 Survey held at **HITACHI**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FRT
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Part by Part \$8020.75. (Red: 1854.75 : 18%)

Rasul, pls see my remarks.

RECEIVED 05 MAR 2019

[Signature]
 4/3/2019

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: **9**

Resurvey No. of Trip: **2**

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

) 5/3/19

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B. : (\$ **8020.75**)

170
50
50+50
102
422



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBC

Date: 09/01/2018

Our Ref: CS/FCI19000358/R1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 1460E

Please be informed that we had conducted the inspection of the abovementioned vehicle 09/01/2019 at the premises of M/s Hitachi Capital have the following to report: -

Workshop Estimate Amount	: S\$ 9,716.25
Revised Estimate Amount	: S\$ 5,519.00
"Check" Items Amount	: S\$ 750.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s
Front portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Rasul
Automotive Assessor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 9 January 2019 1:34 PM
To: Admin-D (LKKAUTO); 'Teo Swee Keong'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: NEW SURVEY ASSIGNMENT - SLE1460E OUR REF: SHB4098L DOA: 03/01/2019
Attachments: PRELI ADVISED SLE 1460E - 1.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLE 1460E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 7 January 2019 5:21 PM
To: 'Teo Swee Keong' <TeoSweeKeong@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT - SLE1460E OUR REF: SHB4098L DOA: 03/01/2019

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo Swee Keong [<mailto:TeoSweeKeong@msfirstcapital.com.sg>]
Sent: Friday, 4 January 2019 6:01 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: NEW SURVEY ASSIGNMENT - SLE1460E OUR REF: SHB4098L DOA: 03/01/2019

Dear Sirs

CPC - GE (SL)

MOTOR SURVEY ASSIGNMENT

Date 4/1/19 Our Ref No. SHB4098L
Accident Date 3/1/19 Claim Type. TP
Insured Vehicle SHB4098L Third Party Vehicle. SLE1460E
Survey Location 8 Fourth Lok Yang Road S'pore 629705
Contact Person.
Contact No. 6833 6274 9643 5107 Fax No. -Nil-
Survey Type DIRECT SETTLEMENT (Est. COR \$10,396.39 / QUANTUM TO BE AGREED)
Appointed Surveyor Lkh
Contact Person
Contact Number. 6256 3561 Fax No. 6841 6315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Cc : Workshop Hitachi Capital Asia Pacific Pte Ltd Attention. Vonn Siow
Cc : TP Solicitor -Nil- TP Solicitor Fax No. -Nil-
Officer Incharge Serene Ler

RECEIVED - 4 JAN 2019

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 March 2019 4:16 PM
To: Denise Tay (LKKAUTO)
Subject: FW: MANUAL SURVEY

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 21 January 2019 2:31 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: Aini Binte Md Min <Aini@msfirstcapital.com.sg>; Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Subject: MANUAL SURVEY

Dear Sir/Madam

Please find below claim reference no.'s for which manual survey was arranged .

REFERENCE NO.	INSURED VEHICLE NO.	TP VEHICLE NO.
D19000222MFSH	SHC7609M	SHD1195Z
D19000225MFSH	SHC2787P	SLH7150U
D19000254MFSH	SHC8180A	SHD5125A
D19000224MFSH	SHD7067X	SLA6386A
D19000230MFSH	SHA6237U	SLU1003H
D19000231MFSH	SHA7858X	SDW1663L
D19000226MFSH	SHA1280B	SLL192Z
D19000234MFSH	SHC1877U	EL8965R
D19000232MFSH	SHC1676H	SJF2465D
D19000256MFSH	SHB4098L	SLE1460E
D19000261MFSH	SH6086X	SMA827Y

Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	0399N

Vehicle Details

Vehicle No.:	SLE1460E
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1ZRY311339
Chassis No.:	MR053REH104553895
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	11 Jul 2016
First Registration Date:	11 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$16,800.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jul 2026
PARF Rebate Amount:	\$12,600.00

Intended COE Rebate Details

COE Expiry Date:	10 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$38,930.00
Total Rebate Amount:	\$51,530.00

The information contained herein is correct as at 03 Jan 2019

OK

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 04/01/2019

MS FIRST CAPITAL
 ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 03/01/2019 @ 07:15
 VRN : SLE1460E
 MODEL : TOYOTA ALTIS
 TP VRN : SHB4098L

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER <i>DE</i>	1	\$ 458.00	\$ 458.00	
2 FRONT BUMPER CLIP <i>neu</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER SIDE RETAINER LH <i>neu</i>	1	\$ 82.00	\$ 82.00	
4 FRONT FOG LAMP LH <i>? CRA</i>	1	\$ 325.00	\$ 325.00	
5 FRONT FOG LAMP COVER LH <i>cut</i>	1	\$ 91.00	\$ 91.00	
6 HEADLAMP LH <i>Bro</i>	1	\$ 850.00	\$ 850.00	
7 HEADLAMP TOP CHROME LH <i>? X suc</i>	1	\$ 200.00	\$ 200.00	
8 FRONT FENDER LH <i>neu</i>	1	\$ 780.00	\$ 780.00	
9 FRONT FENDER LOGO "VVT-I" <i>neu</i>	1	\$ 54.00	\$ 54.00	
10 FRONT FENDER SHIELD LH <i>DE</i>	1	\$ 200.00	\$ 200.00	
11 FRONT FENDER SHIELD CLIP LH <i>neu</i>	10	\$ 5.50	\$ 55.00	
12 FRONT AIR DUCT LH <i>DE</i>	1	\$ 160.00	\$ 160.00	
13 FRONT RIM LH <i>repair suc</i>	1	\$ 1,645.00	\$ 1,645.00	
14 FRONT DOOR LH <i>neu</i>	1	\$ 1,100.00	\$ 1,100.00	
15 FRONT DOOR LH HINGE UPPER <i>? X suc</i>	1	\$ 85.00	\$ 85.00	
16 FRONT DOOR LH HINGE LOWER <i>? X suc</i>	1	\$ 95.00	\$ 95.00	
17 FRONT DOOR LH CHECK <i>? X suc</i>	1	\$ 152.00	\$ 152.00	
18 FRONT DOOR LH WEATHERSTRIP <i>neu</i>	1	\$ 175.00	\$ 175.00	
19 FRONT DOOR LH STICKER <i>neu</i>	1	\$ 42.00	\$ 42.00	
20 FRONT DOOR LH CHROME MOULDING <i>? X suc</i>	1	\$ 143.00	\$ 143.00	
21 FRONT LH SIDE MIRROR <i>CRA</i>	1	\$ 1,250.00	\$ 1,250.00	
22 FRONT LH SIDE MIRROR COVER <i>repair</i>	1	\$ 78.00	\$ 78.00	
			\$ 8,075.00	
Discount -25%			\$ 2,018.75	
			\$ 6,056.25	
23 FRONT SUPPORT PANEL	Repair			
		PARTS TOTAL	\$ 6,056.25	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	\$ 1,500.00
Putty, Blend And Spray Paint on FRONT Affected Area	\$ 1,500.00
Check Wiring, Re-align Headlamps, Ensure Proper Functioning	\$ 30 80.00
Remove and Replace Front Door Window Glass to Facilitate Repair	\$ 60 180.00
Check & Re-adjust and Computerise Wheel Alignment	\$ 60 180.00
Dismantle and Transfer Front LH Door Fittings & Mechanisms to New Door	\$ 80 180.00
Remove, Replace and Balance Rim	\$ 40.00

LABOURS TOTAL \$ 3,660.00

Grand Total : \$ 9,716.25

Add 7% GST : \$ 680.14

Nett Total : \$ 10,396.39

No. of repair days: 12



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Rasul
Ap 90010068

9 days

9/P

07/01/19 @ 1615

Resurvey by paint

4/3/19

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705

Tel : 64663022 Fax : 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 04/01/2019

MS FIRST CAPITAL

ACCIDENT DATE : 03/01/2019 @ 07:15

ATTN: MOTOR CLAIMS DEPT

VRN : SLE1460E

MODEL : TOYOTA ALTIS

TP VRN : SHB4098L

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER <i>OK</i>	1	\$ 458.00	\$ 458.00	
2 FRONT BUMPER CLIP <i>new</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 82.00	\$ 82.00	
✓ 4 FRONT FOG LAMP LH ?	1	\$ 325.00	\$ 325.00	
5 FRONT FOG LAMP COVER LH <i>cut</i>	1	\$ 91.00	\$ 91.00	
6 HEADLAMP LH <i>Bro</i>	1	\$ 850.00	\$ 850.00	
7 HEADLAMP TOP CHROME LH ?	1	\$ 200.00	\$ 200.00	
8 FRONT FENDER LH <i>new</i>	1	\$ 780.00	\$ 780.00	
9 FRONT FENDER LOGO "VVT-I" <i>new</i>	1	\$ 54.00	\$ 54.00	
10 FRONT FENDER SHIELD LH <i>OK</i>	1	\$ 200.00	\$ 200.00	
11 FRONT FENDER SHIELD CLIP LH <i>new</i>	10	\$ 5.50	\$ 55.00	
12 FRONT AIR DUCT LH <i>OK</i>	1	\$ 160.00	\$ 160.00	
✓ 13 FRONT RIM LH <i>repair</i>	1	\$ 1,645.00	\$ 1,645.00	
14 FRONT DOOR LH <i>new</i>	1	\$ 1,100.00	\$ 1,100.00	
15 FRONT DOOR LH HINGE UPPER ?	1	\$ 85.00	\$ 85.00	
16 FRONT DOOR LH HINGE LOWER ?	1	\$ 95.00	\$ 95.00	
17 FRONT DOOR LH CHECK ?	1	\$ 152.00	\$ 152.00	
18 FRONT DOOR LH WEATHERSTRIP <i>new</i>	1	\$ 175.00	\$ 175.00	
19 FRONT DOOR LH STICKER <i>new</i>	1	\$ 42.00	\$ 42.00	
20 FRONT DOOR LH CHROME MOULDING ?	1	\$ 143.00	\$ 143.00	
21 FRONT LH SIDE MIRROR <i>CRA</i>	1	\$ 1,250.00	\$ 1,250.00	
22 FRONT LH SIDE MIRROR COVER <i>repair</i>	1	\$ 78.00	\$ 78.00	
			\$ 8,075.00	
Discount -25%			\$ 2,018.75	
			\$ 6,056.25	
23 FRONT SUPPORT PANEL	Repair			

PARTS TOTAL \$ 6,056.25

7322

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	1800	\$ 1,500.00
Putty, Blend And Spray Paint on FRONT Affected Area	1100	\$ 1,500.00
Check Wiring, Re-align Headlamps, Ensure Proper Functioning		\$ 30 80.00
Remove and Replace Front Door Window Glass to Facilitate Repair		\$ 60 180.00
Check & Re-adjust and Computerise Wheel Alignment		\$ 60 180.00
Dismantle and Transfer Front LH Door Fittings & Mechanisms to New Door		\$ 80 180.00
Remove, Replace and Balance Rim		\$ 40.00
LABOURS TOTAL	2370	\$ 3,660.00

Grand Total : \$ 9,716.25
Add 7% GST : \$ 680.14
Nett Total : \$ 10,396.39

No. of repair days: 12



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Resul
Ap 90010068
9 days
7/P
07/01/19 @ 1615
Resurvey by paint

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

SUPPLEMENTARY VEHICLE ESTIMATE dated 17/01/2019

MS FIRST CAPITAL
 ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 03/01/2019 @ 07:15
 VRN : SLE1460E
 MODEL : TOYOTA ALTIS
 TP VRN : SHB4098L

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
✓ 1 FRONT FENDER PROTECTOR LH <i>CR</i>	1	\$ 75.00	\$ 75.00	(75)
			\$ 75.00	
Discount -25%			\$ 18.75	
			\$ 56.25	
Special Nett				
✓ 2 Front LH Tyre <i>cut</i>	1	\$ 103.00	\$ 103.00	(SN 103)
			\$ 103.00	
PARTS TOTAL			\$ 159.25	

Grand Total : \$ 159.25
 Add 7% GST : \$ 11.15
Nett Total : \$ 170.40

No. of repair days: 9

P = 7322-W
+ supp = 75-W

7397-W
- 25%

5547.75
+ SN = 103-00
+ L = 2370-00

T = 8020.75

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000358/R1td3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4098L	Veh. Inspected	SLE 1460E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000256MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	04/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104553895	Colour	GREY	
Odometer	195044	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HANKOOK	6 mm	
L/H Front Tyre	205/55 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/01/2019	Inspection Date	07/01/2019	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1460E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	458.00	458.00
10	FRONT BUMPER CLIP @\$5.50	NECESSARY	55.00	55.00
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	82.00	82.00
1	FRONT FOG LAMP LH	CRACKED	325.00	325.00
1	FRONT FOG LAMP COVER LH	CUT	91.00	91.00
1	HEADLAMP LH	BROKEN	850.00	850.00
1	HEADLAMP TOP CHROME LH	SERVICEABLE	200.00	-
1	FRONT FENDER LH	BUCKLED	780.00	780.00
1	FRONT FENDER LOGO "VVT-I"	NECESSARY	54.00	54.00
1	FRONT FENDER SHIELD LH	DEFORMED	200.00	200.00
10	FRONT FENDER SHIELD CLIP LH @\$5.50	NECESSARY	55.00	55.00
1	FRONT AIR DUCT LH	DEFORMED	160.00	160.00
1	FRONT RIM LH	SCRATCHED	1,645.00	1,645.00
1	FRONT DOOR LH	BUCKLED	1,100.00	1,100.00
1	FRONT DOOR LH HINGE UPPER	SERVICEABLE	85.00	-
1	FRONT DOOR LH HINGE LOWER	SERVICEABLE	95.00	-
1	FRONT DOOR LH CHECK	SERVICEABLE	152.00	-
1	FRONT DOOR LH WEATHERSTRIP	NECESSARY	175.00	175.00
1	FRONT DOOR LH STICKER	NECESSARY	42.00	42.00
1	FRONT DOOR LH CHROME MOULDING	SERVICEABLE	143.00	-
1	FRONT LH SIDE MIRROR	CRACKED	1,250.00	1,250.00
1	FRONT LH SIDE MIRROR COVER	TO REPAIR SEE LABOUR	78.00	-
1	FRONT FENDER PROTECTOR LH (ADDITIONAL)	CRACKED	75.00	75.00
	LESS 25% DISCOUNT		-2,037.50	-1,849.25
			6,112.50	5,547.75
SPECIAL NETT ITEMS				
1	FRONT SUPPORT PANEL (NPA)(SN)	TO REPAIR SEE LABOUR	-	-
1	FRONT LH TYRE (ADDITIONAL)(SN)	CUT	103.00	103.00
			103.00	103.00

Report Ref No. CS/FCI19000358/R1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF FRONT AFFECTED AREA,INCLUSIVE OF THE REPAIR OF FRONT LH SIDE MIRROR COVER AND FRONT SUPPORT PANEL.		1,500.00	1,000.00
	PUTTY,BLEND AND SPRAY PAINT ON FRONT AFFECTED AREA.		1,500.00	1,100.00
	CHECK WIRING,RE-ALIGN HEADLAMPS,ENSURE PROPER FUNCTIONING.		80.00	30.00
	REMOVE AND REPLACE FRONT DOOR WINDOW GLASS TO FACILITATE REPAIR.		180.00	60.00
	CHECK & RE-ADJUST AND COMPUTERISE WHEEL ALIGNMENT.		180.00	60.00
	DISMANTLE AND TRANSFER FRONT LH DOOR FITTINGS & MECHANISMS TO NEW DOOR.		180.00	80.00
	REMOVE,REPLACE AND BALANCE RIM.		40.00	40.00
			3,660.00	2,370.00
	GRAND TOTAL		9,875.50	8,020.75

RECOMMENDED COST OF REPAIRS			8,020.75
------------------------------------	--	--	-----------------

Report Ref No. CS/FCI19000358/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.