

22/03/2002

ASS. REC. BY:

REF:

CS/EP19000365/Utd30

Special Instruction:

Surveyor:

Menmen

ASSIGNMENT (Office)

From (Person):

Janet Tan

of

EQI

Date/Time:

07/01/19 @ 3:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 27512

Insured:

at Workshop m/s

Soc Leon Motor

Tel:

6747 7858

of

1 kaki Bkt Ave 6 # 01-01 Autobay

Policy No:

DMPPHQ17-006709

Claim No:

DM19H000016

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

27/12/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

8/1/2019

Date/Time:

4:40pm @ 7/1/19

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate check damage consistency
	SJB 27512-CC41/EP19000365/Ajb3 Date: 27/12/2018
8/1 @	Report via menmen Lump Sum Repair
10/1 @ 15:35pm	authorise repair by Joel Goh
11/1 @ 1:33pm	email to soc leon authorise repair excess \$250/-

REF: EQI

ASSIGNMENT

From

Date: 08/01/19

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

8JB 27512

at Workshop m/s

Soc Leon Motor

of

1 kaki Bk Ave 6 #01-01 Autobay

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$500.00

(Client's Record)

Make of Veh:

Check damage consistency

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

20500

IDAC Accident Report:

Consistent?: Yes or No

☒ PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

2

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

net 3517

Veh No

8JB 27512

Yr Regn

1 / 08

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

m.f. Lender OPC

C.C

1499

Colour

Silver / Black

A/C:

Insured / Std / NI / NA

Sp. Reading

269473

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMY/SREY2A84003845

Gen. Cond

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / SRim / STD A/Rim or

Tyre Size:

F:

215/502R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

D.O.I.

8/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R 0/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

net 3517

8/1/19 confirmed a/s \$3500 with AH xing (Red: 1613.81 : 31%)
 cor upst 31-12-2022 16987

RECEIVED 14 JAN 2019

Date/Time, File Pass to?

☐

Preli. Report

1) H1 Typist

☒

Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

-

Survey Fee:

160

Transportation

) \$ + RS. SI

) Photos

) Others

TOTAL

160

Report Format:

OD

Lump Sum / I.B.I. (\$)

3500

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2019 Sendback Est	04 Jan 2019 11:21 S\$5,113.81	07 Jan 2019 15:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ISMAIL BIN SAID , ID: S1595744A, Tel: +6590468113		
Vehicle Reg. No.:	SJB2751Z	Date of Loss:	27/12/2018 05:00 - :59 [131 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DM19HO00016	Policy/Cover Note No.:	DMPPHQ17-006709 (Comprehensive) Coverage: 27/12/2017 - 06/01/2019
		Excess:	S\$500.00
Repairer:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 7858		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by JANET TAN]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/01/2019]		
Driver/Custodian:	ISMAIL BIN SAID (55 / Male), NRIC: S1595744A, Tel: +6590468113		
Adj Asg. Remarks:	EXCESS: \$500.00 KINDLY ASSIST ON OD SURVEY AND REVERT. CHECK IF DAMAGE IS CONSISTENT WITH THIRD PARTY'S VEHICLE WE ARE OF THE VIEW THAT DAMAGE IS INCONSISTENT.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5744A
Vehicle Details	
Vehicle No.:	SJB2751Z
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLS 4A/T
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	4A910070683
Chassis No.:	JMYSRCY2A8U003845
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	07 Jan 2008
First Registration Date:	07 Jan 2008
Transfer Count:	3
Actual ARF Paid:	\$17,693.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,349.00
COE Rebate Amount:	\$16,987.00
Total Rebate Amount:	\$16,987.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Jan 2019

OK

View Received Message

This mail is associated with :

SJB2751Z (DM19HO00016)

OD

Dec 27 2018 5:00AM

[ISMAIL BIN SAID]

Soc Leon Motor Works

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From EQ Insurance Company Ltd (HQ) (EQI_HQ), sent on 10/01/2019 15:35 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3500.00) - SJB2751Z - Claim Handler: JANET TAN

Approved:3500.00:Damage is consistent based on accident video footage Excess: S\$250.00 (50% waiver)

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 11 January 2019 1:33 PM
To: 'slmoi@singnet.com.sg'
Cc: SUR
Subject: SJB 2751Z / OD / EQ

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJB 2751Z (Excess \$250/-). Original \$500, 50% wavier.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/12/2018 16:30
Date Of Accident	27/12/2018 05:30
Exact Location Of Accident	SUNTEC CITY BLVD (ALONG RAFFLES BLVD TWDS FLYER)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB2751Z
Insured/Policyholder	
Name Of Registered Owner	ISMAIL BIN SAID
NRIC No	S1595744A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90468113
Alternative Phone No	OFFICE-90468113

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	40495

Driver

Name of Driver	ISMAIL BIN SAID
NRIC No	S1595744A
Date Of Birth	24/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	10/11/1982
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90468113
Fax Number	
Contact Number	OFFICE-90468113
Email Address	NOEMAIL

Address	BLK 324 SEMBAWANG CLOSE #06-329
Postcode	750324
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR5421Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

•VEH A SJB 2751 Z

VEH B SJR 5421 Y



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 DEC 2018, around 5.30am while I was driving along Temasek Blvd turning into Raffles Blvd while turning my head to see oncoming vehicle is clear then start to drive out and suddenly the vehicle in front of me is moving & slow and I hit onto the rear left side of the front vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Soc Leon Motor Works (Co.Reg.No:20663900K)

1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit

Singapore 417883

Tel: 6747 7858 Fax: 6742 0012 Email: slmoi@singnet.com.sg

INSURER:

EQ Insurance Company Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPPHQ17-006709	Date of Loss:	27/12/2018
Vehicle Reg. No.:	SJB2751Z	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ISMAIL BIN SAID	Contact No:	+6590468113
Driver:	ISMAIL BIN SAID		
Make/Model:	MITSUBISHI LANCER, 1.6 (A)	Vehicle Reg. Date:	07/01/2008
Vehicle Colour:	SILVER	Chassis No:	JMYSRCY2A8U003845
Engine No:	4A910070683		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		

Present Location: SOC LEON MOTOR WORKS (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	3,402.30
Miscellaneous Items	241.51
Labour	1,470.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	5,113.81
- Excess (S\$)	500.00
Nett Amount (S\$)	4,613.81

This claim is handled by: IRENE LEONG SUM PHENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LIK Auto-Consent to repair notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Not Adhered
to
L/S \$3500
Excess \$500
8/1/19
Wm phw Att-Rep
Sdy.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2019)

Parts: 143 MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJB2751Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	Suc *420.00 F ✓
2	1		*BONNET HINGE (2 PCS) @\$45.00	0.00	0.00	n *90.00 F X
3	1		*BONNET LOCK	0.00	0.00	Tw *45.00 F ✓
4	1		*HEADLAMP (RH)	0.00	0.00	BW *380.00 F ✓
5	1		*HEADLAMP SUPPORT PANEL - TOP & LOWER	0.00	0.00	Hy *580.00 F ✓
6	1		*TOP GARNISH	0.00	0.00	To.1 *65.00 F ✓
7	1		*CLIPS (6 PCS) @\$3.00	0.00	0.00	W *18.00 F ✓
8	1		*LOWER BRACKET	0.00	0.00	B *25.00 F ✓
9	1		*FRONT BUMPER	0.00	0.00	To.1 *420.00 F ✓
10	1		*BUMPER LOWER GRILLE	0.00	0.00	Tw *60.00 F ✓
11	1		*BUMPER REINFORCEMENT	0.00	0.00	Suc *260.00 F ✓
12	1		*BUMPER TOP BEAM	0.00	0.00	Hy *58.00 F ✓
13	1		*RUBBER	0.00	0.00	W *48.00 F ✓
14	1		*FOGLIGHT	0.00	0.00	BW *158.00 F ✓
15	1		*FOGLIGHT COVER	0.00	0.00	To.1 *45.00 F ✓
16	1		*TOP GRILLE	0.00	0.00	Tw *168.00 F X
17	1		*CLIPS (10 PCS) @\$3.00	0.00	0.00	Hy *30.00 F ✓
18	1		*FRONT FENDER	0.00	0.00	Suc *125.00 F ✓
19	1		*FENDER INNERSHIELD	0.00	0.00	To.1 *68.00 F ✓
20	1		*CLIPS (10 PCS) @\$3.00	0.00	0.00	W *30.00 F ✓

F=Franchise part.

Sub Total (S\$)	3,093.00
+ Margin on L,N Items 10.00% (S\$)	309.30
Total Parts (S\$)	3,402.30

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	7% GST FROM SUPPLIER BILL	216.51
2	1	APPLY LTA BREAK & RESEAL LICENCE PLATE SEAL (OPC)	25.00
Sub Total (S\$)			241.51

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & FIX AIRCON CONDENSER & REFILL GAS	New	120.00
2	TO KNOCK & REPLACE PARTS	New	600.00
3	SPRAYPAINTING	New	750.00
Gross Labour Cost (S\$)			1,470.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

1/4/2019

Merimen e-Claims

Soc Leon Motor Works (Co.Reg.No:20663900K)

1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit

Singapore 417883

Tel: 6747 7858 Fax: 6742 0012 Email: slmoi@singnet.com.sg

INSURER:

EQ Insurance Company Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPPHQ17-006709	Date of Loss:	27/12/2018
Vehicle Reg. No.:	SJB2751Z	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Thrd Party Involved?	YES
Insured/Claimant:	ISMAIL BIN SAID	Contact No:	+6590468113
Driver:	ISMAIL BIN SAID		
Make/Model:	MITSUBISHI LANCER, 1.6 (A)	Vehicle Reg. Date:	07/01/2008
Vehicle Colour:	SILVER	Chassis No:	JMYSRCY2ABU003845
Engine No:	4A910070683		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		

Present Location: SOC LEON MOTOR WORKS (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	3,402.30
Labour	241.51
Paintwork Labour	1,470.00
Towing	0.00
	0.00
Calculated Gross Total (S\$)	5,113.81
- Excess (S\$)	500.00
Nett Amount (S\$)	4,613.81

This claim is handled by: IRENE LEONG SUM PHENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Not Authorized
 h/b
 L/S
 Excess \$500
 8/1/19
 Wm phw Aik-Regen
 S-Ly.

1/4/2019

Merimen e-Claims

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 04 Jan 2019)
Parts: 143 **MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's **(Price-denominated Standard List)**
Print Code: (Unsubmitted, no print-code for SJB2751Z)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET			
2	1		*BONNET HINGE (2 PCS) @S\$45.00	0.00	0.00	Subc *420.00 F ✓
3	1		*BONNET LOCK	0.00	0.00	1 *90.00 F X
4	1		*HEADLAMP (RH)	0.00	0.00	7.1 *45.00 F ✓
5	1		*HEADLAMP SUPPORT PANEL - TOP & LOWER	0.00	0.00	Subc *380.00 F ✓
6	1		*TOP GARNISH	0.00	0.00	Subc *580.00 F ✓
7	1		*CLIPS (6 PCS) @S\$3.00	0.00	0.00	Subc *65.00 F ✓
8	1		*LOWER BRACKET	0.00	0.00	Subc *18.00 F ✓
9	1		*FRONT BUMPER	0.00	0.00	Subc *25.00 F ✓
10	1		*BUMPER LOWER GRILLE	0.00	0.00	7.1 *420.00 F ✓
11	1		*BUMPER REINFORCEMENT	0.00	0.00	7.1 *60.00 F ✓
12	1		*BUMPER TOP BEAM	0.00	0.00	*260.00 F ?
13	1		*RUBBER	0.00	0.00	*58.00 F ?
14	1		*FOGLIGHT	0.00	0.00	Subc *48.00 F ✓
15	1		*FOGLIGHT COVER	0.00	0.00	Subc *158.00 F ✓
16	1		*TOP GRILLE	0.00	0.00	7.1 *45.00 F ✓
17	1		*CLIPS (10 PCS) @S\$3.00	0.00	0.00	7.1 *168.00 F ✓
18	1		*FRONT FENDER	0.00	0.00	7.1 *30.00 F X
19	1		*FENDER INNERSHIELD	0.00	0.00	Subc *125.00 F ✓
20	1		*CLIPS (10 PCS) @S\$3.00	0.00	0.00	7.1 *68.00 F ✓
				0.00	0.00	Subc *30.00 F ✓
Sub Total (\$)						3,093.00
+ Margin on L,N Items 10.00% (\$)						309.30
Total Parts (\$)						3,402.30

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

1/4/2019

Merimen e-Claims

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

- 1 1 7% GST FROM SUPPLIER BILL *waived*
- 2 1 APPLY LTA BREAK & RESEAL LICENCE PLATE SEAL (OPC)

216.51 X *?*

25.00 *20*

Sub Total (S\$) 241.51

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

- 1 TO REMOVE & FIX AIRCON CONDENSER & REFILL GAS
- 2 TO KNOCK & REPLACE PARTS
- 3 SPRAYPAINTING

New *100* 120.00

New *500* 600.00

New *630* 750.00

Gross Labour Cost (S\$) 1,470.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >





































...CLAIM SUBFOLDER...(Pending for Survey Report)














































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jan 2019 Sendback Est	04 Jan 2019 11:21 S\$5,113.81	07 Jan 2019 15:52 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ISMAIL BIN SAID , ID: S1595744A, Tel: +6590468113									
Vehicle Reg. No.: SJB2751Z		Date of Loss: 27/12/2018 05:00 - :59 [131 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / DM19HO00016		Policy/Cover Note No.: DMPPHQ17-006709 (Comprehensive) Coverage: 27/12/2017 - 06/01/2019							
		Excess: S\$250.00							
Repairer: Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 7858									
Handling Insurer: EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by JANET TAN]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/01/2019]									
Driver/Custodian: ISMAIL BIN SAID (55 / Male), NRIC: S1595744A, Tel: +6590468113									
Adj Asg. Remarks: EXCESS: \$500.00 KINDLY ASSIST ON OD SURVEY AND REVERT. CHECK IF DAMAGE IS CONSISTENT WITH THIRD PARTY'S VEHICLE WE ARE OF THE VIEW THAT DAMAGE IS INCONSISTENT.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> EQL_HQ (10/01/2019): Alert - Adj Mandate Approved (S\$3500.00) - SJB2751Z - Claim Handler: JANET TAN EQL_HQ (10/01/2019): Alert - Adj Mandate Maintained - SJB2751Z - Claim Handler: JANET TAN 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJB2751Z (DM19H000016)
OD
Dec 27 2018 5:00AM
[ISMAIL BIN SAID]
Soc Leon Motor Works

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	04/01/19 11:21	Soc Leon Motor Works (Kaki Bukit)	 Load HTM	
		Repairer Estimates		
No	Finalized On		Thumbnail	Print
1	08/01/19 14:23	LKK Auto Consultants Pte Ltd (HQ)	 Load HTM	
		Adjuster Immediate Advice		
2	08/01/19 14:27	LKK Auto Consultants Pte Ltd (HQ)	 Load HTM	
		Adjuster Immediate Advice		
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
2	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
3	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
4	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
5	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
6	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
7	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
8	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
9	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
10	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
11	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
12	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
13	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
14	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
15	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
16	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
17	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
18	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
19	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
20	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
21	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
22	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
23	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
24	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
25	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
26	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
27	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
28	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
29	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
30	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
31	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
32	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		
33	14/01/19 09:24	LKK Auto Consultants Pte Ltd (HQ)	 Load JPG	<input checked="" type="checkbox"/>
		General View		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)	Thumbnail	Print
				<input checked="" type="checkbox"/>
34	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
58	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
59	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
60	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
61	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
62	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
63	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
64	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
65	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
66	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
67	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
68	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
69	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
70	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
71	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
72	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
73	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
74	14/01/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Soc Leon Motor Works (Kaki Bukit)	Thumbnail	Print
1	04/01/19 11:20	Singapore Accident Statement	 Load JPG	<input checked="" type="checkbox"/>
2	04/01/19 11:20	Singapore Accident Statement	 Load JPG	<input checked="" type="checkbox"/>
3	04/01/19 11:20	Singapore Accident Statement	 Load JPG	<input checked="" type="checkbox"/>
4	04/01/19 11:20	Insured Person's NRIC	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQI19000365/UTD3E2

Date: 16/01/2019

REFERENCE

Insured/Claimant: ISMAIL BIN SAID Policy No: DMPPHQ17-006709
Date of Loss: 27/12/2018 Nature of Claim: OD Claim No: DM19HO00016

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJB2751Z**
Make & Model: MITSUBISHI LANCER, 1.6 (A) Engine No: 4A910070683
Reg. Date: 07/01/2008 (Man. Year: 2007) Chassis No: JMYSRCY2A8U003845
Colour: Black/Silver Odometer: 269473 km
Engine Capacity: 1499 cc
Market Value/New Car Price: S\$20,500.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50Z R17 Rear Tyre Size: 215/50Z R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,402.30	3,085.50	316.80	9.31
Miscellaneous Items	241.51	20.00	221.51	91.72
Labour	1,470.00	1,360.00	110.00	7.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,113.81	4,465.50	648.31	12.68
Approved Total (Overridden) (S\$)		3,500.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
Nett Amount (S\$)	4,613.81	3,000.00	1,613.81	34.98

INSPECTION

Date of Assignment: 07/01/2019 Present Location: Soc Leon Motor Works (Kaki Bukit)
Date Inspected: 08/01/2019 Inspected At: Soc Leon Motor Works (Kaki Bukit)
1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2019)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB2751Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Buckled	420.00 F	*420.00 F
2	1		*BONNET HINGE (2 PCS) @\$45.00 (WCP)	Repair	90.00 F	*- F
3	1		*BONNET LOCK (WCP)	Twisted	45.00 F	*45.00 F
4	1		*HEADLAMP (RH) (WCP)	Broken	380.00 F	*380.00 F
5	1		*HEADLAMP SUPPORT PANEL - TOP & LOWER (WCP)	Bent	580.00 F	*580.00 F
6	1		*TOP GARNISH (WCP)	Torn	65.00 F	*65.00 F
7	1		*CLIPS (6 PCS) @\$3.00 (WCP)	Necessary	18.00 F	*18.00 F
8	1		*LOWER BRACKET (WCP)	Bent	25.00 F	*25.00 F
9	1		*FRONT BUMPER (WCP)	Torn	420.00 F	*420.00 F
10	1		*BUMPER LOWER GRILLE (WCP)	Twisted	60.00 F	*60.00 F
11	1		*BUMPER REINFORCEMENT (WCP)	Bent	260.00 F	*260.00 F
12	1		*BUMPER TOP BEAM (WCP)	Bent	58.00 F	*58.00 F
13	1		*RUBBER (WCP)	Necessary	48.00 F	*48.00 F
14	1		*FOGLIGHT (WCP)	Broken	158.00 F	*158.00 F
15	1		*FOGLIGHT COVER (WCP)	Distorted	45.00 F	*45.00 F
16	1		*TOP GRILLE (WCP)	Not Necessary	168.00 F	*- F
17	1		*CLIPS (10 PCS) @\$3.00 (WCP)	Not Necessary	30.00 F	*- F
18	1		*FRONT FENDER (WCP)	Buckled	125.00 F	*125.00 F
19	1		*FENDER INNERSHIELD (WCP)	Torn	68.00 F	*68.00 F
20	1		*CLIPS (10 PCS) @\$3.00 (WCP)	Necessary	30.00 F	*30.00 F

F=Franchise part.

Sub Total (\$\$)	3,093.00	2,805.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	309.30	280.50
Total Parts (\$\$)	3,402.30	3,085.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	7% GST FROM SUPPLIER BILL	216.51	0.00
2	1	APPLY LTA BREAK & RESEAL LICENCE PLATE SEAL (OPC) (NECESSARY)	25.00	20.00
Sub Total (S\$)			241.51	20.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & FIX AIRCON CONDENSER & REFILL GAS	New	120.00	100.00
2	TO KNOCK & REPLACE PARTS	New	600.00	580.00
3	SPRAYPAINTING	New	750.00	680.00
Gross Labour Cost (S\$)			1,470.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >