

Surveyor

SAN TEE AUTO PTE LTD

BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A SINGAPORE 768761

TEL: (65)67538276 FAX: (65)67592034 H/P: (65)97232449

EMAIL: santeeauto@singnet.com.sg

TO: LONPAC INSURANCS BHD

DATE : 7-Jan-19

ATTN : 3RD PARTY CLAIMS

PAGE: 2 OF 2

RE: 3RD PARTY CLAIMS VEHICLE NO. YP6799J AND YN9516A

S/NO	DESCRIPTION	UNIT PRICE \$	AMOUNT
			\$
	MATERIALS		
1	FRONT RH DOOR DD		2631.21 ✓
2	FRONT DOOR RUBBER		354.96 ?
3	FRONT DOOR REGULATOR AND MOTOR		2139.31 ?
4	FRONT DOOR HINGE		206.42 ?
5	FRONT DOOR INNETR LOCK		511.60 ?
6	FRONT DOOR ACTUATOR		657.02 ?
7	FRONT DOOR GLASS CEA		565.07 ✓
8	FRONT DOOR TRIM LOWER		593.00 ?
9	FRONT DOOR UPPER TRIM		593.09 ?
10	FRONT DOOR RUN CHANNEL		366.64 ?
11	FRONT DOOR OUTER HANDLE NN		197.00 X
12	FRONT DOOR OUTER GARNISH DEF		86.36 ✓
			86.42 X
TOTAL (\$)			\$8,988.10

SAN TEE AUTO PTE LTD
BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A SINGAPORE 768761
TEL: (65)67538276 FAX: (65)67592034 H/P: (65)97232449
EMAIL: santeeauto@singnet.com.sg

TO: LONPAC INSURANCS BHD

DATE : 7-Jan-19

ATTN : 3RD PARTY CLAIM

PAGE: 2 OF 2

RE: 3RD PARTY CLAIMS VEHICLE NO. YP6799J AND YN9516A

S/NO	DESCRIPTION	UNIT PRICE	AMOUNT
		\$	\$
	LABOUR		
	LABOUR TO REMOVE DAMAGED PARTS ,	)	
	AND REPLACE NEW PARTS AND	)	
	DOOR ALIGNMENT	)	450 250.00 ✓
	WIRING ELECTRICAL VENT	)	50 250.00 ✓
	DOOR LOGO <i>MEC</i>		150.00 ✓
	LABOUR TO SPRAY PAINT INNER AND OUTER		400 580.00 ✓
TOTAL (\$)			\$1,730.00

GRAND TTL (\$)

10718.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jie - LKK

8/1/19

L/c 4 days

[Signature]