

Surveyor:

DOI:

ASSIGNMENT

04/01/19

Date / Time:

4.1.19

Registered in Merimen:

2.1.19

Pre-assign / CCU / FTE



Insured Vehicle No.:

S66 9948L

Claim No.:

29557 480565G

Name of Insured:

Mand Marketing P/L

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

28/12/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

S6T 8310L



INSRS:

WSP:

Tel:

Liability:

RMKS:

KARZ WORK



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Pending Curvyer's assignment sheet.

27/5. call me ERNA (OI's insurance). aware of TP claim
A NCD issue. Agree to settle, email LOI.

- MINUSSED

- TP LOD IN

16/10/19

- TYPE REPORT FOR MANDATE APPROVAL

- REPORT DONE

04/11/19

- GIVE MANDATE TO AG

27/11/19

- AG APPROVED MANDATE. SEND 1ST OFFER.

- TP ACCEPTED OFFER.

- ALL BOCS IN ORDER.

- TO CLOS.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L16 S\$ 13,300.00 (18 days) Reduction: 12 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100 (Assessed) BOLA S/N No.: 5

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 13,300.00

OI turn right & hit

Loss of Rental (LOR):

S\$ 2,200.00 22 days x \$100.00

TP who is driving straight

Loss of Use (LOU):

S\$ - (\$ x days)

COPY SENT

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search:

S\$ 36.45

Medical:

S\$ -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

S\$ -

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost:

S\$ -

3) Survey fee:

\$370.00

Total:

S\$ 15,536.45 Global Sum S\$: 15,500.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 15,500.00

Name 1:

KARZ WORKS PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

-

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

-

REF:

376(10)

ASSIGNMENT

CDE: 2023 July

From:

Date:

Veh No:

SKT 530L

in Poss:

2008 July

Estimated Cost:

Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / HIV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Honda Civic

S/C

1595

at Workshop m/s

Colour:

Grey

A/C

Insured / Std / M / NA

at

Sp Reading:

203213

T/T Date: Insured / Std / M / NA

Insured:

Eng/No:

R16A13005969

Policy No:

C/No:

JHMF046

Claims No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Mod: ☒ Nil / ☐ R/Rim / ☐ STD A/Rim or

(Policy Condition)

Tyre Size:


F:

205/55R16

R:

11

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

P/Bal.

S'

mm

R/Bal.

S'

mm

GIA / PR. Descr:

Consistent? : Yes or No

L/Bal.

S'

mm

L/Bal.

S'

mm

Est. Repair:

18

days

Res:

Yes or No

D.O.A.

28/12/2018

D.O.I.

04/01/2019

Lump Sum:

20

%

3 Val:

Yes or No

Survey held at

Ternmark Page ubi

CA / REV / REP. / 24 HRS

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

Front 0/3 7 0/3 Portion

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

AIG SGG 9948 L

MV 32K

LTA 16.7K

NL 15.3K

16/05/19

Jinapw 2/5 13300/- with 18 days of rep
(exp: d 16/05/19/421.)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Inap (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum + L.B.I. (\$)

Survey For:

Transportation

S + R, 24

Fishes

Others

TOTAL



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

AIG Aisa Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

Vehicle number	SKT5310L
Make / Model	Honda / Civic
Chassis number	JHMFD46208S201915
Accident date	28 December 2018
Reference	KM1812-46

Qty Particulars

Honda Civic

PARTS REPLACEMENT - LIST ITEMS		
1	Front bonnet <i>Dented</i>	696.70 ✓
1	Bonnet lock <i>regr</i>	98.30 X
2	Bonnet hinge LH / RH @ \$49 <i>bt</i>	98.00 ✓
1	Front windscreen glass <i>CRACK</i>	1179.20 ✓
1	Front windscreen moulding <i>NH</i>	49.00 ✓
1	Front bumper <i>turn / dented</i>	738.00 ✓
2	Front bumper side retainer LH / RH @ \$24.90 <i>o/s broken N/s NH</i>	49.80 ✓ 24.90
1	Front reinforcement <i>Dented</i>	295.10 ✓
1	Front grille <i>NH</i>	181.80 X
1	Front grille emblem <i>NH</i>	32.70 X
1	Front grille chrome moulding <i>NH</i>	199.40 X
2	Front fender LH / RH @ \$533.60 <i>o/s BWC N/s regr</i>	533.60 1067.20 ✓
1	Front fender inner shield LH <i>deformed</i>	103.10 ✓
1	Front fender side garnish LH <i>deformed</i>	51.00 ✓
2	Headlamp LH / RH @ \$868.70 <i>o/s broken N/s NH</i>	868.70 1737.40 ✓
2	Headlamp control unit @ \$391 <i>NH</i>	782.00 X
2	Headlamp lower bracket LH / RH @ \$47 <i>o/s broken N/s NH</i>	47.00 94.00 ✓
2	Horn @ \$76 <i>NH</i>	152.00 X
1	Support top garnish <i>deformed</i>	97.40 ✓
1	Support panel <i>BWC</i>	509.60 ✓
1	Aircon condenser <i>bt</i>	772.20 ✓
2	Aircon condenser bracket @ \$25 <i>NH</i>	50.00 X
1	Aircon fan cowling <i>NH</i>	102.60 X
1	Aircon fan motor <i>NH</i>	367.90 X
1	Aircon fan blade <i>NH</i>	61.00 X
1	Aircon suction pipe <i>NH</i>	206.80 X
1	Aircon discharge pipe <i>NH</i>	237.60 X
1	Air baffle <i>NH</i>	31.90 X
1	Air intake resonator LH <i>NH</i>	229.30 X
1	Air cleaner resonator assy <i>NH</i>	311.60 X
1	Radiator <i>broken</i>	1267.40 ✓
2	Radiator top bracket @ \$29 <i>NH</i>	58.00 X
1	Radiator cap holder <i>NH</i>	51.40 X

1	Radiator top hose NH		37.20 X
1	Radiator cowling NH		133.00 X
1	Radiator fan motor NH		394.80 X
1	Radiator fan blade NH		73.00 X
1	Radiator expansion tank NH		51.80 X
1	Wiper washer tank <i>defunct</i>		89.30 ✓
1	Chassis member Rh <i>regr</i>		775.30 X
1	Wheel house panel RH <i>enc</i>		441.75 ✓
2	Air bag sensor <i>activated</i>		390.45 ✓
1	Driver Steering Air Bag <i>activated</i>		903.40 ✓
1	Passenger Air bag <i>activated</i>		843.20 ✓
1	Dashboard assy NH		902.40 X
1	Seat belt LH <i>activated</i>		539.50 ✓
1	Seat belt RH <i>activated</i>		549.30 ✓
1	Air bag control unit <i>activated</i>		903.20 ✓
2	Front shock absorber o/s broken N/S NH		304.04 608.09 ✓
2	Front Knuckle arm o/s bt N/S NH		271.55 543.10 ✓
2	Front Knuckle arm bearing o/s Dam N/S NH		104.70 209.40 ✓
2	Front lower arm o/s bt N/S NH		222.50 445.00 ✓
2	Steering tie rod end o/s bt N/S NH		89.50 179.00 ✓
2	Drive shaft NH		1976.00 X
1	Steering rack and pinion NH	13811.89	1519.00 X
1	Front door panel RH <i>dent</i>		808.60 ✓
1	Front door panel Frame sticker <i>Nec</i>	11049.51	60.70 ✓
	<i>4900P</i>		25335.89
		Less 20 %	5067.18
		Subtotal	20268.71
		Balance C/F	20268.71
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
		Balance B/F	20268.71
1	Battery NH		130.00 X
1	Front number plate NH		50.00 X
1	Front bumper clips <i>Nec</i>		38.00 30/-
1	Front fender shield clips <i>Nec</i>		25.00 20/-
1	Front tyre LH <i>SVC</i>		285.00 X
1	Front wheel rim LH <i>ent</i>		580.00 350/-
1	Front windscreen sealant <i>Nec</i>	517.00	50.00 40/-
1	Front windscreen inner seal <i>Nec</i>		35.00 20/-
1	Front windscreen solar film NH		180.00 X
1	IU bracket <i>Nec</i>		25.00 ✓
1	Radiator coolant <i>Nec (tested)</i>		32.00 ✓
		Subtotal	1430.00
		Balance C/F	21698.71
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
		Balance B/F	21698.71
1	Check front wiring and lightning system		70.00 30/-
2	Remove, renew condenser and top up gas		150.00 120/-

3	Remove, renew radiator and top up coolant	450.00	50/-
4	Remove and renew front windscreen	150.00	120/-
5	Remove and renew front dashboard	500.00	NH
6	Remove and renew airbag assy	400.00	250/-
7	Mount vehicle on bench for chassis replacement	500.00	NH
8	Check front wheel alignment	150.00	60/-
9	Remove and renew front undercarriage parts	200.00	150/-
10	Transfer parts, attachment from front RH door to new	200.00	60/-
11	Panel beating on affected areas	1600.00	1200/-
12	Spray painting on affected areas	1500.00	1200/-
13	Apply anti rust on affected areas	150.00	80/-
Subtotal		5720.00	
Grand total		27418.71	

04/01/2019 @ 1600 hrs

N/A Antenna

L/Sum

18 days.

Ryan

LKK Auto

Check Ryan
Limit.

29.11.11

14886.51.

Supp 1772.40

16658.91

L/S 13300/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC: 201015366H
 3RD PARTY CLAIM ESTIMATION

AIG Aisa Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way #07-16
 Singapore 079120

Vehicle number	SKT5310L
Make / Model	Honda / Civic
Chassis number	JHMFD46208S201915
Accident date	28 December 2018
Reference	KM1812-46

Qty Particulars

Honda Civic

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BONNET INSULATOR <i>bt</i>	218.10 ✓
1	ABS CONTROL MODULE <i>broken</i>	1220.50 ✓
1	FRONT RH WING MIRROR <i>broken</i>	346.80 ✓
1	WIPER PANEL GARNISH <i>cut</i>	190.10 ✓
1	FRONT RH BUMPER LOWER GRILLE <i>del cut</i>	240.00 ✓
		2215.50
Less 20 %		443.10
Subtotal		1772.40
Balance C/F		1772.40

ryan

28K Ando

[Signature]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5942A

Vehicle Details

Vehicle No.: SKT5310L

Vehicle to be Exported: No

Intended Deregistration Date: 03 Jan 2019

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6L VTI AUTO

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: R16A13005969

Chassis No.: JHMF462085201915

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$18,699.00

Original Registration Date: 17 Jul 2008

First Registration Date: 17 Jul 2008

Transfer Count: 1

Actual ARF Paid: \$18,699.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Jul 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$18,583.00

COE Rebate Amount: \$16,854.00

Total Rebate Amount: \$16,854.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jan 2019

OK

- Pre repair inspection request - SKT5310L VS SGG9948L (OI) DOA 28/12/2018

From: Azlan, Syazairdina
To: admin-a@kkauto.com; assignments@kkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinnul; Chan, Yoke Shi; Kaur, Baljit; Fan, Winnie-LW
Sent: 4/1/2019 1:46:48 PM
Attachments: 20190103134228637.pdf

Hi,

Please refer to the enclosed request from **KARZ WORKS PTE LTD.**

Claim no : 2955748066SG003

Case Owner : MING YAO LEE

If you have any queries/concerns, please let us know.

Thanks and regards,

Syaza Indira Azlan
AIG
Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

1:55pm @ 4/1/2019
person @ Denon
vehicle In.

From: KARZ WORKS PTE LTD [mailto:karzworks.sg@gmail.com]

Sent: Friday, January 04, 2019 1:38 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinnul; Chan, Yoke Shi; Kaur, Baljit; Fan, Winnie-LW

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGG9948L AND SKT5310L ON 28/12/2018

Importance: High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop.

Darren Ng
KARZ WORKS PTE LTD
53 Ubi Avenue 1
#01-23 Pava Ubi Industrial Park
Singapore 408934
Tel: 6844 5936
Fax: 6844 2474

From: Azlan, Syazairdina [mailto:Syazairdina.Azlan@aig.com]

Sent: Thursday, January 03, 2019 4:18 PM

To: karzworks.sg@gmail.com

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Hor, Yinnul <Yinnul.Hor@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGG9948L AND SKT5310L ON 28/12/2018

Importance: High

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息，如要阅读此信息，请开启附件。

นี่คือการส่งข้อความปลอดภัย/ข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้ปลอดภัย
สมบูรณ์

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부
파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka
attachment.

[Click here](#) by 2019-01-10 16:18 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2000-2017 Proofpoint, Inc. All Rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairinda Azlan@sig.com

To: karzworks.sg@gmail.com

Cc: Andy-SY.Fong@sig.com; Lee-

Ying Chin@sig.com; NoorMariessa.AbuKassim@sig.com; Imran.Ishak@sig.com; ShengYang Lim@sig.com; Aashweenjeetkaur.Mithrasingh@sig.com; Yinnul.Hor@sig.com; yokeeshi.chan@sig.com; Bai

LW Fan@sig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGG9948L AND SKT5310L ON 28/12/2018

Date: Thu, 3 Jan 2019 08:17:46 +0000

Without Prejudice

Your Reference : KM1812-46
Our Reference : SGG9948L

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syazairinda Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations - Auto
SG Claims Operations | AIG Shared Services

Syazairinda.Azlan@sig.com | www.sig.sg

From: Abu Kassim, Noor Mariessa

Sent: Thursday, January 03, 2019 4:03 PM

To: Azlan, Syazairinda

Cc: Md Ishak, Mohd Imran

Subject: FW: OUR REF: KM1812-46 YOUR REF: SGG9948L PRE-REPAIR INSPECTION FOR SKT5310L

Importance: High

From: KARZ WORKS PTE LTD [mailto:karzworks.sg@gmail.com]

Sent: Thursday, January 03, 2019 3:57 PM

To: Abu Kassim, Noor Mariessa; Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

Cc: admin@mycar.sg; 'KARZ WORKS PTE LTD'

Subject: OUR REF: KM1812-46 YOUR REF: SGG9948L PRE-REPAIR INSPECTION FOR SKT5310L

Importance: High

WITHOUT PREJUDICE

OUR REF: KM1812-46

YOUR REF: SGG9948L

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SKT5310T

ACCIDENT INVOLVING 5KT5310T AND SGG9948L

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction – Amendment No. 1 of 2016 of 2016 of Pre-repair inspection for your attention.

Regards,

Darren Ng
KARZ WORKS PTE LTD
53 Ubi Avenue 1
#01-23 Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 5938
Fax: 6844 2474

Print Received Message

This mail is associated with :

***SKT5310L (2955748056SG)
[SGG9948L]**

TP

GOH AH BOON

Dec 28 2018 12:00AM

[MARIC MARKETING PTE LTD]

Karz Work Solutions

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 27/11/2019 14:30 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15536.45) - SKT5310L - Claim Handler: Lee, Ming-Yao

Approved:15536.45:Please settle at best

5015210L

K11812-46

SATISFACTION & DISCHARGE OF VEHICLE (AFTER REPAIR)

I/We GOH AH BOON owner/driver of vehicle no. SKT5310L

declare that the repairs of my/our vehicle has been completed and to my/our satisfaction and I/we agree that I/We hereby irrevocable absolutely accept the settlement amount and the liability from the 3rd party on the repair costs and/or rental and/or loss of use which are final and that the sum of amount are to be release and payment to KARZ WORKS Pte Ltd for such repairs are in full

discharge of my/our claim in respect of the damages caused in the accident at/along Junction Punggol Road & Buangkok Road

I/We further acknowledge that any settlement the workshop may reach on my/our behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s concerned.

I/We acknowledge that the Discharge Voucher applies only to my/our property damage and will not affect any of the personal injuries claim(s) involved and/or uninsured losses claim in a later date. Further the settlement terms herein should not be used as an evidence to prejudice to any personal injuries claim(s) involved and/or other uninsured losses claim arising of the subject matter in the action.

Dated this 29 day of Jan (month) 20 19 (year)

Signature of owner/ *driver (on behalf of owner vehicle) : [Signature]

Name of owner of vehicle / *driver (on behalf of owner vehicle) : GOH AH BOON

NRIC Number of owner/ *driver (on behalf of owner vehicle) : S1765942A

* Please note that by signing of this document, the driver's signature will represent the decision/approval and on behalf of the owner which is final and irrevocable.

* Any amendments made in this form will not be valid unless approved and endorsed by the management of the workshop

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jan 2019 Edit Reg		04 Jan 2019 00:00 Edit Adj Rpt	S\$13,300.00 Edit Estimates	S\$13,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	MARIC MARKETING PTE LTD, Co. Reg. No.: 201620700D		
Main Claimant:	GOH AH BOON, ID: S1765942A		
Vehicle Reg. No.:	SKT5310L	Date of Loss:	28/12/2018 00:00 - :59 [125 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2955748056SG	Policy/Cover Note No.:	0999994660 (Comprehensive)
Vehicle Reg. No. (Insured):	SGG9948L	Policy No. (Claimant):	Z18VP05019069
		Excess:	
Repairer:	Karz Work Pte Ltd (HQ) 53 Ubi Avenue 1 #01-23 Paya Ubi Ind. Park, 408934 Ubi - Tel: 68442475		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	Longpac Insurance Bhd (HQ) - Tel: +65 62507388		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 16/01/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (27/11/2019): Alert - Adj Mandate Approved (S\$15536.45) - SKT5310L - Claim Handler: Lee, Ming-...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT5310L (2955748056SG)
[SGG9948L]
TP
GOH AH BOON
Dec 28 2018 12:00AM
[MARIC MARKETING PTE LTD]
Karz Work Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	11/05/19 11:11	Front View Right		Load JPG	☒		
2	11/05/19 11:11	Front View Left		Load JPG	☒		
3	11/05/19 11:13	General View		Load JPG	☒		
4	11/05/19 11:13	General View		Load JPG	☒		
5	11/05/19 11:13	General View		Load JPG	☒		
6	11/05/19 11:13	General View		Load JPG	☒		
7	11/05/19 11:13	General View		Load JPG	☒		
8	11/05/19 11:13	General View		Load JPG	☒		
9	11/05/19 11:13	General View		Load JPG	☒		
10	11/05/19 11:13	General View		Load JPG	☒		
11	11/05/19 11:13	General View		Load JPG	☒		
12	11/05/19 11:13	General View		Load JPG	☒		
13	11/05/19 11:13	General View		Load JPG	☒		
14	11/05/19 11:13	General View		Load JPG	☒		
15	11/05/19 11:13	General View		Load JPG	☒		
16	11/05/19 11:13	General View		Load JPG	☒		
17	11/05/19 11:13	General View		Load JPG	☒		
18	11/05/19 11:13	General View		Load JPG	☒		
19	11/05/19 11:13	General View		Load JPG	☒		
20	11/05/19 11:13	General View		Load JPG	☒		
21	11/05/19 11:13	General View		Load JPG	☒		
22	11/05/19 11:13	General View		Load JPG	☒		
23	11/05/19 11:13	General View		Load JPG	☒		
24	11/05/19 11:13	General View		Load JPG	☒		
25	11/05/19 11:13	General View		Load JPG	☒		
26	11/05/19 11:13	General View		Load JPG	☒		
27	11/05/19 11:13	General View		Load JPG	☒		
28	11/05/19 11:13	General View		Load JPG	☒		
29	11/05/19 11:13	General View		Load JPG	☒		
30	11/05/19 11:13	General View		Load JPG	☒		
31	11/05/19 11:13	General View		Load JPG	☒		
32	11/05/19 11:13	General View		Load JPG	☒		
33	11/05/19 11:13	General View		Load JPG	☒		
34	11/05/19 11:13	General View		Load JPG	☒		
35	11/05/19 11:13	General View		Load JPG	☒		
36	11/05/19 11:13	General View		Load JPG	☒		
37	11/05/19 11:13	General View		Load JPG	☒		
38	11/05/19 11:13	General View		Load JPG	☒		
39	11/05/19 11:13	General View		Load JPG	☒		
40	11/05/19 11:13	General View		Load JPG	☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	11/05/19 11:13	General View	 Load JPG	☒
42	11/05/19 11:13	General View	 Load JPG	☒
43	11/05/19 11:13	General View	 Load JPG	☒
44	11/05/19 11:13	General View	 Load JPG	☒
45	11/05/19 11:13	General View	 Load JPG	☒
46	11/05/19 11:13	General View	 Load JPG	☒
47	11/05/19 11:13	General View	 Load JPG	☒
48	11/05/19 11:13	General View	 Load JPG	☒
49	11/05/19 11:13	General View	 Load JPG	☒
50	11/05/19 11:13	General View	 Load JPG	☒
51	11/05/19 11:13	General View	 Load JPG	☒
52	11/05/19 11:13	General View	 Load JPG	☒
53	11/05/19 11:13	General View	 Load JPG	☒
54	11/05/19 11:13	General View	 Load JPG	☒
55	11/05/19 11:13	General View	 Load JPG	☒
56	11/05/19 11:13	General View	 Load JPG	☒
57	11/05/19 11:13	General View	 Load JPG	☒
58	11/05/19 11:13	General View	 Load JPG	☒
59	11/05/19 11:13	General View	 Load JPG	☒
60	11/05/19 11:13	General View	 Load JPG	☒
61	11/05/19 11:13	General View	 Load JPG	☒
62	11/05/19 11:13	General View	 Load JPG	☒
63	11/05/19 11:13	General View	 Load JPG	☒
64	11/05/19 11:13	General View	 Load JPG	☒
65	11/05/19 11:13	General View	 Load JPG	☒
66	11/05/19 11:13	General View	 Load JPG	☒
67	11/05/19 11:13	General View	 Load JPG	☒
68	11/05/19 11:13	General View	 Load JPG	☒
69	11/05/19 11:13	General View	 Load JPG	☒
70	11/05/19 11:13	General View	 Load JPG	☒
71	11/05/19 11:13	General View	 Load JPG	☒
72	11/05/19 11:13	General View	 Load JPG	☒
73	11/05/19 11:13	General View	 Load JPG	☒
74	11/05/19 11:13	General View	 Load JPG	☒
75	11/05/19 11:13	General View	 Load JPG	☒
76	11/05/19 11:13	General View	 Load JPG	☒
77	11/05/19 11:13	General View	 Load JPG	☒
78	11/05/19 11:13	General View	 Load JPG	☒
79	11/05/19 11:13	General View	 Load JPG	☒
80	11/05/19 11:13	General View	 Load JPG	☒
81	11/05/19 11:13	General View	 Load JPG	☒
82	11/05/19 11:13	General View	 Load JPG	☒
83	11/05/19 11:13	General View	 Load JPG	☒
84	11/05/19 11:13	General View	 Load JPG	☒
85	11/05/19 11:13	General View	 Load JPG	☒
86	11/05/19 11:13	General View	 Load JPG	☒
87	11/05/19 11:13	General View	 Load JPG	☒
88	11/05/19 11:13	General View	 Load JPG	☒
89	11/05/19 11:13	General View	 Load JPG	☒
90	11/05/19 11:13	General View	 Load JPG	☒
91	11/05/19 11:13	General View	 Load JPG	☒
92	11/05/19 11:13	General View	 Load JPG	☒
93	11/05/19 11:13	General View	 Load JPG	☒
94	11/05/19 11:13	General View	 Load JPG	☒
95	11/05/19 11:13	General View	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	11/05/19 11:13	General View	 Load JPG	☒
97	11/05/19 11:13	Odometer Reading	 Load JPG	☒
98	11/05/19 11:13	Chassis Number	 Load JPG	☒
99	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
100	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
101	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
102	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
103	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
104	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
105	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
106	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
107	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
108	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
109	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
110	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
111	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
112	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
113	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
114	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
115	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
116	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
117	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
118	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
119	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
120	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
121	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
122	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
123	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
124	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
125	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
126	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
127	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
128	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
129	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
130	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
131	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
132	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
133	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
134	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
135	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
136	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
137	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
138	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
139	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
140	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
141	11/05/19 11:15	Reinspection Photo	 Load JPG	☒
142	11/05/19 11:15	Reinspection Photo	Load JPG	☒
143	11/05/19 11:15	Reinspection Photo	Load JPG	☒
144	11/05/19 11:15	Reinspection Photo	Load JPG	☒
145	11/05/19 11:15	Reinspection Photo	Load JPG	☒
146	11/05/19 11:15	Reinspection Photo	Load JPG	☒
147	11/05/19 11:15	Reinspection Photo	Load JPG	☒
148	11/05/19 11:15	Reinspection Photo	Load JPG	☒
149	11/05/19 11:15	Reinspection Photo	Load JPG	☒
150	11/05/19 11:15	Reinspection Photo	Load JPG	☒
151	11/05/19 11:15	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
152	11/05/19 11:15	Reinspection Photo		☒
153	11/05/19 11:15	Reinspection Photo		☒
154	11/05/19 11:15	Reinspection Photo		☒
155	11/05/19 11:15	Reinspection Photo		☒
156	11/05/19 11:15	Reinspection Photo		☒
157	11/05/19 11:15	Reinspection Photo		☒
158	11/05/19 11:15	Reinspection Photo		☒
159	11/05/19 11:15	Reinspection Photo		☒
160	11/05/19 11:15	Reinspection Photo		☒
161	11/05/19 11:15	Reinspection Photo		☒
162	11/05/19 11:15	Reinspection Photo		☒
163	11/05/19 11:15	Reinspection Photo		☒
164	11/05/19 11:15	Reinspection Photo		☒
165	11/05/19 11:15	Reinspection Photo		☒
166	11/05/19 11:15	Reinspection Photo		☒
167	11/05/19 11:15	Reinspection Photo		☒
168	11/05/19 11:15	Reinspection Photo		☒
169	11/05/19 11:15	Reinspection Photo		☒
170	11/05/19 11:15	Reinspection Photo		☒
171	11/05/19 11:16	Finishing Photo		☒
172	11/05/19 11:16	Finishing Photo		☒
173	11/05/19 11:16	Finishing Photo		☒
174	11/05/19 11:16	Finishing Photo		☒
175	11/05/19 11:16	Finishing Photo		☒
176	11/05/19 11:16	Finishing Photo		☒
177	11/05/19 11:16	Finishing Photo		☒
178	11/05/19 11:16	Finishing Photo		☒
179	11/05/19 11:16	Finishing Photo		☒
180	11/05/19 11:16	Finishing Photo		☒
181	11/05/19 11:16	Finishing Photo		☒
182	11/05/19 11:16	Finishing Photo		☒
183	11/05/19 11:16	Finishing Photo		☒
184	11/05/19 11:16	Finishing Photo		☒
185	11/05/19 11:16	Finishing Photo		☒
186	11/05/19 11:16	Finishing Photo		☒
187	11/05/19 11:16	Finishing Photo		☒
188	11/05/19 11:16	Finishing Photo		☒
189	11/05/19 11:16	Finishing Photo		☒
190	11/05/19 11:16	Finishing Photo		☒
191	11/05/19 11:16	Finishing Photo		☒
192	11/05/19 11:16	Finishing Photo		☒
193	11/05/19 11:16	Finishing Photo		☒
194	11/05/19 11:16	Finishing Photo		☒
195	11/05/19 11:16	Finishing Photo		☒
196	11/05/19 11:16	Finishing Photo		☒
197	11/05/19 11:16	Finishing Photo		☒
198	11/05/19 11:16	Finishing Photo		☒
199	11/05/19 11:16	Finishing Photo		☒
200	11/05/19 11:16	Finishing Photo		☒
201	11/05/19 11:16	Finishing Photo		☒
202	11/05/19 11:16	Finishing Photo		☒
203	11/05/19 11:16	Finishing Photo		☒
204	11/05/19 11:16	Finishing Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/01/19 18:45	ACKNOWLEDGEMENT EMAIL TO AIG DD 04.01.2019		Load PDF	
2	07/01/19 18:45	EMAIL FROM AIG DD 04.01.2019		Load PDF	
3	07/01/19 18:45	TP GIA REPORT		Load PDF	
4	16/05/19 20:51	TP ESTIMATE - MARKED		Load PDF	
5	01/11/19 08:42	RENTAL RECEIPT		Load PDF	
6	01/11/19 08:42	LTA SEARCH		Load PDF	
7	01/11/19 08:42	LOD		Load PDF	
8	01/11/19 08:42	GIA SEARCH		Load PDF	
9	01/11/19 08:42	LETTER TO OI		Load PDF	
10	02/12/19 11:26	WORKSHOP INVOICE		Load PDF	
11	02/12/19 11:26	AUTHORISATION TO ACT FORM		Load PDF	
12	02/12/19 11:29	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	08/01/19 09:00	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGG9948L (Insd veh)	Model:	HONDA CIVIC 1.6 VTI (A)
	SKT5310L (TP veh)		
Date of Accident:	28/12/2018		

Global Sum Settlement	:	☒ Yes	☐ No	
Repair Estimate	:	\$		29,191.11
Final Repair Cost	:	\$		15,500.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		22 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		15,500.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Karz Works Pte Ltd	: \$	15,500.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

02 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19000376/DHA3Q2

Date: 02/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994660
Claimant
Vehicle No : SKT5310L **Insured Vehicle No :** SGG9948L
Date of Loss: 28/12/2018 **Nature of Claim:** TP **Claim No:** 2955748056SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT5310L**
 Make & Model: HONDA CIVIC, 1.6 VTI (A) Engine No: R16A13005969
 Reg. Date: 17/07/2008 (Man. Year: 2008) Chassis No: JHMFD46208S201915
 Colour: Grey Odometer: 203213 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,471.11	13,387.47	10,083.64	42.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,720.00	3,320.00	2,400.00	41.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,191.11	16,707.47	12,483.64	42.77
Approved Total (Overridden) (S\$)		13,300.00		
Nett Amount (S\$)	29,191.11	13,300.00	15,891.11	54.44
+ Car Rental (22.0 x S\$100.00/day) (S\$)		2,200.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		15,536.45		
Global Sum Settlement (S\$)		15,500.00		

INSPECTION

Date of Assignment: 04/01/2019

Date Inspected: 04/01/2019 Inspected At:

Karz Work Pte Ltd
 53 Ubi Avenue 1 #01-23, Paya Ubi
 Industrial Park
 Singapore 408934

Estimated Period of Repair: 18.0 days

Adjuster: BRYAN TANI

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	696.70 FL	*696.70 FL
2	1		*BONNET LOCK	Repair	98.30 FL	*- FL
3	2		*BONNET HINGE LH/RH	Bent	98.00 FL	*98.00 FL
4	1		*FRONT WINDSCREEN GLASS	Cracked	1,179.20 FL	*1,179.20 FL
5	1		*FRONT WINDSCREEN MOULDING	Necessary	49.00 FL	*49.00 FL
6	1		*FRONT BUMPER	Torn / Dented	738.00 FL	*738.00 FL
7	1		*FRONT BUMPER SIDE RETAINER LH /RH	O/S Broken / N/S Not Necessary	49.80 FL	*24.90 FL
8	1		*FRONT REINFORCEMENT	Dented	295.10 FL	*295.10 FL
9	1		*FRONT GRILLE	Not Necessary	181.80 FL	*- FL
10	1		*FRONT GRILLE EMBLEM	Not Necessary	32.70 FL	*- FL
11	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	199.40 FL	*- FL
12	1		*FRONT FENDER LH/RH	O/S Buckled / N/S Repair	1,067.20 FL	*553.60 FL
13	1		*FRONT FENDER INNER SHIELD LH	Deformed	103.10 FL	*103.10 FL
14	1		*FRONT FENDER SIDE GARNISH LH	Deformed	51.00 FL	*51.00 FL
15	1		*HEADLAMP LH /RH	O/S Broken / N/S Not Necessary	1,737.40 FL	*868.70 FL
16	2		*HEADLAMP CONTROL UNIT	Not Necessary	782.00 FL	*- FL
17	1		*HEADLAMP LOWER BRACKET LH/RH	O/S Broken / N/S Not Necessary	94.00 FL	*47.00 FL
18	2		*HORN	Not Necessary	152.00 FL	*- FL
19	1		*SUPPORT TOP GARNISH	Deformed	97.40 FL	*97.40 FL
20	1		*SUPPORT PANEL	Buckled	509.60 FL	*509.60 FL
21	1		*AIRCON CONDENSER	Bent	772.20 FL	*772.20 FL
22	2		*AIRCON CONDENSER BRACKET	Not Necessary	50.00 FL	*- FL
23	1		*AIRCON FAN COWLING	Not Necessary	102.60 FL	*- FL
24	1		*AIRCON FAN MOTOR	Not Necessary	367.90 FL	*- FL
25	1		*AIRCON FAN BLADE	Not Necessary	61.00 FL	*- FL
26	1		*AIRCON SUCTION PIPE	Not Necessary	206.80 FL	*- FL
27	1		*AIRCON DISCHARGE PIPE	Not Necessary	237.60 FL	*- FL
28	1		*AIR BAFFLE	Not Necessary	31.90 FL	*- FL
29	1		*AIR INTAKE RESONATOR LH	Not Necessary	229.30 FL	*- FL
30	1		*AIR CLEANER RESONATOR ASSY	Not Necessary	311.60 FL	*- FL
31	1		*RADIATOR	Broken	1,267.40 FL	*1,267.40 FL
32	2		*RADIATOR TOP BRACKET	Not Necessary	58.00 FL	*- FL
33	1		*RADIATOR CAP HOLDER	Not Necessary	51.40 FL	*- FL
34	1		*RADIATOR TOP HOSE	Not Necessary	37.20 FL	*- FL
35	1		*RADIATOR COWLING	Not Necessary	133.00 FL	*- FL
36	1		*RADIATOR FAN MOTOR	Not Necessary	394.80 FL	*- FL
37	1		*RADIATOR FAN BLADE	Not Necessary	73.00 FL	*- FL
38	1		*RADIATOR EXPANSION TANK	Not Necessary	51.80 FL	*- FL
39	1		*WIPER WASHER TANK	Deformed	89.30 FL	*89.30 FL
40	1		*CHASSIS MEMBER RH	Repair	775.30 FL	*- FL
41	1		*WHEEL HOUSE PANEL RH	Buckled	441.75 FL	*441.75 FL
42	1		*AIR BAG SENSOR (2 PCS)	Activated	390.45 FL	*390.45 FL
43	1		*DRIVER STEERING AIR BAG	Activated	903.40 FL	*903.40 FL
44	1		*PASSENGER AIR BAG	Activated	843.20 FL	*843.20 FL
45	1		*DASHBOARD ASSY	Not Necessary	902.40 FL	*- FL
46	1		*SEAT BELT LH	Activated	539.50 FL	*539.50 FL
47	1		*SEAT BELT RH	Activated	549.30 FL	*549.30 FL
48	1		*AIR BAG CONTROL UNIT	Activated	903.20 FL	*903.20 FL
49	1		*FRONT SHOCK ABSORBER		608.09 FL	*304.04 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				O/S Broken / N/S Not Necessary		
50	1		*FRONT KNUCKLE ARM	O/S Bent / N/S Not Necessary	543.10 FL	*271.55 FL
51	1		*FRONT KNUCKLE ARM BEARING	O/S Damaged / N/S Not Necessary	209.40 FL	*104.70 FL
52	1		*FRONT LOWER ARM	O/S Bent / N/S Not Necessary	445.00 FL	*222.50 FL
53	1		*STEERING TIE ROD END	O/S Bent / N/S Not Necessary	179.00 FL	*89.50 FL
54	2		*DRIVE SHAFT	Not Necessary	1,976.00 FL	*. FL
55	1		*STEERING RACK AND PINION	Not Necessary	1,519.00 FL	*. FL
56	1		*FRONT DOOR PANEL RH	Dented	808.60 FL	*808.60 FL
57	1		*FRONT DOOR PANEL FRAME STICKER	Necessary	60.70 FL	*60.70 FL
58	1		*BATTERY	Not Necessary	130.00 FS	*. FS
59	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*. FS
60	1		*FRONT BUMPER CLIPS	Necessary	38.00 FS	*30.00 FS
61	1		*FRONT FENDER SHIELD CLIPS	Necessary	25.00 FS	*20.00 FS
62	1		*FRONT TYRE LH	Serviceable	285.00 FS	*. FS
63	1		*FRONT WHEEL RIM LH	Cut	580.00 FS	*350.00 FS
64	1		*FRONT WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
65	1		*FRONT WINDSCREEN INNER SEAL	Necessary	35.00 FS	*20.00 FS
66	1		*FRONT WINDSCREEN SOLAR FILM	Not Necessary	180.00 FS	*. FS
67	1		*IU BRACKET	Necessary	25.00 FS	*25.00 FS
68	1		*RADIATOR COOLANT	Necessary	32.00 FS	*32.00 FS
69	1		*FRONT BONNET INSULATOR	Bent	218.10 FL	*218.10 FL
70	1		*ABS CONTROL MODULE	Broken	1,220.50 FL	*1,220.50 FL
71	1		*FRONT RH WING MIRROR	Broken	346.80 FL	*346.80 FL
72	1		*WIPER PANEL GARNISH	Cut	190.10 FL	*190.10 FL
73	1		*FRONT RH BUMPER LOWER GRILLE	Cut	240.00 FL	*240.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (S\$)	28,981.39	16,605.09
- List Item Discount on L Items 20.00/20.00% (S\$)	5,510.28	3,217.62	
	Total Parts (S\$)	23,471.11	13,387.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	70.00	30.00
2	REMOVE ,RENEW CONDENSER AND TOP UP GAS	New	150.00	120.00
3	REMOVE,RENEW RADIATOR AND TOP UP COOLANT	New	150.00	50.00
4	REMOVE AND RENEW FRONT WINDSCREEN	New	150.00	120.00
5	REMOVE AND RENEW FRONT DASHBOARD	New	500.00	0.00
6	REMOVE AND RENEW AIRBAG ASSY	New	400.00	250.00
7	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	New	500.00	0.00
8	CHECK FRONT WHEEL ALIGNMENT	New	150.00	60.00
9	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS	New	200.00	150.00
10	TRANSFER PARTS ,ATTACHMENT FROM FRONT RH DOOR TO NEW	New	200.00	60.00
11	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	1,200.00
12	SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	1,200.00
13	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	80.00
Gross Labour Cost (S\$)			5,720.00	3,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >