



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
GINGER CHAN SOOK CHING BLK 128 MARSILING RISE #05-258 SINGAPORE 730128 Contact No Mobile: 90079989	Cust No/Name	LCV06689/GINGER CHAN SOOK CHING
	Reg No/Reg Date	SME4882P*ECB / 01/10/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5015082
	Engine No	G4FGJH707262
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	10/12/2018/ 19:11	QUE	261 / Edwin Caina	40454		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

E PNT88000	RENEW & RE-ALIGN ACCIDENT DAMAGED PORTION:						1650 2750.00
	RENEW FRT DOOR RH & FRT FENDER RH						
	REPAIR SIDE SILL PNL RH & FRT DOOR PILLAR RH						1260 1680.00
E PNT98000	RESpray FRT DOOR RH , FRT FENDER RH , SIDE SILL PNL RH & FRT DOOR PILLAR PNL RH						120.00
E PNT88000	REMOVE & REFIT FRT DOOR COMPONENTS						120.00
E PNT88000	REMOVE & REFIT TRIM . CARPET AND SEAT TO FACILITATE REPAIR						30 50.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM						200.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						80 120.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS						30.00
M SUNDRY	Sundries						
M PANEL-FENDER,RH	repair	1.00	393.00	00.00			393.00
M PANEL ASSY-FRONT DOOR,RH	Ref	1.00	1277.00	00.00			1277.00
M HINGE ASSY-FRT DOOR,RH TOP	Ref	1.00	30.00	00.00			30.00
M HINGE ASSY-DOOR LWR,RHF	Ref	1.00	27.00	00.00			27.00
M LATCH ASSY-FRONT DOOR,RH	Ref	1.00	400.00	00.00			400.00
M BLACK TAPE-FR DR RR,RH	Ref	1.00	13.00	00.00			13.00

SURVEYOR NAME:

Rome - Hy 90010068

SURVEYOR SIGNATURE:

Ref

DATE:

03/01/19 @ 1025

Confirm & accepted by

REMARKS:

5 days

7% GST on

Nett

7210.00

7,210.00

504.70

Total Payable

7,714.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.