

NER: Lynn Khong CC 4 / TP 1900 0394, T1 fuz 32 LKK: 91553
DOI: 8/1/19 Date / Time: 31/1/2019
Registered in Merimen: Sym 017MF

re-assign / CCU / FTE



Insured Vehicle No.: SOE 7799J
Name of Insured: Ang Khim Keay.
Insured Tel No.: HP:
Excess Sec II :SS D.O.A: 21/12/2018
Is driver the owner? (YES / NO)
If NO, Driver Name / Age: (V/L: YES / NO)
Driver Tel No.: 688A 2861P

Claim No.:
Policy No.:
Make / Model: Ayo
Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Other:

Date / Time	STAGE	DATE / PIC
<u>9/1/19</u> <u>CPK</u>	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI: <u>2/3/2019</u>	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: Tauke

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	<u>S\$ 1124.83</u>	(3 days) Reduction: <u>\$539.10</u> % <u>32</u>	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:	If NO or B 28, Ass. Lia:
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No.: <u>TBA</u>	
Repair Cost:	S\$	(days)	
Loss of Rental (LOR):	S\$	(\$ x days)	
Loss of Use (LOU):	S\$	(\$ x days)	
Loss of Income (LOI):	S\$	(\$ x days)	
LOR only ☐ LOU only ☐	☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	S\$		
Medical:	S\$	(e.g. Tow/ Independent)	
Disbursement:	S\$		
Legal Cost	S\$		
Total:	S\$	Global Sum S\$:	Email ☐ Call ☐
FINAL PAYMENT	Date/Time:	Confirm with:	
Payee 1:	S\$	Name 1:	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

COPY SENT
22-01-19

1) Claim status: Normal/Reject/Private Settle
2) Report Format: Independent
3) Survey fee: \$368

Curator

Tanflm

REF: ASmAXA7

ASSIGNMENT

From:

Date:

08012019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKV 710M

at Workshop n/s

Ethoz

of

3D Bukit Batok Crescent

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:


Lee

(Policy Condition)

After lunch

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$62K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

1-61

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKV 710M

Yr Regn:

2015 Aug.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

G.C.

1598

Colour:

8/11/19

A/C:

Insured / Std / NI / NA

Sp. Reading

109704

T/Radio:

Insured / Std / NI / NA

Eng/No:

MR053REH104537388

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

8/1/19 4/5pm

Survey held at

Ethoz BR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$1,124.85, 3 days

P/P \$1047.25
2. Item P/P \$446.90

P/P = \$1124.85

Red. \$614.70 / 37.7

(Red. \$537.10 / 32.1)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

) \$ - RS - SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

100.00
50 x 3 = 150
-
38.00
80.00
-
368.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00002

Version: 1810

Date calculated: 01/24/2019 05:30 PM

Full Report

Registration: SKV710M

Printed: 24/01/2019 5:32 PM

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B420	RENEW REAR BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS DOES NOT INCLUDE: R + R PARKING AID SENSORS		5.0	22.50
NO NUMBER 2711	R + R REAR BUMPER SUPPORT REAR PANEL REPAIR		1.0 15.0*	4.50 67.50
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.10	21.0	94.50
Total of Labour				94.50

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R REAR PANEL REPAIR PAINTING <50%		12.0 10.0	

Paint Material Per Part

Code	Description	Price SGD
2581	REAR BUMPER NEW PART PAINT K1R	53.75
2711	REAR PANEL REPAIR PAINTING <50%	8.50

Labour Cost - Paint

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			22.0	
Preparation Main Work Metal		1.70	17.0	76.50
Preparation Comp. Work Plastic		0.30	3.0	13.50
Total	10 WU/h	4.20	42.0	189.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00002

Version: 1810

Date calculated: 01/24/2019 05:30 PM

Full Report

Registration: SKV710M

Printed: 24/01/2019 5:32 PM

Material Cost - Paint

New Part Painting - Plastic K1R

Repair Painting

Material-constant Metal

Material-constant Plastic

Total

Price SGD

53.75

8.50

18.10

9.00

89.35

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
2581	REAR BUMPER	52159 12934		220.00 <i>de ✓</i>
2618	R/R UPP BUMPER BRKT	52562 12130	<i>CHECK ITEM</i>	24.00 <i>de ✓</i>
2621	L/R BUMPER RR BRKT	52156 12290		38.00 <i>net ✓</i>
2622	R/F BUMPER RR BRKT	52155 12320		38.00 <i>net ✓</i>
2640	CTR REAR BUMPER BRKT	52023 02140	<i>CHECK ITEM</i>	130.00 <i>net ✓</i>
3340	R/R REFLECTOR	81910 12100	<i>CHECK ITEM</i>	30.00 <i>net ✓</i>
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			480.00
u: Used parts	Addition(+15.00%)			72.00
	Total			552.00

Extras

Code	Description	Price SGD
1000	Reverse Sensor S/N	200.00*
	Total Extras	200.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00002

Version: 1810

Date calculated: 01/24/2019 05:30 PM

Full Report

Registration: SKV710M

Printed: 24/01/2019 5:32 PM

Final Calculation

	SGD	SGD
Parts		
Addition(+15.00%)	480.00	
Total Parts	72.00	552.00
Labour Time Base 10 WU/h		
Total 21.0 WU X 45.00 SGD/h	94.50	
Total of Labour		94.50
Total Of Extras		200.00
Paint Work Time Base 10 WU/h		
Labour Cost 42.0 WU X 45.00 SGD/h	189.00	
Material Cost	89.35	
Total Paint Including Material		278.35
Repair Cost Excludes GST		1,124.85
GST (+7.00%)		78.74
Repair Cost Included GST		1,203.59
Lump Sum		1,203.59

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

PARTS: \$480.00 + 15%

\$552.00

S/N: \$200.00

LABOUR: \$372.85

\$1,124.85

COR: \$1,124.85 (PBP)

3 DAYS REPAIR *

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
GST Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
KIT BATOK CRESCENT
PORE 658075
TO: 22 TAMPINES ST 92J
BY BRYAN

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
0-02170 R/B REFLECTOR		1	(SIN)	(SIN)
3-02190 R/REINFORC		1 PCS	30.000	30.00
2-02250 R/B RETAINER		1	130.000	130.00
		1	24.000	24.00
GST Excl Amount :				184.00
Special Discount :				
GST @ 7% :				12.85

OTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

PRINT BY :
YAW 09/01/2019 14:26:01

GOODS RECEIVED

TOTAL

196.88

SIGNATURE

3100

SIGNATURE

Lee Chen Sin

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
GST Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
KIT BATOK CRESCENT
PORE 658075
TO: 22 TAMPINES ST92J
BY BRYAN

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
9-02904 R/BUMPER		1 PCS	(SIN)	(SIN)
5-02140 R/B RETAINER		1	220.000	220.00
5-02140 R/B RETAINER		1	38.000	38.00
		1 PCS	38.000	38.00
GST Excl Amount :				296.00
Special Discount :				
GST @ 7% :				20.72

OTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

PRINT BY :

GOODS RECEIVED

TOTAL

316.72

AUTHORISED STOCKISTS:

NISSAN
Genuine Parts

TOYOTA
GENUINE PARTS

OPEL
GENUINE PARTS

MAZDA
Genuine Parts

GENUINE PARTS

Ford

HYUNDAI

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV

TEL: 62954551
67496954

HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

TAX INVOICE NO.: CL392382

INVOICE DATE: 09/01/2019

CREDIT TERMS: 30 DAYS

SALES ORDER NO.:

SALESMAN: YAW

PAGE(S): 1

AUTHORISED STOCKISTS:

NISSAN
Genuine Parts

TOYOTA
GENUINE PARTS

OPEL
GENUINE PARTS

MAZDA
Genuine Parts

GENUINE PARTS

Ford

HYUNDAI

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV

TEL: 62954551
67496954

HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

TAX INVOICE NO.: CL392344

INVOICE DATE: 09/01/2019

CREDIT TERMS: 30 DAYS

SALES ORDER NO.:

SALESMAN: YAW

PAGE(S): 1

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00002

Version: 1810

Date calculated: 01/24/2019 05:30 PM

FINALIZATION REPORT

Full Report

Registration: SKV710M

Printed: 24/01/2019 5:32 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Ethoz Bukit Batok 02	Currency:	SGD
Claim Reference:		Date of Incident:	2018-12-21
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA
Sub Model:	BASE MODEL
Model Sheet Number:	70 AE 01
Registration:	SKV710M
VIN number:	
Odometer:	

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection: 2019-01-24

Damage Areas

All ☐

Underbody ☐



ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

(LKK)

Claim Reference:

Assessment number: SIN00002

Version: 1712

Date calculated: 01/05/2019 08:37 AM

Full Report

Registration: SKV710M

Printed: 01/05/2019 8:37 AM

Summary Information

Claim

Location: Singapore (SG)
Printed by: Ethoz Bukit Batok 02
Claim Reference:
Estimated Repair Time:
Actual Repair Days:

Work Provider: AXA Insurance Pte Ltd
Currency: SGD
Date of Incident: 2018-12-21
Hire Car Start:
Hire Car End:

Vehicle Details

Vehicle

Manufacturer: TOYOTA
Model: COROLLA
Sub Model: BASE MODEL
Model Sheet Number: 70 AE 01
Registration: SKV710M
VIN number:
Odometer:

Tanpin 97495749
WP
8/1/19 @ 4PM
sure/khanto.com
Resurvey before paint
3 days
sure/khanto.com


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00002

Version: 1712

Date calculated: 01/05/2019 08:37 AM

Full Report

Registration: SKV710M

Printed: 01/05/2019 8:37 AM

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
750171	RENEW BADGE "TOYOTA"		2.0	9.00
750171	RENEW BADGE "TOYOTA"		2.0	9.00
750171	RENEW BADGE "COROLLA"		2.0	9.00
B420	RENEW REAR BUMPER		5.0	22.50
	INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS			
	DOES NOT INCLUDE: R + R PARKING AID SENSORS			
NO NUMBER	R + R REAR BUMPER SUPPORT		1.0	4.50
B407	R + R RIGHT REAR TAILLAMP		1.0	4.50
2711	REAR PANEL REPAIR - photo.		15.0*	67.50
2931	BOOTLID REPAIR		X 10.0*	45.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		3.80	38.0	171.00
Total of Labour				171.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		12.0	
	REAR PANEL REPAIR PAINTING <50%		10.0	
	BOOTLID REPAIR PAINTING <50%		17.0	

Paint Material Per Part

Code	Description	Price SGD
2581	REAR BUMPER NEW PART PAINT K1R	53.75
2711	REAR PANEL REPAIR PAINTING <50%	8.50
2931	BOOTLID REPAIR PAINTING <50%	26.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00002

Version: 1712

Date calculated: 01/05/2019 08:37 AM

Full Report

Registration: SKV710M

Printed: 01/05/2019 8:37 AM

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		39.0	
Preparation Main Work Metal	1.70	17.0	76.50
Preparation Comp. Work Plastic	0.30	3.0	13.50
Total	10 WU/h	59.0	265.50

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	53.75
Repair Painting	34.50
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	115.35

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
2581	REAR BUMPER	52159 12934		all 220.00
2617	L/R UPP BUMPER BRKT	52563 12040		nn?X 24.00
2618	R/R UPP BUMPER BRKT	52562 12130		? 24.00 der✓
2619	L/R CTR BUMPER BRKT	52158 12090		nn X 24.00
2620	R/R CTR BUMPER BRKT	52157 12160		nn X 24.00
2621	L/R BUMPER RR BRKT	52156 12290		nn X 38.00
2622	R/F BUMPER RR BRKT	52155 12320		nn X 38.00
2640	CTR REAR BUMPER BRKT	52023 02140		? 130.00 ht✓
3013	MANUFACTURER BADGE	75441 12A00		nn X 22.00
3015	REAR MANUFACT BADGE	90975 02071		nn X 28.00
3017	BADGE MODEL	75442 12A11		nn X 22.00
3282	R/R OUTER LAMP	81551 12A10		nn X 150.00
3340	R/R REFLECTOR	81910 12100		nn? 30.00 cna✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			774.00
u: Used parts	Addition(+15.00%)			116.10
	Total			890.10

Extras

Code	Description	Price SGD
1000	Reverse Sensor S/A	200 220.00*

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00002

Version: 1712

Date calculated: 01/05/2019 08:37 AM

Full Report

Registration: SKV710M

Printed: 01/05/2019 8:37 AM

Code	Description	Price SGD
	Total Extras	220.00

Final Calculation

	SGD	SGD
Parts	774.00	
Addition(+15.00%)	116.10	
Total Parts		890.10 ✓
Labour Time Base 10 WU/h		
Total 38.0 WU X 45.00 SGD/h	171.00	
Total of Labour	94.50	171.00 ✓
Total Of Extras		220.00 ✓
Paint Work Time Base 10 WU/h		
Labour Cost 59.0 WU X 45.00 SGD/h	265.50 129	
Material Cost	115.35 89.35	
Total Paint Including Material		380.85 ✓
Repair Cost Excludes GST		1,661.95 ✓
GST (+7.00%)		116.34
Repair Cost Included GST		1,778.29

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

◀ Service Request Details

Claim

S8M017MF

Reference

None ✎

Loss Date

21 December 2018

Request Date

7 January 2019

Due Date

14 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKV710M

Make

TPVD

07/01/2019 @ 10:16am
be verification

Service Address

Primary Contact/Insured

ANG KHIM KEONG (HONG QINQIANG)
61A Strathmore Avenue, #08-08, 142061, Singapore
91017799

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

New Message

Catherine Chong (LKK Auto)

From: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Sent: Saturday, 5 January, 2019 8:45 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: ARRANGE SURVEY VEHICLE NO : SKV710M (TP)(AXA)
Attachments: 33_20190105082545.pdf

Categories: Shailendra

Hi,

Appreciate you could arrange survey on above mention vehicle.

Your insured vehicle number : SDE-7799-J

DOA : 21.12.2018

Thank you.

Warmest Regards,
Lee Chen Sin
Motor Claims Operations

ETHOZ

ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

DID: 6654 7520 | FAX: 6654 7542 | Mobile: 8822 8339

www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

02 AUGUST 2019

ANG KHIM KEONG
BLK 61A STRATHMORE AVENUE
#08-08
SINGAPORE 142061

Dear Sir/ Mdm

OUR REF : CC4/ASM19000394/T1fa3 // S8M017MF
YOUR REF : SDE 7799J
ACCIDENT INVOLVING SDE 7799J AND SKV 710M ALONG/AT AYE TOWARDS CTE
AFTER AVE 6 CLEMENTI ON 21/12/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from ETHOZ GROUP LTD acting on behalf of the owner of SKV 710M against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to pohkin@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact as at Mr Poh Kin, Chong (LKK Handler) 6841 2132 or pohkin@lkkauto.com Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Poh Kin Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

cc AXA INSURANCE PTE LTD

Poh Kin (LKKAuto)

From: Taufikh (LKKAuto)
Sent: Friday, 12 April 2019 6:47 PM
To: 'Lee Chen Sin'
Cc: Poh Kin (LKKAuto)
Subject: RE: FINALIZATION REPORT OF SKV-710-M TOYOTA ALTIS (TP)(AXA)
Attachments: 33_20190124172927.pdf; 33_20190124172327.pdf

Hi Lee,

COR \$1124.85 , 3 days, finalize amount subject to our principal approval.

Regards
Taufikh
Lkk Auto

From: Lee Chen Sin [mailto:ChenSin.Lee@ethozgroup.com]
Sent: Thursday, 24 January 2019 5:52 PM
To: 'Taufikh (LKK Auto)'
Cc: SUR
Subject: FINALIZATION REPORT OF SKV-710-M TOYOTA ALTIS (TP)(AXA)

Hi Taufikh,

Attached are the finalization report, supplier invoice, check item photo and photo before paint of above mention vehicle.

Please send acceptance once the COR is confirm.

COR : \$ 1,124.85 (Part By Part)
Repair days : 3


Kindly revert.

Thank you.

Warmest Regards,
Lee Chen Sin
Motor Claims Operations

ETHOZ
ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075
DID: 6654 7520 | FAX: 6654 7542 | Mobile: 8822 8339
www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
Assessment number: SIN00002
Version: 1810
Date calculated: 01/24/2019 05:30 PM

FINALIZATION REPORT

Full Report
Registration: SKV710M
Printed: 24/01/2019 5:32 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Ethoz Bukit Batok 02	Currency:	SGD
Claim Reference:		Date of Incident:	2018-12-21
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA
Sub Model:	BASE MODEL
Model Sheet Number:	70 AE 01
Registration:	SKV710M
VIN number:	
Odometer:	


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection: 2019-01-24

Damage Areas

All ☐
Underbody ☐



ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00002
 Version: 1810
 Date calculated: 01/24/2019 05:30 PM

Full Report
 Registration: SKV710M
 Printed: 24/01/2019 5:32 PM

Labour

		Time Base 10 WU/h	Price = 45.00 SGD/h	
Code	Description		WU	Price SGD
B420	RENEW REAR BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS DOES NOT INCLUDE: R + R PARKING AID SENSORS		5.0	22.50
NO NUMBER 2711	R + R REAR BUMPER SUPPORT REAR PANEL REPAIR		1.0 15.0*	4.50 67.50
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	2.10	21.0	94.50
	Total of Labour			94.50

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		12.0	
	REAR PANEL REPAIR PAINTING <50%		10.0	

Paint Material Per Part

Code	Description	Price SGD
2581	REAR BUMPER NEW PART PAINT K1R	53.75
2711	REAR PANEL REPAIR PAINTING <50%	8.50

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	45.00 SGD/h		22.0	
Time Paint				
Preparation Main Work Metal		1.70	17.0	76.50
Preparation Comp. Work Plastic		0.30	3.0	13.50
Total	10 WU/h	4.20	42.0	189.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00002

Version: 1810

Date calculated: 01/24/2019 05:30 PM

Full Report

Registration: SKV710M

Printed: 24/01/2019 5:32 PM

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	53.75
Repair Painting	8.50
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	89.35

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	52159 12934		220.00
2618	R/R UPP BUMPER BRKT	52562 12130	CHECK ITEM	24.00
2621	L/R BUMPER RR BRKT	52156 12290		38.00
2622	R/F BUMPER RR BRKT	52155 12320		38.00
2640	CTR REAR BUMPER BRKT	52023 02140	CHECK ITEM	130.00
3340	R/R REFLECTOR	81910 12100	CHECK ITEM	30.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			480.00
u: Used parts	Addition(+15.00%)			72.00
	Total			552.00

Extras

Code	Description	Price SGD
1000	Reverse Sensor S/N	200.00*
	Total Extras	200.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00002
 Version: 1810
 Date calculated: 01/24/2019 05:30 PM

Full Report
 Registration: SKV710M
 Printed: 24/01/2019 5:32 PM

Final Calculation

	SGD	SGD
Parts	480.00	
Addition(+15.00%)	72.00	
Total Parts		552.00
Labour Time Base 10 WU/h		
Total 21.0 WU X 45.00 SGD/h	94.50	
Total of Labour		94.50
Total Of Extras		200.00
Paint Work Time Base 10 WU/h		
Labour Cost 42.0 WU X 45.00 SGD/h	189.00	
Material Cost	89.35	
Total Paint Including Material		278.35
Repair Cost Excludes GST		1,124.85
GST (+7.00%)		78.74
Repair Cost Included GST		1,203.59
Lump Sum		1,203.59

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

PARTS : \$ 480.00 + 15%

\$ 552.00

S/N : \$ 200.00

LABOUR : \$ 372.85

\$ 1,124.85

COR: \$ 1,124.85 (PBP)

3 DAYS REPAIR

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62982158, 62942354, 62935021
 Email: ftrgnet@mbx3.singnet.com.sg
 ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
 JKIT BATOK CRESCENT
 APORE 658075
 I TO; 22 TAMPINES ST 92]
 R BY BRYAN

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
10-02170 R/B REFLECTOR		1	(SIN) 30.000	(SIN) 30.00
23-02190 R/REINFORC		1 PCS	130.000	130.00
52-02250 R/B RETAINER		1	24.000	24.00
10m				
169718				
			GST Excl Amount :	184.00
			Special Discount :	
			GST @ 7 % :	12.88

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

PRINT BY :
 YAW 09/01/2019 14:26:01

SIGNATURE

3100

GOODS RECEIVED

Lee Chen Sin

SIGNATURE

TOTAL

196.88

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62982158, 62942354, 62935021
 Email: ftrgnet@mbx3.singnet.com.sg
 ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
 JKIT BATOK CRESCENT
 APORE 658075
 I TO; 22 TAMPINES ST92]
 R BY BRYAN

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
59-02904 R/B BUMPER		1 PCS	(SIN) 220.000	(SIN) 220.00
76-02140 R/B RETAINER		1	38.000	38.00
75-02140 R/B RETAINER		1 PCS	38.000	38.00
10m				
169718				
			GST Excl Amount :	296.00
			Special Discount :	
			GST @ 7 % :	20.72

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

PRINT BY :
 YAW 09/01/2019 00:55:25

GOODS RECEIVED

Lee Chen Sin

SIGNATURE

TOTAL

316.72

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62985333 67455824

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts

MAZDA
 Genuine Parts

HYUNDAI
 Genuine Parts

TOYOTA
 Genuine Parts

NISSAN
 Genuine Parts

OPEL
 Genuine Parts



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ETHOZ AUTOMOTIVE SOLUTIONS LTD		Ref : CC4/TP19000394/T1ga3s2		
30 BUKIT BATOK CRESCENTSINGAPORE 658075		Date : 12-11-2019		
ON BEHALF OF LIM CHIN HUAT JOHNNY		Code : TP513		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SKV 710M	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		07/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053REH104537388	Colour	SILVER	
Odometer	109704	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/12/2018	Inspection Date	08/01/2019	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 710M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (WCP)	DEFORMED	220.00	220.00
1	L/R UPP BUMPER BRKT (WCP)	NOT NECESSARY	24.00	-
1	R/R UPP BUMPER BRKT (WCP)	DEFORMED	24.00	24.00
1	L/R CTR BUMPER BRKT (WCP)	NOT NECESSARY	24.00	-
1	R/R CTR BUMPER BRKT (WCP)	NOT NECESSARY	24.00	-
1	L/R BUMPER RR BRKT (WCP)	NECESSARY	38.00	38.00
1	R/R BUMPER RR BRKT (WCP)	NECESSARY	38.00	38.00
1	CTR REAR BUMPER BRKT (WCP)	BENT	130.00	130.00
1	MANUFACTURE BADGE (WCP)	NOT NECESSARY	22.00	-
1	REAR MANUFACT BADGE (WCP)	NOT NECESSARY	28.00	-
1	BADGE MODEL (WCP)	NOT NECESSARY	22.00	-
1	R/R OUTER LAMP (WCP)	NOT NECESSARY	150.00	-
1	R/R REFLECTOR (WCP)	CRACKED	30.00	30.00
	COST PLUS 15%		116.10	72.00
			890.10	552.00
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	NOT WORKING	220.00	200.00
			220.00	200.00
LABOUR				
	TOTAL OF LABOUR.		171.00	94.50
	PAINT WORK: LABOUR COST.		265.50	189.00
	PAINT WORK: MATERIAL COST.		115.35	89.35
			551.85	372.85
GRAND TOTAL			1,661.95	1,124.85
RECOMMENDED COST OF REPAIRS				1,124.85

Report Ref No. CC4/TP19000394/T1ga3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.