



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ETHOZ AUTOMOTIVE SOLUTIONS LTD

Ref : CC4/TP19000394/T1ga3s2

30 BUKIT BATOK CRESCENTSINGAPORE 658075

Date : 24-10-2019



ON BEHALF OF LIM CHIN HUAT JOHNNY

Code : TP513

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SKV 710M
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	07/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104537388	Colour	SILVER
Odometer	109704	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/12/2018	Inspection Date	08/01/2019
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------