Claim Reference:

Assessment number: SIN00002

Version: 1712

Date calculated: 01/05/2019 08:37 AM

Full Report Registration: SKV710M

Printed: 01/05/2019 8:37 AM

Summary Information

Claim

Location: Printed by: Singapore (SG)

Ethoz Bukit Batok 02

Work Provider:

Currency:

Date of Incident:

Hire Car Start: Hire Car End:

AXA Insurance Pte Ltd

SGD

2018-12-21

Actual Repair Days: **Vehicle Details**

Estimated Repair Time:

Claim Reference:

Vehicle

Manufacturer:

Model:

Sub Model: Model Sheet Number:

Registration: VIN number: TOYOTA

COROLLA BASE MODEL

70 AE 01 SKV710M

Odometer:

Vehicle Condition


Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

AII

Underbody



Claim Reference:

Full Report

Assessment number: SIN00002

Registration: SKV710M

Version: 1712

Printed: 01/05/2019 8:37 AM

Date calculated: 01/05/2019 08:37 AM

La	b	0	u	r
----	---	---	---	---

	Time Base 1	.0 WU/h	Pri	ce = 45.0	0 SGD/h
Code	Description				Price SGD
750171	RENEW BADGE "TOYOTA"	· "我们,我们就是	1 41 1	2.0	9.00
750171	RENEW BADGE "TOYOTA"			2.0	9.00
750171	RENEW BADGE "COROLLA"			2.0	
B420	RENEW REAR BUMPER			5.0	22.50
	INCLUDES: R + R BUMPER AND NECESS	SARY			
	ATTACHED PARTS				
	DOES NOT INCLUDE: R + R PARKING A	ID			
	SENSORS				
NO NUMBER	R + R REAR BUMPER SUPPORT	Na ang Pagalang Paga		1.0	4.50
B407	R + R RIGHT REAR TAILLAMP			1.0	4.50
2711	REAR PANEL REPAIR	and the second of the second		15.0*	
2931	BOOTLID REPAIR			10.0*	45.00
	Labour Cost		Hrs	WU	
	Panel / Mechanical Labour		3.80	38.0	171.00
	Total of Labour				171.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R REAR PANEL REPAIR PAINTING <50% BOOTLID REPAIR PAINTING <50%	10.0

Paint Material Per Part

Code	Description	Price SGD
2581	REAR BUMPER NEW PART PAINT K1R	53.75
2711	REAR PANEL REPAIR PAINTING <50%	8.50
2931	BOOTLID REPAIR PAINTING <50%	26.00

Claim Reference:

Full Report Registration: SKV710M Printed: 01/05/2019 8:37 AM

Assessment number: SIN00002

Version: 1712

Date calculated: 01/05/2019 08:37 AM

M			

Labour Cost - Paint		Hrs	WU	Price SGD	
Factor	45.00 SGD/h				
Time Paint	endernis (CAR PA-ASAC) — 3 Christoffillistadinista ♥ (Art 1990)		39.0		
Preparation Main Work Metal		1.70	17.0	76.50	
Preparation Comp. Work Plastic		0.30	3.0	13.50	
Total	10 WU/h	5.90	59.0	265.50	
Material Cost - Paint				Price SGD	
New Part Painting - Plastic K1R				53.75	
Repair Painting				34.50	
Material-constant Metal				18.10	
Material-constant Plastic				9.00	
Total				115.35	

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	52159 12934		220.00
2617	L/R UPP BUMPER BRKT	52563 12040		24.00
2618	R/R UPP BUMPER BRKT	52562 12130		24.00
2619	L/R CTR BUMPER BRKT	52158 12090		24.00
2620	R/R CTR BUMPER BRKT	52157 12160		24.00
2621	L/R BUMPER RR BRKT	52156 12290		38.00
2622	R/F BUMPER RR BRKT	52155 12320		38.00
2640	CTR REAR BUMPER BRK	T52023 02140		130.00
3013	MANUFACTURER BADGE	75441 12A00		22.00
3015	REAR MANUFACT BADGE			28.00
3017	BADGE MODEL	75442 12A11		22.00
3282	R/R OUTER LAMP	81551 12A10		150.00
3340	R/R REFLECTOR	81910 12100		30.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			774.00
u: Used parts	Addition(+15.00%)			116.10
	Total			890.10

Extras

Code	Description	Price SGD
1000	Reverse Sensor S/N	220 00*

Claim Reference:

Full Report

Assessment number: SIN00002

Registration: SKV710M Printed: 01/05/2019 8:37 AM

Version: 1712

Date calculated: 01/05/2019 08:37 AM

Cod	e
-----	---

Description **Total Extras**

Price SGD 220.00

Final Calculation		
	SGD	SGD
Parts	774.00	
Addition(+15.00%)	116.10	
Total Parts		890.10
Labour Time Base 10 WU/h		
Total 38.0 WU X 45.00 SGD/h	171.00	NAME AND ADDRESS OF THE PARTY O
Total of Labour		171.00
Total Of Extras		220.00
Paint Work Time Base 10 WU/h		
Labour Cost 59.0 WU X 45.00 SGD/h	265.50	
Material Cost	115.35	
Total Paint Including Material		380.85
Repair Cost Excludes GST		1,661.95
GST (+7.00%)		116.34
Repair Cost Included GST		1,778.29

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
Antonio de la companio del companio de la companio del companio de la companio del la companio de la companio d	ACCIDENT STATEMENT
Date Of Report	21/12/2018 21:16
Date Of Accident	21/12/2018 16:20
Exact Location Of Accident	ALONG AYE TOWARDS CITY AFTER EXIT CLEMENTI
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKV710M
nsured/Policyholder	
Name Of Registered Owner	LIM CHIN HUAT JOHNNY
NRIC No	S1733997D
Email Address	JOHNNY@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-98227133
Alternative Phone No	OFFICE-98227133
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	COROLLA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
surance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01011895
Cover Note Number	
Driver	
Name of Driver	LIM CUIN LILIAT TOUNNY

Name of Driver LIM CHIN HUAT JOHNNY

NRIC No S1733997D

Date Of Birth 04/12/1966

Occupation INDOOR

Date Of Driving Pass 26/09/1991

Driving Experience 27 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98227133

Fax Number

Contact Number OFFICE-98227133

EMail Address JOHNNY@SINGNET.COM.SG

Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Foreign Vehicle Registration Number

JGM3122 (PRIVATE CAR)

Number of vehicles (including own vehicle)

avolved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

JURONG WEST N.P.C

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO: T/20181221/2117(LODGED AT JURONG WEST N.P.C) ON 21/12/2018 AT ABOUT 518HRS, I WAS DRIVING ALONG AYER RAJAH EXPRESSWAY TOWARD CITY, I FILTER TO LANE 2 AND SLOWED DOWN FOLLOWED BY A STOP AS THERE'S A JAM IN FRONT OF MY VEHICLE; SKV710M. AFTER STOPPING FOR ABOUT A MINUTE, I FELT AN IMPACT FROM THE REAR AND NOTICED THAT A VEHICLE; SDE7799J HAD COLLIDED ONTO MY VEHICLE. SUBSEQUENTLY, I ALIGHT FROM MY VEHICLE TO CHECK THE DAMAGES AND ONLY DISCOVERED THAT THERE'S THREE MORE VEHICLE AT THE BACK. HENCE, IS CAUSES A CHAIN COLLISION WITH TOTAL OF 05 VEHICLES AT THE LOCATION. ALL DRIVERS EXCHANGED PARTICULARS AND PASSENGERS ON THE SECOND VEHICLE WAS CONVEYED TO HOSPITAL BY AMBULANCE. I HAD IN-CAR CAMERA FOR THE FRONT AND REAR.

Attachment(s)

Are accident photos available for attachment? Was there any video captured by Car Camera? YES YES

NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SDE7799J

Vehicle Make/Model/Colour

B.M.W. / 318I

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

ANG KHIM KEONG (HONG QINQIANG)

NRIC/Passport Number

S7912776J

Contact Number

91017799

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Passenger 1

NAME: : P1

GENDER:

: FEMALE

Passenger 2

NAME:

: P2

GENDER:

: MALE

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

YN9351H

Vehicle Make/Model/Colour

HINO / XZU710R-HKFMS3

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

DAIRIAM JOHN INIKO

NRIC/Passport Number

F7737525L

∩ontact Number

81524264

Address

Postcode

Insurance Company Name

Nature Of Damage

1

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

JGM3122

Vehicle Make/Model/Colour

KAMAL AUFZN B.BANON

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN DRIVER

NRIC/Passport Number

760809017045

Contact Number

0127129013

Address

ostcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

GBA2861P

Vehicle Make/Model/Colour

TOYOTA / HIACE

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NG YUNYONG JERRY

NRIC/Passport Number

S8141227H

Contact Number

81616505

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

PASSENGER 1

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SDE7799J

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

PASSENGER 2

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SDE7799J

Were seat belts worn?

YES

Was this injured conveyed to hospital by


ambulance?

Postcode

YES

'ddress

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

	City after Clementi Ave 6. The traffic was slow
onto my rear and collided on to my car, a rear position., another Malaysia lorry JGI van GBA2861P cannot stop on time and	stop on time, suddenly vehicle SDE7799J hit another lorry YN9351H was hit onto SDE7799J M3122 hit onto YN9351H rear position, another d collided JGM3122 Rear position. Damages of avolved. One women and children was injured
and coveyed to hospital.	,.
Taxi Voucher No.:	
DECLARATION	
I/We declare that the above particulars & information provide	ded above are true in every aspect
VERIFIED BY AJAX MARS REPORTING OFFICER -	
JOHNNY VOO CHEON YEE	
MARS Officer	
	Registered Owner or Driver's Signature
Job Complete Date/Time	Date/Time:
21 December 2018 at 6:15 PM	21 December 2018 at 6:15 PM



Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999



1 013

Report No. T/20181221/2117



	1800-2689			Station Diary No.:
Date/Time Report Made: 21/12/2018 19:18			Vide Report No.: D/20181221/0089	165
Informa	nt's Partic	ulars	Address: APT BLK 273B JURONG WES	T AVENUE 3 #10-15
ID Type / ID No.: NRIC NO / S1733997D		error personal bridge	SINGAPORE 642273 Contact No.: Home/Office:	Mobile: 98227133
NRIC N	3/51/333	EN	Email: Type of Informant:	
Sex: Male	Age: 52	Date of Birth: 04/12/1966	Driver Language:	Institution / School Name;
Race: Chinese			Driving Licence Information:	D. A. of Evrilly
Occupation: ENGINEER			Class: 3	Date of Expiry:

General Infor	- Control - Cont		Drink Drive: No	Date/Time of Accident: 21/12/2018 16:20	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH toward city	EXPRESSWAY	Road	Surface:		Road Speed Limit:
Traffic Flow: Dry		c Control:		Traffic Volume: Moderate	
Oual Carriage Type of Collision					Anyone conveyed by ambulance:

Details of V	ehicle Invo	lved				
Vehicle No.	Type	Make	Model	Color		No of Passenger
GBA2861P	Van	ТОУОТА	HIACE	Silver	Damaged	^
JGU3122	Lorry			et aller de sant 1980 et al le Builder	Slightly Damaged	0
SDE7799J	Car	BMW	318I LED NAV SHAD. LIGHT	Orange	Slightly Damaged	2



Police Stadon Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999



2 of 3

Report No. T/20181221/2117

CONTINUATION OF REPORT

Details of V	ehicle invo	ived	Model	Color		No of Passenge
Vehicle No.		Make		Silver	Slightly	0
SKV710M	Car	TOYOTA	COROLLA ALTIS 1.6L		Damaged	0
YN9351H	Lorry	HINO	HINO XZU710R- HKFMS3	White	Slightly Damaged	0

	ehicle Insurance	Insurance No	Effective	Expiry Date
Vehicle No.	Insurance Company	D18MTPV0101280	28/08/2018	27/08/2019
SKV710M	TENET SOMPO INSURANCE PTE.	B18M1PV0101200	20,00,20	1000000

On 21/12/2018 at about 1618hrs, I was driving along Ayer Rajah Expressway toward city, I filter to lane 2 and slowed down followed by a stop as there's a jam in front of my vehicle; SKV710M. After stopping for about a minute, I felt an impact from the rear and noticed that a vehicle; SDE7799J had collided onto my vehicle. Subsequently, I alight from my vehicle to check for damages and only discovered that there's three more vehicle at the back. Hence, is causes a chain collision with total of 05 vehicles at the location All drivers exchanged particulars and passengers on the second vehicle was conveyed to hospital by ambulance. I had in-car camera for the front and rear.