

INS. CASE OWNER:

CC6 / ALG 1900 0404 / Aps 9

LKK:
IDAC:

Surveyor: LMP DOI: 28/1/18 Date / Time: 28/1/18
Registered in Merimen: 21/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SLK 2706 J
Name of Insured : KINOSTAR HOLDINGS PTE
Insured Tel No. : _____ HP: _____
Excess Sec II :SS _____ D.O.A: 24/12/18
Is driver the owner? (YES / NO) Nature of Accident : _____
If NO, Driver Name / Age : John due May
Driver Tel No. : _____ (V/L: YES / NO)

Claim No. : _____
Policy No. : _____
Make / Model : _____
Place of Accident : OTB
OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability : _____ % Final ? Yes / No

SLX 6534 T



INSRS: _____
WSP: Kinostar
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time		STAGE	DATE / PIC
<u>10/1</u>	<u>SLX 6534 T - x ; SLK 2706 J - x</u>	Non-Reporting ltr (1st):	
<u>04/1</u>		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
<u>19/3/19</u>	<u>OI mobile # not in use, did no answer</u>	Call OI: <u>20/3/19</u>	<u>NO ANSWER (Lina)</u>
<u>20/3/19</u>	<u>NO ANSWER</u>	After call ltr to OI: <u>22/3/19</u>	<u>Lina Udon</u>
<u>22/3/19</u>	<u>Send LOI - File pass to VC to check</u>	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: LMP

Repair Cost: PIP \$5,524.96 (8 days) Reduction: 44 % Email Call

FINAL SETTLEMENT Date/Time: 29.11.19 Confirm with MS KAM Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 29

Repair Cost: W/LCS \$5,911.71

Loss of Rental (LOR): \$5,200.00 (13 days) x 400

Loss of Use (LOU): \$5 - (3 x days)

Loss of Income (LOI): \$5 - (3 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$5 -

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5,111.71 Global Sum \$5:

FINAL PAYMENT Date/Time: 29.11.19 Confirm with: MS KAM Email Call

Payee 1: \$5,111.71 Name 1: WAI MOOR TRADING

Payee 2: (Strike if N.A.) \$5 Name 2: _____

Payee 3: (Strike if N.A.) \$5 Name 3: _____

COPY SENT



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
 TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
 BUS. REG. NO: 44223100L

專業服務：汽車意外保險賠償·拖車·汽車修理及維修服務·打嗎呷·噴漆·

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 27/12/2018

Attn: The Motor Claims Department
 Your Insured veh no : SLK 2706 J.
 AIG ASIA PACIFIC INSURANCE PTE LTD.
 78 Shenton Way
 # 07-16 Chartis Building
 Singapore 079120

TPALG
 Xiao Tang
 \$ 159.80

WITHOUT PREJUDICE

LKK

(By Email Only)

28.12.2018 @

11:00 AM

Dear Sir / Madam

Estimate Cost repair Bill To Honda City No SLX 6534 T & SLK 2706 J ON 24/12/2018.

Resurvey: 02.01.2019

11:28 AM

To Supply:

1pc	Rear Boot Cover	2.5hd		\$ 497.80 ✓
1pc	Rear Boot Cover Rubber	at		\$ 93.70 ✓
2pcs	Rear Boot Cover Hinge	Best	\$ 79.90	\$ 159.80 ✓
1pc	Rear Boot Cover Number Plate Moulding	could		\$ 147.10 ✓
2pcs	Rear Boot Cover Reflector	could	\$ 312.90	\$ 625.80 ✓
1pc	Rear Boot Cover Inner Lock	Best		\$ 126.80 ✓
1pc	Rear boot Cover H Logo	New		\$ 18.30 ✓
1pc	Rear Boot Cover Reverse Recorder	new		\$ 398.00 ✓
2pcs	Rear Lamp (LH & RH)	could	\$ 388.70	\$ 777.40 ✓
1pc	Rear Panel	2.5hd		\$ 333.60 ✓
1pc	Rear Panel Inner Garnish	2hd		\$ 96.60 ✓
1pc	Rear Fender Inner Garnish	new		\$ 168.30 ✓
1pc	Rear Spare Tyre Garnish	3		\$ 139.80 ✓
1pc	Spare Tyre Cover	2hd		\$ 145.00 ✓
1pc	Rear Bumper	2.5hd		\$ 463.70 ✓
2pcs	Rear Bumper Side Retainer	at	\$ 19.50	\$ 39.00 ✓
1pc	Rear Bumper Reverse Sensor	2hd		\$ 487.90 300(2hd)
1pc	Rear Fender RH	2hd		\$ 1,168.80 ✓
1pc	Rear Windscreen Moulding	new	3709.40	\$ 52.80 ✓
1pc	X Spare Tyre Panel	2hd	2567.52	\$ 521.10 ✓
1pc	Rear Numper Plate	Best		\$ 45.00 ✓
1set	Rear Reflector & No. plate garnish " Sticker "	2hd		\$ 200.00 ✓
1pc	Rear Windscreen Sealant	NE m	SN360.	\$ 80.00 ✓
				<u>\$ 6,786.30</u>

To dismantle and replace of the accident damaged parts, knocking, repair, adjust and reshape of same.

To putty, apply primer & spray paint on the affecte portion.

To remove and refix rear windscreen

To check wiring functions.

To remove reverse sensor.

To remove car cushion

5704.96

1940
 Admin Lij
 20/12/18
 CB Pmp.
 Supplementary: 25744
 Total: 5524.56 (P/P)

\$ 980.00 200

\$ 1,200.00 1000

\$ 120.00 ✓

\$ 60.00 20

\$ 80.00 50

\$ 100.00 60

\$ 9,326.30



凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償·拖車·汽車修理及維修服務·打嗎呷·噴漆·
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 02/01/2019

Attn: The Motor Claims Department
Your Insured veh no : SLK 2706 J.
AIG ASIA PACIFIC INSURANCE PTE LTD.
78 Shenton Way
07-16 Chartis Building
Singapore 079120

WITHOUT PREJUDICE

(By Email Only)

Dear Sir / Madam

Supplementary Cost repair Bill To Honda City No SLX 6534 T & SLK 2706 J ON 24/12/2018.

To Supply;

1pc	Antenna interior	<i>3 new</i>	74.1 <i>+</i>
1pc	Buzzer assy smart		82.5 <i>+</i>
1pc	Space tyre tool box	<i>could</i>	321.8 <i>✓</i>

3218

Resubmited Adrian Lj
04/01/19. 257.44

9204.70

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2019 Edit Reg		28 Dec 2018 00:00 Edit Adj Rpt	\$55,524.96 Edit Estimates	\$55,524.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KINETIC HOLDINGS PTE LTD , Co. Reg. No.: 201618392N								
Main Claimant:	TOH YI SHING, GWENDOLENE , ID: S8014110F								
Vehicle Reg. No.:	SLX6534T	Date of Loss:	24/12/2018 08:00 - :59 [20 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1019466958SG	Policy/Cover Note No.:	0999994564 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLK2706J	Policy No. (Claimant):	PNPV2018-00005423						
Repairer:	KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440, 408701 Ubi - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (09/01/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX6534T (1019466958SG)
[SLK2706J]
TP
TOH YI SHING, GWENDOLENE
Dec 24 2018 8:00AM
[KINETIC HOLDINGS PTE LTD]
KAI MOTOR TRADING

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
2	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
3	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
4	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
5	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
6	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
7	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
8	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
9	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
10	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
11	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
12	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
13	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
14	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
15	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
16	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
17	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
18	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
19	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
20	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
21	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
22	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
23	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
24	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
25	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
26	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
27	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
28	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
29	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
30	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
31	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
32	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
33	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
34	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
35	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
36	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
37	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
38	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
39	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	
40	01/04/19 13:05	General View							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	01/04/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
42	01/04/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
43	01/04/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
44	01/04/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
45	01/04/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
46	01/04/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
47	01/04/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
48	01/04/19 13:05	General View	 Load JPG	<input checked="" type="checkbox"/>
49	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	01/04/19 13:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	01/04/19 13:06	Reinspection Photo		<input checked="" type="checkbox"/>
97	01/04/19 13:06	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/01/19 13:39	TP GIA REPORT		<input type="checkbox"/>
2	18/12/19 09:47	WORKSHOP INVOICE		<input type="checkbox"/>
3	18/12/19 09:47	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
4	18/12/19 09:47	RENTAL RECEIPT		<input type="checkbox"/>
5	18/12/19 09:47	LOD		<input type="checkbox"/>
6	18/12/19 09:47	LETTER TO OI		<input type="checkbox"/>
7	26/12/19 13:29	Release Voucher		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/01/19 12:00	OI GIA REPORT		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLK2706J (Insd veh)	Model:	HONDA GRACE 1.5 (A)
	SLX6534T (TP veh)		
Date of Accident:	24/12/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,491.03
Final Repair Cost	:	\$	5,911.71
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	1,200.00 12 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,111.71
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown		
1)	KAI MOTOR TRADING	: \$ 7,111.71
2)		: \$
3)		: \$
4)		: \$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

18 Dec
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19000404/AEA3Q2

Date: 26/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994564
 Claimant Vehicle No : SLX6534T Insured Vehicle No : SLK2706J
 Date of Loss: 24/12/2018 Nature of Claim: TP Claim No: 1019466958SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX6534T
 Make & Model: HONDA GRACE, 1.5 (A) Engine No: L15B4073409
 Reg. Date: 06/04/2017 (Man. Year: 2017) Chassis No: GM61002663
 Colour: White Odometer: 30051 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,264.70	3,584.96	3,679.74	50.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,940.00	600.00	23.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,804.70	5,524.96	4,279.74	43.65
+ GST 7.00/7.00% (S\$)	686.33	386.75	299.58	43.65
Nett Amount (S\$)	10,491.03	5,911.71	4,579.32	43.65
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
	Nett Liability (S\$)	7,111.71		

INSPECTION

Date of Assignment: 28/12/2018
 Date Inspected: 28/12/2018 Inspected At: KAI MOTOR TRADING (HQ)
 BLK 3007 UBI ROAD 1, #01-440
 Singapore 408701
 Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Distorted	497.80 F	*497.80 FL
2	1		*REAR BOOT COVER RUBBER	Cut	93.70 F	*93.70 FL
3	2		*REAR BOOT COVER HINGE	Bent	159.80 F	*159.80 FL
4	1		*REAR BOOT COVER NUMBER PLATE MOULDING	Cracked	147.10 F	*147.10 FL
5	2		*REAR BOOT COVER REFLECTOR	Cracked	625.80 F	*625.80 FL
6	1		*REAR BOOT COVER INNER LOCK	Damaged	126.80 F	*126.80 FL
7	1		*REAR BOOT COVER H LOGO	Necessary	18.30 F	*18.30 FL
8	1		*REAR BOOT COVER REVERSE RECORDER	Not Necessary	398.00 F	*- FL
9	2		*REAR LAMP (LH &RH)	Cracked	777.40 F	*777.40 FL
10	1		*REAR PANEL	Distorted	333.60 F	*333.60 FL
11	1		*REAR PANEL INNER GARNISH	Deformed	96.60 F	*96.60 FL
12	1		*REAR FENDER INNER GARNISH	Not Necessary	168.30 F	*- FL
13	1		*SPARE TYRE COVER)	Deformed	145.00 F	*284.80 FL
14	1		*REAR SPARE TYRE GARNISH)		139.80 F	*- FL
15	1		*REAR BUMPER	Distorted	463.70 F	*463.70 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	39.00 F	*39.00 FL
17	1		*REAR BUMPER REVERSE SENSOR	Damaged	487.90 FS	*300.00 FS
18	1		*REAR FENDER RH	Repair	1,168.80 F	*- FL
19	1		*REAR WINDSCREEN MOULDING	Not Necessary	52.80 F	*- FL
20	1		*SPARE TYRE PANEL	Repair	521.10 F	*- FL
21	1		*REAR NUMBER PLATE	Bent	45.00 F	*45.00 FL
22	1		*SET REAR REFLECTOR & NO.PLATE GARNISH STICKER	Necessary	200.00 FS	*60.00 FS
23	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 F	*- FL
24	1		*ANTENNA INTERIOR	Not Necessary	74.10 F	*- FL
25	1		*BUZZER ASSY SMART	Not Necessary	82.50 F	*- FL
26	1		*SPACE TYRE TOOL BOX	Cracked	321.80 F	*321.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **7,264.70** **4,391.20**
 - List Item Discount on L Items 0.00/20.00% (S\$) 0.00 806.24

Total Parts (S\$) 7,264.70 3,584.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REPLACE OF THE ACCIDENT DAMAGED PARTS,KNOCKING ,REPAIR ,ADJUST AND RESHAPE OF SAME	New	980.00	800.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,200.00	1,000.00
3	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	60.00	30.00
5	TO REMOVE REVERSE SENSOR	New	80.00	50.00
6	TO REMOVE CAR CUSHION	New	100.00	60.00
Gross Labour Cost (S\$)			2,540.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >