

ASS. REC. BY:

REF

CS/SPF19000413/K/d3^{sr}

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person)

Frankie Thuy

of

SPF

Date/Time

8/11/19 @ 11:11am

Estimated Cost

Bill to

OD/TP/WS/TP RES / OB RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 4011C

Insured:

QX 361 E

at Workshop m/s

Tong Jack Auto

Tel:

62500088

of

160 Sin Ming Drive # 07-01/06

Policy No:

Claim No:

AEMD/105/009/2018/187

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

04/2/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11:47am @ 8/11/19

Person Contacted:

Candy

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 4011C - X

Part by part \$1,074.50 (Red: 2378-26; 5490)
Submit

ASS. REC. BY:

REF: SPI-1

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Tony Luck

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKP 4011C Yr Regn: 09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Camry c.c. 2.494

Colour: M. Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 34357 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: NR053AK5004008066

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 8/12/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 8/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>9/1</u>	<u>File pass to est not ready</u>
	<u>Range 1900-3000</u>

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: 280

Transportation: _____
S + RS. SI

Fixtures

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Tuesday, 8 January 2019 11:11 AM
To: Catherine Chong; assignments
Subject: RE : Pre-Repair Inspection for SKP4011C

Your reference: SKP4011C
Our reference : AEMD/105/009/2018/187

Catherine,
Please conduct a Pre-repair Inspection for the vehicle SKP4011C at Tong Luck Auto Pte Ltd, 160 Sin Ming Drive #07-01/06 Sin Ming Autocity Singapore 575722
Kindly contact Ms Candy / Yu Ching at Tel: 62500088 for appointment.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/12/2018 20:35
Date Of Accident	06/12/2018 17:45
Exact Location Of Accident	GUOCO TOWER 1 WALLICH STREET 078881
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP4011C
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	FAIZAL.MOHAMED@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68498118

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.5 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	N.A

Driver

Name of Driver	MOHD RAFI BIN MOHD SADLI
NRIC No	S1421491G
Date Of Birth	02/08/1960
Occupation	OUTDOOR
Date Of Driving Pass	17/04/1980
Driving Experience	38 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94510716
Fax Number	
Contact Number	
Email Address	NOEMAIL

Passenger 2

NAME: : PASSENGER 2

GENDER: : MALE

Passenger 3

NAME: : PASSENGER 3

GENDER: : MALE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
 1 GATEWAY DRIVE
 #15-08 WESTGATE TOWER
 SINGAPORE 608531

TEL : 6849 8118
 ATTN : ACCOUNTS DEPT

FAX :

YOUR REF NO : QX361E
 CLAIM TYPE : THIRD PARTY
 TP INS. CO :
 ACCIDENT DATE : 06/12/2018
 TP VEH REG NO : QX361E

Not Noted

Repair by paint

3 days

ESTIMATE

NO : QUOT201901-000019(00)
 DATE : 08/01/2019
 POLICY NO : 999995580
 VEH REG NO : SKP4011C
 MAKE/MODEL : TOYOTA CAMRY 2.5 AUTO
 CHASSIS NO : MR053AK5004008066
 ENGINE NO : 2ARU158723
 REG. DATE : 2014

Estimate Repair Cost to Vehicle No : SKP4011C

Description	Quantity	Unit Price	Amount
		SS	SS
LIST PRICE			
1 Front door - RH	1	1,316.00	1,316.00
2 Front door trimboard clips - RH	15	4.50	67.50
3 Rear door - RH	1	1,286.00	1,286.00
4 Rear door trimboard clips - RH	15	4.50	67.50
			2,737.00
		Less 25%	684.24
			2,052.76
LABOUR			
5 To transfer RH front and rear damaged door interior mechanism and glass to new door	1	300.00	300.00
6 To check and rectify wiring system	1	80.00	80.00
7 To panel beat and straighten RH door pillar, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
8 To putty and spray paint on affected areas	1	800.00	800.00
9 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00
			2,300.00
		TOTAL	SS 4,352.76
		ADD GST @ 7%	304.69
		GRAND TOTAL	SS 4,657.45

SINGAPORE DOLLAR FOUR THOUSAND SIX HUNDRED FIFTY-SEVEN AND CENTS FORTY-FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : QX361E
CLAIM TYPE : THIRD PARTY
TP INS. CO :
ACCIDENT DATE : 06/12/2018
TP VEH REG NO : QX361E

ESTIMATE

NO : QUOT291901-000019(00)
DATE : 08/01/2019
POLICY NO : 999995580
VEH REG NO : SKP4011C
MAKE/MODEL : TOYOTA CAMRY 2.5 AUTO
CHASSIS NO : MR053AK5004008066
ENGINE NO : 2ARU158723
REG. DATE : 2014

Not resurvey

Resurvey B4 paint

3 days

Estimate Repair Cost to Vehicle No : SKP4011C

Description	Quantity	Unit Price	Amount
		SS	SS
LIST PRICE			
1 Front door - RH	1	1,316.00	1,316.00
2 Front door trimboard clips - RH	15	4.50	67.50
3 Rear door - RH	1	1,286.00	1,286.00
4 Rear door trimboard clips - RH	15	4.50	67.50
			2,737.00
		Less 25%	684.24
			2,052.76
LABOUR			
5 To transfer RH front and rear damaged door interior mechanism and glass to new door	1	300.00	300.00
6 To check and rectify wiring system	1	80.00	80.00
7 To panel beat and straighten RH door pillar, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
8 To putty and spray paint on affected areas	1	800.00	800.00
9 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00
			2,300.00
		TOTAL	SS 4,352.76
		ADD GST @ 7%	304.69
		GRAND TOTAL	SS 4,657.45

SINGAPORE DOLLAR FOUR THOUSAND SIX HUNDRED FIFTY-SEVEN AND CENTS FORTY-FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$ 1,974.50 ✓ ok
7% 138.22
\$ 2,112.72

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19000413/Ktd3s2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 08-02-2019	
ATTN: FRANKIE THAY		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 361E	Veh. Inspected	SKP 4011C
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/187	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	08/01/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MR053AK5004008066	Colour	METALLIC GREY
Odometer	34357	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55R17	MICHELIN	7 mm
L/H Front Tyre	215/55R17	MICHELIN	7 mm
R/H Rear Tyre	215/55R17	MICHELIN	7 mm
L/H Rear Tyre	215/55R17	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/12/2018	Inspection Date	08/01/2019
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 4011C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR - RH	TO REPAIR SEE LABOUR	1,316.00	-
15	FRONT DOOR TRIMBOARD CLIPS - RH @ \$4.50	NOT NECESSARY	67.50	-
1	REAR DOOR - RH	DENTED / WARPED	1,286.00	1,286.00
	LESS 25% DISCOUNT		-667.37	-321.50
			2,002.13	964.50
15	REAR DOOR TRIMBOARD CLIPS - RH @ \$4.50 (SN)	NECESSARY	67.50	50.00
	LESS 25% DISCOUNT		-16.88	-
			50.62	50.00
LABOUR				
	TO TRANSFER RH FRONT AND REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR.		300.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT AND STRAIGHTEN RH DOOR PILLAR, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME. INCLUSIVE OF THE REPAIR OF FRONT DOOR - RH.		1,000.00	400.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		800.00	450.00
	TO APPLY RUST-PROOFING ON REPAIRED AND REOLACED PANELS.		120.00	30.00
			2,300.00	960.00
GRAND TOTAL			4,352.75	1,974.50
RECOMMENDED COST OF REPAIRS				1,974.50

Report Ref No. CS/SPF19000413/Ktd3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$ 1,900.00 - \$3,000.00

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.