

ASS. REC. BY:

REF:

Tm1 / C03 / TML9000418 / Ktlbnz

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

1-B.1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 601A

Yr Regn:

11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1.985

Colour:

M. White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

128018

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1AB615AUC - 283472

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

4/1/19

D.O.I.

7/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/1

Fix parts to Car

SHD 601A - C03 / AXA / 4001364 / Rtlubg2

Date: 22/2/2013

10/1/2019 @ 2:20 PM - Report via email preli advise &amp; AIA

Part by Part \$3354.34 (Red: 23224.16, 87%)

RECEIVED 03 APR 2019

Date/Time, File Pass to?

3/4 Typist

Date/Time, File Return to?



: Preli. Report



: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

S - RS - SI

10

Fixturs

Others

TOTAL

260

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

TP

Lump Sum / I.B. (\$

3354.34

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 10 January 2019 2:29 PM  
**To:** 'Motor Claims'  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 04/1/2018, SHD 601A (TP VEHICLE), SGX 7160R (OI VEHICLE)  
**Attachments:** ESTIMATE\_0001.pdf, GIA REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 601A M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHD601A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003369
Chassis No.:	VF1ABL15AUC283472
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	24 Nov 2017
First Registration Date:	24 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Nov 2025
PARF Rebate Amount:	\$14,998.00

**Intended COE Rebate Details**

COE Expiry Date:	23 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$26,876.00
<b>Total Rebate Amount:</b>	<b>\$41,874.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jan 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/01/2019 13:16
Date Of Accident	04/01/2019 09:50
Exact Location Of Accident	KPE
Country/State Of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD601A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TAN KOK YONG ROBIN
NRIC No	S7535467C
Date Of Birth	26/11/1975
Occupation	OUTDOOR
Date Of Driving Pass	14/05/1999
Driving Experience	19 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97619509
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 238 COMPASSVALE WALK #13-550
Postcode	540238
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 04.01.2019 at about 0950 hours, I was travelling straight on the first lane along KPE when vehicle in front of me made a stop and so I followed suit. Moment later while stationary, I felt an impact. Vehicle B (SGX7160R) hit onto my taxi rear portion. I alighted to check and realized that I was engaged in a chain collision accident involving Vehicle B and Vehicle C (SLE9092G).

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX7160R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	MURUGESAN S/O APPAKKANNU
NRIC/Passport Number	S7038380B
Contact Number	87330544
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLE9092G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	OLISA MARAICAR YASIR
NRIC/Passport Number	S8371603G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

SKETCH PLAN

LANE 1

A	B	C
SHD 601A	SGX 7160R	SLE 9092G

A: SHD 601A  
B: SGX 7160R  
C: SLE 9092G  
KPE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach .GIA report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Amanda  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**Trans-cab Auto Services Pte Ltd**

AAD1901-034

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHD 601A**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

**SHD 601A**

VF1ABL15AUC283472

RENAULT

LATITUDE

4.1.2019

**TOKIO MARINE**

24/11/2017

**PART****LIST**

- |    |                                    |
|----|------------------------------------|
| 1  | 1 BUMPER COVER REAR                |
| 2  | 1 BUMPER LOWER REAR                |
| 3  | 1 BUMPER BRACKET CTR REAR          |
| 4  | 1 BUMEP R BRACKET SIDE RH REAR     |
| 5  | 1 BUMEP R RETAINER RH REAR         |
| 6  | 1 BUMPER REFLECTOR RH              |
| 7  | 1 BUMEP R BRACKET SIDE LH REAR     |
| 8  | 1 BUMPER RETAINER LH REAR          |
| 9  | 1 BUMPER REFLECTOR LH              |
| 10 | 1 BUMPER BEAM REAR                 |
| 11 | 1 BUMPER BEAM BRACKET LH REAR      |
| 12 | 1 BUMPER BEAM BRACKET RH REAR      |
| 13 | 1 OUTER PANEL REAR (End Panel)     |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM |
| 15 | 1 TAILLAMP LH                      |
| 16 | 1 TAILLAMP PANEL LH                |
| 17 | 1 BOOT REAR                        |

\$	<i>Bar</i> 1,108.46	✓
\$	<i>cut / dis</i> 768.84	✓
\$	<i>SL</i> 113.47	} X
\$	<i>SL</i> 135.97	
\$	<i>SL</i> 44.99	
\$	<i>SL</i> 43.61	
\$	<i>SL</i> 135.97	
\$	<i>SL</i> 44.99	}
\$	<i>SL</i> 43.61	
\$	<i>B</i> 777.52	✓
\$	<i>N</i> 225.95	X
\$	<i>N</i> 225.95	X
\$	<i>N</i> 1,471.77	X
\$	<i>SL</i> 404.56	X
\$	<i>SL</i> 552.55	X
\$	<i>N</i> 986.70	X
\$	<i>N</i> 2,872.68	X

\$	9,957.60
10% \$	995.76
\$	<u>8,961.84</u>

**Special Nett**

- |   |                              |
|---|------------------------------|
| 1 | 1SET PARKING AID             |
| 2 | 1SET REAR BUMPER CLIP        |
| 3 | 1SET BUMPER BRACKET CTR CLIP |

\$	<i>SL</i> 700.00	X
\$	<i>N</i> 66.00	✓
\$	<i>N</i> 33.00	✓

*Not Authorised**l.B.I**83354.34**Heavy B & paint*

**Trans-cab Auto Services Pte Ltd****AAD1901-034**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 601A**

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	sn	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	nn	80.00	X
12	1 WINDSCREEN MOULDING	\$	nn	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X

**TOTAL \$ 1,244.82****TOTAL PARTS \$ 10,206.66****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	3001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

**Trans-cab Auto Services Pte Ltd****AAD1901-034**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 601A**

To transfer of rear windscreen fittings and conduct  
water seepage test.

\$ *nn* 170.00 *X*

To check steering geometry and computer wheel  
alignment

\$ *nn* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 26,578.50***17616.65***(PART-BY-PART)****Repair Days****~~10~~ DAYS***2 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19000418/KTBN2

Date: 04/04/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI001640
Claimant Vehicle No :	SHD601A	Insured Vehicle No :	SGX7160R
Date of Loss:	04/01/2019	Nature of Claim:	TP
		Claim No:	M1900116

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD601A	Engine No:	M9R8839C003369
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283472
Reg. Date:	24/11/2017 (Man. Year: 2016)	Odometer:	128018 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,206.65	2,554.34	7,652.31	74.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,410.00	800.00	6,610.00	89.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,616.65</b>	<b>3,354.34</b>	<b>14,262.31</b>	<b>80.96</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,233.17</b>	<b>234.80</b>	<b>998.37</b>	<b>80.96</b>
<b>Nett Amount (S\$)</b>	<b>18,849.82</b>	<b>3,589.14</b>	<b>15,260.68</b>	<b>80.96</b>

## INSPECTION

Date of Assignment:	10/01/2019	
Date Inspected:	07/01/2019	Inspected At:
		Trans Cab Auto Services Pte Ltd - Amk (HQ)
		No 2 Ang Mo Kio St 63
		Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	<b>Version:</b> 1.0 (Last Synchronised: 04 Apr 2019)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD601A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Cut/Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
17	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
18	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
19	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
20	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
21	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
22	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
23	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
24	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
25	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
26	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
27	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
28	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
30	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,202.41</b>	<b>2,819.82</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>995.76</b>	<b>265.48</b>
<b>Total Parts (\$\$)</b>	<b>10,206.65</b>	<b>2,554.34</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			<b>7,410.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >