

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 206H**AAD1901-028**

Not Authored
11 Sep 8 900h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 206H

VF1ABL15AUC282394

RENAULT

LATITUDE

3.1.2019

AIG

2/10/2015

PART**LIST**

- | | |
|----|------------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMPER BRACKET SIDE RH REAR |
| 5 | 1 BUMPER RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMPER BRACKET SIDE LH REAR |
| 8 | 1 BUMPER RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 OUTER PANEL REAR (End Panel) |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM |
| 15 | 1 TAILLAMP LH |
| 16 | 1 TAILLAMP PANEL LH |
| 17 | 1 BOOT REAR |

\$	<i>11</i>	1,108.46	X
\$	<i>nd/h</i>	768.84	✓
\$	<i>SL</i>	113.47	}
\$	<i>SL</i>	135.97	
\$	<i>SL</i>	44.99	
\$	<i>SL</i>	43.61	
\$	<i>SL</i>	135.97	
\$	<i>SL</i>	44.99	
\$	<i>SL</i>	43.61	} X
\$	<i>11</i>	777.52	
\$	<i>11</i>	225.95	
\$	<i>11</i>	225.95	
\$	<i>11</i>	1,471.77	
\$	<i>SL</i>	404.56	
\$	<i>SL</i>	552.55	}
\$	<i>SL</i>	986.70	
\$	<i>11</i>	2,872.68	

\$	9,957.60
10% \$	995.76
\$	8,961.84

Special Nett

1 1SET PARKING AID	\$	<i>SL</i>	700.00	X
2 1SET REAR BUMPER CLIP	\$	<i>nn</i>	66.00	X
3 1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	X

Trans-cab Auto Services Pte Ltd**AAD1901-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 206H

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i>	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>nn</i>	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	X
12	1 WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	X

TOTAL \$ 1,244.82**TOTAL PARTS \$ 10,206.66****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>2200</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>1500</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1901-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 206H

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 26,578.50****(LUMP SUM)****Repair Days**~~10 DAYS~~*1 1/2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: