

INS. CASE OWNER:

Irene.

CC 6, CTI 1900 0425, Kpa3 n2

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KSL

DOI:

21/19

Date / Time:

21/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

62 1296 L

Name of Insured:

TOP 1AS1E PL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

29/12/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Muen King Wong

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SNM-1902001702

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

747



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SKG 6340 - NCI/NCI 301 3445 / 11 0663 ; 00A 14/9/13
62 1296 L - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

3370.50

Loss of Rental (LOR):

S\$

50.00

(5 days)

x 11W

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

3877.95

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3877.95

Name 1:

T&T Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

ASS. REC. BY:

REF: CTZ/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

8/11

File pass to Car

US \$3150

Cred # 3167.73

5067

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - R.S. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI19000425/Kpa3

Date: 10.01.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKG 634D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.01.2019 at the premises of M/s T&T Auto Services Pte Ltd - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	6,317.73
Revised Estimate Amount	: S\$	3,342.05
"Check" Items Amount	: S\$	634.35
Total (Including Check Items)	: S\$	3,976.40
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 2095E

Vehicle Details

Vehicle No.: SKG634D
Vehicle to be Exported: No
Intended Deregistration Date: 02 Jan 2019
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Black
Manufacturing Year: 2012
Engine No.: 1ZRX214325
Chassis No.: MR053REE104143336
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$14,885.00
Original Registration Date: 27 Jul 2012
First Registration Date: 27 Jul 2012
Transfer Count: 0
Actual ARF Paid: \$14,885.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Jul 2022
PARF Rebate Amount: \$9,675.00

Intended COE Rebate Details

COE Expiry Date: 26 Jul 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$68,656.00
COE Rebate Amount: \$24,472.00
Total Rebate Amount: \$34,147.00

The information contained herein is correct as at 02 Jan 2019

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7108000E



Name
TAN HENG SOON
(CHEN XINGSHUN)
陈兴顺

Race
CHINESE

Date of Birth
07-03-1971

Country of Birth
SINGAPORE

Sex
M






REPUBLIC OF SINGAPORE **DRIVING LICENCE**

License Number: **S7108000E**

Name:
TAN HENG SOON
(CHEN XINGSHUN)

Birth Date: **07 Mar 1971**
 Issue Date: **30 Jul 2003**

2530870



NRIC No. **S7108000E**



Blood Group: **B+** Date of Issue: **23-11-1994**

Address
APT BLK 357 ADMIRALTY DRIVE #09-172
SINGAPORE 750357
NRIC No. S7108000E

Date: **04/06/2011** (R) No: **6836149**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms


PASS DATE
16 Sep 1989

NP 428A

TO OPEN

CRACK

Licence No: **S7108000E**



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5096360427

Cover : drive CLASSIC

- | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SKG634D |
| Chassis Number | : MR053REE104143336 |
| 2. Name of Policyholder | : KEE HUI TIANG |
| 3. Effective Date of Insurance | : 05 Dec 2017 |
| 4. Expiry Date of Insurance | : 26 Jan 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: KEE HUI TIANG
NAMED DRIVER (1)	: TAN HENG SOON
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: DBS BANK LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)


Agency : TELESales-DIRECT MARKETING (0000601661)
 Date of Issue : 01 Dec 2017 14:43 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

KEE HUI TIANG
BLK 220 SERANGOON AVE 4
#09-234
SINGAPORE 550220

Not Noted
Clay & ?
Resurvey After Paint
5 days

ESTIMATE

DATE : 07/01/2019
VEHICLE NO : SKG 634 D
MAKE/MODEL : Toyota Altis
ACC DATE : 29/12/2018

PARTICULAR AMOUNT SS

LIST ITEMS:				
1	1	BOOTLID		<i>By</i> 758.00 ✓
2	1	BOOTLID TOP LOCK		<i>Del</i> 85.10 ✓
3	1	BOOTLID LOWER LOCK		<i>R</i> 43.40 X
4	1	BOOTLID WEATHERSTRIP		<i>Del/Dit</i> 78.50 <i>50% in</i>
5	1	BOOTLID OUTER GARNISH		<i>CM</i> 256.00 ✓
6	1	BOOTLID LOGO		<i>Mr</i> 38.50 ✓
7	1	BOOTLID EMBLEM - I.6		<i>Mr</i> 31.60 ✓
8	1	BOOTLID EMBLEM - E		<i>Mr</i> 30.50 ✓
9	1	BOOTLID EMBLEM - VVTI		<i>Mr</i> 36.50 ✓
10	1	BOOTLID EMBLEM - COROLLA		<i>Mr</i> 47.40 ✓
11	1	BOOTLID EMBLEM - ALTIS		<i>Mr</i> 45.20 ✓
12	2	BOOTLID REFLECTOR	<i>n/s</i> 179.90	<i>ols ?</i> 359.80
13	1	REAR BUMPER		<i>Br</i> 475.80 ✓
14	2	REAR BUMPER BRACKET	57.20	114.40 7
15	2	REAR BUMPER SIDE RETAINER	28.90	<i>sn</i> 57.80 X
16	2	REAR TAIL LAMP	<i>ols</i> 285.80	571.60 <i>LT</i>
17	1	REAR END PANEL		438.90 ?
18	1	REAR END PANEL TOP GARNISH		112.60 7
19	1	REAR FLOOR PANEL TOP BOARD		<i>sn</i> 148.70 X
				3,730.30
Less Discount:			25%	932.58
				2,797.73

SPECIAL NETT ITEMS:

- 1 REAR NUMBER PLATE
- 10 REAR BUMPER CLIP
- 2 REAR TAIL LAMP CLIP
- 2 REAR END PANEL TOP GARNISH CLIP
- 1 REAR REVERSE SENSOR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<i>Del</i>	50.00	<i>45%</i>
<i>Mr</i>	50.00	✓
<i>nn</i>	10.00	X
<i>Mr</i>	10.00	✓
<i>Shan</i>	350.00	<i>200%</i>
		470.00

LABOUR CHARGES:

- 1 TO CHECK WIRING
- 2 TO TUFF KOTE
- 5 TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
- 6 TO REMOVE/REFIX REVERSE SENSOR
- 7 TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
- 8 TO SPRAY PAINTING ON AFFECTED AREA

50.00	<i>20%</i>
250.00	<i>60%</i>
150.00	<i>60%</i>
100.00	<i>50%</i>
1,300.00	<i>60%</i>
1,200.00	<i>60%</i>
3,050.00	

GRAND TOTAL

6,317.73

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

KEE HUI TIANG
BLK 220 SERANGOON AVE 4
#09-234
SINGAPORE 550220

Not Notion
Call by @3150h
Return After Point
5 days

ESTIMATE

DATE : 07/01/2019
VEHICLE NO : SKG 634 D
MAKE/MODEL : Toyota Altis
ACC DATE : 29/12/2018

PARTICULAR AMOUNT S\$

LIST ITEMS:				
1	1	BOOTLID	Bt	758.00 ✓
2	1	BOOTLID TOP LOCK	nd	85.10 ✓
3	1	BOOTLID LOWER LOCK	n	43.40 x
4	1	BOOTLID WEATHERSTRIP	nd/nr	78.50 50.00 3P-255n
5	1	BOOTLID OUTER GARNISH	cm	256.00 ✓
6	1	BOOTLID LOGO	nr	38.50 ✓
7	1	BOOTLID EMBLEM - 1.6	nr	31.60 ✓
8	1	BOOTLID EMBLEM - E	nr	30.50 ✓
9	1	BOOTLID EMBLEM - VVTI	nr	36.50 ✓
10	1	BOOTLID EMBLEM - COROLLA	nr	47.40 ✓
11	1	BOOTLID EMBLEM - ALTIS	nr	45.20 ✓
12	2	BOOTLID REFLECTOR	n/12 x	179.90 o/s 2A 359.80 ✓
13	1	REAR BUMPER	Bu	475.80 ✓
14	2	REAR BUMPER BRACKET	o/1nd	57.20 114.40 2x
15	2	REAR BUMPER SIDE RETAINER	o/1nd	28.90 57.80 x
16	2	REAR TAIL LAMP	o/1nd	285.80 571.60 4x
17	1	REAR END PANEL	Bt	438.90 ✓
18	1	REAR END PANEL TOP GARNISH	ny Dis	112.60 ✓
19	1	REAR FLOOR PANEL TOP BOARD	nr	148.70 x
				3,730.30
Less Discount:			25%	932.58
				2,797.73

SPECIAL NETT ITEMS:	
1	1 REAR NUMBER PLATE
2	10 REAR BUMPER CLIP
3	2 REAR TAIL LAMP CLIP
4	2 REAR END PANEL TOP GARNISH CLIP
5	1 REAR REVERSE SENSOR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

nd	50.00	45.00
nr	50.00	✓
nr	10.00	x
nr	10.00	✓
shar	350.00	200.00
		470.00

LABOUR CHARGES:	
1	TO CHECK WIRING
2	TO TUFF KOTE
5	TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
6	TO REMOVE/REFIX REVERSE SENSOR
7	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
8	TO SPRAY PAINTING ON AFFECTED AREA

	50.00	20.00
	250.00	60.00
	150.00	60.00
	100.00	50.00
	1,300.00	600.00
	1,200.00	640.00
		3,050.00

GRAND TOTAL 6,317.73

Mei Kwan (LKKAuto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 28 January, 2019 9:18 AM
To: Mei Kwan (LKKAuto)
Cc: Mei Kwan (LKKAuto)
Subject: CTP REF NO. SNM19D200117C02 - Direct Settlement - Accident Involving GZ1296L (OI : CTI - TBA) and SKG634D (TP : LKK REF - CC6/CTI19000425/Kpa3) on 29/12/2018
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf; TP GIA REPORT.pdf; GZ1296L.pdf
Importance: High
Categories: HMK

WITHOUT PREJUDICE

Dear Mei Kwan,

We refer to the above matter and your email below.

We enclosed herewith our Insured's GIA Report for your attention.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 2 February 2019 2:35 PM
To: 'Claims Dept of CTI'
Cc: Irene Tay; Admin A
Subject: <Seek Mandate> Direct Settlement - Accident Involving GZ1296L (OI : CTI - SNM19D200117C02) and SKG634D (TP : LKK REF - CC6/CTI19000425/Kpa3) on 29/12/2018
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos 1.pdf; LKK Resurvey Photos 2.pdf; TP LOD-SKG634D.pdf

Your ref : **SNM19D200117C02**
Our ref : CC6/CTI19000425/Kpa3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GZ1296L(OI) & SKG634D(TP) ON 29/12/2018

We refer to the above matter.

This is a head-to-rear collision. Liability is not in our insured driver's favour.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer " **T&T AUTO SERVICES PTE LTD**" at **\$3,877.95(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 6,759.96	\$ 3,370.50
2. Loss of Rental (5days x \$180.00)	\$ 900.00	\$ 500.00 (5days x \$100.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 7,667.41	<u>\$ 3,877.95</u>

**05 days recommendation for repair

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 23 January 2019 2:24 PM
To: claimsdept@sg.cntaiping.com
Cc: irene.tay@sg.cntaiping.com; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 1 March 2019 3:23 PM
To: 'tntautoservices@gmail.com'
Cc: Admin A
Subject: RE: Accident Involving GZ1296L / SKG634D on 29/12/2018 *LKK REF: CC6/CTI19000425/Kpa3

Without Prejudice

Dear Sirs/Mdm,

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 3,370.50
2. Loss of Rental (5days x \$100.00)	\$ 500.00
3. LTA/ GIA Search Fee	\$ 7.45
TOTAL	<u>\$ 3,877.95</u>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 30 January 2019 9:17 AM
To: 'tntautoservices@gmail.com' <tntautoservices@gmail.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Accident Involving GZ1296L / SKG634D on 29/12/2018 *LKK REF: CC6/CTI19000425/Kpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Our insured had reported the accident. Attached is a copy of our insured's report for your easy reference.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19000425/Kpa3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-03-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 1296L	Veh. Inspected	SKG 634D
Policy No.	DMCVSN3038471800	Coverage (\$)	0.00
Claim No.	SNM19D200117C02	Excess (\$)	0.00
Assign From		Assign Date	07/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	MR053REE104143336	Colour	METALLIC BLACK
Odometer	263165	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	BRIDGESTONE	8 mm
L/H Front Tyre	195/65 R15	BRIDGESTONE	8 mm
R/H Rear Tyre	195/65 R15	BRIDGESTONE	8 mm
L/H Rear Tyre	195/65 R15	BRIDGESTONE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/12/2018	Inspection Date	07/01/2019
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 634D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	BENT	758.00	758.00
1	BOOTLID TOP LOCK	DENTED	85.10	85.10
1	BOOTLID LOWER LOCK	TO REPAIR SEE LABOUR	43.40	-
1	BOOTLID OUTER GARNISH	CRACKED	256.00	256.00
1	BOOTLID LOGO	NECESSARY	38.50	38.50
1	BOOTLID EMBLEM -1.6	NECESSARY	31.60	31.60
1	BOOTLID EMBLEM -E	NECESSARY	30.50	30.50
1	BOOTLID EMBLEM -VVTI	NECESSARY	36.50	36.50
1	BOOTLID EMBLEM -COROLLA	NECESSARY	47.40	47.40
1	BOOTLID EMBLEM -ALTIS	NECESSARY	45.20	45.20
2	BOOTLID REFLECTOR @\$179.90	N/S SERVICEABLE / O/S CUT	359.80	179.90
1	REAR BUMPER	BUCKLED	475.80	475.80
2	REAR BUMPER BRACKET @\$57.20	O/S DENTED	114.40	57.20
2	REAR BUMPER SIDE RETAINER @\$28.90	SERVICEABLE	57.80	-
2	REAR TAIL LAMP @\$285.80	O/S CUT	571.60	285.80
1	REAR END PANEL	BENT	438.90	438.90
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	112.60	112.60
1	REAR FLOOR PANEL TOP BOARD	SERVICEABLE	148.70	-
	LESS 25% DISCOUNT		-912.95	-719.75
			2,738.85	2,159.25
1	BOOTLID WEATHERSTRIP (50%) (SN)	DENTED / DISTORTED	78.50	39.25
	LESS 25% DISCOUNT		-19.63	-
			58.87	39.25
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	DENTED	50.00	45.00
10	REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
2	REAR TAIL LAMP CLIP (SN)	NOT NECESSARY	10.00	-

Report Ref No. CC6/CTI19000425/Kpa3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	10.00	10.00
1	REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
			470.00	305.00
	LABOUR			
	TO CHECK WIRING .		50.00	20.00
	TO TUFF KOTE.		250.00	60.00
	TO REMOVE /REFIX UPHOLSTERY ,CUSHION SEAT & ROOF LINING.		150.00	60.00
	TO REMOVE/REFIX REVERSE SENSOR .		100.00	50.00
	TO PANEL BEATING ,REMOVING & REPLACING OF NEW PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID LOWER LOCK .		1,300.00	600.00
	TO SPRAY PAINTING ON AFFECTED AREA.		1,200.00	640.00
			3,050.00	1,430.00
GRAND TOTAL			6,317.72	3,933.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,150.00

Report Ref No. CC6/CT19000425/Kpa3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.