



ATAN MOTORING SUPPLY PTE LTD

Blk 3006 Ubi Road 1, #01-368/370 Singapore 408700.
Tel: 67431351 Fax: 67432719 Email: annasimsl@yahoo.com.sg
Business Registration No. A03552/1989W

4 January 2019

India Int'l Insurance Pte Ltd
Motor Claim Department
64 Cecil Streer #04/05
IOB Bldg
Singapore 049711

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FY9021C - Estimate Bill (Honda CB400L)

1 pc	Front Mudguard	/ Cust .	165.00
1 pc	Right Signal Light Front		65.00
1 pc	Head Lamp Complete	/ Cust BR	330.00
1 pc	Right Balancer	/ Cust	25.00
1 pc	Handle Bar	/ BT.	180.00
1 set	Meter	/ P/S	850.00
1 pc	Brake Lever	/ Cust	55.00
1 pc	Right Front Footrest	/ Cust .	50.00
1 pc	Exhaust Pipe	/ Cust	750.00
1 pc	Clutch Cover	/ Cust	360.00
1 pc	Clutch Gasket	/ WCL.	35.00
1 pc	Rear Mudguard	/ RL	185.00
1 pc	Tail Lamp Cover	/ BR	220.00
1 pc	Rear Rim	/ BT.	780.00
1 pc	Rear Tyre	/ TV	195.00
1 pc	Rear Spoket	/ BT	160.00
1 pc	Rear Brake Disc	/ BT.	280.00
1 pc	Chain Adjuster	/ BT.	35.00
1 pc	Left Signal Light Rear	/ BT. BR.	75.00
1 pc	Number Plate	/ Cust .	18.00
1 set	Box Bracket	/ BT	210.00
1 pc	Top Box	/ P/S	220.00
3 litre	Engine Oil	/ WCL @22.00	66.00
1 set	Press Fork		280.00
	2 Way Transport to Idac to workshop		70.00
	Labour Charges		380.00
	Sub Total		6039.00
	Add GST 7%		422.73
	Total		6461.73

3 Days. spray painting - 150
 Lumpsum Repair.
 After repair photos.
 Gmo@iap - 82880282
 07/1/2019

120.
60.
280.
5388.1
29% 4300
Total U/S \$4300.