

ASS. REC. BY:

REF:

CS/EGIL19000434/Ulsbnz

Special Instruction:

Surveyor

Marius.

ASSIGNMENT (Office)

From (Person):

Steve Lim

of

EGL

Date/Time:

09/01/2019 11:14am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 9577T

Insured:

GBF 8957G

at Workshop m/s

Mh Solution

Tel:

of

23 Kaki Bukit Ave 4 # 02-03B

Policy No:

Claim No:

GBF 8957G

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

09/01/2019 11:23am

Person Contacted:

Shawn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBE 9577T - NA / CTL19000369/v3

D.O.A. 04/01/2019

GBF 8957G - x

10/01/19

@ 11:45 a.m. revised PA to Steve via email.

(08/11/13) wef

REF:

ER1/

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: GBC 9577Tat Workshop m/s MG

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
☒	☐

Bal. or Market Value: 45

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBC 9577T Rr Regn: 5116

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or LAMake: FIAT DOBLO CARGO 1598Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 88755 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 2FA26300006C33917

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ChromoFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 4/1/19 D.O.I. 8/1/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Ree-

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/1/19 LT 18554
confirmed 2/5 \$8000 with sharon.

10/01/18 Confirmed HS \$2,000/- @ 4 days with Marcus
(\$8,148.52 Red - 51%)

RECEIVED 14 JAN 2019

Date/Time, File Pass to?

14/01/19☐ : Prel. ReportDays Of Repair: 41) Typical☒ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

350

Report Format :

Lump Sum / I.B.I. (\$ 8,000/- HS)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 10 January 2019

Our Ref: CS/EGI19000434/Usb

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. GBE 9577T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/01/2019 at the premises of M/s MG Solution Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 16,148.52
Revised Estimate Amount	: S\$ 10,026.32
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 4 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Steve Lim <steve.lim@ergo.com.sg>
Sent: Monday, 14 January 2019 10:41 AM
To: Shirley Hiew (LKK Auto)
Cc: Siti Rahman; ERGO Insurance Pte. Ltd. (Claims Department); assignments; Admin-D (LKKAuto)
Subject: RE: GBE 9577T -(PRE-INSPECTION) ; YOUR REF : GBF8957G -DOA ON 04/01/2019

Hi Shirley,

Kindly quote our insured's vehicle number as our claim number

Steve Lim
Manager - Claims

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9197
Fax.: +65 6829 9247
steve.lim@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, 10 January, 2019 11:45 AM
To: Steve Lim
Cc: Siti Rahman; ERGO Insurance Pte. Ltd. (Claims Department); assignments; Admin-D (LKKAuto)
Subject: RE: GBE 9577T -(PRE-INSPECTION) ; YOUR REF : GBF8957G -DOA ON 04/01/2019

Dear Steve,

Enclosed preliminary revised of vehicle GBE 9577T.

Kindly provide us claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 10 January 2019 11:45 AM
To: 'Steve Lim'
Cc: 'Siti Rahman'; 'ERGO Insurance Pte. Ltd. (Claims Department)'; 'assignments'; 'Admin-D (LKKAuto)'
Subject: RE: GBE 9577T -(PRE-INSPECTION) ; YOUR REF : GBF8957G -DOA ON 04/01/2019
Attachments: GBE 9577T - Preli Advise -.pdf

Dear Steve,

Enclosed preliminary revised of vehicle GBE 9577T.

Kindly provide us claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 9 January 2019 11:17 AM
To: 'Steve Lim' <steve.lim@ergo.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Siti Rahman' <Siti.Rahman@ergo.com.sg>; 'ERGO Insurance Pte. Ltd. (Claims Department)' <claims@ergo.com.sg>; assignments <assignments@lkkauto.com>
Subject: RE: GBE 9577T -(PRE-INSPECTION) ; YOUR REF : GBF8957G -DOA ON 04/01/2019

Dear Steve,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steve Lim [mailto:steve.lim@ergo.com.sg]
Sent: Wednesday, 9 January, 2019 11:14 AM
To: SUR (sur@lkkauto.com) <sur@lkkauto.com>; Admin-D (LKKAuto) (admin-d@lkkauto.com) <admin-d@lkkauto.com>
Cc: Siti Rahman <Siti.Rahman@ergo.com.sg>; ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Subject: FW: GBE 9577T -(PRE-INSPECTION) ; YOUR REF : GBF8957G -DOA ON 04/01/2019

Hi LKK,

Catherine Chong (LKK Auto)

From: Steve Lim <steve.lim@ergo.com.sg>
Sent: Wednesday, 9 January, 2019 11:14 AM
To: SUR (sur@lkkauto.com); Admin-D (LKKAuto) (admin-d@lkkauto.com)
Cc: Siti Rahman; ERGO Insurance Pte. Ltd. (Claims Department)
Subject: FW: GBE 9577T -(PRE-INSPECTION) ; YOUR REF : GBF8957G -DOA ON 04/01/2019
Attachments: GBE 9577T -(PRE-INSPECTION) ; YOUR RF GBF8957G -DOA ON 04012019.pdf, OI report.pdf

Hi LKK,

Please attend attached inspection.

Steve Lim
Manager - Claims

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9197
Fax: +65 6829 9247
steve.lim@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference. ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Sharon [mailto:mg3solution@gmail.com]
Sent: Wednesday, 9 January, 2019 11:11 AM
To: ERGO Insurance Pte. Ltd. (Claims Department); Steve Lim
Subject: FW: GBE 9577T -(PRE-INSPECTION) ; YOUR REF : GBF8957G -DOA ON 04/01/2019

Dear Steve,

As spoken on our tele conversation, please find resend attached PRI for your onward action .
Thank You.

Best Regards,

Sharon Chia

MG Solution Pte Ltd

No 23 Kaki Bukit Avenue 4

Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

From: Yan [mailto:mg3solution@gmail.com]

Sent: Monday, 7 January, 2019 6:04 PM

To: 'ERGO-HQ' <claims@ergo.com.sg>

Subject: GBE 9577T -(PRE-INSPECTION) ; YOUR REF : GBF8957G -DOA ON 04/01/2019

Dear Person In Charge,

Please refer to attach file and arrange for pre-inspection.

we prefer our single joint expert as below:

ADRIAN LING WAI PING	LKK AUTO CONSULTANTS PTE LTD
----------------------	------------------------------

Thank You.

Best Regards,

Jamie Yan

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing)

#02-03B Vicom Inspection Centre

Singapore 415933

Tel : 6744 4165

Fax : 6744 4604

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

500+ dealers
competed to
buy my car!



► Sell ur Car for More Cash
► Highest Price or Get \$100 Free
► Get Paid Now, Handover Later

SELL YOUR CAR

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Honda Vezel 1.5X A.



Low Mileage And Excellent
Condition With New Interior
Direct Owner - See Ad

PRIME MOT
(CHENG YONG CREDIT ENTERPRISES)
With over 200 units of veh
to choose from, ranging fr
all European to Japanese

Browse by Category

Sort by Date Posted

12 vehicles

fiat doblo

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	fiat doblo		Any	Any	2016	Any	Any	
		Fiat Doblo Cargo Maxi 1.6A	\$48,800	\$6,630 /yr	20-May-2016	1,598 cc	-	
		Fuel Type: Diesel						
		Near New Condition, Ready To Drive Away Anytime! No Repairs Required! With 2 Digit Number Plate And Aluminium Chequered Plate D Now!						
		Yes Motoring						
		Posted: 08-Jan-2019 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat						
		Fiat Doblo Cargo Maxi 1.6A	\$49,800	\$6,310 /yr	30-Nov-2016	1,598 cc	37,000 km	
		Fuel Type: Diesel						
		Selling Cheap Yet Negotiable.1 Owner! Fully Serviced And Maintained By Motorviva. Low Mileage Done At 37000Km Only. Like New! We By Previous Owner! For Peace Of Mind Buying With Road Link...						
		Roadlink Auto Pte Ltd						
		Posted: 08-Jan-2019 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat						
		Fiat Doblo Cargo Maxi 1.6A	\$68,888	\$8,860 /yr	17-Oct-2016	1,598 cc	-	
		Fuel Type: Diesel						
		5 Years And 160000km Warranty By Motorviva Pte Ltd.						
		Posted: 06-Jan-2019 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat						
		Fiat Doblo Cargo Maxi 1.6M	\$42,800	\$5,930 /yr	28-Mar-2016	1,598 cc	80,260 km	
		Fuel Type: Diesel						
		1 Owner, Still Under Agent Warranty 3 Years Or 100K Km Whichever Come First. Buy With Peace Of Mind, Low Depreciation, Cheaper T Van, Please Call For Viewing.						
		Posted: 04-Jan-2019 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat						
		Fiat Doblo to be sold in the US as Ram						
		Fiat will market its Doblo van under the Ram badge in the US and Canada, as part of the alliance agreement between Fiat and Chrysler						
		Read this article						

Fiat Doblo Cargo Maxi 1.6A **\$48,800** **\$6,530 /yr** **29-Jun-2016** **1,598 cc**

e: Diesel

Compare

1 New One When This Vehicle Condition Is Exactly Like New. Well Maintain Exterior And Interior.Fully Service By Agent Since [

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5940E

Vehicle Details

Vehicle No.: GBE9577T

Vehicle to be Exported: No

Intended Deregistration Date: 09 Jan 2019

Vehicle Make: FIAT

Vehicle Model: DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE

Primary Colour: Grey

Manufacturing Year: 2016

Engine No.: 263A50007592334

Chassis No.: ZFA26300006C33917

Maximum Power Output: -

Open Market Value: \$19,306.00

Original Registration Date: 04 May 2016

First Registration Date: 04 May 2016

Transfer Count: 0

Actual ARF Paid: \$966.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 03 May 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$39,028.00

COE Rebate Amount: \$28,554.00

Total Rebate Amount: \$28,554.00

The information contained herein is correct as at 09 Jan 2019

OK

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: ERGO	DATE	: 07/01/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: GBE9577T		
MODEL	: FIAT DOBLO 1.3JTD		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 4-Jan-19
		TIME	: 15:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR LH <i>Body</i>	1	\$ 2,355.50	\$ 2,355.50
2	REAR DOOR EMBLEM "DOBLO" <i>all</i>	1	\$ 80.20	\$ 80.20
3	REAR DOOR EMBLEM "MAXI" <i>all</i>	1	\$ 62.50	\$ 62.50
4	REAR DOOR HINGE LH <i>lower part</i>	2	\$ 115.20	\$ 230.40
5	REAR DOOR CHECKER LH <i>17</i>	1	\$ 160.00	\$ 160.00
6	REAR DOOR LOCK LH <i>1.7</i>	1	\$ 350.60	\$ 350.60
7	REAR DOOR INNER BOARD <i>Di/GRA</i>	1	\$ 288.70	\$ 288.70
8	REAR DOOR OUTER HANDLE <i>17</i>	1	\$ 115.20	\$ 115.20
9	REAR DOOR WEATHERSTRIP BIG <i>121</i>	1	\$ 244.60	\$ 244.60
10	REAR DOOR GLASS MOULDING LH <i>NS</i>	1	\$ 234.50	\$ 234.50
11	REAR DOOR NUMBER PLATE GARNISH <i>34</i>	1	\$ 310.50	\$ 310.50
12	REAR DOOR NUMBER PLATE LAMP <i>17</i>	1	\$ 135.00	\$ 135.00
13	REAR DOOR KEY LOCK <i>17</i>	1	\$ 223.50	\$ 223.50
14	REAR DOOR RH <i>1844.71</i>	1	\$ 2,355.50	\$ 2,355.50
15	REAR DOOR WEATHERSTRIP RH <i>(17)</i>	1	\$ 133.50	\$ 133.50
16	REAR DOOR GLASS MOULDING RH <i>NS</i>	1	\$ 234.50	\$ 234.50
17	REAR DOOR FIAT LOGO <i>139.15</i>	1	\$ 180.50	\$ 180.50
18	REAR DOOR FIAT LOGO GARNISH <i>17</i>	1	\$ 155.60	\$ 155.60

19	REAR DOOR EMBLEM "PROFESSIONAL" <i>nll</i>	1	\$ 80.00	\$ 80.00	✓
20	REAR DOOR EMBLEM "90" <i>nll</i>	1	\$ 52.50	\$ 52.50	✓
21	REAR DOOR EMBLEM "MULTISET" <i>multiset nll</i>	1	\$ 52.50	\$ 52.50	✓
22	TAIL LAMP RH <i>cm</i>	1	\$ 422.10	\$ 422.10	✓
23	TAIL LAMP PANEL <i>n</i>	1	\$ 166.50	\$ 166.50	X
24	REAR BUMPER <i>734.34 100/22</i>	1	\$ 833.90	\$ 833.90	✓
25	REAR BUMPER LOWER LID <i>complete</i>	1	\$ 455.20	\$ 455.20	X
26	REAR BUMPER SIDE RETAINER <i>n/sat</i>	2	\$ 75.40	\$ 150.80	IPC
27	REAR BUMPER REFLECTOR <i>65 n/s cm</i>	2	\$ 80.10	\$ 160.20	IPC
28	REAR BUMPER REINFORCEMENT <i>520.92 sat</i>	1	\$ 680.20	\$ 680.20	✓
29	REAR BUMPER REINFORCEMENT BRACKET <i>n/s sat</i>	2	\$ 88.60	\$ 177.20	IPC
30	REAR END PANEL <i>n</i>	1	\$ 780.90	\$ 780.90	X
31	REAR END PANEL TOP GARNISH <i>tw</i>	1	\$ 230.00	\$ 230.00	?

TOTAL PRICE \$ 12,092.80
 LESS 10% \$ 1,209.28
 SUB TOTAL PRICE \$ 10,883.52

7895.92
 7106.32

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>sat</i>	1	\$ 50.00	\$ 50.00	40
2	REAR DOOR '6PAX' STICKERS <i>nll</i>	1	\$ 45.00	\$ 45.00	10
3	REAR DOOR '70KM/H' STICKERS <i>nll</i>	1	\$ 40.00	\$ 40.00	10
4	REAR DOOR GLASS SEALANT LH <i>nll</i>	1	\$ 80.00	\$ 80.00	40
5	REAR DOOR GLASS SEALANT RH <i>nll</i>	1	\$ 80.00	\$ 80.00	40
6	REAR BUMPER CLIP (SET) <i>nll</i>	1	\$ 30.00	\$ 30.00	✓
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>n 1</i>	1	\$ 20.00	\$ 20.00	X
8	REAR END PANEL INSULATION SEAL <i>n 1</i>	1	\$ 120.00	\$ 120.00	X
9	REVERSE SENSOR <i>shd</i>	1	\$ 220.00	\$ 220.00	200
10	REVERSE CAMERA <i>shd</i>	1	\$ 350.00	\$ 350.00	300

TOTAL \$ 1,035.00

670

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	1000	
3	TUFF COAT	\$ 150.00	60	
4	WIRING CHECK	\$ 80.00	20	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50	
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 120.00		
8	TRANSFER REAR DOOR MECHANISM LH	\$ 180.00	60	

10	REMOVE AND REFIX REAR DOOR WINDSCREEN LH	\$ 120.00	100	
8	TRANSFER REAR DOOR MECHANISM RH	\$ 180.00	60	
10	REMOVE AND REFIX REAR DOOR WINDSCREEN RH	\$ 120.00	100	
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	11X	

TOTAL

\$4,230.00

2250

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,918.52
TOTAL LABOUR COST : \$ 4,230.00
TOTAL REPAIR COST : \$ 16,148.52

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Not Ackd
n/bk
8/1/19
L/S \$8000/-
Wh photo After rep-
4 by.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To survey damaged part(s) during resurvey
- Photo must be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed or is subject to final approval from Insurance Co

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI19000434/Usbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 14-01-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 8957G	Veh. Inspected	GBE 9577T	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBF 8957G	Excess (\$)	0.00	
Assign From	STEVE LIM	Assign Date	09/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZFA26300006C33917	Colour	GREY	
Odometer	88755	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	CHRONO	6 mm	
L/H Front Tyre	195/60 R16	CHRONO	6 mm	
R/H Rear Tyre	195/60 R16	CHRONO	6 mm	
L/H Rear Tyre	195/60 R16	CHRONO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/01/2019	Inspection Date	09/01/2019	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9577T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR LH	BADLY DENTED	2,355.50	2,355.50
1	REAR DOOR EMBLEM "DOBLO"	NECESSARY	80.20	80.20
1	REAR DOOR EMBLEM "MAXI"	NECESSARY	62.50	62.50
2	REAR DOOR HINGE LH @\$115.20	LOWER BENT	230.40	115.20
1	REAR DOOR CHECKER LH	NOT NECESSARY	160.00	-
1	REAR DOOR LOCK LH	NOT NECESSARY	350.60	-
1	REAR DOOR INNER BOARD	DEFORMED / CRACKED	288.70	288.70
1	REAR DOOR OUTER HANDLE	NOT NECESSARY	115.20	-
1	REAR DOOR WEATHERSTRIP BIG	TWISTED	244.60	244.60
1	REAR DOOR GLASS MOULDING LH	NO SUCH PARTS	234.50	-
1	REAR DOOR NUMBER PLATE GARNISH	BENT	310.50	310.50
1	REAR DOOR NUMBER PLATE LAMP	NOT NECESSARY	135.00	-
1	REAR DOOR KEY LOCK	NOT NECESSARY	223.50	-
1	REAR DOOR RH	DENTED	2,355.50	1,844.71
1	REAR DOOR WEATHERSTRIP RH	CUT	133.50	133.50
1	REAR DOOR GLASS MOULDING RH	NO SUCH PARTS	234.50	-
1	REAR DOOR FLAT LOGO	NECESSARY	180.50	139.15
1	REAR DOOR FLAT LOGO GARNISH	NOT NECESSARY	155.60	-
1	REAR DOOR EMBLEM "PROFESSIONAL"	NECESSARY	80.00	80.00
1	REAR DOOR EMBLEM "90"	NECESSARY	52.50	52.50
1	REAR DOOR EMBLEM "MULTIJET"	NECESSARY	52.50	52.50
1	TAIL LAMP RH	CRACKED	422.10	422.10
1	TAIL LAMP PANEL	TO REPAIR SEE LABOUR	166.50	-
1	REAR BUMPER }	DENTED / DEFORMED	833.90	734.34
1	REAR BUMPER LOWER LID }		455.20	-
2	REAR BUMPER SIDE RETAINER @\$75.40	N/S BENT	150.80	75.40
2	REAR BUMPER REFLECTOR @\$80.10	N/S CRACKED	160.20	65.00
1	REAR BUMPER REINFORCEMENT	BENT	680.20	520.92
2	REAR BUMPER REINFORCEMENT BRACKET @\$88.60	N/S BENT	177.20	88.60

Report Ref No. CS/EGI19000434/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	TO REPAIR SEE LABOUR	780.90	-
1	REAR END PANEL TOP GARNISH	TWISTED	230.00	230.00
	LESS 10% DISCOUNT		-1,209.28	-789.59
			10,883.52	7,106.33
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00
1	REAR DOOR "6PAX" STICKERS (SN)	NECESSARY	45.00	10.00
1	REAR DOOR "70KM/H" STICKERS (SN)	NECESSARY	40.00	10.00
1	REAR DOOR GLASS SEALANT LH (SN)	NECESSARY	80.00	40.00
1	REAR DOOR GLASS SEALANT RH (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
1	REVERSE SENSOR (SN)	SHORTED	220.00	200.00
1	REVERSE CAMERA (SN)	SHORTED	350.00	300.00
			1,035.00	670.00
	LABOUR			
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
	PANEL BEATING,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL AND REAR END PANEL.		1,600.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	1,000.00
	TUFF COAT.		150.00	60.00
	WIRING CHECK.		80.00	20.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING. }		120.00	50.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING. }		100.00	-
	TRANSFER REAR DOOR MECHANISM LH.		180.00	60.00
	REMOVE AND REFIX REAR DOOR WINDSCREEN LH.		120.00	100.00
	TRANSFER REAR DOOR MECHANISM RH.		180.00	60.00

Report Ref No. CS/EGI19000434/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REAR DOOR WINDSCREEN RH.		120.00	100.00
			4,230.00	2,250.00
	GRAND TOTAL		16,148.52	10,026.33
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,000.00

Report Ref No. CS/EGI19000434/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.