

Not Authorized
I.B.I
Running B4 paint

84743.60

6 days



ESTIMATE TO REPAIR

VEHICLE NO. : SLR 1865 C
MAKE : HONDA
MODEL : SHUTTLE 1.5G CVT
YEAR : 2017
CHASSIS NO : GK81101702

SURVEYOR NAME	
DATE OF SURVEY	09 JAN 2019
TIME OF SURVEY	

DATE : 5-Jan-19
DATE OF ACCIDENT : 3-Jan-19
THIRD PARTY REF : SJT 1592 C / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			Ry \$	1,150.60
2-pcs	Rear Bumper Retainer		\$ 26.50	\$	53.00
1 pc	Rear Bumper Tow Cover			\$	16.50
1 pc	O/S Rear Bumper Reflector			\$	45.00
1 pc	O/S Rear Bumper Reflector Garnish			\$	45.00
1 pc	Rear End Panel			\$ Ry	560.80
1 pc	Rear End Panel Garnish			\$ Ry	155.50
1 pc	Tailgate			\$ Ry	1,193.00
1 pc	Tailgate Rubber			\$	168.50
1 pc	Tailgate Lock			\$	157.10
1 pc	Tailgate Inner Trim			\$	320.00
1 pc	Tailgate Inner Handle			\$ Ry	25.00
1 pc	Tailgate Centre Emblem			\$ Ry	38.00
1 pc	Tailgate SHUTTLE Emblem			\$ Ry	55.00
1 pc	Rear Windscreen Moulding			\$ Ry	120.60
1 pc	O/S Rear Fender Inner Trim			\$	489.60
	Less 20%		Parts	\$3467.00	\$ 4,593.20
			- 20%	\$693.40	\$ 918.64
1 tube	Rear Windscreen Sealant	S.Nett		\$2773.60	\$ 40.00
1 set	Rear Bumper Sensor	S.Nett		\$	200.00
1 set	Tailgate Sticker	S.Nett	SIN	\$490.00	\$150 380.00
	To putty and spray painting		Labour	\$1480.00	\$ 800.00
	To transfer tailgate fittings				\$ 80.00
	To remove & refix rear windscreen		POP	\$4743.60	\$ 120.00
	To anti-rust				\$ 80.00
	Labour Charges		OG	days	\$ 700.00
TG/RA-					\$ 6,074.56

Lim Tan Motor Pte Ltd

Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

Co Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd.