INS. CASE OWNER	Jum	CC 6 / LOF 1900	0438	UPasy IDAC
* Surveyor.	MApril	DOI: ASSIGN	MENT.	Date/Time: 8/1/9
Pre-assign / CCU / Insured Vehicle No Name of Insured Insured Tel No. Excess Sec II :SS Is driver the owner!	YES (NO)	HP: D.O.A: 31/2019 Nature of Accident:	Claim No. Policy No. Make / Model Place of Acci	dent:
If NO, Driver Nam Driver Tel 1		(V/L: YES)NO)	Insured Liabil	ORT (YES / NO ; TP GIA REPORT: YES / NO lity: % Final ? Yes / No
C1818 2530	₽			
INSRS: WSP. Tel: Liability: RMKS:	INSRS WSP- Tel: Liabiliti RMKS	,	INSRS: WSP: Tel: Linbility: RMKS:	INSRS: WSP: Tel: Liability: RMKS:
Date/ Time	Charles D &	Innan	s.t.	STAGE DATE/PIC
PRELIMINARY ADVICE	DV 5-12  File -> MIC-h  Date/Time:	Sent By:		Non-Reporting ltr (1st):  Non-Reporting ltr (2nd):  Notification ltr (if non-pickup):  Call Ot:  After call ltr to OI:  Documentation Check Livt: Handler Typist  Notification ltr (if non-pickup)  After call ltr to OI:  Authorisation To Act:  Release Voucher:  Final Repair Bill:  Car Rental Invoice:  Towing Invoice  LTA / GIA :  Medical Bill:  PIR:  Mandate/Reject Instruction:  LOD  Payment Breakdown Form:  Post-Repair Photos:
				Others:
FINALIZATION Repair Cost:	Date/Time:	Confirm with: days) Reduction:	%	Confirm by:
FINAL SETTLEMENT Final Liability: Repair Cost: &	Date/Time: 1144	Confirm with SUCON  (Assessed) BOLA S/N No. : V	7,	Email   Call   If NO or B 28, Ass. Lin :
Loss of Rental (LOR): Loss of Use (LOU): Loss of Income (LOI):	55 - W.W (590 x 55 - (5 x	days)		Calvia
LOR only LOU only GIA/LTA Search Medical: Disbursement:	SS Z YS SS — SS —	OR + LOI [Tick only one (e.g. Tow/ Independen		Claim status: Normal/Reject/Private Settle     Report Format:
Legal Cost	ss —	(e.g. 10w/ independe	.,	3) Survey fee: \$72000
Total:	ss 27-47-45	Global Sum SS:		
Payee 1: Payee 2: (Strike if N.A.)	SS 7AVA-V3	Name 2:	her Auto	Engineerry Workshop.
Payee 3: (Smike II N.A.)	22	[Notic 3: ]		

(08/11/13) Well REF:	A16/
ASS. REC. BY: MOVELS . ASS	IGNMENT
	Veh No: GBB 2830 P Yr Regn: 1010 P Type: NLGar / NLCycle / Bug / Veh / Lorry / Taxi / Prime Mover / Truck / Trailer or GM / Make: 7/77 Do 5/5
Bal, or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No  Consistent?: Yes or No  Est. Repairs:  Y days Res.: Yes or No  Lum Sum:  Adays Res.: Yes or No  1960  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT  Date:  Person Contacted:  Date / Time   Action / Instruction  LTA / LCC 39-9-	The U/C / Chassis frame / Body Structure affected due to collision.
Distertione, File Pass to?  1)	Days Of Repair:  Resurvey No. of Trip:  Survey Fee: Transportation:  Site Insp (\$ )S+RSSI  Interview (\$ ) Photos Tech. Invs (\$ ) Others  Weekend (\$ )

LIU'S BROTHER AUTO ENGINEERING WORKSHOP No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

Invoice/Ref No: GBB2530P190103

Custon		No: 53291793] . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com	1	stimate
Name:		sia Pacific Insurance Pte Ltd Claims Department	Date:	07-01-19
		enton Way #07-16	Vehicle No:	GBB2530P
		uilding Singapore 0/9120	Model/Make:	Fiat Doblo Cargo
Item No.		Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear	Bumper 30/De	\$ 627.00	
2	1	Bumper Side A (	\$ 283.70	
3	1	Bumper Side Holder A G Sul	\$ 72.50	
4	1	Bumper Clips 1 set	\$ 50.00	SN -
5		Bumper Reinforcement 324	\$ 475.30	L
	1	Bumper Reflector 3/10	\$ 98.00	
7	1	Bumper Reverse Sensor Shall	\$ 220.00	SN 2005.N
8	1	End Panel	\$ 430.00	J. 2005.A
9	1	Tail Lamp	\$ 388.70	
10	1	Tail Lamp Outer Garnish /M 11	\$ 154.40	21 1
11	1	Tailgate	\$ 2,156.00	X.
12	1	Tailgate "FIAT Logo" Emblem	\$ 87.80	-
13		Tailgate "Doblo" Emblem	s 96.65	
	To che	ck all wiring & electrical component for proper function	\$ 50.00	- 20
	Remov	e and refix rear tailgate components & wiper mechanism e and refix rear bumper reverse sensor	E 121	
	Labor	for Panel Boating Cur. Wold Caminham 8 Pt. 1	\$ 60,00	- 50
	To put	for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs	\$ 680.00	- 480
	Remov	y & spray painting & including touch up paint on accident affecteed are e & reinstall Tailgate Glass to facilitate repairs		- 500
	To app	ly Rust Proofing, rareal ruff continue repairs	\$ 120.00	- × 11
	Co. of the	ly Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	V. 1.

Total Parts & Labour of estimate for damaged vehicle

\$ 6,700.05

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

M/s Liu's Brother Auto Engrg Wks

#### > Back to OneMotoring

#### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1196N

Vehicle Details

Vehicle No.:

GBB2530P

Vehicle to be Exported:

No

Intended Deregistration Date:

07 Jan 2019

Vehicle Make: Vehicle Model: FIAT

DOBLO CARGO 1.9MJTD

Primary Colour:

White

Manufacturing Year: Engine No.:

2007

Chassis No.:

223810005593784

ZFA22300005544049

Maximum Power Output:

Open Market Value: Original Registration Date: \$20,267.00 28 Oct 2008

First Registration Date:

28 Oct 2008

Transfer Count:

1

Actual ARF Paid:

\$1,014.00

Intended PARF Rebate Details PARF Eligibility:

No

PARF Eligibility Expiry Date:

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

30 Sep 2023

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid.

\$15,348.00

COE Rebate Amount:

\$14,520,00

Total Rebate Amount:

\$14,520.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle. The information contained herein is correct as at 07 Jan 2019

OK

#### SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

.

Share

Login



# CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more

flat doblo

Price Range

Depreciation

> 10 year(: \*

Vehicle Type

Map

More Actions

80

Home > Used Cars > Direct Owners > Flat Doblo 1.9JTD (COE till 11/2023)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



## Fiat Doblo 1.9JTD (COE till 11/2023)

Overview **Financial** Accessories Similar Research **Photos** Add to Shortlist Add to Compare Add a Nobe Report Error Car Details Price. \$23,900 Depreciation \$4,920 /yr 0 Reg Date 18-Nov-2008 (4yrs 10mths 8days COE left) Lifespan 17-Nov-2028 Manufactured 2008 0

Mileage

Transmission Auto

Engine Cap 1,910 cc

Curb Weight

Fuel type Diesel

Features

Low Mileage: Genuinely Well-Maintained Condition. New 5 Years COE. Very Responsive Engine. Great For

Any Business Start Up. Feel Free To Enquire.

Accessories

Only \$380 Monthly Installment, Cheaper Than Public Transport, Cosy And Can Do Gogovan Or Lalamovel

Start Your Own Business Today!

COE

\$14,367

1,300 kg

OMV

\$21,051

ARF

\$1,053

Dereg Value

No. of Owners

Type of Veh

Category

COE Car, Direct Owner Sale

\$13,958 as of today (change)

Availability

Available

DIRECT OWNER

Add to Shartlist

Add to Compare

Add a Note

Posted on: 08-Jan-2019 | Last Updated on: 08-Jan-2019

Tags: First Doblo, flat doblo, 2008 First Doblo, 2008 flat doblo, Fiat. Doblo, doblo, Used Fiat.













Seller Information

Contact Person(s)

Contact No.

83373:

Enquiry

0



USEFUL FORMS

Indemnity form

= Receipt

Ownership Transfer

Instructions on how to co consumer deal

Regardless of buying or selli your paperwork, loans & ins.

Compare

Our Ref:

GBB2530P190103

Date: 22/01/2019

Your Ref:

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 Chartis Building Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

#### TRAFFIC ACCIDENT ALONG AIRPORT ROAD FILTER TO EUNOS LINK INVOLVING GBB2530P AND SLQ6839B ON 03/01/2019

We/I, Messers Goldbell Leasing Pte Ltd (Nric / ROC No: 199001196N), the registered owners of m/vehicle — GBB2530P at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my on his recommendation for S\$2,300-00 being the repair for 04 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle SLQ6839B when the same was involved in the aforesaid accident with our/my m/vehicle — GBB2530P.

We/I whereby you are the insurers of m/vehicle SLQ6839B and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – GBB2530P has suffered loss and damage as follows:

100			
(e)	Towing Fee		0-00
(d)	GIA / LTA search fee		7-45
(c)	LOU Fee for 04 days @S\$80-00		320-00
(b)	LOU for pre-repair notice 02 days @\$80-00		160-00
(a)	Cost of repairs	S\$	2,300-00

We/I enclose herewith copies of the supporting documents for vehicle no. GBB2530P as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of M/s Liu's Brother Auto Engineering Workshop. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,

X

The owner of m/vehicle GBB2530P Messers Goldbell Leasing Pte Ltd cc. Liu's Bro Auto Engrg Ws

#### Hsiao Tong (LKKAuto)

From:

Susan Low < liusbro@ymail.com>

Sent:

Wednesday, 3 April 2019 12:29 PM

To:

Hsiao Tong (LKKAuto)

Subject:

Re: Your Ref: GBB2530P190103 \*Our Ref: CC6/LCR19000438/Upa3 [ACCIDENT

INVOLVING SLQ 6839B(AIG) & GBB 2530P ON 03/01/2019]

We hereby confirm acceptance of your offer.

Kindly let us have your discharge for our client's execution and your cheque made in our favour as soon as possible.

Thank,

Best Regards,

Susan Low M/s Liu's Brother Auto Engineering Workshop No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

Tel: 67411730 Fax: 67445746

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

To: Susan Low sbro@ymail.com> Sent: Sunday, 31 March 2019, 12:23

Subject: Your Ref: GBB2530P190103 \*Our Ref: CC6/LCR19000438/Upa3 [ACCIDENT INVOLVING SLQ

6839B(AIG) & GBB 2530P ON 03/01/2019]

Your Ref: GBB2530P190103 Our Ref: CC6/LCR19000438/Upa3 Without Prejudice

Dear Sirs/Madam.

#### ACCIDENT INVOLVING SLQ 6839B(AIG) & GBB 2530P ON 03/01/2019

We refer to the above matter.

We propose settlement as follows: -

Cost of Repair	\$ 2,300.00
2. Loss of Use (5days x \$80.00)	\$ 400.00
3. LTA/ GIA Search Fee	\$ 7.45
Total	\$ 2,707.45

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a> | fax: 6741-4108 Blk 51. Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Saturday, 2 March 2019 9:30 AM

To:

'Insurance LCR SG'; 'Eileen, May Hwee Yap'

Subject:

ACCIDENT INVOLVING SLQ 6839B(AIG) AND GBB 2530P ON 03/01/2019

Your Ref: SLQ 6839B

Our Ref: CC6/LCR19000438/Upa3

Dear Sirs/Madam,

#### ACCIDENT INVOLVING SLQ 6839B(AIG) AND GBB 2530P ON 03/01/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from GBB 2530P against your insurance policy.

Based on the accident report and accident scenario, liability is not in your driver's favour as it is a head-to rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# **AUTHORISATION TO ACT**

## (AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

We / I, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singpore 639142 (address), owner of GBB2530P (vehicle No.) hereby authorize M/s Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and/or rental and/or loss of use ("claim") for my / our vehicle no. GBB2530P that was damaged pursuant to the accident which occurred on 03/01/2019 (date) along Airport Road Filter To Eunos Link (location) involving vehicle no / s SLQ6839B ("the accident").

We / I further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

We / I further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / is concerned.

Dated this 23-4 (day) of April (month) 20 19 (years)

a GOLDBELL FEASING

Ly

Signed by "the third party claimant" Messers Goldbell Leasing Pte Ltd 199001196N GBB2530P



Signed by "the workshop"

# RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, LIU'S BROTHER AUTO ENGINEERING WORKSHOP ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS2,300,00 (Repair Cost), SS400,00 (Loss of Use/Rental), SS7.45 (Disbursement) for vehicle no. GBB 2530P that was damaged pursuant to the accident which occurred on 03/01/2019 (date) along AIRPORT RD FILTER TO EUNOS LINK (location) involving vehicle no/s SLQ 6839B. This is pursuant to the inspection conducted on 08/01/2019 (date) at "the workshop"

We/I confirm that we/I are/am authorized by the owner GOLDBELL LEASING PTE LTD (the third party claimant") of vehicle no. GBB 2530P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to <a href="GBB 2530P">GBB 2530P</a> (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23-4 (day) of April (month) 20 19 (year)

(LKK)) ck

Signed by appointed surveyor

Signed by "the workshop" (with chop) Liu's Brother Auto Engineering Workshop ROB No. 53291793J

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

# LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

Invoice/Ref No: GBB2530P190103

ROB No: 53291793] . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com Final Bill

Name: AIG Asia Pacific Insurance Pte Ltd Date:

Address: Motor Claims Department Vehicle No: GBB2530P

78 Shenton Way #07-16 Model/Make: Fiat Doblo Cargo AIG Building Singapore 079120 1.9 MJTD

Original Revised Item Descriptions Of Parts Quotation / Quotation / No. Cost Of Repair Estimation

Rear Lh Bumper 627.00 Bumper Side 2 283.70 Bumper Side Holder 3 72.50 Bumper Clips 1 set 4 5 50.00 Bumper Reinforcement 5 475.30 6 Bumper Reflector 98.00 S 7 Bumper Reverse Sensor 220.00 8 End Panel 430.00 Tail Lamp Q 388.70 Tail Lamp Outer Garnish 10 154.40 11 Tailgate 2,156,00 5 S Tailgate "FIAT Logo" Emblem 12 87.80 Tailgate "Doblo" Emblem 13 s 96.65 To check all wiring & electrical component for proper function 50.00 Remove and refix rear bumper reverse sensor 60.00 Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs 680.00 To putty & spray painting & including touch up paint on accident affecteed are 600,00 5 Remove & reinstall Tailgate Glass to facilitate repairs 5 120.00 \$ To apply Rust Proofing, reseal tuff-coating treatment on accident area 5 50,00 s

Total Parts & Labour of estimate for damaged vehicle

\$ 6,700.05

Total amount in Lump Sum Basis for repaired vehicle

SDLS: Two Thousand Three Hundred Only



\$ 2,300,00

22-01-10

M/s Liu's Brother Auto Engrg Wks

#### > Back to OneMotoring

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

07 Jan 2019 / 10:39:13

Receipt Date/Time: 07 Jan 2019 / 10:39:13

# Tax Invoice/Receipt

Receipt No.: ITNET-00000-190107-000811

Previous Receipt No.

S/N Item Description/		Amount	GST	Amount
Business Transaction Reference		Before	Amount	After GST
No.		GST (S\$)	(S\$)	
Result of Insurance Enquiry - SLQ6839B As at 03 Jan 2019/18:55:00 Insurance Co. AIG ASIA PACIFIC INSURA 1 Insurance Enquiry - SLQ6839B	NCE PTE. LTD.	001 (00)	(53)	(S\$)
Enquiry Fee 20190107103744460013		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Credit Card: Visa/MasterCard		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

#### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	05 Jan 2019 Edit Reg		08 Jan 2019 00:00 Edit Adj Rpt	5\$2,300.00 Edit Estimat	1 1 1 1 1 1 1	2,300.00 lew Rpt		Pending Report Cancel C	for Survey
	Main	R	eference	Claim	Details		Documents	1	Show All
CLAIM SU	BFOLDER DE	TAILS				[Created	by adjuster]		
Insured:	LCRF PTE	LTD, Co. Reg. N	io.: 201624597K						
Main Claimant:	GOLDBEL	L LEASING PTE I	TD, Co. Reg. No.:	199001196N					
Vehicle Reg No.:	GBB253	0P		Dat	e of Loss:		9 00:00 - :59 hs and <b>6</b> Days Fro	m LTA Reg Da	ite (Man Yr)]
Claim Type:	TP / 694	0702985SG			cy/Cover e No.:	(Comprehe	nsive)		
Vehicle Reg No. (Insured):		SLQ6839B			cy No. imant):	D-18090757MFCV			
				Exc	ess:				
Repairer:	Liu's Brot Kaki Bukit	her Auto Engine 417883 Kaki Buk	ering Workshop (k it - Tel:	aki Bukit) (H	2) Blk 1 K	aki Bt Ave 6	#01-01 Auto Bay	@ Kaki Bt Sin	gapore 41788
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expres	s) - Tel: 65-64	19-3000 .	[Handled b	y Boyogan, Joan	e) Joane Boy	ogan@aig.com
Claimant's Insurer:	MS First (	Capital Insurance	Ltd (HQ) - Tel: 62	222311					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 625	6-3561 [Ha	ndled by F	MARCUS CH	JA] [Final Rp	t due 17/0	1/2019]
ASSOCIAT	ED MAIL RE	CEIVED					Vies	v All Com	pose Case Mail
<ul> <li>AIG_SG</li> </ul>	(09/01/2019)	TP GIA REPORT							
ALL ASSO	CIATED TAS	Ks⊟			J.	View Alt   S	earch Tasks   C	reate New Tasi	c Complete
Due Date No results.	Priority	Type Task	Group Subject	Handler	-	ned By	Completed On	Created	

#### Claim Documents

\*GBB2530P (6940702985SG)

[SLQ6839B]

TP

GOLDBELL LEASING PTE LTD

Jan 3 2019 12:00AM

[LCRF PTE LTD]

[LCRF PTE LTD] Liu's Brother Auto Engineering Workshop (kaki Bukit)

Let	ters/Corresponder	nces	1 per i	page V	V
Νa	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	0	Edit	
Pho	otos/Images		3 per s	page V	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	08/01/19 16:39	Chassis Number	0	Load JPG	V
2	08/01/19 16:39	Odometer Reading	0	Load JPG	V
3	08/01/19 16:40	General View	0	Load JPG	V
4	08/01/19 16:40	General View	0	Load JPG	V
5	08/01/19 16:40	General View	0	Load JPG	V
6	08/01/19 16:40	General View	0	Load JPG	N.
7	08/01/19 16:40	General View	0	Load JPG	V
В	08/01/19 16:40	General View	0	Load JPG	12
9	08/01/19 16:40	General View	0	Load 3PG	V
10	08/01/19 16:40	General View	0	Load JPG	V
11	08/01/19 16:40	General View	0	Load JPG	V
12	08/01/19 16:40	General View	0	Load JPG	V
13	08/01/19 16:40	General View	0	Load JPG	V
14	08/01/19 16:40	General View	0	Load JPG	2
15	08/01/19 16:40	General View	0	Load JPG	V
16	08/01/19 16:40	General View	0	Load JPG	V
17.	08/01/19 16:40	General View	0	Load JPG	V
18	08/01/19 16:40	General View	0	Load 3PG	2
19	08/01/19 16:40	General View	0	Load JPG	V
20	08/01/19 16:40	General View	0	Load JPG	V
21	08/01/19 16:40	General View	0	Load 3PG	V
22	08/01/19 16:40	General View	0	Load JPG	50
23	08/01/19 16:40	General View	0	Load JPG	V
24	08/01/19 16:40	General View	0	Load JPG	V
25	08/01/19 16:40	General View	0	Load 3PG	1
26	08/01/19 16:40	General View	0	Load JPG	1
27	08/01/19 16:40	General View	0	Load JPG	V
28	08/01/19 16:40	General View	0	Load JPG	N
29	08/01/19 16:40	General View	0	Load JPG	V
30	08/01/19 16:40	General View	0	Load JPG	V
31	08/01/19 16:40	General View	0	Load JPG	V
32	09/01/19 16:29	Reinspection Photo	0	Load JPG	<b>S</b>
33	09/01/19 16:29	Reinspection Photo	0	Load JPG	V
34	09/01/19 16:29	Reinspection Photo	0	Load JPG	

Let	ters/Corresponde	nces	1 per	page 🔻	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					V
35	09/01/19 16:29	Reinspection Photo	0	Load JPG	V
36	09/01/19 16:29	Reinspection Photo	0	Load JPG	V
37	09/01/19 16:29	Reinspection Photo	0	Load JPG	V
38	09/01/19 16:29	Reinspection Photo	0	Load JPG	Ø
39	09/01/19 16:29	Reinspection Photo	0	Load JPG	V
40	09/01/19 16:29	Reinspection Photo	0	Load JPG	V
41	09/01/19 16:29	Reinspection Photo	0	Load JPG	2
42	09/01/19 16:29	Reinspection Photo	0	Load JPG	<b>Z</b>
43	09/01/19 16:29	Reinspection Photo	0	Load JPG	<b>V</b>
44	16/01/19 18:26	Reinspection Photo	0	Load JPG	V
45	16/01/19 18:26	Reinspection Photo	0	Load JPG	V
46	16/01/19 18:26	Reinspection Photo	0	Load JPG	V
47	16/01/19 18:26	Reinspection Photo	0	Load JPG	V
48	16/01/19 18:26	Reinspection Photo	0	Load 3PG	V
Doc	umentation		1 per i	page V	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	A per i	Thumbnail	-
1	14/01/19 19:27	TP GIA REPORT	0	Load PDF	Fine
2	02/03/19 09:27	TP ESTIMATE MARKED	Õ	Load PDF	
3	13/05/19 10:18	WORKSHOP INVOICE	ŏ	Load PDF	
4	13/05/19 10:18	AUTHORISATION TO ACT FORM	0	Load PDF	
5	13/05/19 10:18	Release Voucher	0	Load PDF	
6	13/05/19 10:18	LTA SEARCH	Ö	Load PDF	
7	13/05/19 10:18	LETTER TO OI	0	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	09/01/19 11:41	OI GIA REPORT	0	Load PDF	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			V
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

LKK Auto Consultants Pte Ltd

TEA		

# THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

	-	39B (Ins			Model:		JTD (M)	.9 D CARGO
Date of Accident:	GBB2530P (TP veh) of Accident: 03/01/2019		- SID (M)					
	1							
Global Sum Settlem	ent :	[ ]	Yes	Т	X] No			
Repair Estimate			: \$	<u> </u>	6,70	0.05		
Final Repair Cost			: \$		2,300	-		
Loss of Use			:\$		400	00.0	5.00 days at \$8	0.00 per day
Rental (if any)			: S		(	0.00	days	
LTA / GIA Search F	ee		: \$		7	.45		
Others:			: \$			00.0		
			: \$					
Final Settlement Su	m		: \$		2,707	45		
A) For Non GIA R			hop:		Agreed Liab BOLA Appli			
B) For GIA Raniel	ered Wo	orkshop:						
B) For GIA Regist BOLA Liability: * Assessed Liab			ly for cha	in co			(*):(es where BOLA doe	The state of the s
BOLA Liability: * Assessed Liab			lly for cha	in co			Marian and the second second	The state of the s
BOLA Liability: * Assessed Liab Remarks	bility to b	e filled or		in co			Marian and the second second	The second second second
BOLA Liability: * Assessed Liab Remarks Payment Instruction	bility to b	e filled or	kdown	in co			Marian and the second second	es not apply.
BOLA Liability: * Assessed Liab Remarks Payment Instruction	bility to b	e filled or	kdown	in co	ollisions and t		Marian and the second second	The second second second

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

Date

### LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/LCR19000438/UPA3Q2

Date:

13/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle

**GBB2530P** 

Insured Vehicle No:

SLQ6839B

Date of Loss:

03/01/2019

Nature of Claim:

Claim No: 6940702985SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

**GBB2530P** 

Make & Model:

FIAT DOBLO, 1.9 D CARGO JTD (M)

Engine No:

223B10005593784

Reg. Date: Colour

28/10/2008 (Man. Year: 2007)

Chassis No: Odometer:

ZFA22300005544049 272049 km

Engine Capacity:

1910 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side:

Kumho 6 mm

Rear Left Side: Rear Right Side: Kumho 6 mm Kumho 6 mm

Front Right Side: Kumho 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,140.05	1,816.85	3,323.20	64.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,060.00	500.00	32.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,700.05	2,876.85	3,823.20	57.06
Approved Total (Overridden) (S\$)	dden) (S\$)			
Nett Amount (S\$)	6,700.05	2,300.00	4,400.05	65.67
+ Loss of Use (5.0 x S\$	80.00/day) (S\$)	400.00		
+ Doc/S	earch Fee (S\$)	7.45		
Ne	tt Liability (S\$)	2,707.45		

INSPECTION

Date of Assignment:

08/01/2019

Date Inspected:

08/01/2019 Inspected At:

Liu's Brother Auto Engineering Workshop

(kaki Bukit) (HQ)

Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit

Singapore 417883

Estimated Period of Repair.

4.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 13/5/2019

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_... 13/5/2019

# REPAIR DETAILS

# Recommended Parts

Part No. Particulars	Condition	Repairer's	Amount
*REAR BUMPER	Dented / Deformed	627.00 F	*627.00 FL
*REAR BUMPER SIDE HOLDER N/S	Bent	72.50 F	*72.50 FL
*REAR BUMPER SIDE N/S	Deformed	283.70 F	*283.70 FL
*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
*REAR BUMPER REINFORCEMENT	Bent	475.30 F	*475.30 FL
*REAR BUMPER REFLECTOR	Broken	98.00 F	*98.00 FL
*REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
*REAR END PANEL	Repair	430.00 F	*-FL
*REAR TAIL LAMP	Not Necessary	388.70 F	*-FL
*REAR TAIL LAMP OUTER GARNISH	Not Necessary	154.40 F	*-FL
*REAR TAILGATE	Repair	2,156.00 F	*-FL
*REAR TAILGATE FIAT LOGO EMBLEM	Necessary	87.80 F	*87.80 FL
*REAR TAILGATE DOBLO EMBLEM s part. S=SpcNett. L=ListItemDisc.	Necessary	96.65 F	*96.65 FL
W 17	Sub Total (S\$)	5,140.05	1,990.95
- List Item Discount on	L Items 0.00/10.00% (S\$)	0.00	174.10
	Total Parts (S\$)	5,140.05	1,816.85
	Report was unsubmitted du	Total Parts (S\$)	

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	30.00
REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	60.00	50.00
LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	680.00	480.00
TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	500.00
REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	0.00
TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	0.00
Gross Labor	ır Cost (S\$)	1,560.00	1,060.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION REMOVE AND REFIX REAR BUMPER REVERSE SENSOR LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION  REMOVE AND REFIX REAR BUMPER REVERSE SENSOR New  LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & New REPLACING PARTS ETCS  TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS  REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE New REPAIRS  TO APPLY RUST PROOFING ,RESEAL TUFF-COATING New	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR New 50.00 PROPER FUNCTION  REMOVE AND REFIX REAR BUMPER REVERSE SENSOR New 60.00 LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & New 680.00 REPLACING PARTS ETCS  TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP New 600.00 PAINT ON ACCIDENT AFFECTED AREAS  REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE New 120.00 REPAIRS  TO APPLY RUST PROOFING, RESEAL TUFF-COATING New 50.00 TREATMENT ON ACCIDENT AREA

< END OF ESTIMATES >