COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 1921A

MAKE :

DATE 7/1/2019 11:20

JN JN

Qty	: HYUNDAI IONIQ Parts Description/ Labour Rear Bumper		Type	Unit Price		Amount		
Qi)			Type	Unit	Unit Price		Amount	1
						\$	459.40	
	Rear Bumper Reinforcement Rear Bumper Reinforcement Bracket (LH/RH)					\$	294.80	
				\$	138.10	\$	276.20	
	Rear Bumper Centre Moulding Assy					\$	451.25	10
	Rear Bumper Lower Centre Mouldin	g Assy				\$	47.50	
	Rear Bumper Stay					\$	138.10	
	Rear Bumper Side Bracket (LH/RH)			\$	33.10	\$	66.20	
	Rear Bumper Cover Clips					\$	22.00	
	Rear Bumper Reflector Lamp (LH/RH)			\$ 14-7	31.90	\$	63.80	
	Rear Bumper Towing Cover					\$	98.80	14
		SUB TOTAL				\$	1,918.05	
		LESS 20%				\$	383.61	
	DISCOU	NTED TOTAL				\$	1,534.44	
	Pass Passas P							
	Rear Bumper Reverse Sensor				dis	\$	135.70	
	Rear Bumper Reserve Light				one	\$		N
	Rear Bumper Rubber Mat				au-	\$	50.00	N
	LK	Auto Consultants he	nce notifi			_		-
	the	Repairer of the follow	ring:			\$	442.80	-
		resurvey before/after spray display damaged part(s) di		ey				
	• Pa	rts prices are subject to co	nfirmation		J 1			
		rd party survey is on a "Wi illegal modification(s) is al		fice" basis				
	Labour Charge	pplementary item(s) must t	be resurvey	ed and				
	Panel Beating	ubject to final approval fro	m Insurance	Company				3
	Ackr	owledged by Repairer				\$	400.00	
	Wining Channel	ature:				\$	300.00	
	Towing Charge-King Dolly					\$	30.00	-
	Remove/Refix Reverse Sensor					\$	160.00	
	Remove/Renx Reverse Sensor					\$	120.00	Bo
	Tanjum 9749 5749							
	() wp 10	TAL LABOUR				\$	1,010.00	
	Taufill 97495749 TOTAL LABOUR FILLIAGE Spar Resums before paint Part by Part. Hays taufilling librantonium.				-	_		
	Player letter paint ESTI	MATE TOTAL				\$	2,987.24	
	4 de	15						
	Part by part.							
	tay filling lillian to con							
	This is an initial estimate based on a visua	inspection of the al	bove veh	icle. The fin	al repair qua	antur	n will	