

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3394H

DATE 7/1/2019 16:53

AKA

MAKE :

Chiang

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>DE</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>new</i>			\$ 22.00
	<i>Rear bumper under cover cut</i>			
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 1,160.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resul
Hp 900 100 68
2 days
48
08/01/19 @ 1505
Resuy after repair

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.