

ASS. REC. BY:

REF

CS/MSG19000445/Ktd3m2

Special Instruction:

Survivor:

Menner

Kenneth

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

8/11/19 @ 2pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 3414R

Insured:

FBD 2227E

at Workshop n/s:

Cheng He Motor

Tel:

G481 2001

of

10 AMK Ind. Park 2A # 01-04

Policy No:

MSD/VMFT/18-991942

Claim No:

MSC/V/19-000029

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/01/2019

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

2:17pm 8/11/19

Person Contacted:

Dorlyn

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 3414R-X
	FBD 2227E-CC4/AxA16005675/R/wg3y2 DUA: 17/3/16
12/13	87759.87 Cabins & Fuel (Red: 3103.27:53%)

ASS. REC. BY:

REF: MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 3414R Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Wish c.c. 1798

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading 43554 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDG 20W 40J005335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 4/1/19

Survey held at

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 8/1/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/1 File pass to

Date/Time, File Pass to?

13/3 Typist

Date/Time, File Return to?

☐ : Prell. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + P.S. \$

Photos

Others

TOTAL

150
10

160

Report Format: TP

Lump Sum / I.B.I. (\$) 2759.87

14/3/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019 11:20		08 Jan 2019 14:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KANG AI BENG, ID: S7402135B		
Main Claimant:	TAN CHEE KIONG, ID: S7632392E		
Vehicle Reg. No.:	SLG3414R	Date of Loss:	04/01/2019 07:00 - :59 [27 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/19-000029	Policy/Cover Note No.:	MSD/VMFT/18-991942 (TP, Fire & Theft) Coverage: 02/05/2018 - 01/05/2019
Vehicle Reg. No. (Insured):	FBD2227E	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/01/2019]		
Driver/Custodian (Insured):	KANG AI BENG (), NRIC: S7402135B		
Adj Asg. Remarks:	Liability down, TP want to use LKK as the SJE. Contact Person: Dorlyn Li / 6481 2001.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	2392E

Vehicle Details

Vehicle No.:	SLG3414R
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	2ZR1836764
Chassis No.:	JTDGG20W40J005335
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	28 Sep 2016
First Registration Date:	28 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,955.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2026
PARF Rebate Amount:	\$14,966.00

Intended COE Rebate Details

COE Expiry Date:	27 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$44,018.00
Total Rebate Amount:	\$58,984.00

The information contained herein is correct as at 07 Jan 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO.201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 04/01/2019

TP Veh Reg No: FBD2227E

Estimate No: ES1991019/AMK

Date: 08 Jan 2019

Policy No: D18MTPV01014874

Veh Reg No: SLG3414R

Make/Model: TOYOTA WISH 1.8 CVT

Chassis No: JTDGG20W40J005335

Engine No: 2ZR1836764

Reg. Date: 28/09/2016

Estimate Repair Cost to Vehicle No :SLG3414R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	623.70	1 PC	623.70	✓
2 REAR BUMPER SIDE RETAINER	90.57	2 PC	181.14	✓
3 REAR BUMPER CLIP	3.89	5 PC	19.45	✓
4 REAR TAILGATE	1,640.10	1 PC	1,640.10	X
5 TAILGATE LOGO	61.70	1 PC	61.70	✓
6 TAILGATE EMBLEM 'VMATIC'	49.30	1 PC	49.30	✓
7 TAILGATE WINDSCREEN GLASS MOULDING	252.70	1 PC	252.70	X
8 TAILGATE INNER LOCK	391.60	1 PC	391.60	X
9 TAILGATE INNER RUBBER	341.10	1 PC	341.10	X
10 REAR END PANEL	540.30	1 PC	540.30	✓
11 REAR END PANEL INNER TOP GARNISH	278.60	1 PC	278.60	X
12 TAILLAMP LOWER RETAINER	61.20	2 PC	122.40	X
13 REAR END PANEL BUZZER SENSOR	171.19	1 PC	171.19	X
			4,673.28	
		Less 25%	1,168.32	3,504.96
Net Price				
14 REAR BUMPER PARKING SENSOR	185.10	1 PC	370.20	✓
			370.20	
		Less 10%	37.02	333.18
Special Net				
15 REAR NUMBER PLATE	35.00	1 PC	35.00	X
16 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	X
			75.00	75.00
Labour				
17 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	X
18 REMOVE & REFIX REAR BUMPER, TAILGATE & ATTACHMENTS, TAILLAMPS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR FENDERS, REAR LUGGAGE PANEL & REALIGN THE SAME	800.00	1 LA	800.00	600
19 PUTTY & RESPRAY REAR BUMPER, TAILGATE, BOTH FENDERS, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	850.00	1 LA	850.00	640
20 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	✓
21 RUSTPROOFING	90.00	1 LA	90.00	630
			1,910.00	1,910.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department
WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 04/01/2019
TP Veh Reg No: FBD2227E

Estimate No: ES1991019/AMK
Date: 08 Jan 2019
Policy No: D18MTPV01014874
Veh Reg No: SLG3414R
Make/Model: TOYOTA WISH 1.8 CVT
Chassis No: JTDGG20W40J005335
Engine No: 2ZR1836764
Reg. Date: 28/09/2016

Estimate Repair Cost to Vehicle No :SLG3414R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,823.14
			Add GST @ 7%	407.62
			Total Amount Payable	<u>S\$ 6,230.76</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19000445/KTD3N2

Date: 15/03/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMFT/18-991942
Claimant Vehicle No :	SLG3414R	Insured Vehicle No :	FBD2227E
Date of Loss:	04/01/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000029

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG3414R	Engine No:	2ZR1836764
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W40J005335
Reg. Date:	28/09/2016 (Man. Year: 2016)	Odometer:	43554 km
Colour:	Metallic Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,913.14	1,439.87	2,473.27	63.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,320.00	590.00	30.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,823.14	2,759.87	3,063.27	52.61
+ GST 7.00/7.00% (S\$)	407.62	193.19	214.43	52.61
Nett Amount (S\$)	6,230.76	2,953.06	3,277.70	52.61

INSPECTION

Date of Assignment:	08/01/2019	
Date Inspected:	08/01/2019 Inspected At:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG3414R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	623.70 FL	*623.70 FL
2	2		*REAR BUMPER SIDE RETAINER	Distorted	181.14 FL	*181.14 FL
3	5		*REAR BUMPER CLIP	Necessary	19.45 FL	*19.45 FL
4	1		*REAR TAILGATE	Repair	1,640.10 FL	* FL
5	1		*TAILGATE LOGO	Necessary	61.70 FL	*61.70 FL
6	1		*TAILGATE EMBLEM VMATIC	Necessary	49.30 FL	*49.30 FL
7	1		*TAILGATE WINDSCREEN GLASS MOULDING	Not Necessary	252.70 FL	* FL
8	1		*TAILGATE INNER LOCK	Repair	391.60 FL	* FL
9	1		*TAILGATE INNER RUBBER	Serviceable	341.10 FL	* FL
10	1		*REAR END PANEL	Bent	540.30 FL	*540.30 FL
11	1		*REAR END PANEL INNER TOP GARNISH	Serviceable	278.60 FL	* FL
12	2		*TAILLAMP LOWER RETAINER	Serviceable	122.40 FL	* FL
13	1		*REAR END PANEL BUZZER SENSOR	Serviceable	171.19 FL	* FL
14	1		*SET REAR BUMPER PARKING SENSOR	Shorted	370.20 FN	*370.20 FN
15	1		*REAR NUMBER PLATE	Serviceable	35.00 FS	* FS
16	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	40.00 FS	* FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	5,118.48	1,845.79
- List Item Discount on L Items 25.00/25.00% (S\$)	1,168.32	368.90
- Nett Item Discount on N Items 10.00/10.00% (S\$)	37.02	37.02
Total Parts (S\$)	3,913.14	1,439.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
2	REMOVE & REFIX REAR BUMPER, TAILGATE & ATTACHMENTS. TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR FENDERS, REAR LUGGAGE PANEL & REALIGN THE SAME	New	800.00	600.00
3	PUTTY & RESPRAY REAR BUMPER, TAILGATE, BOTH FENDERS, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	New	850.00	640.00
4	REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	New	50.00	50.00
5	RUSTPROOFING	New	90.00	30.00
Gross Labour Cost (\$\$)			1,910.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >