



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28/07/2020

Survey Details:

Date of loss	5-Jan-19
Date of appointment	8-Jan-19
Date of survey	8-Jan-19
Location of survey	REMIER AUTOMOTIVE SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHD 1175G
Make and Model	HYUNDAI I30 GDH 1.6 TCI
Date of registration	21/9/2016
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 7,027.71
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,412.89
Check items (estimate)	
Labour	\$ 1,140.00
Total	\$ 4,552.89
Lump Sum(if applicable)	\$ -

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Insured driver rear-ended third party

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/gst)	\$ 4,871.59	
Loss of use	NIL	
Loss of rental (6 days x \$103.79)	\$ 622.74	no. of days
Loss of income (6 days x \$50.00)	\$ 300.00	no. of days
GIA search fees	\$ 2.00	
Others	NIL	
Proposed Total	\$ 5,796.33	