## COMFORTDELGRO ENGINEERING PTE LTD

## **REPAIR ESTIMATE\***

MAKE

: SH 9647H VEHICLE NO

: HYUNDAI

DATE:

4. Jan. 2019

MODEL	: IONIQ		DOA:	4. Jan. 2019	EQ	
Qty	Parts Description,	Labour	Туре	Unit Price	Amount	
	1 Rear Bumper (Moulday &	3 lack ) All		price?	\$459.40	XR
	Rear Bumper Clips	( )		\$2.20	\$22.00	$\times NN$
1	1 Bracket Assy – Rear Bumper	Side – RH			\$33.10	2
		SUB TOTAL LESS 20% DISCOUNTED TOTAL  LKK Auto Consultants in the Repairer of the follo • To resurvey before/after spr • To display damaged part(s) • Parts prices are subject to e • Third party survey is on a "	ving: ay painting during resurvey onfirmation Vithout Prejudic	e" besis	\$514.50 \$102.90 \$411.60	
		a No illegal modification(s) is	allowed		\$-	
		Supplementary item(s) mus is subject to final approval	rom Insurance	Company		
	Labour Charge	Acknowledged by Repairer				
	Panel Beating	Signature:			\$300.00	200
	Spray Painting Charge	Date:			\$300.00	200
1	Remove/refix reverse sensor				\$100.00	20
Larry Ng	HILLIA 1600 NAZ LAK 441 PIP  CHECK ITEMS PHO APTEL RESOUR PHO		4	icle. The final repair qu	\$700.00 \$1,111.60	