

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9741E**AAD1812-242***Not Authenticated**11 Sep 8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9741E

VF1ABL15AUC273069

RENAULT

LATITUDE

29.12.2018

EQ

31/7/2013

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu/mir</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
4	1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
6	1	BUMPER RETAINER FRT RH	\$	<i>CM</i> 150.77
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
12	1	BUMPER BEAM FRT	\$	<i>N</i> 914.08
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61
14	1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
16	1	RADIATOR GRILLE FRAME	\$	1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>N</i> 177.22 X
20	1	HORN	\$	<i>SL</i> 314.17 X
21	1	HORN BRACKET	\$	<i>N</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>SL</i> 1,184.43 X
22	1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
22	1	HEADLAMP RH	\$	<i>CM</i> 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
22	1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15 ✓
26	1	BONNET	\$	<i>B</i> 1,941.63 ✓

Trans-cab Auto Services Pte Ltd**AAD1812-242**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9741E

27	1	BONNET INSULATOR	\$	SL	405.73	
28	1	BONNET STRUT LH	\$	SL	88.61	
29	1	BONNET STRUT RH	\$	SL	88.61	
30	1	BONNET HINGE LH	\$	N	348.31	
31	1	BONNET HINGE RH	\$	N	348.31	
32	1	BONNET LOCK	\$	N	305.48	
33	1	BONNET CABLE	\$	SL	119.19	
34	1	BONNET CABLE COVER	\$	SL	161.03	
35	1	BONNET SEAL OUTER	\$	SL	92.36	
36	1	BONNET SEAL INNER	\$	SL	157.28	
37	1	FENDER PANEL FRT RH	\$	N	783.83	✓
38	1	WHEELARCH FRT RH	\$	N	278.84	✓
39	1	FENDER BRACKET LOWER RH	\$	SL	15.79	X
40	1	FENDER INSULATOR RH	\$	SL	130.84	X
41	1	FENDER PANEL INNER FRT RH	\$	N	1,693.77	X
42	1	FENDER PANEL REINFORCEMENT FRT RH	\$	N	1,096.22	X
43	1	WHEEL HOUSING PANEL FRT RH	\$	N	5,173.47	X
44	1	WIPER RESERVOIR	\$	N	348.25	✓
45	1	WIPER RESERVOIR NECK	\$	SL	136.11	
46	1	WIPER RESERVOIR MOTOR	\$	SL	270.06	
47	1	AIR CLEANER LOWER	\$	SL	271.26	
48	1	AIR CLEANER HOSE	\$	SL	76.14	
49	1	AIR CLEANER BOX	\$	SL	464.20	
50	1	TURBO DUCT	\$	SL	1,027.80	
51	1	A/C HEATER VALVE	\$	SL	484.50	
52	1	SUBFRAME OUTER FRT	\$	SL	2,652.45	
53	1	SUBFRAME BRACKET OUTER LH	\$	N	92.36	
54	1	SUBFRAME BRACKET OUTER RH	\$	N	92.36	
55	1	ENGINE UNDERTRAY	\$	SL	564.98	
56	1	A/C CONDENSER	\$	SL	2,020.37	
57	1	A/C CONDENSER GARNISH LH UPPER	\$	SL	39.67	
58	1	A/C CONDENSER GARNISH RH UPPER	\$	SL	39.67	
59	1	A/C CONDENSER GARNISH LH	\$	SL	58.81	
60	1	A/C CONDENSER GARNISH RH	\$	SL	59.60	
61	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SL	208.39	
62	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SL	658.72	
74	1	A/C PIPE COMPRESSOR	\$	SL	334.29	
75	1	A/C PIPE	\$	SL	658.72	

Trans-cab Auto Services Pte Ltd**AAD1812-242**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9741E

76	1	A/C COMPRESSOR	\$	SL	2,684.61	
77	1	AIR COOLER	\$	SL	792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	SL	1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	SL	375.14	
80	1	TRANSMISSION COOLER	\$	SL	1,219.30	
81	1	TRANSMISSION COOLER PAD	\$	SL	17.96	
82	1	RADIATOR	\$	SL	1,202.20	X
83	2	RADIATOR STUD UPPER	\$	SL	14.41	
84	2	RADIATOR BUSH UPPER	\$	SL	50.12	
85	2	RADIATOR MTG LOWER	\$	SL	55.85	
86	1	RADIATOR FAN COWLING	\$	SL	820.54	
87	1	RADIATOR FAN MOTOR LH	\$	SL	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	SL	1,479.46	
89	1	RADIATOR TANK	\$	SL	324.62	
90	1	RADIATOR HOSE UPPER	\$	SL	240.56	
91	1	RADIATOR HOSE LOWER	\$	SL	491.18	
92	1	RADIATOR TANK HOSE	\$	SL	61.18	
93	1	DOOR PANEL FRT RH	\$	B	2,844.66	✓
94	1	DOOR MIRROR ASSY RH	\$	CR1	1,483.40	✓
95	1	LOWER ARM RH	\$		685.76	?
96	1	KUNCKLE ARM RH	\$	B	846.98	✓
97	1	ABSORBER FRT RH	\$	B	360.54	✓
98	1	STABILIZER BAR FRT	\$		604.65	?
99	1	DRIVESHAFT RH	\$		1,747.45	?
100	1	WIPER RESERVOIR	\$	SL	348.25	X
101	1	WIPER RESERVOIR NECK	\$	SL	136.11	X
102	1	WIPER RESERVOIR MOTOR	\$	SL	270.06	X

TOTAL	\$	58,463.76
10%	\$	5,846.38
	\$	52,617.38

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	SL	52.00	X
2	1SET	BUMPER CLIP FRT	\$	SL	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	SL	12.00	X

Trans-cab Auto Services Pte Ltd**AAD1812-242**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9741E

4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	}	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00		
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50		
7	1	TOW COVER FRT	\$	sn	14.50		
8	1SET	RADIATOR GRILLE SCREW	\$	na	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
21	1	Windscreen moulding	\$	na	100.00		
22	1SET	Front licence plate with holder	\$	sn	80.00	}	X
23	1	DOOR CHECK BOLT	\$	sn	22.69		
24	1	DOOR GUIDE SCREW	\$	sn	10.85		
25	1	DOOR HINGE BOLT	\$	sn	10.85		
26	1	DOOR HINGE NUT RH	\$	sn	14.60		
27	1	DOOR CHECK BOLT	\$	sn	22.69		
28	1	DOOR CHECK NUT	\$	sn	3.75		
29	1	DOOR LOCK SCREW L70Y	\$	sn	6.12		
30	1	DOOR CATCH SCREW L70Y	\$	sn	10.06		
31	1	FRONT RIGHT TYRE RIM	\$	Rn	380.00		
32	1	FRONT RIGHT TYRE	\$	Rn	330.00		

TOTAL	\$	1,374.13
TOTAL PARTS	\$	53,991.51

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 4,000.00 600

Towing Fees.

\$ 120.00 50

To apply paint protection system (PPS) maintain
and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 4,000.00 1100

Trans-cab Auto Services Pte Ltd**AAD1812-242**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9741E

To rust-proofing of the affected areas.	\$	170.00 Pol
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 Pol
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 Y
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To remove and refit air bag system and reset.	\$	nn 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 100%
To replace, refix and top up coolant for radiator	\$	170.00 50%
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1812-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9741E

To Transfer Of Bonnet Fittings, Attachments And
Perform Water Seepage Test.

\$ *nn* 170.00X

To Transfer Of Door Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 *601***TOTAL \$ 13,000.00****Over All Total \$ 66,991.51****Repair Days (Lump Sum)*****20* days***5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: