

SERVICE ESTIMATE

68632 - C00001 SL: SERVICE SALES - PC

Mr Patrick Raymon Mc Goldrick
27 Balmoral Road
#04-27

Singapore 259808

Closed by : Patricia Kueh Anak S
Svc Consultant :
Remarks : Mr Patrick Raymon Mc

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 04/01/2019
WIP No. . : 46765
Veh.In/Out:
*Tel.No. . : Mobile: 98157730
Reg.No. . : SKD3699M
Reg.date . : 25/11/2011
Mileage ... : 0
Chassis No: SAJAC0669CDS31436

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, 900	0	2700.00	0		2,700.00	\$ 1800
	FRT LH FENDER, FRT LH HEADLAMP, ETC						
800	TO PUTTY SPRAYPAINT ON	0	2400.00	0		2,400.00	\$ 1600
	FRT BUMPER, FRT LH FENDER, 200						
	BONNET, ETC						
0031	TO REPLACE FRT LH RIM	0	50.00	0		50.00	\$ ✓
0031	TO REPLACE FRT LH TYRE	0	950.00	0	80%	950.00	\$ punctured @ 760
419	WHEEL ALIGNMENT	0	280.00	0		280.00	\$ ✓
280	TO FOCUS HEADLAMP	0	162.00	0		162.00	\$ ✓?
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00	\$ ✓
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	JC2Z17044/ALLOY 18"	1.0 EA	1420.10			1,420.10	\$ cut ✓
	BUMPER COVER FRT S20	1.0 EA	2074.70			2,074.70	\$ cut ✓
	BUMPER BRACKET FRT L	1.0 EA	45.60			45.60	\$ ✓
	BUMPER BRACKET FRT R	1.0 EA	45.60			45.60	\$?
	JC2Z12921/HEADLAMP R	1.0 EA	2951.90			2,951.90	\$?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
WP
8/1/19 @ 2pm
Resurvey before paint.
4-5 days
sure lkkauto.com

SERVICE ESTIMATE

68632 - C00001 SL: SERVICE SALES - PC

Mr Patrick Raymon Mc Goldrick

27 Balmoral Road

#04-27

Singapore 259808

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 04/01/2019

WIP No. : 46765

Veh.In/Out:

*Tel.No. : Mobile: 98157730

Reg.No. : SKD3699M

Reg.date : 25/11/2011

Mileage : 0

Chassis No: SAJAC0669CDS31436

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Mr Patrick Raymon Mc

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	FENDER PANEL FRT RH	1.0 EA	1355.60			1,355.60	S ^{Rp}
	FENDER BRACKET FRT R	1.0 EA	41.70			41.70	S ^X
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	S ^{See}

L for bumper

Gross Total. 15,512.30

Labour Total	7,028.00
Parts Total	8,484.30
Package Total	0.00

Net.....	15,512.30
GST @ 7.0%	1,085.86
Total.....	16,598.15
Paid.....	0.00
Please Pay..	16,598.15

GST: S=StdRated; O=OutOfScope; Z=ZeroRated