

INS. CASE OWNER:

CHAN MAN NING

CC

3, ALG 1900

0467, R1h30

LKK:
IDAC:

Surveyor:

KASUL

DOI:

ASSIGNMENT

14/01/19

Date / Time:

8/1/19

Registered in Merimen:

8/1/19

Pre-assign / CCU / FTE

SLX 3521 A



Insured Vehicle No.:

Name of Insured:

My Yui Wei

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

3/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

2179270031SG

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SGA 2662M



INSRS:

WSP:

Tel:

Liability:

RMKS:

PML



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

1st

2nd

21-1-19

06/09/19

SGA 2662M - X ; SLX 3521 A - X

REC'D VIA FROM TP - DI HIGHLIGHTED
TP FROM MINER NO.

TP LOD IN BY EMAIL

TP CONFIRMED OWNER DO OP.
SUBMIT WP REPORT TO ALG.
TO CLOSE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

WP REPORT

3) Survey fee:

\$210.00

COPY SENT
10/9/19

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

288, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/836 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

#Car in#
08 JAN 2019

ESTIMATE

Estimate No. : b1 49688
Date Estimated : 08/01/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Choo Way Jiang
70 Shrewsbury Road

Singapore 307836

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0

DESCRIPTION

To replace rear bumper, reinforcement, rear RH tail
light & all attachments cause by accident.

To repair on rear boot & rear RH side panel

Painting on rear bumper, rear RH side panel & rear boot

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

VALUE

1700 3,480.00

1730 2,808.00

150 177.00

? 150.00

Total Labour 1: 6,535.00

DESCRIPTION

RR BUMPER CARRIER ECE ?
REINFORCEMENT BUMPER REAR BOTTOM ?
RR BUMPER TRIM STRIP (LUXURY LINE) CEA
REAR BUMPER CENTRE GUIDE ?
COVER ?
RR LH RETAINING STRIP FOR TRIM STRIP ?
RR RH RETAINING STRIP FOR TRIM STRIP ?
FLAP TOWING EYE PRIMED X MV
REAR BUMPER PANEL PRIMED (LINES) SEA
RR BUMPER LH SIDE GUIDE X MV
RR BUMPER RH SIDE GUIDE ?
REAR PDC HOLDER SET (PDC & PMA) ?
REAR PDC HOLDER SET (PDC & PMA) ?
LETTERING 420I X
REAR RH WATER GUTTER COVER ?
RR BUMPER RH REFLECTOR ?
REAR LIGHT RH IN THE SIDE PANEL PAN Bto
DECOUPLING RING PDC TORQUE CONVERTE ?
PDC SENSOR MIDNIGHT BLUE (B38) MS
(DG/SL) ADHESIVE SET K6 RA

QTY	PRIC	VALUE
1	467.95	467.95
1	70.90	70.90
1	149.20	149.20
1	56.80	56.80
1	62.20	62.20
1	13.50	13.50
1	13.50	13.50
1	43.25	43.25
1	1,207.45	1,207.45
1	49.30	49.30
1	49.30	49.30
1	66.95	66.95
1	66.95	66.95
1	64.10	64.10
1	40.85	40.85
1	36.80	36.80
1	447.50	447.50
4	5.05	20.20
1	368.80	368.80
1	53.05	53.05

Total Parts : 3,348.55



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747773

289, Tampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

113, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)


GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49688
Date Estimated : 08/01/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0



Claims OD (Ord Party / Uninsured losses / Direct Settlement)

Regn No. _____ Claim No. _____

Date & Time 14/01/19 @ 1730 Excess S\$ _____Surveyor's Name Rafael Sign _____Surveyor's Tel 900110068 Authorized Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR: Yes / No _____ PML: Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	6,535.00
Parts	:	3,348.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	691.85
Grand Total	:	10,575.40

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Friday, 6 September, 2019 5:36 PM
To: Chan, Kian-Meng
Cc: Admin A; Vic (LKKAuto)
Subject: <TP COVERT OD CLAIM> Your Ref: 2179276631SG - ACCIDENT INVOLVING VEHICLES SLX 3521A AND SGA 2662M ON 07/01/2019 - LKK REF CC3/AIG19000467/R1ha3
Attachments: SKM_558e19090615070.pdf

Your Ref: 2179276631SG

Dear Kian Meng,

ACCIDENT INVOLVING VEHICLES SLX 3521A AND SGA 2662M ON 07/01/2019

We refer to the above matter.

Please be informed that TP had converted to OD claim.

As such, we will proceed to close case and submit our report in merimen.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Vic (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 6 September, 2019 5:26 PM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: Re: LOD REMINDER - SGA2662M & SLX3521A ON 07/01/2019 - LKK REF CC3/AIG19000467/R1ha3

Dear Vic

Please ignore the email below. I will redirect to AIG.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Sent: Friday, 6 September 2019 4:59 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: 南珊 @ <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: LOD REMINDER - SGA2662M & SLX3521A ON 07/01/2019 - LKK REF CC3/AIG19000467/R1ha3

Without Prejudice

Dear Caroline,

We refer to your below email.

We would like to request for a copy of your client's video footage for our further action.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: PBSP [mailto:pml-pbsp@sime-darby.com.sg]
Sent: Friday, 6 September, 2019 4:09 PM
To: CS A Team; Admin A
Subject: LOD REMINDER - SGA2662M & SLX3521A ON 07/01/2019

LOD REMINDER

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 Chartis Building
Singapore 079120
Attention: Motor Claims

"Without Prejudice"

Your Ref :

Our Ref :

Date :

Subject :

28 March 2019

ACCIDENT INVOLVING VEHICLES SGA2662M & SLX3521A ON 07.01.2019

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Excess	:	S\$	642.00
Loss of use	:	S\$	960.00 (S\$120.00 x 8 days)
GIA search fee	:	S\$	2.00
Total	:	S\$	1604.00

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & Excess bill & GIA search slip
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License & **CD**
5. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438160
Tel AfterSales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

**LETTER OF AUTHORISATION**

ACCIDENT INVOLVING SGA 2662M & SLX 3521A **ON** 7/1/19.

I, Choo Way Jiang owner of Vehicle Registration No. SGA 2662M
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:

Name: CHOO WAY JIANG (Date)

NRIC No.: S1240934F

In the presence of:

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Name: _____ (Date)

NRIC No.:

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**

Repair Order No. : B1 1334366	Page No. : 1 of 2
Date IN : 29/01/2019	Invoice Number : 2079833 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 25/03/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -Mdm Choo Way Jiang
70 Shrewsbury Road

Singapore 307836

- INVOICE TO - 509Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

REGN. NO. SGA2662M	CHASSIS NO. D967694	REGN. DATE 22/05/2015	MODEL 420IA GC	MILEAGE 25084
------------------------------	-------------------------------	---------------------------------	--------------------------	-------------------------

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments, rear right light in side panel including make good the rear right fender, bootlid and knock out dented area caused by the accident.	2,125.00
To respray rear bumper, rear right fender and bootlid.	2,527.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. OD CLAIMS.	0.00
DATE OF ACCIDENT : 07.01.2019. POLICY NO : D18MTPV01008170	
YOUR REF NO : CMTD1900216/GPL.	
VEHICLE WAS SURVEYED BY MR TEO SL FROM SOMPO INSURANCE ON 28.01.2019. AUTHORISED REPAIR BY MS GRACE TEO FROM SOMPO INSURANCE ON 29.01.2019 VIA EMAIL.	
UNINSURED LOSSES HANDLED BY T.A. AGAINST AIG INSURANCE.	0.00
3RD PARTY CAR : SLX3521A. INSURANCE EXCESS = \$642.00.	
PROPOSE LOSS OF USE = \$120x8. GIA SEARCH FEE = \$2.00.	
THE LOU AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	
VEHICLE WAS ALSO SURVEYED BY MR RASUL FROM LKK AUTO ON 14.01.2019 AT 5:30PM.	0.00

Total Labour 1: **4,882.00****- - - - PARTS - - - -**

	Qty	Retail Price	NETT
REAR PDC HOLDER SET (PDC & PMA)	1	66.95	66.95
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
PDC SENSOR MIDNIGHT BLUE (B38)	1	368.80	368.80
REAR VENTILATION	1	39.35	39.35
RR BUMPER TRIM STRIP (LUXURY LINE)	1	149.20	149.20
REAR BUMPER PANEL PRIMED (LINES)	1	1,207.45	1,207.45
LETTERING 420I	1	64.10	64.10



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Tampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63445773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190536 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : **B1 1334366**
Date IN : **29/01/2019**
Cust. Svc. Advisor: **Kevin Leong Wai Kit**

Page No. : **2 of 2**
Invoice Number : **2079833 / WSB**
Invoice Date : **25/03/2019**
Payment Terms : **30 Days From Invoice**
Invoice By : **Toh Jing Xuan**

REAR LIGHT RH IN THE SIDE PANEL PAN
RR BUMPER RH SIDE GUIDE

1	447.50	447.50
1	49.30	49.30
Total Parts :		2,465.90

Labour Charges : **4,802.00**
Parts Charges : **2,465.90**
Lubricant/Misc : **80.00**

Total Labour & Parts Charges	: S\$	7,347.90
Less Insurance Excess	: S\$	600.00
Invoice Total Amount Exclude GST	: S\$	6,747.90
GST @ 7%	: S\$	472.35
Invoice Total Amount Include GST	: S\$	7,220.25

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 7,220.25**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

303 Alexandra Road, Sime Darby Performance Centre, Singapore 159941

Tel: 63190100 (Sales & Admin) 63190111 (AfterSales)

**OFFICIAL RECEIPT**

Receipt No. : 818025

B1

Page No. : 1 of 1

Txn: 520874

Receipt Date : 16 Feb 2019

Print Date : 16 Feb 2019 11:05:03AM

- Received From -

Customer No. : 45000

Choo Way Jiang

70 Shrewsbury Road

Singapore 307836

Issued By : Doris Ng Siew Po

Invoice No. : 0

Txn Type : Service Insurance Excess

Sales Rep : -

Registration No. : SGA2662M

VSA No. :

Quotation No. :

Chassis No. : D967694

Cust Order No. :

Repair Order No. :

Payment	Description	Date	Amount
Visa			642.00

Remarks : CSA: Kevin off / Joseph off - counter

GST @ 0.00% (Taxable Supplies SGD\$ 0.00)**RECEIPT TOTAL :SGD\$ 642.00**Note : This receipt will only be valid subject to cheque clearance.
This is a computer generated receipt. No signature is required.

Original

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

303 Alexandra Road, Sime Darby Performance Centre, Singapore 159941

Tel: 63190100 (Sales & Admin) 63190111 (AfterSales)

**OFFICIAL RECEIPT**

Receipt No. : 818025

B1

Page No. : 1 of 1

Txn: 520874

Receipt Date : 16 Feb 2019

Print Date : 16 Feb 2019 11:05:03AM

- Received From -

Customer No. : 45000

Choo Way Jiang

70 Shrewsbury Road

Singapore 307836

Issued By : Doris Ng Siew Po

Invoice No. : 0

Txn Type : Service Insurance Excess

Sales Rep : -

Registration No. : SGA2662M

VSA No. :

Quotation No. :

Chassis No. : D967694

Cust Order No. :

Repair Order No. :

Payment	Description	Date	Amount
Visa			642.00

Remarks : CSA: Kevin off / Joseph off - counter

GST @ 0.00% (Taxable Supplies SGD\$ 0.00)**RECEIPT TOTAL :SGD\$ 642.00**Note : This receipt will only be valid subject to cheque clearance.
This is a computer generated receipt. No signature is required.

Finance

Third Party Insurer Enquiry

Our Ref No: GR-19-003808

Date of Request: 08/01/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 08/01/2019

Enquiry By Melanie Setiawati

TP Vehicle No. SLX3521A

Accident Date 07/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLX3521A	AIG Asia Pacific Insurance Pte. Ltd.	26/03/2018-25/03/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-003808

Date of Request: 08/01/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 08/01/2019
Enquiry By Melanie Setiawati
TP Vehicle No. SLX3521A
Accident Date 07/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

PRIVATE CAR POLICY SCHEDULE

Intermediary Code : 11L19900

Policy No. : D18MTPV01008170

This Schedule is issued in accordance and should be read in conjunction with the terms, conditions and exceptions of the PRIVATE CAR Policy wordings, ref. MTP.27

Insured : CHOO WAY JIANG
Address : 70, SHREWSBURY ROAD
SINGAPORE 307836
Business/Profession : RETIREE

INSURED DETAILS

Date of Birth & Age : 16 APR 1957 & 61 years old
Driving Experience in Singapore : 39 years

Marital Status : MARRIED
Gender : Female

Identification Type : NRIC(Singaporean)

Identification No. : S1240934F

Period of Insurance : 22 MAY 2018 00:00 TO 21 MAY 2019 23:59

Persons or Classes of Persons entitled to drive : Refer to Certificate of Insurance

Limitations as to use : Refer to Certificate of Insurance

VEHICLE DETAILS

Vehicle Registration No. : SGA2662M
Chassis No. : WBA4A12050D967694
Engine No. : B2070640N20B20B
Vehicle Make & Model : BMW 420i GRAN COUPE
Engine Capacity/Tonnage : 1997
Type of Body : SALOON
Year of Registration : 2015
Seating Capacity (including driver) : 4
Estimated value of Vehicle : Market value at time of loss
Hire Purchase Owner : UNITED OVERSEAS
BANK LIMITED

PREMIUM DETAILS

Premium	2,307.84
Less No Claim Discount (50%)	(1,153.92)
Less Offence free Discount (5%)	(57.70)
Add others :	
Less Loyalty Discount(5%)	(54.81)
Total	S\$ 1,041.41
GST	S\$ 72.9
Premium (incl. GST)	S\$ 1,114.31

Coverage : Comprehensive - EXCELDRIIVE PRESTIGE

Excess : \$ 600 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)

Voluntary Excess : N.A

Additional Excess : Named Young and/or Inexperienced Drivers or Elderly Drivers - \$1,500
Un-named Young and/or Inexperienced Drivers or Elderly Drivers - \$3,000
Un-named All Other Drivers - \$500

The terms shall be defined as follows:

'Young Drivers' shall be defined as drivers (including the Insured) who are below 25 years old.

'Inexperienced Drivers' shall be defined as drivers (including the Insured) who have less than 2 years of driving experience in Singapore

'Elderly Drivers' shall be defined as drivers (including the Insured) who are above 70 years old.

Paragraph 2 of Endorsement E in the policy will not apply to insured's spouse provided he/she is 25 years old & above but less than 70 years old &/or has 2 or more years driving experience

Windscreen Excess : S\$100.00 - Waived if Repair at ExcelDrive Workshop

Endorsements Applicable : Endorsement D - Young and/or Inexperienced or Elderly Drivers Excess
Endorsement E - Excess Clause
Endorsement H - Total Loss
Endorsement L - Hire Purchase
Endorsement M - Inclusion Of Special Perils
Endorsement P6 - Riot And Strike Endorsement
Endorsement V - No Claim Discount Protection
Endorsement Y1 - ExcelDrive Prestige Plan

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1240934F



Name

CHOO WAY JIANG



朱 慰 然

Race

CHINESE

Date of Birth

18-04-1957

Sex

F

Country of Birth


SINGAPORE

S1240934F



07311

NRIC No: S1240934F



Blood Group

O+

Date of issue

10-01-1993

Address

1 TO 540245607 ROAD
SINGAPORE 1120

NRIC No: S1240934F

Date: 18-12-1994

No: 1575541


REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S1233886D**
 Name: **POON WAI TUCK**
 Birth Date: **19 Apr 1957**
 Issue Date: **20 Oct 2003**

000833067D

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1233886D




POON WAI TUCK
潘偉德
 Race: **CHINESE**
 Date of Birth: **19-04-1957** Sex: **M**
 Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)


Class	Vehicle Class	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	14 Dec 1984



NP 428A



2994


 NRIC No: **S1233886D**
 Blood Group: **O+** Date of Issue: **14-04-1997**
 Address:
70 SHREWSBURY ROAD
SINGAPORE 307836

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190886 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796401 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49688
Date Estimated : 08/01/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Choo Way Jiang
70 Shrewsbury Road

Singapore 307836

- ACCOUNT - 509

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0

DESCRIPTION

To replace rear bumper, reinforcement, rear RH tail light & all attachments cause by accident.

To repair on rear boot & rear RH side panel

Painting on rear bumper, rear RH side panel & rear boot

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

2/25 3,400.00

2527 2,808.00

150 177.00

? 150.00

Total Labour 1: 6,535.00

DESCRIPTION

RR BUMPER CARRIER ECE ?
REINFORCEMENT BUMPER REAR BOTTOM ?
RR BUMPER TRIM STRIP (LUXURY LINE) —
REAR BUMPER CENTRE GUIDE ?
COVER
RR LH RETAINING STRIP FOR TRIM STRIP ?
RR RH RETAINING STRIP FOR TRIM STRIP ?
FLAP TOWING EYE PRIMED X
REAR BUMPER PANEL PRIMED (LINES) —
RR BUMPER LH SIDE GUIDE ?
RR BUMPER RH SIDE GUIDE ?
REAR PDC HOLDER SET (PDC & PMA) —
REAR PDC HOLDER SET (PDC & PMA) —
LETTERING 420I —
REAR RH WATER GUTTER COVER ?
RR BUMPER RH REFLECTOR ?
REAR LIGHT RH IN THE SIDE PANEL —
DECOUPLING RING PDC TORQUE CONVERTER —
PDC SENSOR MIDNIGHT BLUE (B38) —
(DG/SL) ADHESIVE SET K6 —

QTY	PRIC	VALUE
1	467.95	467.95
1	70.90	70.90
1	149.20	149.20
1	56.80	56.80
1	62.20	62.20
1	13.50	13.50
1	13.50	13.50
1	43.25	43.25
1	1,207.45	1,207.45
1	49.30	49.30
1	49.30	49.30
1	66.95	66.95
1	66.95	66.95
1	64.10	64.10
1	40.85	40.85
1	36.80	36.80
1	447.50	447.50
4	5.05	20.20
1	368.80	368.80
1	53.05	53.05

Total Parts : 3,348.55



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190537/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796628 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49688
Date Estimated : 08/01/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0

Claims CD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>28711/19</u>	Claim No. _____
Date & Time <u>28/1/19</u>	Excess S\$ <u>600</u>
Surveyor's Name <u>Pan Loong</u>	Signature <u>?</u>
Surveyor's Tel <u>6883333</u>	Authorised Yes / No
Authorised Date <u>21/1</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend _____	

Pan Loong

5-6 95

Labour 1	:	6,535.00
Parts	:	3,348.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	691.85
Grand Total	:	10,575.40

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2019 Edit Reg		14 Jan 2019 00:00 Edit Adj Rpt	\$55,806.00 Edit Estimates	\$55,806.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: NG YUI WEI , ID: 57343460B									
Main Claimant: CHOO WAY JIANG , ID: S1240934F									
Vehicle Reg. No.:	SGA2662M	Date of Loss:	07/01/2019 18:00 - :59 [43 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2179276631SG	Policy/Cover Note No.:	1800024465 (Comprehensive) Coverage: 26/03/2018 - 25/03/2020						
Vehicle Reg. No. (Insured):	SLX3521A	Policy No. (Claimant):	D18MTPV01008170						
Excess:									
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com									
Claimant's Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/01/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGA2662M (2179276631SG)**
[SLX3521A]
TP
CHOO WAY JIANG
Jan 7 2019 6:00PM
[NG YUI WEI]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page 1 <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/09/19 13:35	TP Video - Accident	Load AVI	
Photos/Images			1 per page 1 <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/19 17:41	Odometer Reading	Load JPG <input checked="" type="checkbox"/>	
2	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
3	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
4	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
5	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
6	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
7	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
8	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
9	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
10	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
11	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
12	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
13	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
14	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
15	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
16	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
17	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
18	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
19	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
20	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
21	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
22	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
23	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
24	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
25	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
26	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
27	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
28	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
29	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
30	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
31	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
32	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
33	06/09/19 17:42	General View	Load JPG <input checked="" type="checkbox"/>	
Documentation			1 per page 1 <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/19 18:37	TP ESTIMATE + docs	Load PDF	
2	08/01/19 18:37	TP GIA REPORT	Load PDF	
3	17/01/19 16:58	TP ESTIMATE - MARKED	Load PDF	
4	06/09/19 17:33	EMAIL FROM TP	Load PDF	
5	06/09/19 17:37	EMAIL TO AIG	Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	09/01/19 12:12	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19000467/R1HA3Q2

Date: 16/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800024465
Claimant SGA2662M **Insured Vehicle No :** SLX3521A
Vehicle No : SGA2662M
 Date of Loss: 07/01/2019 Nature of Claim: TP Claim No: 2179276631SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGA2662M**
 Make & Model: BMW 420i, 2.0 Gran Coupe (A) Engine No: B2070940N20B20B
 Reg. Date: 22/05/2015 (Man. Year: 2014) Chassis No: WBA4A12050D967694
 Colour: Blue Odometer: 25083 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,498.55	2,226.00	1,272.55	36.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,385.00	3,580.00	2,805.00	43.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,883.55	5,806.00	4,077.55	41.26
+ GST 7.00/7.00% (S\$)	691.85	406.42	285.43	41.26
Nett Amount (S\$)	10,575.40	6,212.42	4,362.98	41.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 14/01/2019
 Date Inspected: 14/01/2019 Inspected At: Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	*Check	150.00 FS	*- FS
2	1		*RR BUMPER CARRIER ECE	*Check	467.95 FS	*- FS
3	1		*REINFORCEMENT BUMPER REAR BOTTOM	*Check	70.90 FS	*- FS
4	1		*RR BUMPER TRIM STRIP (LUXURY LINE)	Cracked	149.20 FS	*149.20 FS
5	1		*REAR BUMPER CENTRE GUIDE	*Check	56.80 FS	*- FS
6	1		*COVER	*Check	62.20 FS	*- FS
7	1		*RR LH RETAINING TRIP FOR TRIM STRI	*Check	13.50 FS	*- FS
8	1		*RR RH RETAINING TRIP FOR TRIM STRI	*Check	13.50 FS	*- FS
9	1		*FLAP TOWING EYE PRIMED	Not Necessary	43.25 FS	*- FS
10	1		*REAR BUMPER PANEL PRIMED (LINES)	Scratched	1,207.45 FS	*1,207.45 FS
11	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	49.30 FS	*- FS
12	1		*RR BUMPER RH SIDE GUIDE	*Check	49.30 FS	*- FS
13	1		*REAR PDC HOLDER SET (PDC & PMA)	*Check	66.95 FS	*- FS
14	1		*REAR PDC HOLDER SET (PDC & PMA)	*Check	66.95 FS	*- FS
15	1		*LETTERING 420I	Not Necessary	64.10 FS	*- FS
16	1		*REAR RH WATER GUTTER COVER	*Check	40.85 FS	*- FS
17	1		*RR BUMPER RH REFLECTOR	*Check	36.80 FS	*- FS
18	1		*REAR LUGHT RH IN THE SIDE PANEL PAN	Broken	447.50 FS	*447.50 FS
19	4		*DECOUPLING RING PDC TORQUE CONVERTE	*Check	20.20 FS	*- FS
20	1		*PDC SENSOR MIDNIGHT BLUE(B38)	Missing	368.80 FS	*368.80 FS
21	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
Total Parts (\$\$)					3,498.55	2,226.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,REINFORCEMENT ,REAR RH TAIL LIGHT & ALL ATTACHMENTS CAUSE BY ACCIDENT TO REPAIR ON REAR BOOT & REAR RH SIDE PANEL	New	3,400.00	1,700.00
2	PAINTING ON REAR BUMPER ,REAR RH SIDE PANEL & REAR BOOT	New	2,808.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			6,385.00	3,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >